

A U T O M O T I V E D A T A B O O K B U L L E T I N #4-941
February 7, 1995

		FRONT FMSI NO.	SYSTEM F/R	REAR FMSI NO.
<u>ALFA ROMEO</u>				
1995, 164		7469-D590**	D/D	7498-D228**
<u>AUDI</u>				
1995, S6		7306-D419**	D/D	7309-D228**
	OR	7434-D555**	D/	
<u>BUICK</u>				
1995-92, Roadmaster Station Wagon		7214A-D52	D/BH	2134BTT-S652
<u>CADILLAC</u>				
1995, Brougham		7214A-D52	D/BH	2134BTT-S652
	OR		/BH	2073AT-S653
1995, DeVille Concours		7384-D623**	D/D	7387-D508**
<u>CHEVROLET</u>				
1995, Caprice Station Wagon		7214A-D52	D/BH	2134BTT-S652
1995, Caprice Police		7506-D614**	D/D	7505-D628**
<u>CHEVROLET TRUCK/GMC TRUCK</u>				
P30/P3500 1995		7081A-D149	D/BH	2042BT-S655
	OR		/BH	2157AT-S656
P30DRW/P3500DRW 1995		7081A-D149	D/BH	2157AT-S656
	OR		/D	7081-D543**
<u>CHRYSLER</u>				
1995, Sebring		7365-D484**	D/N	1445-S658*
	OR		/D	7272-D383**
1995, Lebaron		7403A-D521	D/N	1456-S657*
	OR		/D	7438A-D559
1995, Town and Country		7403A-D521	D/BH	2176T-538
1995, Town and Country AWD		7403A-D521	D/BH	2025T-446*
<u>DODGE</u>				
1995, Avenger		7365-D484**	D/N	1445-S658*
	OR		/D	7272-D383**
1995, Intrepid		7470A-D642	D/N	1456-S657*
	OR		/D	7438A-D658
1995, Spirit		7403A-D521	D/N	1456-S657*
	OR		/D	7438A-D559
1995, Stealth FWD		7412-D530**	D/D	7272-D383**
1995, Stealth AWD		7413-D531**	D/D	7510-D631**
1995, Viper		7471-D592**	D/D	7472-D491**
1995, Caravan		7403A-D521	D/BH	2176T-538
1995, Grand Caravan		7403A-D521	D/BH	2176T-538
1995, Grand Caravan AWD		7403A-D521	D/BH	2025T-446*
<u>DODGE TRUCK</u>				
Caravan C/V 1995		7403A-D521	D/BH	2176T-538
Extended Caravan C/V 1995		7403A-D521	D/BH	2176T-538

SEE DISCLAIMER AT END OF BULLETIN

FMSI® and FMS® are registered trademarks of the Friction Materials Standards Institute, Inc.

Copyright© by Friction Materials Standards Institute, Inc.

		FRONT	SYSTEM	REAR
		FMSI NO.	F/R	FMSI NO.
<u>EAGLE</u>				
1995, Summit		7482-D602**	D/N	1415-S677*
	OR	7483-D602**	D/D	7474-D596**
1995, Talon		7365-D484**	D/D	7447-D567**
1995, Talon 4WD		7412-D530**	D/D	7414-D532**
1995, Vision		7470A-D642	D/D	7438A-D658
<u>FORD</u>				
1995, Aspire		7219-D466**	D/N	1472-S688*
1995, Crown Victoria		7537-D659**	D/D	7424A-D544
		(Notes #1 & #8)		
1995, Crown Victoria Police		7537-D659**	D/D	7424A-D544
1995, Escort		7353-D473**	D/N	1463-S678*
	OR		/D	7338-D458**
1995, Mustang		7478-D600**	D/D	7504-D627**
1995, Mustang Cobra		7300-D412**	D/D	7524-D627**
1995, Probe		7515-D637**	D/N	1407-S667*
	OR		/D	7464-D584**
1995, Taurus		7479-D601**	D/N	1395-599
	OR		/D	7489A-D610
1995, Taurus Wagon		7479-D601**	D/N	7496-S618
	OR		/D	7499A-D610
1995, Taurus Police		7479-D601**	D/D	7499A-D610
1995, Taurus SHO		7479-D601**	D/D	7499A-D610
1995, Thunderbird		7478-D600**	D/N	1407-S667*
1995, Thunderbird SC		7478-D600**	D/D	7499A-D610
<u>FORD TRUCK (See Comments & Corrections)</u>				
Aerostar	1995	7488-D607**	D/BH	2179T-581*
				(Note #7)
Bronco	1995	7503-D632**	D/BH	2141AT-582
Ranger	1995		/BH	2151T-569
			/BH	2179T-581*
E-150	1995	7503-D632**	D/BH	2141AT-582
E-250	1995	7436-D557**	D/BH	2146T-316
			/BH	2140AT-314
F-150	1995	7503-D632**	D/BH	2141AT-582
F-450 Super Duty	1995	7299-D411**	D/D	7299-D411**
E-350	1994		/BH	2178T-583*
				(Note #6)
F-350	1994		/BH	2178T-583*
E-350	1995	7436-D557**	D/BH	2140AT-314
			/BH	2178T-583*
F-350	1995	7535-D655**	D/BH	2140AT-314
			/BH	2178T-583*
<u>GEO (See Comments & Corrections)</u>				
1995, Tracker		7305-D418**	D/N	1483-S641*
				(Note #5)
1994, Tracker			/N	1483-S641*
<u>HONDA</u>				
1995, Civic		7439-D560**	D/N	1379-S639*
	OR	7493-D617**	D/N	1364-576*
	OR		/D	7443-D564**
1995, Civic del Sol		7439-D560**	D/N	1379-S639*
	OR	7493-D617**	D/D	7443-D564**
1995, Passport		7347-D363**	D/N	1360-S619*
	OR	7459-D579**	D/D	7460-D580**

		FRONT FMSI NO.	SYSTEM F/R	REAR FMSI NO.
<u>ISUZU (Commercial)</u>				
Truck NPR 1995-92		7425-D546**	D/N	1417-S612
	OR	1482-S699	N/N	1482-S699
		(Notes #4 & #9)		
Truck NPR Flat Low 1992-87		7425-D546**	D/N	1454-S668
	OR	1417-S612	N/	
<u>JAGUAR (See Comments)</u>				
1994, XJ6		7395-D394**	D/D	7539-D517** (Note #3)
1993-91, XJ6		7395-D394**	D/D	7396-D517**
1994, XJ12		7519-D640**	D/D	7539-D517**
1995, XJS		7067-D135**	D/D	7466-D586**
1994, XJS		7067-D135**	D/D	7539-D517**
	OR		/D	721-D9**
1993-89, XJS		7067-D135**	D/D	721-D9**
<u>JEEP</u>				
1995, Cherokee		7507A-D477	D/BH	2176T-538
	OR		/BH	2174TT-S670*
1995, Grand Cherokee		7507A-D477	D/	
1995, Wrangler		7507A-D477	D/BH	2176T-538
<u>KIA</u>				
1995, Sephia		7529-D649**	D/N	1480-S697*
<u>LAND ROVER</u>				
1995, Ranger Rover County		7401-D520**	D/D	7399-D518**
1995, Ranger Rover County LWB		7401-D520**	D/D	7399-D518**
1995, Defender		7401-D520**	D/D	7399-D518**
1995, Discovery		7401-D520**	D/D	7399-D518**
<u>LEXUS</u>				
1995, ES 300		7357-D476**	D/D	7223-D325**
1995, GS 300		7495-D619**	D/D	7452-D572**
<u>LINCOLN</u>				
1995, Continental		7479-D601**	D/D	7489A-D610
1995, Mark VIII		7476-D598**	D/D	7477A-D599
1995, Town Car		7537-D659**	D/D	7424A-D544
<u>MAZDA (See Comments & Corrections)</u>				
1995, Protege		7353-D473**	D/N	8104-S659*
	OR		/D	7338-D458**
1995, MX3		7353-D473**	D/N	8104-S659*
	OR		/D	7453-D573**
1995, Miata		7513-D635**	D/D	7514-D636**
1995, MPV 2WD		7429-D550**	D/BH	2177-609*
	OR		/D	7432-D553**
1995, MPV AWD		7430-D551**	D/BH	2177-609*
	OR		/D	7432-D553**
1994, MPV 2WD	OR		/D	7432-D553**
1994, MPV AWD	OR		/D	7432-D553**
1994, Navajo	OR		/BH	2179T-581*
<u>MERCEDES (See Comments)</u>				
1995, C220		7523-D645**	D/D	7315-D335**
	OR		/D	7496-D620**
1995, C250		7523-D645**	D/D	7315-D335**
	OR		/D	7496-D620**

	FRONT FMSI NO.	SYSTEM F/R	REAR FMSI NO.
<u>MERCEDES (con't)</u>			
1995, C280	7523-D645**	D/D	7315-D335**
	OR	/D	7496-D620**
1995, E300D	7311-D423**	D/D	7315-D335**
1995, E320	7525-D561**	D/D	7374-D495**
	OR	D/D	7374-D495**
	(Note #2)		
1995, S320	7538-D561**	D,	7374-D495**
1995, E420	7538-D561**	D/L	7374-D495**
1995, E500	7525-D561**	D/D	7374-D495**
1995, SL320	7525-D561**	D/D	74-D495**
1995, SL500	7525-D561**	D/D	74-D495**
1995, SL600	7525-D561**	D/D	74-D603**
1995, S500	7457-D577**	D/D	7484-D603**
1995, S600	7457-D577**	D/D	7484-D603**
<u>MERCURY (See Corrections)</u>			
1995, Cougar XR7	7478-D600**	D/N	1396-S618
	OR	/D	7477A-D599
1995, Grand Marquis	7537-D659**	D/D	7424A-D544
1995, Grand Marquis Police	7537-D659**	D/D	7424A-D544
1995, Sable	7479-D601**	D/N	1395-599
	OR	/D	7489A-D610
1995, Sable Police	7479-D601**	D/D	7489A-D610
1995, Sable Wagon	7479-D601**	D/N	1396-S618
	OR	/D	7489A-D610
1995, Tracer	7353-D473**	D/N	1463-S678*
	OR	/D	7338-D458**
1994, Tracer		/N	1463-S678*
1995, Villager	7456-D576**	D/N	1452-S665
<u>MITSUBISHI</u>			
1995, 3000 GT	7412-D530**	D/D	7272-D383**
1995, 3000 GT VR4	7413-D531**	D/D	7510-D631**
1995, Diamante	7412-D530**	D/D	7272-D383**
1995, Galant	7365-D484**	D/N	1445-S658*
	OR	/D	7272-D383**
	OR	/D	7447-D567**
1995, Mirage	7482-D602**	D/N	1415-S677*
	OR	D/D	7474-D596**
1995, Pick-Up	7241-D349**	D/N	1370-524*
<u>NISSAN</u>			
1995, Quest	7456-D576**	D/N	1452-S665
<u>PLYMOUTH</u>			
1995, Acclaim	7403A-D521	D/N	1456-S657*
	OR	/D	7438A-D559
1995, Voyager	7403A-D521	D/BH	2176T-538
1995, Grand Voyager	7403A-D521	D/BH	2176T-538
1995, Grand Voyager AWD	7403A-D521	D/BH	2025T-446*
<u>PORSCHE</u>			
1995, 911	7327-D609**	D/D	7326-D446**
1995, 911 Carrera 2	7327-D609**	D/D	7326-D446**
1995, 911 Carrera 4	7327-D609**	D/D	7326-D446**
1995, 911 Turbo	7327-D609**	D/D	7326-D446**

		FRONT FMSI NO.	SYSTEM F/R	REAR FMSI NO.
SAAB				
1995, 900		7522-D644**	D/D	7316-D427**
1995, 9000		7292-D403**	D/D	7221-D322**
SUBARU				
1995, Impreza		7442-D563**	D/N	1462-S676*
	OR	7350-D470**	D/D	7351-D471**
1995, Legacy		7350-D470**	D/D	7351-D471**
TOYOTA				
1995, Camry		7441-D562**	D/N	1447-587*
	OR	7357-D476**	D/D	7223-D325**
1995, MR2		7153-D242**	D/D	7409-D528**
	OR	7462-D582**	D/D	7409-D657**
1995, Tercel		7153-D242**	D/N	1439-S642*
1994-93, Supra		7495-D619**	D/D	7452-D572**
VOLKSWAGEN				
1995, Golf III		7209-D569**	D/N	1450-S662
	OR	7177-D227**	D/D	7234-D340**
1995, Golf GTI		7177-D227**	D/D	7234-D340**
	OR	7143-D290**	D/	
1995, Jetta III		7209-D569**	D/N	1450-S662
	OR	7177-D227**	D/D	7234-D340**
	OR	7143-D290**	D/	
1995, Passat		7177-D227**	D/D	7234-D340**
	OR	7143-D227**	D/	
	OR	7434-D555**	D/	
1995, Cabriolet		7143-D290**	D/D	7234-D340**
1995, Eurovan		7461-D581**	D/N	1453-S666*
	OR	7516-D638**	D/	
VOLVO				
1995, 850		7494-D618**	D/D	736-D31**
1995, 940		7512-D634**	D/D	7279-D391**
	OR		/D	7422-D541**
1995, 960		7512-D634**	D/D	7422-D541**

C O M M E N T S**Existing shoe with new lining:**

Shoe	Assembly	Application
581	2179T-581	1995 Ford Truck Aerostar Rear
		1995 Ford Truck Ranger Rear
		1994 Mazda Navajo Rear
583	2178T-583	1995-94 Ford Truck E-350 Rear
		1995-94 Ford Truck F-350 Rear
S641	1483-S641	1995-94 GEO Tracker Rear
D517	7539-D517	1994 Jaguar XJS, XJ6, XJ12 Rear
D561	7538-D561	1995 Mercedes E320, S320 & E420 Front

C O R R E C T I O N S

1994 Catalog listed Ford Truck optional 12 1/8 x 3 1/2 rear brake as FMSI 2171T-583. The correct listing is 2178T-583.

1994 GEO Tracker originally listed rear drum brake as 1440-S641. The correct listing is 1483-S641.

Added rear disc brake option of Mazda 1994 MPV and MPV-AWD.

1994 Mercury Tracer shows rear drum brake FMSI 8104-S659. The correct listing is 1463-S678.

DISC BRAKE LINING ASSIGNMENTS

Note #1	<u>FMSI 7537</u>	7537-D659
	52.6 x 17.1 x 122.9	4 IM
	(2.07 x .673 x 4.84)	

Note #2	<u>FMSI 7538</u>	7538-D561
	57.7 x 14.0 x 99.8	4 IM
	(2.27 x .550 x 3.93)	

Note #3	<u>FMSI 7539</u>	7539-D517
	37.3 x 13.3 x 89.7	4 IM
	(1.47 x .525 x 3.53)	

DRUM BRAKE LINING ASSIGNMENTS

Note #4	<u>FMSI 1482</u>	1482-S699
	320.0dd - 100.0 x 11.0 x 335.0	4 - 48
	(12.60 - 3.94 x .433 x 13.19)	

Note #5	<u>FMSI 1483</u>	1483-S641
	220.0dd - 34.0 x 5.0 x 210.3	4 Bonded
	(8.66 - 1.34 x .197 x 8.28)	

Note #6	<u>FMSI 2178T</u>	2178T-583
	12.13dd - 3.50 x .219 x 11.17	4 Bonded
	3.50 x .281 x 11.82	

Note #7	<u>FMSI 2179T</u>	2179T-581
	10.00dd - 2.50 x .188 x 8.46	2 Bonded
	- 2.50 x .250 x 9.75	2

DISC BRAKE SHOE ASSIGNMENTS

Note #8	<u>FMS D659</u>	7537-D659	Ford
	144.5 x 7.4		Mercury
	(5.69 x .291)		Lincoln

DRUM BRAKE SHOE ASSIGNMENTS

Note #9	<u>FMS S699</u>	1482-S699	Isuzu
	320.0 x 100.0		(Commercial)
	(12.60 x 3.94)		

The data shown in this bulletin has been supplied by sources considered to be reliable. While we believe that such information is correct, the Institute cannot and does not accept any responsibility or liability for errors or omissions, or harm resulting therefrom.

The data shown in this bulletin indicates dimensions only and in no way refers to quality of any materials that may be embodied in the product or particular application involved, and moreover SINCE FIELD CONDITIONS AND OTHER FACTS MAY NECESSARILY VARY FROM ONE APPLICATION TO ANOTHER, FRICTION MATERIALS SUPPLIERS AND INSTALLERS SHOULD RELY ULTIMATELY AND SOLELY UPON THEIR OWN EXPERTISE AND JUDGMENT AS TO QUALITY AND DIMENSIONAL SIZE. Under no circumstances should replacement items be used when they do not appear to fit, nor be "forced" to fit, nor be modified in the field instead of obtaining a proper sized item from a supplier. If such items are modified in the field to fit, the Institute specifically disclaims all liability and responsibility for any harm resulting therefrom.

If any error or omission is noted in this bulletin, it should be reported immediately to the Friction Materials Standards Institute, Inc., 588 Monroe Turnpike, Monroe, Connecticut 06468.