

ORIG: ENVR: FILE



March 19, 1986

CWH 000000316

Mr. R. A. Conrad

• March 19, 1986

Page Two


- 3) What is the Full Load Amperage (FLA) of the Wet EDC Pump (P-103) that tripped? You have attributed the trip to increased flow to the wash section; does this mean that a wide open pump discharge will require an exceedance of the FLA? If not, please explain the nature of the trip.

Louisiana R.S. 1089(I) places the responsibility of proving that a discharge constitutes an emergency emission (and thereby a non-preventable situation) on the facility. Any more input into clarification of this point is welcome.

We do ask that you respond promptly and submit your reply within fifteen days of receipt of this letter.

For any questions, please call me at (504) 342-9046.

Sincerely,



Chris Kuttruff
Environmental Program Specialist
LESHAP Unit

CK:aa

File: 12.40.2

CWH 000000317