

V. ALM#3

C.V.

106

MAKING INSTRUCTIONS: BATCH UNIT

D.V.

CG 46 CODE YT-808-D PKG.

F2L19

6/24/82

EST. WGT.

0

LBS.

STD. HRS.

TIME

3 P.M.

PROCESSES	APPROVED BY
()	()
()	()
()	()
()	()
TYPED BY	

46 YC-40-A 93 51064-1 2139#

46 YC-40A 98 51064-1 18H

(Reg. No. 10823)

Total wt ~~2082#~~ 2082#

3 P.M.

NON-BLEEDING

EQUIPMENT	NAME:	USE LBS.	N CODE	ACCT. LBS.
PREP,	DALAMAR Yellow			
ALM	1 OBTAIN YC40-A LISTED ABOVE 12 DRUMS		YC40-A	2157
2	2 PLUG ALM OUTLET & RUN IN 1000# WATER			
	3 START AGITATOR, DUMP & RINSE IN YC-A			
	LOT NO DRS			
	5-1064 3			
	4 STIR 5-10 MINUTES ADDING WATER AND/OR			
	YC-40-A TO SMOOTH SLURRY			
SV	5 PUMP ALM WITHOUT AGITATION INTO V-106			
3	6 REPEAT STEPS 2 THRU 5 FOR AS MANY			
	SET-UP AS NECESSARY			
	SET-UP NO DRUMS			
	3 3			
	3 3			
	3 3			
SV	7 WASH ALM & PUMP INTO SV			
4	8 ADD TO 60" (6000G) AT 120-130°F			

START
3:00 P.M.FIN
4:00 P.M.OPTR
3X1

RECEIVED YC40A AT 4:15 P.M.

JUN 24 1982

N38147