

Eaton Corporation
Industrial Drives Operations
Airflex Division
9919 Clinton Road
Cleveland, Ohio 44144
Telephone (216) 281-2211

October 7, 1980

Mr. Neil Leonhard
Owens-Illinois, Inc.
P. O. Box 1035
Toledo, Ohio 43666

Dear Mr. Leonhard:

EATON

In response to your request, we are furnishing information relating to asbestos content in friction materials furnished by Airflex. Refer to the attached copy of Sales Department Letter #76-46 for details.

Any clutch maintenance work, such as, cleaning, sanding, filing, sawing, grinding or machining of friction material may result in exposure levels to asbestos fibers that exceed prescribed limits. Under these conditions, an approved type respirator must be used.

Please contact us if you have any questions or comments.

Very truly yours,

R. W. Rosenow, Manager
Service & Safety

RWR/pl
attachment:

cc: R. Burks	R. Schier
R. Petkash	D. Keck
D. Haller	T. Thompson

SCF-EC-2060

FAW 16913