



NO. 95-04-2062-C

RALPH ANTHONY NICKERSON et al.,

Plaintiffs,

vs.

MISSOURI PACIFIC RAILROAD
COMPANY, et al.

Defendants

§
§
§
§
§
§
§
§

IN THE DISTRICT COURT OF

CAMERON COUNTY, TEXAS

197TH JUDICIAL DISTRICT

**DEFENDANT MISSOURI PACIFIC RAILROAD COMPANY d/b/a
UNION PACIFIC RAILROAD COMPANY'S THIRD SUPPLEMENTAL
OBJECTIONS AND RESPONSES TO PLAINTIFF'S REQUEST FOR PRODUCTION**

TO: Ernest Lissy, Plaintiff, by and through his attorneys of record, Baron & Budd, The Centrum, 3102 Oak Lawn Avenue, Suite 1100, Dallas, Texas 75219-4281.

Pursuant to Rules 166b and 167 of the Texas Rules of Civil Procedure, Defendant Union Pacific Railroad Company, Defendant herein, hereby submits its Third Supplemental Objections and Responses to Plaintiff's First Request for Production.

General Objections

1. Defendant objects to the Requests to the extent that they request information protected from disclosure by the attorney-client privilege and/or the attorney work-product doctrine. Any information subject to any such privilege inadvertently provided by Defendant in response to the Interrogatories shall not constitute or be deemed to constitute a waiver of any such privilege.
2. Defendant objects to the Requests to the extent that they request information that is neither relevant nor likely to lead to the discovery of admissible evidence.
3. Defendant objects to the Requests to the extent that they exceed the scope of permissible discovery under the Texas Rules of Civil Procedure.
4. Defendant objects to the Requests to the extent that they purport to require Defendant to provide information that is available to Plaintiff where the burden of deriving or ascertaining such information is substantially the same as for Plaintiff as for Defendant.

5. Defendant objects to the Requests to the extent that they purport to require Defendant to provide information pertaining to any time period other than the relevant time period which Plaintiff was allegedly employed by Defendant.

6. Defendant objects to the Requests to the extent that they purport to allege Plaintiff was employed by Missouri Pacific Railroad Company as opposed to Union Pacific Railroad Company.

7. Defendant reserves the right to supplement or amend its responses as appropriate.; and

8. This request is duplicitous. All documents responsive to the following requests have been previously produced in the *Antons* case. To avoid unnecessary expense, copies of the actual documents produced in the *Antons* case are not included herewith however, reference to Bates numbers is provided.

REQUESTS FOR PRODUCTION


REQUEST FOR PRODUCTION NO. 44: Provide copies of any and all documentation evidencing Defendant's compliance with the Boiler Inspection Act, formerly U.S.C. §20701, during the last thirty-five (35) years.

RESPONSE:

Objection. This Request is vague, ambiguous, overly broad, unduly burdensome and seeks information which is neither relevant nor likely to lead to the discovery of admissible evidence. Additionally, this request demands documents outside the time period during which plaintiff was allegedly employed by Defendant. Subject to but without waiver of these objections, Defendant has located no documents responsive to this Request for the years of plaintiff's alleged employment. In compliance with agreement with counsel for plaintiff and court order, Defendant is producing an example of the earliest maintenance log available that has been located in response to this Request attached hereto and numbered 000001-000085. Due to the records retention policy of Defendant, no records earlier than those produced herein have been located. These documents are indicative of the past and present maintenance records maintained by Defendant and its employees to ensure compliance with the BIA/LIA.

Respectfully submitted,

PHELPS DUNBAR

By 

Deborah Newman

Texas State Bar No. 01237257

Mark Schaffer

Texas State Bar No. 00792199

3040 Post Oak Boulevard

Suite 900

Houston, TX 77056


(713) 626-1386

(713) 626-1388 FAX

Attorneys for Defendant Missouri Pacific Railroad
Company d/b/a Union Pacific Railroad Company

CERTIFICATE OF SERVICE

The undersigned hereby certifies that a true and correct copy of the foregoing Defendant Missouri Pacific Railroad Company d/b/a Union Pacific Railroad Company's Fourth Supplemental Objections and Responses to Plaintiff's Requests for Production has been sent via First Class Mail to other parties of record on attached service list and via Certified Mail to Plaintiff's counsel of record, Baron & Budd, 3102 Oak Lawn Avenue, Suite 1100, Dallas, Texas 75219-4281, this 2 day of Mar, 1998.


Mark B. Schaffer

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
OMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	LOCATION	DETAIL	WORK CODES
UP 001213	01/01/70	03/02/92	ALBINA	MOVE TO CHANGE POWER ASSY AND CARD THE LOCOMOTIVE	USOB
			ALBINA	(>) #1 ASSY WATER LEAK FROM HEAD	USOB
			ALBINA	(>) T&C	USOB
			ALBINA	(>) DU BM	USOB
			ALBINA	(>) DU PI QM	USOB
			ALBINA	(AGS)DUE LU	USOB
			ALBINA	(CAS/REH) CHECK FOR FUEL LEAKS (VIS 13.0) NONE FOUND	USOB
			ALBINA	(LDS) REPLACED OBT AS S/N 001075 HAD INOP KEYBOARD	USOB
			ALBINA	(LDS) TESTED NEW OBT S/N 001091 FOR PROPER OPERATION. TESTED OK	USOB
			ALBINA	(LDS) TESTED RADIO FOR PROPER OPERATION	USOB
			ALBINA	(LDS) TESTED UNIT FOR LOADING FORWARD AND REVERSE	USOB
			ALBINA	(JLB) CHANGE WORN BRAKE SHOES, ADJUSTED PISTON TRAVEL	USOB
			ALBINA	(JLB) CHECKED ALL FLUID LEVELS.	USOB
			ALBINA	(JLB) CLEANED AND SUPPLIED CAR.	USOB
			ALBINA	(JLB) TESTED HORN, BELL, WIPERS AND SANDERS.	USOB
			ALBINA	(JLB)(LJM) FUEL AND SANDED UNIT.	USOB
	01/12/88	01/15/88	SALLAKCIT	(CEP)*SM* TI FRA DUE 01/05/88	TIPJEWELWALT
			SALLAKCIT	(CEP)CAB CARPENTER TO FINISH SHEETS	TIPJEWELWALT
			SALLAKCIT	(CEP)RE-COVER CAB FLOOR	TIPJEWELWALT
			SALLAKCIT	(CEP)REBRUSH MAIN GENERATOR	TIPJEWELWALT
			SALLAKCIT	(CEP)W/AIR	TIPJEWELWALT
			SALLAKCIT	(DLG)APPLY CARBODY FILTERS	TIPJEWELWALT
			SALLAKCIT	(DLG)WASH	TIPJEWELWALT
			SALLAKCIT	(EEF)MACH TESTOUT	TIPJEWELWALT
			SALLAKCIT	(EFF)W/TM'S	TIPJEWELWALT
			SALLAKCIT	(JRM)TEST & CARD	TIPJEWELWALT
			SALLAKCIT	(PIT)*SM* LU DUE 01/05/88	TIPJEWELWALT
			SALLAKCIT	HELD 01/12	TRACK OS TIPJEWELWALT
	01/24/88	01/25/88	SALLAKCIT	(JRM)*ST* ADD ENG. OIL	TW
			SALLAKCIT	(JRM)*ST* FLATS ON ALL WHEELS. OVER 2" AND TRUEABLE.	TW
			SALLAKCIT	HELD 01/24 PI-1 DUE	TRACK OS TW
	02/02/88	02/02/88	SALLAKCIT	(GEC)SET GOVERNOR TO MAX FLD START	NLAB
			SALLAKCIT	(GGJ)START & CHECK	NLAB
			SALLAKCIT	(JEA)*ST* BRAKES SLOW IN RELEASING	NLAB
			SALLAKCIT	(JEA)*ST* 2 " FLAT SPOTS ON WHEELS	NLAB
			SALLAKCIT	(JFC)*ST* DROPS LOAD - LOADS IN IDLE	NLAB
			SALLAKCIT	(JFC)*ST* UNIT USELESS FOR SWITCHING AND UNSAFE	NLAB
			SALLAKCIT	(JFC)C/O CONTROLLER	NLAB
			SALLAKCIT	(DKK)PROJECTS (005***)(054***)(079***)(097***)	NLAB
			SALLAKCIT	HELD 02/02 PI DUE 04/16/88	TRACK OS NLAB
	02/09/88	02/09/88	SALLAKCIT	(>)ST*CAME IN DIC UNIT KEEPS DYING AND HAS DEAD BATTERIES(CAF) BACR	BACR
			SALLAKCIT	(>)PROJECTS (05-***)(54-***)(79-***)(97-***)	BACR
			SALLAKCIT	(MMH)*ST*CAME IN DIC UNIT KEEPS DYING AND HAS DEAD BATTERIES(CAF) BACR	BACR
			SALLAKCIT	(OKOK)PROJECTS (05-***)(54-***)(79-***)(97-***)	BACR
			SALLAKCIT	HELD 02/09DUE TRACK OS	BACR
	02/25/88	03/01/88	SALLAKCIT	(BPC)*ST* WT FLATS	GRTW

- T00000

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
OMNT459.FOCUS.MAINTING

LOCOMOTIVE	PLACE	DATE	RELEASE	DATE	LOCATION	DETAIL	WORK CODES
NUMBER	MO	DA	YR	MO	DA	YR	
UP	001213	02/25/88	03/01/88		SALLAKCIT	(DTC)*ST* GR	GRTW
					SALLAKCIT	(GGJ)START & CHECK	GRTW
					SALLAKCIT	(JEA)*ST* B/O HORN	GRTW
					SALLAKCIT	(JEA)*ST* IND. BRAKE VALVE B/O	GRTW
					SALLAKCIT	(OKK) PROJECTS (05***)(54**)(79***)(97***)	GRTW
					SALLAKCIT	(PIT)*ST* ENG OIL LOW	GRTW
					SALLAKCIT	HELD 02/25	TRACK 08 GRTW
	03/17/88	03/17/88			SALLAKCIT	()PROJECTS (05***)(54***)(79***)(97***)	TW
					SALLAKCIT	(GEC)*ST*R-7 SWINGING HANGER BRAKE RIGGING BOLT MISSING(CAF)	TW
					SALLAKCIT	(GEC)*ST*R-7 SWRVICING HANGER BRAKE RIGGING BOLT MISSING(CAF)	TW
					SALLAKCIT	(GEC)*TW*CHECK ALL WHEELS FOR FLATS(CDR)	TW
					SALLAKCIT	(GEC)*TW*L-1 WHEEL HAS A 3" FLAT SPOT(CAF)	TW
					SALLAKCIT	(GEC)WT ALL WHEELS	TW
					SALLAKCIT	(PIT)*ST*RADIO NOT RECEIVING PROPERLY(CAF)	TW
					SALLAKCIT	HELD 03/17/88 DUE	TRACK 08 TW
	04/07/88	04/08/88			SALLAKCIT	(ND) PROJECTS (05***)(54**)(79***)(97***)	TW
					SALLAKCIT	(RLV)*ST* WT FLATS	TW
					SALLAKCIT	(SPT)*ST* ENGINE OIL LOW	TW
					SALLAKCIT	(SPT)*ST* WARNING LIGHT LENS CRACKED	TW
					SALLAKCIT	HELD 04/07	TRACK 05 TW
	04/15/88	04/18/88			SALLAKCIT	(BA)*ST* C/O THIN BRAKE SHOES	PIGMLNALT
					SALLAKCIT	(BA)*ST* PI DUE 04/15/88	PIGMLNALT
					SALLAKCIT	(BA)*ST* SMALL FLAT SPOTS	PIGMLNALT
					SALLAKCIT	(BA)*ST* WHITE LAB	PIGMLNALT
					SALLAKCIT	(BA)INSPT. (H-OK)(E-OK)(CC-OK)	PIGMLNALT
					SALLAKCIT	(BA)PROJECTS (05*OK)(54*OK)(79*OK)(97*OK)	PIGMLNALT
					SALLAKCIT	(BA)W/AIR	PIGMLNALT
					SALLAKCIT	(BA)WORK TH'S	PIGMLNALT
					SALLAKCIT	(GWO)APPLY CARBODY FILTERS	PIGMLNALT
					SALLAKCIT	(GWO)WASH-CLEAN CAB	PIGMLNALT
					SALLAKCIT	(REJ)TEST & CARD	PIGMLNALT
					SALLAKCIT	HELD 04/15 PI DUE 4/15/88	TRACK 01 PIGMLNALT
	05/16/88	05/16/88			SALLAKCIT	(LER)*ST* CLEAN EDUCTOR TUBES	RA
					SALLAKCIT	(LER)*ST* CONVERTOR B/O	RA
					SALLAKCIT	HELD 05/16 PI DUE	TRACK 05 RA
	05/19/88	05/22/88			SALLAKCIT	(BEB)*ST*FLAT SPOTS ALL WHEELS	GRTWEL
					SALLAKCIT	(DTC)UNHOOK MAIN GEN HYPOT 400 VOLTS	GRTWEL
					SALLAKCIT	(DTC)*ST* REPORTED GROUND RELAY	GRTWEL
					SALLAKCIT	(DTC)CHECK TMS	GRTWEL
					SALLAKCIT	(DWD)APPLY BRUSH HOLDER IN MAIN GEN	GRTWEL
					SALLAKCIT	(DWD)CLEAN MAIN GEN BRUSH HOLDERS, INSULATORS.	GRTWEL
					SALLAKCIT	(PIT)*ST* OVER RIDING BRAKE SHOES	GRTWEL
					SALLAKCIT	(REJ)HOOK UP MAIN GEN LEADS (DWD)	GRTWEL
					SALLAKCIT	(REJ)HV LEADS TO HV CABINET ARE GROUNDED.(LOAD AMETER SHUNT)	GRTWEL
					SALLAKCIT	(REJ)MAIN GENERATOR GROUNDED	GRTWEL
					SALLAKCIT	HELD 05/19	TRACK 08 GRTWEL

000002

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
OMNT459.FOCUS.MAINTING

LOCOMOTIVE	PLACE	DATE	RELEASE DATE	LOCATION	DETAIL	WORK CODES
NUMBER	MO	DA	YR	MO	DA	YR
UP	001213	06/03/88	07/13/88	SALLAKCIT	() *ST* RADIO MISSING.	RMADEWNA
				SALLAKCIT	(DLG) RIGHT SIDE FUEL TANK LEVEL GAGE STOLEN FOR 1222	RMADEWNA
				SALLAKCIT	(DLG) WASH ENG (COVERED WITH OIL)	RMADEWNA
				SALLAKCIT	(DTC) AC2 FAN CONT MISSING ((IN STAFF OFFICE))	RMADEWNA
				SALLAKCIT	(DTC) APPLY AND WIRE REAR 27 POINT RECEPTACLE	RMADEWNA
				SALLAKCIT	(DTC) ECP PANEL MISSING	RMADEWNA
				SALLAKCIT	(GEC) *ST* FUEL BY-PASSING.	RMADEWNA
				SALLAKCIT	(GEC) *ST* JUMP SEAT MISSING.	RMADEWNA
				SALLAKCIT	(GEC) *ST* OIL LEAK AT GOVERNOR.	RMADEWNA
				SALLAKCIT	(GEC) *ST* REAR 27 POINT RECEPTACLE STAND BROKEN.	RMADEWNA
				SALLAKCIT	(GEC) APPLY LMSD (OK) (GEC) PIPE (GEC)	RMADEWNA
				SALLAKCIT	(GEC) MACH TEST OUT	RMADEWNA
				SALLAKCIT	(OEN) PAINT AX	RMADEWNA
				SALLAKCIT	(REJ) REPLACE BATTERIES AFTER AX REPAIRS COMPLETED	RMADEWNA
				SALLAKCIT	(RLV) *RM* ACCIDENT DAMAGE.	RMADEWNA
				SALLAKCIT	HELD 06/03 PI DUE 7/18/88	TRACK 12 RMADEWNA
				SALLAKCIT	2ND SHIFT ROBBED IT SO LET THEM WORRY ABOUT IT. ??????	RMADEWNA
	07/19/88	07/19/88		SALLAKCIT	(DTC) *ST* BATTERIES TO REPLACE	BA -
				SALLAKCIT	(DTC) *ST* BATTERY TERMINAL BURNT OFF	BA -
				SALLAKCIT	(DTC) C/O BATTS	BA
				SALLAKCIT	HELD 07/19/88 DUE	TRACK 05 BA
	07/27/88	08/01/88		SALLAKCIT	ALL CHARGE OUT DOCUMENTS *****	RHADTKENDTWA
				SALLAKCIT	RIGHT SIDE PIECE	RHADTKENDTWA
				SALLAKCIT	(BEB) *****MO 97013 JOB 044 XING AX PLEASE SHOW ON TIME CARDS AND	RHADTKENDTWA
				SALLAKCIT	(BEB) *RM* ACCIDENT DAMAGE AT PROVO-R FRONT STEPS-FRONT PILOT BENT	RHADTKENDTWA
				SALLAKCIT	(GEC) PIPE TRUCKS	RHADTKENDTWA
				SALLAKCIT	(GEC) DOUBLE TRUCK C/O	RHADTKENDTWA
				SALLAKCIT	(JRB) ETO	RHADTKENDTWA
				SALLAKCIT	(OEN) PAINT AX	RHADTKENDTWA
				SALLAKCIT	(REJ) ELECT TO HOOK UP TRUCKS	RHADTKENDTWA
				SALLAKCIT	(REJ) ST & CK	RHADTKENDTWA
				SALLAKCIT	HELD 07/27	TRACK 12 RHADTKENDTWA
	08/02/88	08/02/88		SALLAKCIT	(JEA) *ST* BRAKES RELEASE TOO SLOW (CDR)	ABEM
				SALLAKCIT	(JEA) *ST* BYPASSING FUEL (CDR)	ABEM
				SALLAKCIT	HELD 08/02/88 DUE	TRACK 05 ABEM
	08/12/88	08/12/88		SALLKSERT	(CAF) *ST* C/O FUEL FILTERS	FF
				SALLKSERT	HELD 08/12 DUE	TRACK 40 FF
	08/17/88	08/19/88		SALLAKCIT	() MACH TEST OUT	PIWA
				SALLAKCIT	(BJF) TEST AND CARD	PIWA
				SALLAKCIT	(GMD) *SI* INSPECTION DUE	PIWA
				SALLAKCIT	(GMD) INSP (M-OK) (E-OK) (CC-OK)	PIWA
				SALLAKCIT	(GMD) W/AIR	PIWA
				SALLAKCIT	(GMD) W/BRAKES	PIWA
				SALLAKCIT	(GMD) W/TMS	PIWA
				SALLAKCIT	(JRM) C/O FUEL PUMP MOTOR	PIWA
				SALLAKCIT	(PPA) APPLY CARBODY FILTERS AFTER WASH	PIWA

000003

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
DMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE DATE MO DA YR	LOCATION	DETAIL	WORK CODES
UP 001213	08/17/88	08/19/88		SALLAKCIT	(PPA)BNK WORK(WELD REAR COUPLER CARRIER POCKET SIDE)	PIWA
				SALLAKCIT	(PPA)WASH / CLEAN CAB	PIWA
				SALLAKCIT	(REJ)MACH TEST OUT	PIWA
				SALLAKCIT	HELD 08/17 DUE	TRACK OS FIWA
	09/10/88	09/11/88		SALLAKCIT	() *LM* FUEL LEAKS	TW
				SALLAKCIT	() *ST* MODIFY CONTROL STAND TO TAKE DIGITAL RADIO	TW
				SALLAKCIT	(DLG)*ST* ENG OIL 4" LOW	TW
				SALLAKCIT	(DLG)*ST* LARGE FLAT SPOTS ALL WHEELS	TW
				SALLAKCIT	HELD 09/10 DUE	TRACK OS TW
	02/22/89	03/01/89		ALBINA	(JSN) WASH UNIT COMPLETE	AILURN
				ALBINA	(LDS) RADIO APPLIED	AILURN
	04/05/89	04/06/89		ALBINA	(CAC) #4 PR WHEELS TO CHG. ACCT FLAT	RYMC
	05/29/89	06/01/89		HINKLE	() TEST & CARD ELECT.	PIQMLU TK
				HINKLE	() FRONT & REAR COUPLERS HAVE A LOT OF SLACK	PIQMLU TK
				HINKLE	() MACH. WORKED ON PI	PIQMLU TK
				HINKLE	() NOTE (RM) ABOUT THE ABOVE NOTE (RM).	PIQMLU TK
				HINKLE	() REFER STILL B/O CHANGED CIRCUIT BREAKER INSIDE REFER B/O	PIQMLU TK
				HINKLE	(AFH) NEED TO UNHOOK LEADS TO #1TH, SO MACH. CAN DROP IT OUT TO—	PIQMLU TK
				HINKLE	(RER) REFER OK REPAIRED PLUG OK	PIQMLU TK
				HINKLE	(TJB) FRONT & REAR END PLATES TO HIGH	PIQMLU TK
				HINKLE	(TJB) I GOT THE BINDERS OFF AND SOME THE BRAKE RIGGING	PIQMLU TK
				HINKLE	(VLH) (RM) CHECKED REVERSERS FOUND NOTHING WRONG.	PIQMLU TK
				HINKLE	(WAM-WAM) FABRICATED REAR DOOR LATCH STRIKER & APPLIED.	PIQMLU TK
				HINKLE	(WAM, RDB)—REPLACE LEFT #1 BEARING RETAINER WEDGE IT IS BROKEN	PIQMLU TK
	07/10/89	07/11/89		ALBINA	(LAK) UNIT TO WASH	MCWW
				ALBINA	(LRS) RADIO TO REPLACE	MCWW
				ALBINA	(LRS)(CAC)(JIM) #1 PR. WHEELS TO CHG. ACCT. FLAT	MCWW
	08/28/89	09/01/89		ALBINA	(JLB) MACH. TEST & CARD	PIEM
				ALBINA	(JLB) REMOVE EX. MANIFOLDS, CLEAN & REAPPLY	PIEM
				ALBINA	(JLB) TEST & CLEAN SANDERS	PIEM
				ALBINA	(LAK) WASH UNIT COMPLETE	PIEM
				ALBINA	(LJM) INSP. UNIT FOR FRA DEFECTS	PIEM
				ALBINA	(LRS) ELECT. TEST & CARD	PIEM
	10/07/89	10/07/89		ALBINA	(DGR) LU WORKED	LU
				ALBINA	(DGR) LUBE SAMPLE TAKEN	LU
				ALBINA	(KAR) REPLACED SANDING SWITCHACCT. B/O	LU
	12/04/89	12/05/89		HINKLE	(ALL) ENG. ENG. ROOMAIR COMP. ROOM AND WALK WAYS NEED WASHED BAD.	PIQM LU
				HINKLE	(MFC) TEST AND CARD FOR ELECT.	PIQM LU
				HINKLE	(REH) DUE PI	PIQM LU
				HINKLE	(REH) MACH WORKED ON PI SEE WORK REPORT	PIQM LU
				HINKLE	(REH) REPORTED (LM) WHITE CK FUEL LEAKS 2X	PIQM LU
	01/07/90	01/07/90		HINKLE	APART, DROPS AMPS ALSO TENDS TO LOAD IN IDLE ALL BY	RMLULVOL
				HINKLE	ITSELF (HEAVY) WILL NOT SHUT DOWN, EXCESSIVE OIL	RMLULVOL
				HINKLE	LEAKS UNDER SUMP S	RMLULVOL
				HINKLE	C/O THS 1-8 SWITCH FOR LOADING IN IDLE.	RMLULVOL
				HINKLE	(LRP) DUE LU	RMLULVOL

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
OMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE DATE MO DA YR	LOCATION	DETAIL	WORK CODES
UP 001213	01/07/90	01/07/90		HINKLE	(LRP) FIREMANS FRONT WINDOW WIPER BLADE MISSING.	RMLULVOL
				HINKLE	(MFC) REPAIRED HEADLIGHT WIRE. REPAIRED HEATER.	RMLULVOL
				HINKLE	(MFC)*RM* REAR HEADLIGHTS NOT WORKING DIM , ENG HEATER FALLING	RMLULVOL
	01/19/90	01/19/90		HINKLE	(RES) **RM**NO THROTTLE SPEEDS IN #2,4,6,8	RMLT
				HINKLE	(RES) REPLACED THS 2,4,6, & 8	RMLT
	02/04/90	02/04/90		ALBINA	(JLM) APPLIED BRAKE SHOE ALIGNMENT PLATES FOR OVERRIDING SHOES	LU
				ALBINA	(JLM) CHANGED WORN BRAKE SHOES	LU
				ALBINA	(JLM) LU DONE	LU
				ALBINA	(JLM) MECHANICAL INSPECTED	LU
				ALBINA	(JLM) REPLACED REAR ENG WIPER MOTOR	LU
	02/05/90	02/07/90		ALBINA	(D-R) HAND BRAKE CHAIN BROKEN (J-B)	WC
				ALBINA	(KAR)(D-R)(J_B) CHANGE #4 TH ACCT. FLAT	WC
	02/08/90	02/08/90		ALBINA	(KAR)(D-R)(J_B) #1 TH TO CHG. ACCT. PINION BEARINGS NOISY	TH
	02/13/90	02/14/90		ALBINA	(KAR) VR11 MOD REPLACED ACCT. BO	PJLU
				ALBINA	(KLF) ATCS MOD APPLIED	PJLU
	03/03/90	03/08/90		ALBINA	ACCT. SIDE BEARINGS CONTACT	AILUMINA
				ALBINA	* BELL RINGER VALVE REPLACED--BO	AILUMINA
				ALBINA	(D-R)(J-B)(KAR) DROP #2 TRUCK & PLACE LINER IN CENTER CASTING	AILUMINA
				ALBINA	(D-R) TEST & CARD-MACH	AILUMINA
				ALBINA	(KAR) TEST & CARD- ELECT	AILUMINA
				ALBINA	(LJM) INSP. UNIT FOR FRA DEFECTS	AILUMINA
				ALBINA	* CENTER CASTING INNER RING REPLACED	AILUMINA
				ALBINA	* WATER COOLER REPLACED--BO	AILUMINA
				ALBINA	* SANDERS CLEANED & TESTED	AILUMINA
	05/19/90	05/19/90		POCATELLO	(JEW) **RF** REPT. 2" FLAT SPOTS	RFRMTMBA
				POCATELLO	(JEW) C/D #12 ASSY WATER LEAKS	RFRMTMBA
				POCATELLO	(JEW) DEAD BATTERIES	RFRMTMBA
				POCATELLO	(JEW) FLAT SPOTS LESS THAN 1"	RFRMTMBA
				POCATELLO	(JEW) WATER LEAKS	RFRMTMBA
	06/11/90	06/15/90		POCATELLO	(MCM) DO 057 MOD	PIQMPJ
				POCATELLO	(MCM) PI QM INSP. PAST DUE	PIQMPJ
				POCATELLO	(MCM) PI TEST & CARD	PIQMPJ
				POCATELLO	(MCM) REPORTED FLAT SPOTS 1" FLAT SPOTS ON #4 .	PIQMPJ
	06/20/90	06/20/90		ALBINA	(D-R)(J-B)(LRS) CHGD. #4 PR. WHEELS ACCT. FRA FLAT	WC
	06/26/90	07/11/90		SALLAKCIT	()CONNECT TB UNDER FLOOR AND RING OUT TRAINLINE	RHNGWAENGULT
				SALLAKCIT	()START & CHECK	RHNGWAENGULT
				SALLAKCIT	(AOK)RECONNECT AUX. GENERATOR, ELECT.	RHNGWAENGULT
				SALLAKCIT	(BA)*RM*06/20/90 OPS00 MAIN GEN ARMATURE BRGN. BO	RHNGWAENGULT
				SALLAKCIT	(BA)BLNKR TO UNCOVER MAIN GEN	RHNGWAENGULT
				SALLAKCIT	(BA)COUPLE & ALIGN GEN. **BOLTS IN FLYWHEEL BUT NOT TORQUED**	RHNGWAENGULT
				SALLAKCIT	(BPC)*ST*FLAT SPOTS (LER)	RHNGWAENGULT
				SALLAKCIT	(BPC)*ST*OVER RIDING BRAKES (LER)	RHNGWAENGULT
				SALLAKCIT	(BPC)APPLY FLY WHEEL GUARDS	RHNGWAENGULT
				SALLAKCIT	(BPC)APPLY HORN & PIPE	RHNGWAENGULT
				SALLAKCIT	(BPC)WASH - CLEAN CAB	RHNGWAENGULT
				SALLAKCIT	(DTC)APPLY MCP SERIAL #520	RHNGWAENGULT

000003

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
ORNT459.FOCUS.MAINTING

LOCOMOTIVE	PLACE	DATE	RELEASE DATE			
NUMBER	MO	DA	YR	MO	DA	YR
				LOCATION	DETAIL	WORK CODES
UP 001213	06/26/90	07/11/90		SALLAKCIT	(EFF)APPLY NEW MAIN GEN.	RHNGNAEWGULT
				SALLAKCIT	(EFF)APPLY R. BLOWER & PIPE	RHNGNAEWGULT
				SALLAKCIT	(EFF)APPY AUX. GEN & ALIGN	RHNGNAEWGULT
				SALLAKCIT	(EFF)C/O MAIN GEN. (B.O. BEARING) **REMOVED**	RHNGNAEWGULT
				SALLAKCIT	(EFF)CLEAN BASE	RHNGNAEWGULT
				SALLAKCIT	(EFF)REAM & DOWEL GEN. **REAMED O.K. NEEDS DOWELS	RHNGNAEWGULT
				SALLAKCIT	(EFF)REMOVE MAIN GEN. *** READY TO LIFT ***	RHNGNAEWGULT
				SALLAKCIT	(IST)LOAD NEW MAIN GEN. ***FIN*** 8TH TO DO	RHNGNAEWGULT
				SALLAKCIT	(JEA)C/O #10 FLASHCOCK	RHNGNAEWGULT
				SALLAKCIT	(JEA)C/O GOVERNOR	RHNGNAEWGULT
				SALLAKCIT	(JRB)RECONNECT MAIN GENERATOR, ELECT.	RHNGNAEWGULT
				SALLAKCIT	(MLJ)CUT AUX. GENERATOR, ELECT.	RHNGNAEWGULT
				SALLAKCIT	(MLJ)CUT MAIN GENERATOR, ELECT.	RHNGNAEWGULT
				SALLAKCIT	(PDB)INBOUND INSP. (DEAD)	RHNGNAEWGULT
				SALLAKCIT	(PPA)APPLY HOOD	RHNGNAEWGULT
				SALLAKCIT	(REJ)SEAT BRUSHES AND BLOW OUT GEN	RHNGNAEWGULT
				SALLAKCIT	(REJ)13T WIRE OPEN TO REAR 27 PT RECT	RHNGNAEWGULT
				SALLAKCIT	(1ST)CONNECT TB UNDER FLOOR AND RING OUT TRAINLINE	RHNGNAEWGULT
				SALLAKCIT	(1ST)START & CHECK	RHNGNAEWGULT
				SALLAKCIT	COMPUTATOR BADLY SCORED	RHNGNAEWGULT
				SALLAKCIT	HELD 06/26	RHNGNAEWGULT
	08/19/90	08/19/90		POCATELLO	(JGS) *RM* LEFT FRONT UNCOUPLING LEVER HANDLE FOULED. PUC DEFS	CDPJICDE
				POCATELLO	(JGS) DO SPCL 015 APPLY NEW STYLE CAB CARD HOLDER & RELATED KIT	CDPJICDE
				POCATELLO	(JGS) WASHED CARBODY AND WALKWAYS	CDPJICDE
	09/10/90	09/11/90		HINKLE	(JSS) DUE PI INSP	PISHBMLU
				HINKLE	(LRP) DUE LU	PISHBMLU
				HINKLE	(WAM) TEST AND CARD FOR MACHINIST	PISHBMLU
				HINKLE	(WBS) TEST AND CARD FOR ELECTRICIAN	PISHBMLU
	10/13/90	10/15/90		ALBINA	() CLEAN ENGINE ROOM OF EXCESS OIL (FRA)	LU
				ALBINA	() DO LU (TAKE LUBE OIL SAMPLE)	LU
				ALBINA	() REPAIR FUEL LEAK AT REAR OF FUEL TANK (FRA)	LU
				ALBINA	() REPAIR L. MAIN RES. BRACKET ACCT. BROKEN (FRA)	LU
				ALBINA	() REPAIR OVERRIDING BRAKE SHOE RT#4 (FRA)	LU
				ALBINA	() REPAIR REAR TRUCK BOLSTER ACCT. CRACKED AT #4 AIR DUCT(FRA)	LU
	10/21/90	10/27/90		SALLAKCIT	—OIL ON ENG ROOM FLOOR	RHMLTKFLWA
				SALLAKCIT	AT LEFT REAR OF FUEL TANK—LEFT M RES	RHMLTKFLWA
				SALLAKCIT	BOLSTER CKD. AT #4 AIR DUCT—FUEL LEAK	RHMLTKFLWA
				SALLAKCIT	MOUNT BRACKET BROKEN—R4 SHOE OVERRIDE	RHMLTKFLWA
				SALLAKCIT	ON BACK SIDE UNDER REMARKS ADD O/S 6-3-88	RHMLTKFLWA
				SALLAKCIT	ROOTS BLOWER BY POS. TO JIM KRAMER PH.	RHMLTKFLWA
				SALLAKCIT	SIDES TO LOCO RECORDS RM 900 OMAHA	RHMLTKFLWA
				SALLAKCIT	TO 7-13-88—40 DAYS. CORRECTED CY BOTH	RHMLTKFLWA
				SALLAKCIT	TRANSPONDER TAGS	RHMLTKFLWA
				SALLAKCIT	82713056 OR SEND TO PRTR LATA 1623777...	RHMLTKFLWA
				SALLAKCIT	(***)*RM* 10/12/90 OMA PLS FURNISH SERIAL NOS ON AUX GEN & BOTH	RHMLTKFLWA
				SALLAKCIT	(CDR)CHANGE OUT #2 TRUCK(CRACKED FRAME)	RHMLTKFLWA

000006

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
DMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE MO DA YR	LOCATION	DETAIL	WORK CODES
UP 001213	10/21/90	10/27/90		SALLAKCIT	(DLW)REPAIR CRACKED MAIN RES. BRACKET	RHMLTKFLWA
				SALLAKCIT	(DLW)REPAIR RETURN FUEL LINE PIPE AT TOP OF TANK	RHMLTKFLWA
				SALLAKCIT	(DTC)HOOK UP TRUCKS(M-CDR)(P-BA)(E-DTC)	RHMLTKFLWA
				SALLAKCIT	(DWD)SPECIAL (29A-***) APPLY TWO AUTOMATIC EQUIPMENT ID (AEI)	RHMLTKFLWA
				SALLAKCIT	(GGC)ELECT TESTOUT	RHMLTKFLWA
				SALLAKCIT	(GGC)MACH TESTOUT	RHMLTKFLWA
				SALLAKCIT	(GGC)REPLACE SPOOL TYPE CAB SEAT	RHMLTKFLWA
				SALLAKCIT	(GGJ)*RM* 10/15/90 DF500 FRA DEFECTS TO CORRECT REAR TRUCK	RHMLTKFLWA
				SALLAKCIT	(GGJ)REPAIR R#4 OVERIDING BRAKE SHOE	RHMLTKFLWA
				SALLAKCIT	(LLS)*RM* 09/20/90 DMA ON FRA BLUE FORM ADD 40 DAYS TO BOX 11	RHMLTKFLWA
				SALLAKCIT	(PIT)*RM* 10/20/90 IY061 OIL SAMPLES IN CAB FOR SLC LAB	RHMLTKFLWA
				SALLAKCIT	HELD 10/21/90 DUE	TRACK 07 RHMLTKFLWA
11/24/90	11/25/90			SALLAKCIT	(BK)*ST*C/O WORN BRAKE SHOES AND ADJ BRAKE TRAVEL (BK)	HNMS
				SALLAKCIT	(GWB)REPAIR SANDERS #2 TRUCK	HNMS
				SALLAKCIT	(REJ)*ST*REPORTED WHEEL SLIP (BK) (NOTHING FOUND)	HNMS
				SALLAKCIT	HELD 11/24	TRACK 05 HNMS
12/07/90	12/11/90			SALLAKCIT	(DTC)*RM* 12/07/90 SLC FLAT WHEELS-B/O HDLT ON DIM	PIGRHNAICPJ
				SALLAKCIT	(FCR)APPLY CARBODY FILTERS	PIGRHNAICPJ
				SALLAKCIT	(FCR)TEST & CARD	PIGRHNAICPJ
				SALLAKCIT	(FCR)WASH	PIGRHNAICPJ
				SALLAKCIT	(GMD)BOTH STACKS SPARK ARRESTORS ARE PLUGGED(CUT & CLEANED)(	PIGRHNAICPJ
				SALLAKCIT	(JRH)*TW* TRUE WHEELS(MJL)	PIGRHNAICPJ
				SALLAKCIT	(DEM)PAINT CAB	PIGRHNAICPJ
				SALLAKCIT	(REJ)APPLY NEW REEFER AFTER CAB PAINTED	PIGRHNAICPJ
				SALLAKCIT	(REJ)CLEAN CAB	PIGRHNAICPJ
				SALLAKCIT	(REJ)INBOUND INSPECT	PIGRHNAICPJ
				SALLAKCIT	(REJ)RESTORE & STENCIL CAB	PIGRHNAICPJ
				SALLAKCIT	(REJ)WORK CAB PROJECT SHEET	PIGRHNAICPJ
				SALLAKCIT	(RLV)*PI* DUE INSPN 12/12/90	PIGRHNAICPJ
				SALLAKCIT	(RLV)INSPECT (H-OK) (E-OK) (CC-OK) (B-OK)	PIGRHNAICPJ
				SALLAKCIT	(RLV)WORK BRAKES	PIGRHNAICPJ
				SALLAKCIT	(RLV)WORK TH'S	PIGRHNAICPJ
				SALLAKCIT	HELD 12/07	PI INSPECTION
02/19/91	03/04/91			SALLAKCIT	VEE/WIPED OUT WATER /NO ML FOUND ON ASSYS***	TRACK 01 PIGRHNNAICPJ
				SALLAKCIT	(DTC)NEEDS DELAY TIMER APPLIED	TIRMEOLEWNAWPNL
				SALLAKCIT	(EFF)*RM*PRESSURE MAINTAINING B/O	TIRMEOLEWNAWPNL
				SALLAKCIT	(EFF)MTD	TIRMEOLEWNAWPNL
				SALLAKCIT	(EFF)TEST & CARD	TIRMEOLEWNAWPNL
				SALLAKCIT	(GMD)#2 #5 #6 AND #12 ASSYS MLK***NOTE***WASH WATER IN ENG	TIRMEOLEWNAWPNL
				SALLAKCIT	(GMD)#7 ASSY BAD THRUST WASHER***LEAD READING OK***	TIRMEOLEWNAWPNL
				SALLAKCIT	(GMD)APPLY CARBODY FILTERS	TIRMEOLEWNAWPNL
				SALLAKCIT	(GMD)R#3 BRK ROD LINKAGE PIN MISSING AT PISTON	TIRMEOLEWNAWPNL
				SALLAKCIT	(GMD)SPCL(050A-***) REMOVE WARNING LIGHT PER INSTRUCTION	TIRMEOLEWNAWPNL
				SALLAKCIT	(GMD)TAKE & RECORD WHEEL SIZES.	TIRMEOLEWNAWPNL
				SALLAKCIT	(GMD)W/TMS	TIRMEOLEWNAWPNL
				SALLAKCIT	(JEA)*RM*ENG OIL LEAK, AND USING WATER	TIRMEOLEWNAWPNL

000007

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
OMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE LOCATION	DETAIL	WORK CODES
UP 001213	02/19/91	03/04/91	SALLAKCIT	(JEA)*ST*ENG ROOM VERY OILY (PPA)	TIRMELOLEWAWPWL
			SALLAKCIT	(JEA)C/O RIGHT WATER PUMP (LEAKING)	TIRMELOLEWAWPWL
			SALLAKCIT	(JEA)PRESSURE CHECK - CK RPLS	TIRMELOLEWAWPWL
			SALLAKCIT	(JEA)WASH	TIRMELOLEWAWPWL
			SALLAKCIT	(OK)WORK INBOUND REPORTS *** (E-OK) (M-OK)	TIRMELOLEWAWPWL
			SALLAKCIT	(OK1)C/O R FRONT WINDSHIELD OUT/NIS	TIRMELOLEWAWPWL
			SALLAKCIT	(OK1)WORK TRI. 3 YR AIR.	TIRMELOLEWAWPWL
			SALLAKCIT	(PDB)INBOUND INSPECTION	TIRMELOLEWAWPWL
			SALLAKCIT	HELD 02/19/91 DUE	TRACK 05 TIRMELOLEWAWPWL
	04/29/91	05/13/91	ALBINA	(DGR) CHANGED BAGGIE TYPE AIR FILTERS	RFLUHH
			ALBINA	(DGR) CHANGED CAR BODY AIR FILTERS	RFLUHH
			ALBINA	(DGR) TOOK LUBE OIL SAMPLE	RFLUHH
			ALBINA	(JLB)(DGR)(LRS) CHANGED #1 TRACTION MOTOR ACCT. FED. FLAT SPOTS.	RFLUHH
			ALBINA	(KAR)(JHM)(JLB) CHG'D #3 PR. WHEELS ACCT. FLAT	RFLUHH
			ALBINA	(KAR)(LRS) COMPLETELY REWIRED HEADLIGHT CIRCUIT	RFLUHH
	06/07/91	06/09/91	HINKLE	(MFC) TEST AND CARD FOR ELECTRICIAN	PISMRMLU
			HINKLE	(MFC) WASH BATTERIES	PISMRMLU
			HINKLE	(MFC)"RM" LOADS WHEN THROTTLE IN IDLE	PISMRMLU
			HINKLE	(TJS) TEST AND CARD FOR MACHINIST.	PISMRMLU
			HINKLE	(TJS)ENGR. REPORTS REAR SANDERS INOPERTIVE	PISMRMLU
			HINKLE	(WAM)"RM" DISTRIBUTING VALVE SET TO APPROX. 12 LBS	PISMRMLU
			HINKLE	(YES) DUE PI INSP.	PISMRMLU
	06/17/91	06/17/91	ALBINA	(KME) CHANGED OUT THS1-8 & CHECKED OK.	LULU
			ALBINA	(KME) LOADS IN IDLE.	LULU
	06/30/91	07/01/91	ALBINA	(DGR) CLEANED AND SUPPLIED CAB	TP
			ALBINA	(DGR)(JLB) CHANGED WORN BRAKE SHOES AND ADJUSTED PISTON TRAVEL	TP
			ALBINA	(JLB)CHECKED FLUID LEVELS	TP
	07/04/91	07/10/91	ALBINA	(JLB) HAND BRAKE CHAIN REPAIRED ACCT. DAMAGED	DE
	08/10/91	08/11/91	ALBINA	(JLM) *LU*	RHMLUFF
			ALBINA	(JLM) *RM*	RHMLUFF
			ALBINA	(JLM) CHANGED OUT FUEL FILTERS.	RHMLUFF
			ALBINA	(RS) *RM*PLS.FURNISH #3844 T/M SERIAL NO.S TO JIM KRAMER-PHONE	RHMLUFF
			ALBINA	**** 8 271-3056 OR SEND TO PRINTER LATA I623777.	RHMLUFF
	08/22/91	08/23/91	ALBINA	(DEB) CHANGE WORN BRAKE SHOES AND ADJUST TRAVEL	TP
			ALBINA	(DEB) CHECK HORN BELL AND WIPERS	TP
			ALBINA	(DEB) CHECK LIGHTS & RADIO	TP
			ALBINA	(DEB) CHECK LOAD SPEEDS AND DIRECTION	TP
			ALBINA	(DEB) REPAIR L2 SAND HOSE	TP
			ALBINA	(DEB) REPAIR R FRONT MU HOSES	TP
			ALBINA	(KMG) CHECK FLUID LEVELS	TP
			ALBINA	(KMG) CLEAN AND SUPPLY CAB	TP
	09/04/91	09/11/91	ALBINA	(JHM) CHECKED BUCKEYE FUEL FILL	PISMRMLUWASNTK
			ALBINA	(JHM) CHECKED FOR FUEL LEAKS	PISMRMLUWASNTK
			ALBINA	(JHM) CHECKED FOR PROPER FIRST AID KIT	PISMRMLUWASNTK
			ALBINA	(JHM) CHECKED PIPING OF INDEP. AND AUTO. BRK VALVES	PISMRMLUWASNTK
			ALBINA	(JHM) INSPECTED AIR BOXES	PISMRMLUWASNTK

000008

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
OMNT459. FOCUS. MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE DATE	LOCATION	DETAIL	WORK CODES
UP 001213	09/04/91	09/11/91		ALBINA	(JHM) INSPECTED SAND TRAPS	PISHRMLUNASNTK
				ALBINA	(JHM) MECH. OUT BOUND TEST IE: SANDERS, HORN, BELL, WIPERS ECT.	PISHRMLUNASNTK
				ALBINA	(JHM) WASHED TRUCKS AND CARBODY	PISHRMLUNASNTK
				ALBINA	(KAR) CHECKED ALARM BELL AND ALARM SYSTEMS	PISHRMLUNASNTK
				ALBINA	(KAR) CHECKED FUSES AND SUPPLIED	PISHRMLUNASNTK
				ALBINA	(KAR) CHECKED HIGH AND LOW VOLTAGE GRNDS.	PISHRMLUNASNTK
				ALBINA	(KAR) CHECKED HIGH VOLTAGE CAB. AND EQUIP.	PISHRMLUNASNTK
				ALBINA	(KAR) CHECKED MAIN GEN. AND ALT. SLIP RINGS	PISHRMLUNASNTK
				ALBINA	(KAR) CHECKED RADIO AND ANTENNA	PISHRMLUNASNTK
				ALBINA	(KAR) CHECKED RER. FOR OPERATION	PISHRMLUNASNTK
				ALBINA	(KAR) CHECKED WHEEL SLIP	PISHRMLUNASNTK
				ALBINA	(KAR) DIRECTIONAL LOAD TEST	PISHRMLUNASNTK
				ALBINA	(KAR) REPAIRED HEATER	PISHRMLUNASNTK
				ALBINA	(KAR) REPLACED ENG. HEATER MOTOR	PISHRMLUNASNTK
				ALBINA	(KAR) TESTED GROUND RELAY	PISHRMLUNASNTK
				ALBINA	(KAR) WASHED AND FILLED BATT. WITH WATER	PISHRMLUNASNTK
				ALBINA	(KAR) WORKED ALL LIGHTS	PISHRMLUNASNTK
				ALBINA	(KAR) WORKED ALL SMALL MOTORS	PISHRMLUNASNTK
				ALBINA	(KAR) WORKED TRACTION MOTORS.	PISHRMLUNASNTK
				ALBINA	(WRH) CHANGED OUT BAGGY TYPE FILTERS, AIR INTAKE	PISHRMLUNASNTK
				ALBINA	(WRH) LUBRICATED HAND BRAKE	PISHRMLUNASNTK
				ALBINA	(WRH) CHANGE LUBE OIL FILTERS	PISHRMLUNASNTK
				ALBINA	(WRH) CHANGED OUT CARBODY FILTERS	PISHRMLUNASNTK
				ALBINA	(WRH) CHANGED OUT FUEL FILTERS PRIMARY	PISHRMLUNASNTK
				ALBINA	(WRH) CHANGED OUT FUEL FILTERS SECONDARY	PISHRMLUNASNTK
				ALBINA	(WRH) CLEANED FUEL SIGHT GLASS	PISHRMLUNASNTK
				ALBINA	(WRH) CRANKCASE INSPECTION	PISHRMLUNASNTK
				ALBINA	(WRH) TOOK COMPRESSOR OILSAMPLE	PISHRMLUNASNTK
				ALBINA	(WRH) TOOK COOLING WATER SAMPLE	PISHRMLUNASNTK
	09/17/91	09/18/91		ALBINA	(LDS) UNIT REPORTED LOADING PROBLEMS. FOUND THAT CONTACTORS WERE	NL
				ALBINA	SLOW TO PICKUP BUT UNIT LOADED WELL AND PROPERLY.	NL
	09/29/91	11/05/91		ALBINA	(JHM)(JLB) REPLACE AIR HORN CONTROL VALVE	WCPD
				ALBINA	(JLB)(DGR)(LRS) CHANGED #1&2&3&4 TRACTION MOTORS ACCT. FED. FLAT	WCPD
				ALBINA	SPOTS.	WCPD
	12/18/91	12/23/91		ALBINA	(JLB) CHANGED WORN BRAKE SHOES, ADJUSTED PISTON TRAVEL.	RHMLU
				ALBINA	(JLB) CHECKED ALL FLUID LEVELS.	RHMLU
				ALBINA	(JLB) CLEANED AND SUPPLIED CAB.	RHMLU
				ALBINA	(JLB) WORKED (LU) AND (HM), OIL SAMPLE TAKEN. ALSO CAR BODY AND	RHMLU
				ALBINA	BAGGIE AIR FILTERS CHANGED.	RHMLU
	12/24/91	12/24/91		ALBINA	(JLB) CHANGED WORN BRAKE SHOE, ADJUSTED PISTON TRAVEL.	SURHTP
				ALBINA	(JLB) CHECKED ALL FLUID LEVELS.	SURHTP
				ALBINA	(JLB) FUELED AND SANDED UNIT.	SURHTP
	12/30/91	01/02/92		ALBINA	(JLB) CHANGED WORN BRAKE SHOES, ADJUSTED PISTON TRAVEL.	WCTPSV
				ALBINA	(JLB) CHECKED ALL FLUID LEVELS.	WCTPSV
				ALBINA	(JLB) CLEANED AND SUPPLIED CAB.	WCTPSV
				ALBINA	(JLB)(DGR)(CHM) CHANGED #2 TRACTION MOTOR ACCT. FED. FLAT SPOTS.	WCTPSV

000000

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
OMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE MO DA YR	LOCATION	DETAIL	WORK CODES
UP 001213	12/30/91	01/02/92		ALBINA	(JLB)(DGR)(KAL) CHANGED #3 TRACTION MOTOR ACCT.FED. FLAT SPOTS.	WCTPSV
				ALBINA	(JLB)(DGR)(LRS) CHANGED #4 TRACTION MOTOR ACCT.FED. FLAT SPOTS.	WCTPSV
	01/04/92	01/06/92		ALBINA	(DGR) REPLACED FLAIR FITTING ON FUEL TANK PIPE	TF
	01/09/92	01/10/92		ALBINA	(LDS) REPAIRED THROTTLE CONTROL PANEL AND REPLACED A VALVE MICRO-	TPSV
				ALBINA	SWITCH AS UNIT SKIPPED RUNS 3 AND 5.	TPSV
	01/14/92	01/21/92		ALBINA	(LDS) CHECK COMPRESSOR FOR PROPER CUT-IN AND OUT	PNPQMRHSNTKICW
				ALBINA	(LDS) CHECK COOLING FANS AND SHUTTERS FOR PROPER OPERATION	PNPQMRHSNTKICW
				ALBINA	(LDS) CHECK DRAIN VALVES FOR PROPER OPERATION	PNPQMRHSNTKICW
				ALBINA	(LDS) CHECK EMERGENCY FUEL SHUTOFF VALVE FOR PROPER OPERATION	PNPQMRHSNTKICW
				ALBINA	(LDS) CHECK GROUND RELAY FOR PROPER OPERATION	PNPQMRHSNTKICW
				ALBINA	(LDS) TESTED WHEELSLIP OPERATION	PNPQMRHSNTKICW
				ALBINA	(JJM) CHANGED OUT BAG TYPE ENGINE AIR INTAKE FILTERS	PNPQMRHSNTKICW
				ALBINA	(JJM) CHANGED OUT CARBODY FILTERS	PNPQMRHSNTKICW
				ALBINA	(JJM) CHANGED OUT COMPRESSOR AIR INTAKE FILTERS	PNPQMRHSNTKICW
				ALBINA	(JJM) CHANGED OUT ENGINE OIL FILTERS	PNPQMRHSNTKICW
				ALBINA	(JJM) CHANGED OUT FUEL PRIMARY FILTER	PNPQMRHSNTKICW
				ALBINA	(JJM) CHANGED OUT FUEL SECONDARY FILTERS	PNPQMRHSNTKICW
				ALBINA	(JJM) CHANGED OUT 8 BRAKE SHOES AND ADJUSTED	PNPQMRHSNTKICW
				ALBINA	(JJM) CHECKED FUEL MOUNTING BOLTS	PNPQMRHSNTKICW
				ALBINA	(JJM) CHECKED LATCHES AND LUBED	PNPQMRHSNTKICW
				ALBINA	(JJM) CHECKED M.U. HOSES AND GASKETS	PNPQMRHSNTKICW
				ALBINA	(JJM) CHECKED SANDERS, SAND TRAPS, HOSES ECT.	PNPQMRHSNTKICW
				ALBINA	(JJM) CHECKED SEATS, TRIPOD MOUNTS ECT. AND LUBED THE SAME	PNPQMRHSNTKICW
				ALBINA	(JJM) GREASED COUPLER SHANK	PNPQMRHSNTKICW
				ALBINA	(JJM) LUBE ALL HINGES	PNPQMRHSNTKICW
				ALBINA	(JJM) REPLACED RIGHT #2 SLK. ADJSTER PIN.(MISSING)	PNPQMRHSNTKICW
				ALBINA	(JJM) TOOK ENGINE OIL, WATER, AND COMPRESSOR OIL SAMPLES	PNPQMRHSNTKICW
				ALBINA	(JLB) CHECKED ALL FLUID LEVELS.	PNPQMRHSNTKICW
				ALBINA	(JLB) CLEANED AND SUPPLIED CAB.	PNPQMRHSNTKICW
				ALBINA	(JLB) TESTED HORN, BELL, WIPERS AND SANDERS.	PNPQMRHSNTKICW
				ALBINA	(JLB)(LDS) TEST AND CARD.	PNPQMRHSNTKICW
				ALBINA	(JLB)(LRS) TEST AND CARD.	PNPQMRHSNTKICW
				ALBINA	(KAR) CHECKED ALARM BELL AND ALARM SYSTEMS	PNPQMRHSNTKICW
				ALBINA	(KAR) CHECKED ALL LIGHTS	PNPQMRHSNTKICW
				ALBINA	(KAR) CHECKED HIGH AND LOW VOLTAGE	PNPQMRHSNTKICW
				ALBINA	(KAR) CHECKED HIGH VOLTAGE CAB. AND EQUIP.	PNPQMRHSNTKICW
				ALBINA	(KAR) CHECKED MAIN GEN. AND ALT. SLIP RINGS AND BRUSHES	PNPQMRHSNTKICW
				ALBINA	(KAR) CHECKED RADIO AND ANTENNA	PNPQMRHSNTKICW
				ALBINA	(KAR) CHECKED SMALL MOTORS	PNPQMRHSNTKICW
				ALBINA	(KAR) CHECKED TRACTION MOTORS	PNPQMRHSNTKICW
				ALBINA	(KAR) WASHED AND FILLED BATT. WATER GREASED TERMINAL	PNPQMRHSNTKICW
	01/30/92	01/31/92		ALBINA	(JLB) CHANGED WORN BRAKE SHOES, ADJUSTED PISTON TRAVEL.	TPSV
				ALBINA	(JLB) CHECKED ALL FLUID LEVELS.	TPSV
				ALBINA	(JLB) CLEANED AND SUPPLIED CAB.	TPSV
				ALBINA	(JLB) TESTED HORN, BELL, WIPERS AND SANDERS.	TPSV
	01/31/92	02/03/92		ALBINA	(JLB)(DGR) REPLACED RT.#1 BEARING ADAPTOR.	USWC

000010

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
DMRT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE DATE MO DA YR	LOCATION	DETAIL	WORK CODES
UP 001213	01/31/92	02/03/92		ALBINA	(JLB)(DGR)(LRS) CHANGED #1&2 TRACTION MOTOR ACCT.FED.FLAT SPOTS.	USWC
	03/15/92	03/16/92		ALBINA	(JLM) REPT. REAR DOOR WON'T STAY LATCHED.	TPICSN
				ALBINA	(JLM) R2 SAND HOSE OFF.	TPICSN
	03/19/92	03/25/92		ALBINA	(JLB)(DGR) CHANGED LT.#1 INSIDE BRAKE HEAD.	SVTPTK
				ALBINA	(JLB)(DGR) CHANGED WORN BRAKE SHOES,ADJUSTED PISTON TRAVEL.	SVTPTK
				ALBINA	(JLB)(DGR) CHECKED ALL FLUID LEVELS.	SVTPTK
				ALBINA	(JLB)(DGR) CLEANED AND SUPPLIED CAB.	SVTPTK
				ALBINA	(JLB)(DGR) TESTED HORN,BELL,WIPERS AND SANDERS.	SVTPTK
	03/29/92	03/30/92		ALBINA	(WRH) CHECKED AND ADJUSTED BRAKES AND RIGGING	TP
				ALBINA	(WRH) CHECKED FLUIDS	TP
				ALBINA	(WRH) CLEANED CAB	TP
	03/31/92	04/01/92		ALBINA	(JLB)(DGR) ADDED ENGINE COOLING WATER ANTI RUST COMPOUND.	USLUNC
				ALBINA	(JLB)(DGR) CHANGED OUT LEFT SIDE WATER PUMP.	USLUNC
				ALBINA	(JLB)(DGR)(LRS) CHANGED #3 TRACTION MOTOR,ACCT.FLAT SPOTS.	USLUNC
	04/06/92	04/10/92		ALBINA	(DGR) CHECKED BRAKES AND ADJUST PISTON TRAVEL	PHAIAMSNMATKIC
				ALBINA	(DGR) CHECKED PILOT HEIGHTS CLEARANCES	PHAIAMSNMATKIC
				ALBINA	(DGR) CHECKED SIDE BEARING CLEARANCES	PHAIAMSNMATKIC
				ALBINA	(DGR) GREASED COUPLER SHANK WEAR PLATES	PHAIAMSNMATKIC
				ALBINA	(DGR) LUBRICATED ALL DOOR HINGES	PHAIAMSNMATKIC
				ALBINA	(DGR) LUBRICATED TRIPOD SEAT POST AND PIVOTS AND WINDOW SLIDES	PHAIAMSNMATKIC
				ALBINA	(DGR) STEAMED CLEANED INTERIOR ENGINE COMPARTMENT.	PHAIAMSNMATKIC
				ALBINA	(DGR-LDS) REPLACED FIREMAN'S SIDE WINDOW AND SLIDE BUSHINGS	PHAIAMSNMATKIC
				ALBINA	(JLB) APPLIED NEW LEFT #4 SAND HOSE.	PHAIAMSNMATKIC
				ALBINA	(JLB) CHANGED AIRCOMPRESSOR AIR INTAKE FILTERS.	PHAIAMSNMATKIC
				ALBINA	(JLB) CHANGED ALL FUEL FILTERS.	PHAIAMSNMATKIC
				ALBINA	(JLB) CHANGED CAR BODY AND BAGGIE AIR FILTERS.	PHAIAMSNMATKIC
				ALBINA	(JLB) CHANGED LUBE OIL FILTERS.	PHAIAMSNMATKIC
				ALBINA	(JLB) CHECKED ALL FLUID LEVELS.	PHAIAMSNMATKIC
				ALBINA	(JLB) CHECKED CONDITION OF (MU) HOSES,FRONT AND REAR OF UNIT.	PHAIAMSNMATKIC
				ALBINA	(JLB) CHECKED CONDITION OF THE FIRST AID KIT.	PHAIAMSNMATKIC
				ALBINA	(JLB) CHECKED MANUALLY OPERATION OF COOLING FAN SHUTTERS.	PHAIAMSNMATKIC
				ALBINA	(JLB) CHECKED OPERATION OF ENGINE PROTECTIVE (COP) SWITCH.	PHAIAMSNMATKIC
				ALBINA	(JLB) CHECKED OPERATION OF AIR COMPRESSOR GOVENER.	PHAIAMSNMATKIC
				ALBINA	(JLB) CLEANED FUEL SYSTEM SIGHT GLASSES.	PHAIAMSNMATKIC
				ALBINA	(JLB) CLEANED LUBE OIL SUCTION STREAMERS.	PHAIAMSNMATKIC
				ALBINA	(JLB) ENGINE LUBE OIL,AND COOLING WATER SAMPLE TAKEN.	PHAIAMSNMATKIC
				ALBINA	(JLB) INSPECTED SAND PIPES AND HOSES FOR DEFECTS.	PHAIAMSNMATKIC
				ALBINA	(JLB) INSURED THAT AUTOMATIC AND INDEPENDENT BRAKE VALVES ARE	PHAIAMSNMATKIC
				ALBINA	(JLB) LUBRICATED AND CHECKED OPERATION OF THE HAND BRAKE.	PHAIAMSNMATKIC
				ALBINA	(JLB) TESTED HORN,BELL,WIPERS AND SANDERS.	PHAIAMSNMATKIC
				ALBINA	(JLB)(CHM) TEST AND CARD.	PHAIAMSNMATKIC
				ALBINA	(YKK) CHANGED RADIO VOLTAGE 12 TO 72	PHAIAMSNMATKIC
				ALBINA	(YKK) CHECKED ALL LIGHTS	PHAIAMSNMATKIC
				ALBINA	(YKK) CHECKED CAB HEATER MOTOR,FUEL PUMP,AND SLIP RING BRUSHES	PHAIAMSNMATKIC
				ALBINA	(YKK) CHECKED ELECTRICAL CABINET	PHAIAMSNMATKIC
				ALBINA	(YKK) CHECKED HIGH VOLTAGE MEG	PHAIAMSNMATKIC

000011

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
DMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE DATE	LOCATION	DETAIL	WORK CODES
UP 001213	04/06/92	04/10/92		ALBINA	(YKK) CHECKED MAIN GEN. AND TRACTION MOTOR BRUSHES(LEAD AND COVER)	PMIAIAMSNIATKIC
				ALBINA	(YKK) CHECKED REVERSER HANDLE INTERLOCK	PMIAIAMSNIATKIC
				ALBINA	(YKK) CLEAR ALL LOW VOLTAGE	PMIAIAMSNIATKIC
				ALBINA	(YKK) INSPECTED BATTERY	PMIAIAMSNIATKIC
				ALBINA	VENTED BELOW THE FLOOR.	PMIAIAMSNIATKIC
	05/19/92	05/21/92		HINKLE	(CAS/DLH) #1 TH TO FINISH	USLUTH
				HINKLE	(CAS/DLH) C/O #1 TMFOR WELDED FLATS	USLUTH
				HINKLE	(CAS/DLH) C/O #2 TMFOR WELDED FLATS	USLUTH
				HINKLE	(CAS/DLH) RM:5-04-92 #1 & #2 WHEELS WELDED.	USLUTH
				HINKLE	(DLH) DUE LU	USLUTH
	07/10/92	07/14/92		HINKLE	(MJB) #1 & 2 TM. CABLES TO HOOK UP.	USLUTH
				HINKLE	() CHANGE DISTRIBUTING VALVE	PMHI LU
				HINKLE	() DUE BM	PMHI LU
				HINKLE	() DUE PI	PMHI LU
				HINKLE	() T & C FOR ELECTRICIANS.	PMHI LU
				HINKLE	() TEST AND CARD FOR MACHINIST.	PMHI LU
				HINKLE	() WATER LEAK #1 ASSY.	PMHI- LU
				HINKLE	(AGS) DUE LU	PMHI- LU
				HINKLE	(CAS/REH) CHECK FOR FUEL LEAKS (VIS. 13.0) NONE FOUND	PMHI LU
				HINKLE	(DAC) DUE QM	PMHI LU
			07/17/92	POCATELLO	(J W) CHECK & SIGN OFF WORK REPORT	PMPIQH ENWAAS
				POCATELLO	(J W) DO SPCL 009 RADIO MODS PER LDI 7200 THRU 7203 & FREQ LSIT	PMPIQH ENWAAS
				POCATELLO	(J W) DO SPCL 036 FRA CHECK LIST	PMPIQH ENWAAS
				POCATELLO	(J W) ELECT RUNNING CHECKS	PMPIQH ENWAAS
				POCATELLO	(J W) MACH RUNNING CHECKS	PMPIQH ENWAAS
				POCATELLO	(J W) PAINT GRAB IRONS & PINLIFTERS WHITE	PMPIQH ENWAAS
				POCATELLO	(J W) PI TO TEST AND CARD	PMPIQH ENWAAS
				POCATELLO	(J W) SA-TO POC FOR PI AND #1 ASSY.	PMPIQH ENWAAS
				POCATELLO	(J W)MICHIANA FILTER HOUSEING LEAKING	PMPIQH ENWAAS
				POCATELLO	(JEW) ENGINE OIL-COMPRESSOR OIL AND WATER SAMPLE	PMPIQH ENWAAS
				POCATELLO	(JEW) PAST DUE BM-C/O DISTRIBUTING VALVE 619-4540	PMPIQH ENWAAS
				POCATELLO	(JEW) PAST DUE PI-QM 07/09/92	PMPIQH ENWAAS
				POCATELLO	(JEW) SA-TO POC FOR PI AND #1 ASSY. C/O	PMPIQH ENWAAS
				POCATELLO	(JEW) TAGEED-#1 ASSY LEAKING WATER AT HEAD	PMPIQH ENWAAS
				POCATELLO	(JEW) TAGEED-#1 ASSY LEAKING WATER AT HEAD C/O	PMPIQH ENWAAS
08/07/92	08/07/92			ALBSERTRK	(DEB) CHECK BRAKES AND PISTON TRAVEL	SVTP
				ALBSERTRK	(DEB) CHECK FLUID LEVELS	SVTP
				ALBSERTRK	(KMG) CLEAN AND SUPPLY CAB	SVTP
08/14/92	08/15/92			ALBSERTRK	(KGB) CHECK FLUID LEVELS	LUSV
				ALBSERTRK	(KGB) DO LU (TAKE LUBE OIL SAMPLE)	LUSV
				ALBSERTRK	(LKR) CLEAN AND SUPPLY CAB	LUSV
				ALBSERTRK	(LP) CHECK LIGHTS RADIO AND REFER	LUSV
				ALBSERTRK	(LP) RUNNING CHECKS	LUSV
				ALBSERTRK	(WRH) CHANGE WORN BRAKE SHOES AND ADJUST TRAVEL	LUSV
				ALBSERTRK	(WRH) REPAIR FRONT TRAINLINE VALVE AND HOSE	LUSV
				ALBSERTRK	(WRH) RUNNING CHECKS	LUSV

000012

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
DMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE DATE MO DA YR	LOCATION	DETAIL	WORK CODES
UP 001213	08/21/92	08/27/92		ALBINA	(JJM) FRA: HANDBRAKE CHAIN WORN IN HALF	USDETK
				ALBINA	(LJM) FRA: R-2 TRUCK FRAME COIL SPRING POCKET BROKEN (JJM)(JJE)	USDETK
	09/01/92	09/02/92		ALBSERTRK	(JLB) CHANGED WORN BRAKE SHOES, ADJUSTED PISTON TRAVEL	TPSV
				ALBSERTRK	(JLB) CHECKED ALL FLUID LEVELS.	TPSV
				ALBSERTRK	(JLB) CLEANED AND SUPPLIED CAB.	TPSV
				ALBSERTRK	(JLB) TESTED HORN, BELL, WIPERS AND SANDERS.	TPSV
	09/06/92	09/08/92		ALBSERTRK	(JLB) CHANGED WORN BRAKE ADJUSTED PISTON TRAVEL.	TPSV
				ALBSERTRK	(JLB) CHECKED ALL FLUID LEVELS.	TPSV
				ALBSERTRK	(JLB) CLEANED AND SUPPLIED CAB.	TPSV
				ALBSERTRK	(JLB) WORKED (HM) CHANGED CAR BODY AND BAGGIE AIR FILTERS.	TPSV
	09/11/92	09/13/92		ALBINA	(JJM) DUE BM	PNBMMPLUBA
				ALBINA	(KGB) DUE LU	PNBMMPLUBA
				ALBINA	(KGB) DUE MM	PNBMMPLUBA
				ALBINA	(YKK) BATTERIES TO C/O	PNBMMPLUBA
	09/16/92	09/17/92		ALBSERTRK	(JLB) CHECKED ALL FLUID LEVELS.	TPSV
				ALBSERTRK	(JLB) CLEANED AND SUPPLIED CAB.	TPSV
				ALBSERTRK	(JLB) TESTED HORN, BELL, WIPERS AND SANDERS.	TPSV
	09/19/92	09/22/92		ALBINA	(JLB) CHANGED #2 T/M ACCT GROUNDED (DGR)	USTE-
	09/29/92	09/29/92		ALBINA	(JLB)(RD)(LRS) CHANGED #2 TRACTION MOTOR, ACCT. GROUNDED ARM.	PNMC
	10/10/92	10/10/92		ALBINA	() DUE EM	PNMI
				ALBINA	() DUE LU	PNMI
				ALBINA	() DUE PI INSP.	PNMI
	10/14/92	10/16/92		SALLAKCIT	(EFF)SPOT ONE (INBOUND)	PNPIEMMA
				SALLAKCIT	(GWO)*ST* LEFT REAR FUEL TANK ANCHOR BOLTS LOOSE(RAP)	PNPIEMMA
				SALLAKCIT	(GWO)*ST* NO FRONT TOGGLE CLEARANCE(RAP)	PNPIEMMA
				SALLAKCIT	(GWO)CHECK RPLS(NO DEFECTS FOUND)	PNPIEMMA
				SALLAKCIT	(GWO)SPOT FOUR "A"	PNPIEMMA
				SALLAKCIT	(GWO)SPOT FOUR "B"	PNPIEMMA
				SALLAKCIT	(GWO)SPOT THREE) ELECTRICAL)	PNPIEMMA
				SALLAKCIT	(RAP) TAKE WHEEL SIZE *** WHEELS OK ***	PNPIEMMA
				SALLAKCIT	(RLV)*PI* DUE INSPECTION 10/16/92	PNPIEMMA
				SALLAKCIT	(RLV)*ST* DIC(RAP)	PNPIEMMA
				SALLAKCIT	(RLV)SPOT SIX	PNPIEMMA
				SALLAKCIT	(RLV)SPOT TWO (WASH)	PNPIEMMA
				SALLAKCIT	(WCG)*LM*RED LAB CHANGE LUBE OIL & FILTERS	PNPIEMMA
				SALLAKCIT	(WCG)FILL W/ENG OIL/REPT ON /LL402	PNPIEMMA
				SALLAKCIT	(WCG)SPECIAL (009A-***) WINTERIZATION	PNPIEMMA
				SALLAKCIT	(WCG)SPOT FIVE	PNPIEMMA
				SALLAKCIT	(WCG)SPOT FOUR "C"	PNPIEMMA
				SALLAKCIT	HELD 10/14/92	TRACK 01 PNPIEMMA
	10/24/92	10/25/92		SALLAKCIT	(***)SPCL(090-***)APPLY LOCOMOTIVE INSPECTION STICKER/DECAL	USNL
				SALLAKCIT	(BEB)*ST* REV. CONTACTOR INTERLOCK B/O(GGC) (NO LOAD IN REVERSE)	USNL
				SALLAKCIT	(BEB)USE AS SWITCH ENGINE AROUND SHOP CAN FIND NOTHING WRONG(BEB)	USNL
				SALLAKCIT	HELD 10/24/92 DUE	TRACK 05 USNL
	11/18/92	11/19/92		SALLAKCIT	(***)INBOUND PROCESS	USTW
				SALLAKCIT	(BA)*ST* FLAT WHEELS(KGP)	USTW

000013

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
DMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE DATE MO DA YR	LOCATION	DETAIL	WORK CODES
UP 001213	11/18/92	11/19/92		SALLAKCIT (BA)	*ST* REPORTED WEATHER STRIPPING(KGP)	USTW
				SALLAKCIT (BA)	WT ALL WHEEL'S (FLATS)	USTW
				SALLAKCIT	HELD 11/18/92	TRACK 08 USTW
	12/14/92	12/14/92		SALLAKCIT (JRM)	*ST* BRAKE SHOES WORK(KGP)	USTW
				SALLAKCIT (JRM)	*ST* FLAT WHEELS(KGP)	USTW
				SALLAKCIT (JRM)	*TW* TURN WHEELS	USTW
				SALLAKCIT	HELD 12/14/92	TRACK 05 USTW

000014

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
OMNT459. FOCUS. MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE DATE MO DA YR	LOCATION	DETAIL	WORK CODES
UP 001218	12/31/87	01/01/88		SALLAKCIT	(BEJ)*ST* MON'T STAY RUNNING. (DTC)	CR
				SALLAKCIT	(JRL)OUT OF ENG OIL	CR
				SALLAKCIT	HELD 12/31 DUE	TRACK 05 CR
	01/06/88	01/06/88		SALLAKCIT	() *PROJECTS*(05***).	TW
				SALLAKCIT	() *ST* REFER B/O...	TW
				SALLAKCIT	(GEC)*ST* CHECK ALL WHEEL FLATS..WT ALL	TW
				SALLAKCIT	(GEC)*ST* R3 WHEEL 3 1/2 " FLATS...	TW
				SALLAKCIT	(MM)*ST* REFER B/O...	TW
				SALLAKCIT	HELD 01/06 PI DUE	TRACK 08 TW
	01/16/88	01/17/88		SALLAKCIT	() *PROJECTS*(05***).	TWFP
				SALLAKCIT	(GEC)*ST* B/O FUEL PUMP.	TWFP
				SALLAKCIT	(GEC)*ST* DIC.. WHEEL TRUE FLATS.	TWFP
				SALLAKCIT	(JRB)START & CHECK	TWFP
				SALLAKCIT	(OKK)*PROJECTS*(05***).	TWFP
				SALLAKCIT	HELD 01/16 PI DUE	TRACK 08 TWFP
	02/02/88	02/04/88		SALLAKCIT	() PROJECTS (05***)	TWENFSAB
				SALLAKCIT	(DLG)*ST* FLAT SPOTS	TWENFSAB
				SALLAKCIT	(DLG)*ST* GOV OIL LOW	TWENFSAB
				SALLAKCIT	(DLG)*ST* WHEEL TRUE 1-2-3-4 MILS FLATSPOTS	TWENFSAB
				SALLAKCIT	(DLG)*ST* X BELL B/O	TWENFSAB
				SALLAKCIT	(DLG)C/O FUEL FILTERS	TWENFSAB
				SALLAKCIT	(LMF)*ST* BY PASS FUEL	TWENFSAB
				SALLAKCIT	(LMF)REMOVED LARGE FUEL PUMP & APPLY SMALL ONE	TWENFSAB
				SALLAKCIT	HELD 02/02	TRACK 05 TWENFSAB
	02/16/88	02/16/88		SALLAKCIT	() PROJECTS (05-***)	LV
				SALLAKCIT	(CDR)*LV*HEADLIGHT CURRENT BO(CDR)	LV
				SALLAKCIT	(DTC)*ST*ERRATIC LOAD LOADS IN IDLE SOMETIMRS(CDR)	LV
				SALLAKCIT	HELD 02/16/88 DUE	TRACK 05 LV
	03/04/88	03/04/88		SALLAKCIT	(JEA)*TW*FLAT SPOTS ALL WHEELS	TW
				SALLAKCIT	(JRL)PROJECTS (05-NIS)	TW
				SALLAKCIT	(PIT)*ST*ENGINE OIL LOW(CDR)	TW
				SALLAKCIT	HELD 03/04/88 DUE	TRACK 08 TW
	06/10/88	06/18/88		SALLAKCIT	(BA)*DUE TRIANNUAL FRA INSPECTION	TIRMENWAABDGTW
				SALLAKCIT	(BA)FIN INSP REPORTS	TIRMENWAABDGTW
				SALLAKCIT	(BA)INSP(M-OK)(E-OK)(CC-OK)(BM-OK)	TIRMENWAABDGTW
				SALLAKCIT	(BA)NEED 3 YR. AIR KIT	TIRMENWAABDGTW
				SALLAKCIT	(BA)WASH - CLEAN CAB	TIRMENWAABDGTW
				SALLAKCIT	(BA)WORK AI & 3 YR AIR	TIRMENWAABDGTW
				SALLAKCIT	(BPC)C/O FRONT DRAFT GEAR(BO PIN & BUSHINGS)(GMD)**OUT, TO APPLY**	TIRMENWAABDGTW
				SALLAKCIT	(CEP)APPLY PILOT PLATE	TIRMENWAABDGTW
				SALLAKCIT	(DLG)WT ALL WHEELS(FLATS)	TIRMENWAABDGTW
				SALLAKCIT	(GMD) PROJECTS (05*OK)	TIRMENWAABDGTW
				SALLAKCIT	(GMD)W/BRAKES	TIRMENWAABDGTW
				SALLAKCIT	(JEA)APPLY CAR BODY DOORS & COVER AUX	TIRMENWAABDGTW
				SALLAKCIT	(JEA)APPLY MISS BOLTS IN CARBODY	TIRMENWAABDGTW
				SALLAKCIT	(JEA)APPLY STACK COVER	TIRMENWAABDGTW

000015

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
OMMT459.FOCUS.MAINTING

LOCOMOTIVE	PLACE	DATE	RELEASE	DATE	LOCATION	DETAIL	WORK CODES
NUMBER	MO	DA	YR	MO	DA	YR	
UP 001218	06/10/88	06/18/88			SALLAKCIT (JRB)TEST & CARD	CARDED 06/17/88	TIRNEWMAABDGTW
					SALLAKCIT (LMF)ALIGN AUX GEN		TIRNEWMAABDGTW
					SALLAKCIT (LMF)C/O ENGINE BLOWERS(OVERHEATED)**FIN**		TIRNEWMAABDGTW
					SALLAKCIT (LMF)CLEAN AIR BOX DRAINS		TIRNEWMAABDGTW
					SALLAKCIT (LMF)CLEAN OIL SEP FILTER		TIRNEWMAABDGTW
					SALLAKCIT (LMF)GET RING INSP AFTER BLOWERS C/O (WON'T TURN OVER)		TIRNEWMAABDGTW
					SALLAKCIT (LMF)HYDRO WASH & OIL AIR BOXES		TIRNEWMAABDGTW
					SALLAKCIT (PDB)W/TH'S		TIRNEWMAABDGTW
					SALLAKCIT HELD 06/10		TRACK 10 TIRNEWMAABDGTW
	07/10/88	07/24/88			SALLAKCIT (BJF)*ST* DIC - NO OIL PRESSURE		OPEN
					SALLAKCIT (DLG)APPLY AIR COMP GUARDS		OPEN
					SALLAKCIT (DLG)RIGHT FUEL SIGHT GLASS ROBBED (REPLACED-ROBBED 1221)		OPEN
					SALLAKCIT (DTC)ECP IN ELECTSHOP		OPEN
					SALLAKCIT (DWD)*ST* CHECK BATT. CHARGING VOLTAGE		OPEN
					SALLAKCIT (DWD)ADJUST LOAD REGULATOR TO MAX.FLD		OPEN
					SALLAKCIT (DWD)CHECK OPERATION OF ECP		OPEN
					SALLAKCIT (DWD)ELECT TEST OUT		OPEN
					SALLAKCIT (NIS)*ST* DEAD BATTERIES (DRY) NEEDS NEW RETURN WHEN AVAILBLE!		OPEN
					SALLAKCIT (PDB)MACH TEST OUT		OPEN
					SALLAKCIT (PPA)*ST* CLEAN SPARK ARRESTORS		OPEN
					SALLAKCIT (PPA)ADD LUBE OIL		OPEN
					SALLAKCIT (PPA)OIL SCAVENGE PUMP B.O.C/O**PIPE**		OPEN
					SALLAKCIT (PPA)REPLACE AIR BOX COVER GSKTS 7-12		OPEN
					SALLAKCIT HELD 07/10	PI DUE	TRACK 05 OPEN
	07/28/88	08/04/88			SALLAKCIT	CHANGE OUT WHEN BATTS AVAILABLE.	RHEMBAERNA
					SALLAKCIT (DLG)BLOCK BATTERYS		RHEMBAERNA
					SALLAKCIT (JEA)*ST* BATTEY BOX LIDS HAVE BROKEN HINGES(CDR)		RHEMBAERNA
					SALLAKCIT (JEA)C/O L BLOWER DON'T TURN**APPLY**		RHEMBAERNA
					SALLAKCIT (JEA)CLEAN OIL SEP.FILTER		RHEMBAERNA
					SALLAKCIT (LMF)*ST* REPORTED BURNT UP(CDR)		RHEMBAERNA
					SALLAKCIT (LMF)ALIGN AUX GEN		RHEMBAERNA
					SALLAKCIT (LMF)C/O BAGGIES		RHEMBAERNA
					SALLAKCIT (LMF)PIPE & COVER LEFT BLOWER		RHEMBAERNA
					SALLAKCIT (LMF)WASH		RHEMBAERNA
					SALLAKCIT (REJ)*RM* 07/24/88 UZ029 RETURN TO SL SHOP FOR BATTERY		RHEMBAERNA
					SALLAKCIT HELD 07/28/88	DUE	TRACK 02 RHEMBAERNA
	08/05/88	08/06/88			SALLAKCIT (BEB)*ST* ALL WHEELS FLAT		TW
					SALLAKCIT (BEB)ADJUST BRAKE TRAVEL		TW
					SALLAKCIT (BEB)WHEEL TRUE #1-2-3-4		TW
					SALLAKCIT HELD 08/05		TRACK 08 TW
	09/18/88	09/21/88			SALLAKCIT (DLG)*ST* DIC(RAP)		PIGHEMNA
					SALLAKCIT (DLG)TEST & CARD	CARDED 09/20/88	PIGHEMNA
					SALLAKCIT (DWD)CLEAN CAB		PIGHEMNA
					SALLAKCIT (DWD)INSP(M-OK)(E-OK)(CC-OK)(BHK-OK)		PIGHEMNA
					SALLAKCIT (DWD)W/BRAKES		PIGHEMNA
					SALLAKCIT (DWD)W/THS		PIGHEMNA

000010

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
CHNT459. FOCUS. MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE DATE MO DA YR	LOCATION	DETAIL	WORK CODES
UP 001218	09/18/88	09/21/88		SALLAKCIT	(DMD)WASH	PIDMEWMA
				SALLAKCIT	(GMD)*PI* DUE INSPECTION 09/17/88	PIDMEWMA
				SALLAKCIT	(PDB)C/O COMP CONTROL SWITCH	PIDMEWMA
				SALLAKCIT	(PDB)HTO	PIDMEWMA
				SALLAKCIT	HELD 09/18/88 DUE PI 09/17/88	TRACK 05 PIDMEWMA
	10/17/88	10/22/88		SALLAKCIT	ARE PIPED BELOW THE CAB FLOOR.....	EWMAEB
				SALLAKCIT	(BEJ)*ST* HAD AIR BOX FIRE	EWMAEB
				SALLAKCIT	(BEJ)START & CHECK	EWMAEB
				SALLAKCIT	(JEA)ALIGN AUX GEN	EWMAEB
				SALLAKCIT	(JEA)APPLY AUX GEN HATCH & CARBODY DOORS	EWMAEB
				SALLAKCIT	(JEA)C/O BAGGIES	EWMAEB
				SALLAKCIT	(JEA)C/O L BLOWER SEALS**LMF** ***APPLY***NEED GASKET***	EWMAEB
				SALLAKCIT	(JEA)LEFT AIR BOX DRAIN PLUGGED	EWMAEB
				SALLAKCIT	(JEA)PIPE LEFT BLOWER	EWMAEB
				SALLAKCIT	(JEA)PRESSURE CHECK - CK RPLS	EWMAEB
				SALLAKCIT	(JRB)WASH & OIL AIR BOXES	EWMAEB
				SALLAKCIT	(OK)*SPCL**04**INSPECT AUTOMATIC & INDP. BRAKE VALVE EXHAUSTS	EWMAEB
				SALLAKCIT	(FIT)*ST* BRAKE TRAVEL LONG	EWMAEB
				SALLAKCIT	HELD 10/17 PI DUE	TRACK 02 EWMAEB
	11/18/88	11/27/88		SALLAKCIT	(BA)*ST* FIRE OUT STACK	RHTWLEMPAWAEBLT
				SALLAKCIT	(BA)*#2 EXH STACK PLUGGED	RHTWLEMPAWAEBLT
				SALLAKCIT	(BA)*APPLY R BLOWER	RHTWLEMPAWAEBLT
				SALLAKCIT	(BA)*BLOW BY TEST(OK)*C/O # 2,4,5,6,9 ASSYS(WET CROWN)	RHTWLEMPAWAEBLT
				SALLAKCIT	(BA)*C/O #1 ASSY(WL)	RHTWLEMPAWAEBLT
				SALLAKCIT	(BA)*PRESS CK L-BLOWER OIL SEALS	RHTWLEMPAWAEBLT
				SALLAKCIT	(CEP)*ST* C/O THIN BRAKE SHOES	RHTWLEMPAWAEBLT
				SALLAKCIT	(CEP)*ST* WT FLATS	RHTWLEMPAWAEBLT
				SALLAKCIT	(CEP)COVER EXHAUST STACK	RHTWLEMPAWAEBLT
				SALLAKCIT	(CEP)PRESS CK-CK RPL'S(AIR BOX FIRE L-SIDE)	RHTWLEMPAWAEBLT
				SALLAKCIT	(DLL)*ST* NO LOAD	RHTWLEMPAWAEBLT
				SALLAKCIT	(DLL)START & CHECK**METAL TO METAL NOISE ON START UP)	RHTWLEMPAWAEBLT
				SALLAKCIT	(DMD) SPECIAL 035-APPLY H.U.L JUMPER CABLE "CAN" TO EACH END	RHTWLEMPAWAEBLT
				SALLAKCIT	(DMD)REMOVE #2 STACK AND CLEAN (JRL) (OFF)	RHTWLEMPAWAEBLT
				SALLAKCIT	(JEA)APPLY DOORS & COVERS	RHTWLEMPAWAEBLT
				SALLAKCIT	(JEA)C/O AIR INTAKE BAGGIE FILTERS(PLUGGED)	RHTWLEMPAWAEBLT
				SALLAKCIT	(JEA)C/O R & L BLOWERS (WON'T TURN) ***APPLY***	RHTWLEMPAWAEBLT
				SALLAKCIT	(JEA)PIPE FILTER ADAPTERS	RHTWLEMPAWAEBLT
				SALLAKCIT	(JEA)PIPE L & R BLOWERS	RHTWLEMPAWAEBLT
				SALLAKCIT	(JEA)PURGE CHECK OIL FLOW TO BLOWERS	RHTWLEMPAWAEBLT
				SALLAKCIT	(JEA)WASH	RHTWLEMPAWAEBLT
				SALLAKCIT	(JRB)PIPE #1 ASSY	RHTWLEMPAWAEBLT
				SALLAKCIT	(JRL)CHECK MAIN LUBE PUMP FOR PRESSURE	RHTWLEMPAWAEBLT
				SALLAKCIT	(PDB)ALIGN AUX GEN	RHTWLEMPAWAEBLT
				SALLAKCIT	HELD 11/18	TRACK 02 RHTWLEMPAWAEBLT
	12/02/88	12/05/88		SALLAKCIT	(GEC)*ST* #3 * #4 TH GEAR CASE BENT (UNIT HAS BEEN ON GROUND	EWADTKTRTWMA
				SALLAKCIT	(GEC)*ST* #3 GC LEAKING FROM CRACK	EWADTKTRTWMA

000017

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
OMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE DATE MO DA YR	LOCATION	DETAIL	WORK CODES
UP 001218	12/02/88	12/05/88		SALLAKCIT	(GEC)*ST* C/O THIN & WORN BRAKE SHOES	EWADTKTRTUNA
				SALLAKCIT	(GEC)*ST* OVERRIDING BRAKE	EWADTKTRTUNA
				SALLAKCIT	(GEC)C/O R#4 COIL SPRING POCKET	EWADTKTRTUNA
				SALLAKCIT	(GWB)C/O R #3 ELIPTIC SPRING HOLDER	EWADTKTRTUNA
				SALLAKCIT	(JRM)*ST* PART OF L #4 WHEEL FLANGE MISSING WT	EWADTKTRTUNA
				SALLAKCIT	(JRM)*ST* R MR AUTO DRAIN B/O	EWADTKTRTUNA
				SALLAKCIT	HELD 12/02	TRACK OS EWADTKTRTUNA
	12/06/88	12/07/88		SALLAKCIT	UNCOUPLING LEVER HANDLE(RAP)	CD
				SALLAKCIT	(LMF)*ST* RELOCATE MU CABLE HOLDERS BOTH ENDS, INTERFERES WITH	CD
				SALLAKCIT	HELD 12/06/88 DUE	TRACK OS CD
	12/18/88	12/21/88		SALLAKCIT	(DWD) SPECIAL 004 - INSPECT AUTOMATIC AND INDEPENDENT BRAKE VALVE	PISMTW
				SALLAKCIT	(DWD)*ST* PI INSP.	PISMTW
				SALLAKCIT	(DWD)INSP(M-DK)(E-DK)(CC-DK)(B-DK)	PISMTW
				SALLAKCIT	(DWD)REPAIR FRONT DOOR (TRIM DAMAGED)	PISMTW
				SALLAKCIT	(DWD)WASH - CLEAN CAB	PISMTW
				SALLAKCIT	(DWD)WORK AIR	PISMTW
				SALLAKCIT	(DWD)WORK BRAKES	PISMTW
				SALLAKCIT	(DWD)WORK WHITE SHEETS	PISMTW
				SALLAKCIT	(GEC)*ST* ALL WHEELS HAVE FLAT SPOTS. WT	PISMTW
				SALLAKCIT	(GEC)WHEEL TRUE ALL (FLATS)	PISMTW
				SALLAKCIT	(JRM)TEST & CARD	CARD 12/20/88 PISMTW
				SALLAKCIT	(JRM)WORK TH'S	PISMTW
				SALLAKCIT	(PDB)MACH TESTOUT	PISMTW
				SALLAKCIT	HELD 12/18/88	PI DUE TRACK OS PISMTW
	12/29/88	12/30/88		SALLAKCIT	(DLG)FILL WITH WATER	TWEN
				SALLAKCIT	(DLG)WASH	TWEN
				SALLAKCIT	(GEC)*ST* EXHAUST STACK CAP MISSING FROM EXHAUST STACK	TWEN
				SALLAKCIT	(GEC)*ST* EXHAUST STACK CAP MISSING FROM EXHAUST STACK	TWEN
				SALLAKCIT	(GEC)*ST* FLAT WHEELS	TWEN
				SALLAKCIT	HELD 12/29	TRACK OS TWEN
	01/14/89	01/14/89		SALLAKCIT	EXHAUSTS ARE PIPED BLOW CAB FLOOR.....	RMTW
				SALLAKCIT	(BEJ)*SPCL*04*INSPECT UNIT TO INSURE AUTO & INDP BRAKE VALVE	RMTW
				SALLAKCIT	(CEP)*ST* TRUE WHEEL - 3" FLANGE	RMTW
				SALLAKCIT	(REJ)*RM* APPLY RADIO ANTENNA ON ROOF WHEN SHOPPED	RMTW
				SALLAKCIT	HELD 01/14	PI DUE TRACK OS RMTW
	01/27/89	02/11/89		SALLAKCIT	()TO SERVICE FOR FUEL	EXWA
				SALLAKCIT	(JEA)CLEAN #1 STACK SPARK ASSRESTER CAP	EXWA
				SALLAKCIT	(JEA)WASH	EXWA
				SALLAKCIT	(LMF)*ST*#2 STACK BASE GASKETS LEAKING	EXWA
				SALLAKCIT	(PIT)*ST* GRCD NOT SEALED.	EXWA
				SALLAKCIT	(PIT)*ST* SAND LIGHT IS OUT.	EXWA
				SALLAKCIT	HELD 01/27/89	PI DUE 3/22/89 TRACK OS EXWA
	02/11/89	02/11/89		SALLKSERT	(SRT)M.M.	NH
				SALLKSERT	HELD 02/11	NH
	02/16/89	02/21/89		SALLAKCIT	(BA)*ST* AIRBOX FULL OF OIL(MJL)	EWOLWALT
				SALLAKCIT	(BA)AIR BOX DRAINS PLUGGED	EWOLWALT

000018

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
OMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE MO DA YR	LOCATION	DETAIL	WORK CODES
UP 001218	02/16/89	02/21/89		SALLAKCIT	(BA)C/O BAGGIES -PLUGGED	EWOLWALT
				SALLAKCIT	(BA)CK R&L BLOWERS - FOLD OK	EWOLWALT
				SALLAKCIT	(BA)PRE-WASH	EWOLWALT
				SALLAKCIT	(BA)PRESS CK RPLS'S CK FOR ML'S	EWOLWALT
				SALLAKCIT	(JRB)ST & CK	EWOLWALT
				SALLAKCIT	(LMF)BELL RINGER BO (WEAK)	EWOLWALT
				SALLAKCIT	HELD 02/16/89 DUE	TRACK 05 EWOLWALT
	02/27/89	03/01/89		SALLAKCIT	(GEC)*ST* WHEEL TRUE - ENGR REPORTS FLATS	TWTH
				SALLAKCIT	(JEA)*ST* L. NO. 2 SANDER HOSE AND NOZZLE MISSING	TWTH
				SALLAKCIT	(JEA)*ST* LUBE OIL LOW	TWTH
				SALLAKCIT	(JEA)C/O #1 WHL (THIN & FLATS)	TWTH
				SALLAKCIT	(REJ)*ST* GAUGE AND GROUND LITE CIRCUIT B/O	TWTH
				SALLAKCIT	(REJ)*ST* LOW VOLTAGE GROUND	TWTH
				SALLAKCIT	HELD 02/27 PI DUE	TRACK 05 TWTH
	03/10/89	03/14/89		SALLAKCIT	(BA)*ST* A/C ROOM OILY.	EWOLTKMAEX
				SALLAKCIT	(BA)*ST* L. WALKWAY AND FRONT OF UNIT VERY OILY AND SLIPPERY.	EWOLTKMAEX
				SALLAKCIT	(BA)*ST* OIL OUT STACK.	EWOLTKMAEX
				SALLAKCIT	(BA)*ST* R. AUTO DRAIN BO.	EWOLTKMAEX
				SALLAKCIT	(BA)*ST* 9-10-11 AIR BOX COVERS LEAKING.	EWOLTKMAEX
				SALLAKCIT	(BA)C/O ALL TOP DECK COVER LATCHES (DEF)	EWOLTKMAEX
				SALLAKCIT	(BA)C/O BAGGIES (PLUGGED)	EWOLTKMAEX
				SALLAKCIT	(CEP)CLEAN CARBON FROM STACKS	EWOLTKMAEX
				SALLAKCIT	(CEP)CLEAN VEE OF ENGINE	EWOLTKMAEX
				SALLAKCIT	(CEP)CUT HOLES IN STACK FOR CLEANING	EWOLTKMAEX
				SALLAKCIT	(CEP)REMOVE #1 & 2 STACKS	EWOLTKMAEX
				SALLAKCIT	(JEA)*ST* DEAD AND DRAINED.	EWOLTKMAEX
				SALLAKCIT	(JEA)COVER STACKS	EWOLTKMAEX
				SALLAKCIT	(JEA)PIPE WYE PIPE	EWOLTKMAEX
				SALLAKCIT	(JEA)REAPPLY STACKS	EWOLTKMAEX
				SALLAKCIT	(PDB)START & CHECK	EWOLTKMAEX
				SALLAKCIT	HELD 03/10/89	TRACK 05 EWOLTKMAEX
	03/22/89	03/24/89		SALLAKCIT	(BEB)ELEC TEST OUT	PIGMABAEX
				SALLAKCIT	(CEP)APPLY CARBODY FILTERS	PIGMABAEX
				SALLAKCIT	(CEP)C/O BATTERIES (BROKEN TRAY) (FIN)	PIGMABAEX
				SALLAKCIT	(CEP)WASH / CLEAN CAB	PIGMABAEX
				SALLAKCIT	(PDB)MECH TEST OUT #2 STACK BASE GSKT STILL LEAKS C/O**	PIGMABAEX
				SALLAKCIT	(RLV)*PI* DUE INSP	PIGMABAEX
				SALLAKCIT	(RLV)INSPECT(M-OK)(E-OK)(CC-OK)(B-OK)	PIGMABAEX
				SALLAKCIT	(RLV)TEST & CARD	PIGMABAEX
				SALLAKCIT	(RLV)WHEELS	PIGMABAEX
				SALLAKCIT	(RLV)WORK BRAKES	PIGMABAEX
				SALLAKCIT	(RLV)WORK TMS	PIGMABAEX
				SALLAKCIT	HELD 03/22 PI INSPECTION	TRACK 05 PIGMABAEX
				SALLAKCIT	HELD 03/22 PI INSPECTION	TRACK 02 PIGMABAEX
	04/12/89	04/14/89		SALLAKCIT	BOTH SIDES	TW
				SALLAKCIT	(DLG)*ST* B/O AUTO DRAINS	TW

000019

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
OMNT459.FOCUS.MAINTING

LOCOMOTIVE	PLACE	DATE	RELEASE	DATE	LOCATION	DETAIL	WORK CODES
NUMBER	MO	DA	YR	MO	DA	YR	
UP 001218	04/12/89	04/14/89			SALLAKCIT	(DLG)*ST* ENG AND GOV OIL LOW	TW
					SALLAKCIT	(DLG)*ST* FRA REPORTS INSUFFICIENT HANDHOLD CLEARANCE (VERTICAL)	TW
					SALLAKCIT	(DLG)*ST* OIL ON GENERATOR	TW
					SALLAKCIT	(DLG)*ST* REAR PILOT HIGH	TW
					SALLAKCIT	(DLG)*ST* REAR PILOT PLATE HIGH AND DAMAGED	TW
					SALLAKCIT	(JEA)*ST* LEFT NO. 1. WHEEL HAS 2-1/2 FLAT SPOT	TW
					SALLAKCIT	(JEA)WHEEL TRUE ALL (FLATS)	TW
					SALLAKCIT	(JRB)*ST* HAS SHORT BRAKE RIGGING* UNABLE TO REPLACE BRAKE SHOE	TW
					SALLAKCIT	(JRB)*ST* LEFT NO. 1 INSIDE SHOE BROKEN IN HALF	TW
					SALLAKCIT	(JRB)FIN WORK BRAKES	TW
					SALLAKCIT	HELD 04/12	TRACK DS TW
	04/20/89	04/21/89			SALLAKCIT	ENG ROOM AND A/C ROOM OILY(CDR)	SU
					SALLAKCIT	()**XG** STORED UNTIL MAIN GENERATOR AVAILABLE*****	SU
					SALLAKCIT	()*GR* GROUND RELAY(CDR)	SU
					SALLAKCIT	()*ST* DIC(CDR)	SU
					SALLAKCIT	()*ST* GENPIT, GEN BLOWERS, AUX GEN, OIL SEPARATOR, ENGINE,	SU
					SALLAKCIT	()*ST* OS DRAIN LEAKING(CDR)	SU
					SALLAKCIT	()*ST* OVERRIDING BRAKES(CDR)	SU
					SALLAKCIT	()*ST* SMALL FLATS(CDR)	SU
					SALLAKCIT	()*ST* WORK BRAKES(CDR)	SU
					SALLAKCIT	()INSPECT MAIN GEN (SHOWS SIGNS OF DEFECTIVE ARMATURE**XG**)	SU
					SALLAKCIT	(DND)*ST* MAIN GEN OVERHEATED(CDR) **VERIFIED**	SU
					SALLAKCIT	HELD 04/20/89 DUE	TRACK DS SU
	05/19/89	05/23/89			SALLAKCIT	(BA)**M* INSP TO DO ***C/D FUEL FILTERS***	MILUNGENWALT
					SALLAKCIT	(BA)BLMK TO COVER	MILUNGENWALT
					SALLAKCIT	(BA)PIPE RIGHT BLOWER	MILUNGENWALT
					SALLAKCIT	(BA)REAM AND DOWEL GEN	MILUNGENWALT
					SALLAKCIT	(CDR)START & CHECK	MILUNGENWALT
					SALLAKCIT	(GWB)REAPPLY GEN GAURDS	MILUNGENWALT
					SALLAKCIT	(JEA)APPLY AND LINE	MILUNGENWALT
					SALLAKCIT	(JEA)CHANGE MAIN GEN.	MILUNGENWALT
					SALLAKCIT	(JES)APPLY AUX GEN AND ALIGN	MILUNGENWALT
					SALLAKCIT	(JES)APPLY HOOD	MILUNGENWALT
					SALLAKCIT	(JES)APPLY HORN & BRACKET	MILUNGENWALT
					SALLAKCIT	(JES)C/D OIL SEPARATOR FILTER	MILUNGENWALT
					SALLAKCIT	(JRM)CONVERTER MISSING-ETO	MILUNGENWALT
					SALLAKCIT	(JRM)MACH TEST OUT	MILUNGENWALT
					SALLAKCIT	(JRM)PIPE BELL	MILUNGENWALT
					SALLAKCIT	(JRM)PIPE HORN	MILUNGENWALT
					SALLAKCIT	(JRM)WASH	MILUNGENWALT
					SALLAKCIT	(PPA)APPLY RIGHT BLOWER	MILUNGENWALT
					SALLAKCIT	(REJ)CONNECT MAIN GENERATOR AND AUX GEN.	MILUNGENWALT
					SALLAKCIT	(REJ)LOAD NEW MAIN GEN *****SEAT THE BRUSHES.*****	MILUNGENWALT
					SALLAKCIT	HELD 05/?? DUE	TRACK DS MILUNGENWALT
	06/03/89	06/04/89			SALLAKCIT	(***) PROJECTS 015-APPLY NEW CAB CARD ORGANIZER	NLEW
					SALLAKCIT	(BEB)*ST* REPT DROPS LOAD	NLEW

000020

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
OMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE DATE MO DA YR	LOCATION	DETAIL	WORK CODES
UP 001218	06/03/89	06/04/89		SALLAKCIT	(JES)C/O BAGGIE FILTERS(PLUGGED)	NLEW
				SALLAKCIT	(PIT)*ST* LUBE OIL 4" LOW	NLEW
				SALLAKCIT	HELD 06/03	TRACK 05 NLEW
	06/06/89	06/11/89		SALLAKCIT	() START & CHECK	EWMAEB
				SALLAKCIT	(GMB)C/O LEFT BLOWER DEF SEALS**LMF** ***APPLY***	EWMAEB
				SALLAKCIT	(JES)*ST* REPORTED ENGINE OIL LOW	EWMAEB
				SALLAKCIT	(JES)*ST* REPORTED ENGINE SMOKES	EWMAEB
				SALLAKCIT	(JES)CLEAN GEN PIT	EWMAEB
				SALLAKCIT	(JES)PRESS CK-CK RPLS	EWMAEB
				SALLAKCIT	(JES)RIGHT AIR BOX DRAIN PLATE LKS BAD	EWMAEB
				SALLAKCIT	(LMF)PRE-WASH	EWMAEB
				SALLAKCIT	HELD 06/06 AI DUE	TRACK 05 EWMAEB
	06/15/89	06/17/89		SALLAKCIT	(***) PROJECTS 015-APPLY NEW CAB CARD ORGANIZER	TWMA
				SALLAKCIT	(BEB)WHEEL TRUE FLATS	TWMA
				SALLAKCIT	HELD 06/15	TRACK 05 TWMA
	06/21/89	06/25/89		SALLAKCIT	WIRES. (ORDERED IN NEW ONES)	AITWENWATK
				SALLAKCIT	(GMD)W/BRAKES	AITWENWATK
				SALLAKCIT	(GMD)W/TMS	AITWENWATK
				SALLAKCIT	(JEA)MTD	AITWENWATK
				SALLAKCIT	(JRB)LEFT SIDE FRONT TRUCK COIL SPRING POCKET CRACKED	AITWENWATK
				SALLAKCIT	(REJ)TEST & CARD CARDED 06/22/89	AITWENWATK
				SALLAKCIT	(RLV)*ST* DUE ANNUAL INSPECTION	AITWENWATK
				SALLAKCIT	(RLV)APPLY CARBODY FILTERS	AITWENWATK
				SALLAKCIT	(RLV)AUX GEN FAN HOUSING LOOSE AT TOP OF MAIN GEN	AITWENWATK
				SALLAKCIT	(RLV)INSP(H-OK)(E-OK)(CC-OK)(BMK-OK)	AITWENWATK
				SALLAKCIT	(RLV)REMOVE R & L BLOWER FILTER ADAPTER & REPAIR BROKEN & LOOSE	AITWENWATK
				SALLAKCIT	(RLV)WASH / CLEAN CAB	AITWENWATK
				SALLAKCIT	HELD 06/21	TRACK 06 AITWENWATK
	07/25/89	07/26/89		POCATELLO	() DIC CRANK CASE EXPLOSION	RM
	07/27/89	08/02/89		SALLAKCIT	(***) SPECIAL (15-***) APPLY NEW CAB CARD ORGANIZER	TWRNEMEBNAPAFI
				SALLAKCIT	(GGJ)ELECT TEST OUT	TWRNEMEBNAPAFI
				SALLAKCIT	(JEA)APPLY CARBODY FILTERS	TWRNEMEBNAPAFI
				SALLAKCIT	(JEA)C/O #7-8 INJ LKS	TWRNEMEBNAPAFI
				SALLAKCIT	(JEA)WASH	TWRNEMEBNAPAFI
				SALLAKCIT	(JES)C/O BAGGIE AIR FILTERS	TWRNEMEBNAPAFI
				SALLAKCIT	(JES)C/O*LEFT BLOWER OVERHEAT	TWRNEMEBNAPAFI
				SALLAKCIT	(JES)PIPE LEFT BLOWER	TWRNEMEBNAPAFI
				SALLAKCIT	(JRA)C/O #2(JRA) #3(PPA) #4(PPA)	TWRNEMEBNAPAFI
				SALLAKCIT	(LMF)**LAB 2.7 FUEL DIL.**	TWRNEMEBNAPAFI
				SALLAKCIT	(LMF)*RM* 07/26/89 POC LEFT BLOWER B/O FIRE IN AIRBOX	TWRNEMEBNAPAFI
				SALLAKCIT	(LMF)#2 TRUCK ON GROUND CHECK DERAIL DAMAGE	TWRNEMEBNAPAFI
				SALLAKCIT	(LMF)APPLY BLOWER HATCH	TWRNEMEBNAPAFI
				SALLAKCIT	(LMF)APPLY LUBE OIL	TWRNEMEBNAPAFI
				SALLAKCIT	(LMF)BLACKLITE	TWRNEMEBNAPAFI
				SALLAKCIT	(LMF)C/O #6 ASSY WLS**FINISH**	TWRNEMEBNAPAFI
				SALLAKCIT	(LMF)C/O BAGGIES	TWRNEMEBNAPAFI

000021

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
OMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE DATE MO DA YR	LOCATION	DETAIL	WORK CODES
UP	001218	07/27/89	08/02/89	SALLAKCIT	(LMF)C/O LUBE FILTERS	TWRMEWBWAPAFI
				SALLAKCIT	(LMF)C/DW LEFT WATER PUMP LEAKS(MJL)	TWRMEWBWAPAFI
				SALLAKCIT	(LMF)CK TOP DECK COVER SEALS	TWRMEWBWAPAFI
				SALLAKCIT	(LMF)PIPE L WATER PUMP	TWRMEWBWAPAFI
				SALLAKCIT	(LMF)PRE-WASH	TWRMEWBWAPAFI
				SALLAKCIT	(LMF)PRESS CK CK RPL'S	TWRMEWBWAPAFI
				SALLAKCIT	(LMF)REPAIR TOP DECK LATCH'S	TWRMEWBWAPAFI
				SALLAKCIT	(LRB)START & CHECK	TWRMEWBWAPAFI
				SALLAKCIT	(PPA)#3 GEAR CASE DEF	TWRMEWBWAPAFI
				SALLAKCIT	HELD 07/27/89 DUE	TRACK 05 TWRMEWBWAPAFI
	08/09/89	08/12/89		SALLAKCIT	(***) SPECIAL 015-APPLY NEW CAB CARD ORGANIZER	MHEWBLT
				SALLAKCIT	(BEB)START & CHECK	MHEWBLT
				SALLAKCIT	(JEA)*SM* DUE MM	MHEWBLT
				SALLAKCIT	(JEA)CLEAN AIR BOX DRAINS PLUGGED	MHEWBLT
				SALLAKCIT	(JEA)WASH	MHEWBLT
				SALLAKCIT	(LMF)*ST* ENG REPORETS=NOT LOADING=BLACK SMOKE=OLD FLAT SPOTS	MHEWBLT
				SALLAKCIT	(LMF)*ST* HEAVY EXHAUST OUT AIR BOX COVERS	MHEWBLT
				SALLAKCIT	(LMF)*ST* HEAVY SMOKE	MHEWBLT
				SALLAKCIT	(LMF)BM TO APPLY DOORS & COVER	MHEWBLT
				SALLAKCIT	(LMF)C/O BAGGIES	MHEWBLT
				SALLAKCIT	(LMF)C/O L BLOWER NOT TURNING **BROKEN SHAFT**	MHEWBLT
				SALLAKCIT	(PIT)*ST* WORK BRAKES	MHEWBLT
				SALLAKCIT	HELD 08/09	TRACK 05 MHEWBLT
	08/21/89	09/07/89		SALLAKCIT	(BA)APPLY & ALIGN AUX GEN ***USE SAME AUX GEN***	GRXGELEWAGVLTU
				SALLAKCIT	(BA)APPLY BLOWERS *FIN*R-SIDE ON-APPLY LEFT SIDE	GRXGELEWAGVLTU
				SALLAKCIT	(BA)CHANGE BLOWER SHAFT FOR LEFT SIDE APPLICATION	GRXGELEWAGVLTU
				SALLAKCIT	(BA)REAM & DOWEL AUX GEN.	GRXGELEWAGVLTU
				SALLAKCIT	(BA)REAM & DOWEL MAIN GEN	GRXGELEWAGVLTU
				SALLAKCIT	(DTC)CHECK TMS	GRXGELEWAGVLTU
				SALLAKCIT	(DTC)CONNECT AUX GEN WHEN APPLIED.	GRXGELEWAGVLTU
				SALLAKCIT	(DTC)EC PANEL MISSING	GRXGELEWAGVLTU
				SALLAKCIT	(DWD)HOOK TO LOAD BOX	GRXGELEWAGVLTU
				SALLAKCIT	(DWD)LOAD & CHECK FOR GROUND RELAY	GRXGELEWAGVLTU
				SALLAKCIT	(DWD)MAIN GEN SHUNT FIELD HYPOT ZERO	GRXGELEWAGVLTU
				SALLAKCIT	(DWD)RAISE HIGH VOLTAGE TO GROUND READING IN MAIN GENERATOR	GRXGELEWAGVLTU
				SALLAKCIT	(DWD)UNHOOK MAIN GEN / AUX GEN	GRXGELEWAGVLTU
				SALLAKCIT	(JEA)APPLY GOV	GRXGELEWAGVLTU
				SALLAKCIT	(JEA)APPLY HORN & PIPE	GRXGELEWAGVLTU
				SALLAKCIT	(JEA)FIN COVER CARBODY	GRXGELEWAGVLTU
				SALLAKCIT	(JEA)GOV MISSING (STOLEN FOR UNIT 1234)	GRXGELEWAGVLTU
				SALLAKCIT	(JEA)SET RACKS	GRXGELEWAGVLTU
				SALLAKCIT	(JEA)WASH	GRXGELEWAGVLTU
				SALLAKCIT	(JEA)WELD JOINT ON HOOD	GRXGELEWAGVLTU
				SALLAKCIT	(JES)APPLY HOOD	GRXGELEWAGVLTU
				SALLAKCIT	(JRB)*GR* GROUND RELAY(MJL)	GRXGELEWAGVLTU
				SALLAKCIT	(JRB)LOAD NEW MAIN GENERATOR , SEAT BRUSHES.	GRXGELEWAGVLTU

000022

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
QWNT459.FOCUS.MAINTING

LOCOMOTIVE	PLACE	DATE	RELEASE DATE	LOCATION	DETAIL	WORK CODES
NUMBER	MO	DA	YR	MO	DA	YR
UP 001218	08/21/89	09/07/89		SALLAKCIT	(KGP)APPLY & ALIGN MAIN GEN	GRXGELEWAGULTLI
				SALLAKCIT	(KGP)C/D MAIN GEN (BREAKS DOWN WHEN LOADING)	GRXGELEWAGULTLI
				SALLAKCIT	(REJ)BATTERY FIELD CONTACTOR MISSING	GRXGELEWAGULTLI
				SALLAKCIT	(REJ)CONNECT MAIN GEN AND D14	GRXGELEWAGULTLI
				SALLAKCIT	HELD 08/21	TRACK 05 GRXGELEWAGULTLI
	09/18/89	09/18/89		SALLAKCIT	(BEB)*LM*WHITE LAB CK. FUEL LEAKS	TMLHFL
				SALLAKCIT	(GEC)*ST* FLATS ALL WHEELS.	TMLHFL
				SALLAKCIT	(JRM)BLACKLITE ENGINE	TMLHFL
				SALLAKCIT	(JRM)C/D #2 FUEL LINE(CRACKED	TMLHFL
				SALLAKCIT	HELD 09/18/89 PI DUE 9/22/89	TRACK 05 TMLHFL
	09/20/89	09/21/89		SALLAKCIT	(***)SPECIAL (15-**) APPLY NEW CAB CARD ORGANIZER	PIGHAS
				SALLAKCIT	(GMD)INSPECT (H-OK) (E-OK) (CC-OK) (B-OK)	PIGHAS
				SALLAKCIT	(GMD)WORK BRAKES	PIGHAS
				SALLAKCIT	(JRB)TEST & CARD CARDED 09/21/89	PIGHAS
				SALLAKCIT	(JRB)WASH / CLEAN CAB	PIGHAS
				SALLAKCIT	(RLV)*PI* DUE INSPECTION 09/22/89	PIGHAS
				SALLAKCIT	(RLV)WORK TH'S	PIGHAS
				SALLAKCIT	HELD 09/20 PI INSPECTION	TRACK 01 PIGHAS
	11/27/89	11/27/89		LDSANGELE	(LB) L-ROOTS BLOWER B/D; DIC TO SLC;SEALS LEAKING	EW -
	11/29/89	12/02/89		SALLAKCIT	(***)*SPCL*015*APPLY NEW CAB CARD ORGANIZER	EW
				SALLAKCIT	(***)*SPCL*053*ATCS WORKORDER MODIFICATIONS	EW
				SALLAKCIT	(EFF)APPLY CARBODY FILTERS	EW
				SALLAKCIT	(EFF)FILL WITH LUBE OIL****FIN***	EW
				SALLAKCIT	(EFF)WASH	EW
				SALLAKCIT	(GEC)*SPCL*002*UPDATE THE UM SCREEN THE LOCO MANGEMENT	EW
				SALLAKCIT	(GEC)*SPCL*014*REMOVE DEAD MAN PEDAL	EW
				SALLAKCIT	(GEC)*ST*CRANK CAS OVER FILLED	EW
				SALLAKCIT	(GEC)*ST*SMALL FLATS	EW
				SALLAKCIT	(GEC)*ST*TAGGED DEAD AND DRAINED	EW
				SALLAKCIT	(GEC)C/D & F	EW
				SALLAKCIT	(GEC)PRESS CK WATER LKS	EW
				SALLAKCIT	(JRB)ST & CK	EW
				SALLAKCIT	HELD 11/29 PI DUE	TRACK 05 EW
	12/02/89	12/13/89		SALLAKCIT	(LMF)*EW*EXHAUST STACKS PLUGGED (SMOKING)	EW
				SALLAKCIT	(LMF)C/D BAGGIES (PLUGGED)	EW
				SALLAKCIT	HELD 12/02 PI DUE	TRACK 03 EW
	12/19/89	12/20/89		SALLAKCIT	(***)SPECIAL (53-**) ATCS WORKORDER MODIFICATION	PIENWAICEM
				SALLAKCIT	(DWD)TEST & CARD CARDED 12/20/89	PIENWAICEM
				SALLAKCIT	(JEA)MECH TEST OUT	PIENWAICEM
				SALLAKCIT	(RLV)*PI* DUE INSPECTION 12/21/89	PIENWAICEM
				SALLAKCIT	(RLV)*ST* FREE UP REAR CAB DOOR(RAP)	PIENWAICEM
				SALLAKCIT	(RLV)*ST* REPORTED RADIO NOT TRANSMITTING PROPERLY(RAP)	PIENWAICEM
				SALLAKCIT	(RLV)INSP(H-OK) (E-OK) (CC-OK) (B-)	PIENWAICEM
				SALLAKCIT	(RLV)WASH / CLEAN CAB	PIENWAICEM
				SALLAKCIT	(RLV)WORK AIR	PIENWAICEM
				SALLAKCIT	(RLV)WORK BRAKES	PIENWAICEM

000023

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
OMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE MO DA YR	LOCATION	DETAIL	WORK CODES
UP 001218	12/19/89	12/20/89		SALLAKCIT	(RLV)WORK TH'S	PIENWAICEN
				SALLAKCIT	HELD 12/19	TRACK OS PIENWAICEN
	01/12/90	01/13/90		SALLAKCIT	ADVANCED TOO SOON. DIRECTIONAL CHANGE TIMING (M.J.L)	TW
				SALLAKCIT	(BA)*TW* FLAT WHEELS (M.J.L)	TW
				SALLAKCIT	(DWD)*ST* LOADING PROBLEMS (INTERMITTENT LOAD IF THROTTLE	TW
				SALLAKCIT	(DWD)REPAIR OVERHEATED HEADLIGHT RESISTOR WIRE LUGS	TW
				SALLAKCIT	(M.J.L)*ST*ENGINE OIL LOW (M.J.L)	TW
				SALLAKCIT	****PROPERLY	TW
				SALLAKCIT	***UNIT IS EQUIPED WITH DIRECTION DELAY MOD, AND IS WORKING	TW
				SALLAKCIT	HELD 0112/90 DUE	TRACK OS TW
	01/21/90	01/21/90		SALLAKCIT	(DWD)*ST*SURGES FROM 4TH TO 8TH RUN	EW
				SALLAKCIT	(DWD)INSPECT & CHECK LOADING CIRCUIT (CHECKS OK)	EW
				SALLAKCIT	HELD 01/21	TRACK OS EW
	02/12/90	02/13/90		SALLAKCIT	(***)*SPCL*015*APPLY NEW CAB ORGANIZER, CREW PACK HOLDER	HNHL
				SALLAKCIT	(***)*SPCL*053*ATCS WORKORDER MODIFICATION.	HNHL
				SALLAKCIT	(DWD)*ST*NOT LOADING	HNHL
				SALLAKCIT	(JRM)*ST*B/O HORN	HNHL
				SALLAKCIT	(JRM)C/O GOVERNOR (SHORTED)	HNHL
				SALLAKCIT	(JRM)SET RACKS	HNHL
				SALLAKCIT	(PDB)START & CHECK	HNHL
				SALLAKCIT	HELD 02/12	TRACK OS HNHL
	03/11/90	03/12/90		SALLAKCIT	INTERFERES WITH HANDLE	RNTWAB
				SALLAKCIT	(***)SPECIAL (15-**) APPLY NEW CAB CARD ORGANIZER	RNTWAB
				SALLAKCIT	(***)SPECIAL (53-**) ATCS WORKORDER MODIFICATION	RNTWAB
				SALLAKCIT	(EFF)*RM* 02/19/90 UZ029 FLAT WHEELS	RNTWAB
				SALLAKCIT	(EFF)*ST* FLAT SPOTS ALL WHEELS	RNTWAB
				SALLAKCIT	(EFF)*ST* L #2 BRAKE SHOE WORN INTO BRAKE LEAD	RNTWAB
				SALLAKCIT	(EFF)*ST* 2 1/2" #2 WHEELS	RNTWAB
				SALLAKCIT	(EFF)*TW* TRUE WHEELS	RNTWAB
				SALLAKCIT	(JRB)*RM* 02/27/90 UZ029 FRONT TRAINLINE VALVE BRACKET BENT-	RNTWAB
				SALLAKCIT	(JRB)*ST* ENGINE OIL LOW	RNTWAB
				SALLAKCIT	HELD 03/11/90 DUE P: 03/22/90	TRACK OS RNTWAB
	03/22/90	03/25/90		SALLAKCIT	(***)SFCL(015***) APPLY NEW CAB CARD ORGANIZER	PIQHRNTWAB
				SALLAKCIT	(***)SPCL(053***) ATCS WORKORDER MODIFICATION	PIQHRNTWAB
				SALLAKCIT	(BEB)IN-BOUND	PIQHRNTWAB
				SALLAKCIT	(GWD)APPLY CARBODY FILTERS	PIQHRNTWAB
				SALLAKCIT	(GWD)WASH / CLEAN CAB	PIQHRNTWAB
				SALLAKCIT	(JRM)TEST & CARD	PIQHRNTWAB
				SALLAKCIT	(KGP)*RM* 03/13/90 UZ029 3" FLATS	PIQHRNTWAB
				SALLAKCIT	(KGP)MECH TEST OUT	PIQHRNTWAB
				SALLAKCIT	(RLV)*PI* DUE INSPECTION 03/22/90	PIQHRNTWAB
				SALLAKCIT	(RLV)*RM* 03/13/90 UZ029 FRONT TRAINLINE BRACKET BENT	PIQHRNTWAB
				SALLAKCIT	(RLV)*RM* 03/13/90 UZ029 INTERFERS WITH HANDLE	PIQHRNTWAB
				SALLAKCIT	(RLV)INSPECT (M-OK) (E-OK) (CC-OK) (B-OK)	PIQHRNTWAB
				SALLAKCIT	(RLV)WORK BRAKES	PIQHRNTWAB
				SALLAKCIT	(RLV)WORK TH'S	PIQHRNTWAB

000024

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
OMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE DATE MO DA YR	LOCATION	DETAIL	WORK CODES
UP 001218	03/22/90	03/25/90		SALLAKCIT	HELD 03/22 PI INSPECTION	TRACK 01 PIGNHMTWAA
	04/07/90	04/08/90		SALLAKCIT	(BA)*ST*WORK BRAKES(LER)	TK
				SALLAKCIT	(DWD)*ST*#3 TH TOP COVER LOOSE(LER)	TK
				SALLAKCIT	(JRK)*ST*RIGHT #6 BRAKE HEAD B/D(LER)	TK
				SALLAKCIT	HELD 04/07/90 DUE	TRACK 05 TK
	06/23/90	07/03/90		LOSANGELE	(DH) REAR UPPER DOOR GLASS GONE. —HERE—TO APPLY	AICW
				LOSANGELE	(ES) MACH TO WORK & SIGN BLUE CARD.	AICW
				LOSANGELE	(HV) ATO TO WASH INSIDE & OUT.	AICW
				LOSANGELE	(JGM) ELECT TO WORK & SIGN BLUE CARD. COMPLETED, BLUE CARD SIGNED	AICW
	08/16/90	08/21/90		LOSANGELE	WASH COMPLETE AND CHECK FOR LEAKS	MMLUTWDEMA
				LOSANGELE	*** TO AMTRAK ON 6-16-90 *** BACK ON 8-20-90***	MMLUTWDEMA
				LOSANGELE	(AG) FRA REPORT—EXCESSIVE OIL IN ENG AND GENERATOR COMPARTMENTS	MMLUTWDEMA
				LOSANGELE	(DRK) #4 MHL HAS 2 1/2" FLATS, REST SMALL FLATS	MMLUTWDEMA
	09/16/90	09/17/90		LOSANGELE	(ES) TRAIN LINE COUPLING BROKE—RT/REAR	LUOT
	10/03/90	10/05/90		LOSANGELE	(AM) ELECT TO WORK & SIGN BLUE CARD	PIGNMA
				LOSANGELE	(ES) MACH TO WORK & SIGN BLUE CARD.	PIGNMA
				LOSANGELE	(JG) WASH COMPLETE INSIDE AND OUT	PIGNMA
	12/08/90	12/11/90		LOSANGELE	(RE) BOTTOM—UNIT HIT BOGGIE IN LA YARD REPAIRED, O/K.	LUAD—
				LOSANGELE	(RE) LEFT REAR STEP HANDRAILS TO REPAIR—BOTH ARE BROKE OFF AT	LUAD
	01/03/91	01/05/91		LOSANGELE	(B.H) PI/SM ELECT TO DO WORK HAS BEEN COMPLE. BL. CARD. SIGN.	PISM
				LOSANGELE	(ES) PI/SM MACH TO DO P.I. DONE.	PISM
				LOSANGELE	(MP) CHECK EXH MANIFOLD TRAPS	PISM
				LOSANGELE	AA) WASH COMPLETE	PISM
	02/04/91	02/04/91		LOSANGELE	(ALM) OVEREXCITATION. CHANGED POWER PANNEL. O/K.	LUEL
	04/08/91	04/11/91		LOSANGELE	(MP) MACH. PI TO WORK. PI FINISHED BUT SEE NOTE;	PIGNLU
				LOSANGELE	(ACG) ATO—WASH COMPLETE.	PIGNLU
				LOSANGELE	(ES) BACK DOOR HAS BROKEN HINGE NEEDS WELDING. SIGN BLUE CARD.	PIGNLU
				LOSANGELE	(ES) NOTE; AIR LEAKING EQ. 6 PSI. PER MIN. CANT FIND LEAK.	PIGNLU
				LOSANGELE	(JGM) ELECT. PI TO WORKED. CARD TO SIGN.	PIGNLU
	06/22/91	07/01/91		SALLAKCIT	(BK) CLEAN VEE & APPLY NEW STACKS	TI ABENMAEX
				SALLAKCIT	(BK) SCRAP OLD STACKS PER MPK	TI ABENMAEX
				SALLAKCIT	(GMD)*ST*WORK BRAKES (GGC)	TI ABENMAEX
				SALLAKCIT	(GMD) REMOVE OLD EXHAUST STACKS	TI ABENMAEX
				SALLAKCIT	(GMD) TAKE & ENTER WHEEL SIZES	TI ABENMAEX
				SALLAKCIT	(GMD) W/TMS	TI ABENMAEX
				SALLAKCIT	(GMD) WORK 3YR AIR	TI ABENMAEX
				SALLAKCIT	(JRA) INBOUND PROCESS	TI ABENMAEX
				SALLAKCIT	(JRA) RESTORE & STENCIL CAB	TI ABENMAEX
				SALLAKCIT	(JRM) APPLY CARBODY FILTERS AFTER WASH	TI ABENMAEX
				SALLAKCIT	(JRM) APPLY REFER	TI ABENMAEX
				SALLAKCIT	(JRM) PAINT GRAB IRONS WHITE (FRONT & REAR)	TI ABENMAEX
				SALLAKCIT	(JRM) SPCL (015-***) APPLY NEW CAB CARD ORGANIZER	TI ABENMAEX
				SALLAKCIT	(JRM) TEST & CARD CARD 06/28/91	TI ABENMAEX
				SALLAKCIT	(JRM) WASH/CLEAN CAB	TI ABENMAEX
				SALLAKCIT	(JRM) WORK MACH WHITE SHEETS (FINISH)	TI ABENMAEX
				SALLAKCIT	(KGN) PAINT CAB	TI ABENMAEX

000025

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
OMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE DATE MO DA YR	LOCATION	DETAIL	WORK CODES
UP 001218	06/22/91	07/01/91		SALLAKCIT	(OK) SPCL(050A-***). REMOVE WARNING LIGHT PER INSTRUCTION	TI ABEWMAEX
				SALLAKCIT	(OK-) SPCL(029A-***). APPLY TWO AUTO EQUIP ID TAGS	TI ABEWMAEX
				SALLAKCIT	(REJ) SPCL(053-***). ATCS WORKORDER MOD**TESTED AND NO MCP APPLIED**	TI ABEWMAEX
				SALLAKCIT	(RLV)*TI* DUE INSPECTION 06/21/91	TI ABEWMAEX
				SALLAKCIT	(RLV) WORK AI INSP //// TI AIR	TI ABEWMAEX
				SALLAKCIT	* ENG HAS STUDS FOR STACKS -- 1 3/4" LONG -- NEW STACK BASE IS	TI ABEWMAEX
				SALLAKCIT	*****	TI ABEWMAEX
				SALLAKCIT	DIFFERENT SET OF STACKS. *(BRASS NUTS USED ON STUDS)	TI ABEWMAEX
				SALLAKCIT	HELD 06/22 3YR AIR ONLY TRACK 01	TI ABEWMAEX
				SALLAKCIT	TO FIN APPLYING THE TOP HACH AND APPLY WATER	TI ABEWMAEX
				SALLAKCIT	2 1/4' THICK** MUST REMOVE ALL STUDS FROM ENG BLOCK OR GET	TI ABEWMAEX
	08/04/91	08/07/91		SALLAKCIT	(EFF) APPLY NEW STYLE EXHAUST MANIFOLDS (ON TRACK SIX)	MILU
				SALLAKCIT	(EFF) REMOVE OLD EXHAUST	MILU
				SALLAKCIT	(EFF) REMOVE STUDS AND REPLACE WITH STACK BASE BOLTS (1 STUD LEFT)	MILU
				SALLAKCIT	(JRM) BLNKR TO COVER	MILU
				SALLAKCIT	(JRM) WASH - CLEAN CAB	MILU
				SALLAKCIT	HELD 8/04 TRACK 05	MILU
	08/13/91	08/17/91		LOSANGELE	(AG) ATO TO WASH INSIDE & OUT.	PA -
				LOSANGELE	(ES) MACH TO C/O #4 ASSEMBLY ACCT B/O PISTON. OK.	PA -
	09/28/91	10/03/91		LOSANGELE	(AM) FINISHED BLUE CARD TO SIGN. O/K.	PIGMBHLU
				LOSANGELE	(ES) MACH. PI FINISHED. SIGN CARD. O/K.	PIGMBHLU
				LOSANGELE	(JC) MACH. TO FINISH. PI	PIGMBHLU
				LOSANGELE	(MH) ELECT. TO FINISH. PI	PIGMBHLU
				LOSANGELE	(JC) ATO TO WASH COMPLETE.	PIGMBHLU
	01/04/92	01/08/92		LOSANGELE	(***) # 12 ASSY WATER LEAK INSIDE.	PISH LU
				LOSANGELE	(***) # 12 ASSY WATER LEAK INSIDE.	PISH LU
				LOSANGELE	(***) OBT BRACKET IS REPORTED LOOSE	PISH LU
				LOSANGELE	(***) R-ROOTS BLOWER BASE GASKET LEAKING.	PISH LU
				LOSANGELE	(***) R-WATER PUMP LEAKING.	PISH LU
				LOSANGELE	(***) WASH UNIT COMPLETE--INSIDE AND OUT	PISH LU
				LOSANGELE	(AM) PI/SM ELECT TO DO ALL DONE, RUNNING CHECKES TO GET.	PISH LU
				LOSANGELE	(ES) DUE PI/SM MACH TO DO ALL DONE, RUNNING CHECKES TO GET.	PISH LU
	01/10/92	01/25/92		SALLAKCIT	(BEB) START & CHECK	USPAENWLSBEB
				SALLAKCIT	(DLL) MACH TESTOUT	USPAENWLSBEB
				SALLAKCIT	(DWD)*RM* 01/09/92 UZ029 MCP PROBLEMS REPORTED OSS-2971	USPAENWLSBEB
				SALLAKCIT	(DWD) C/O MCP (DEFECTIVE)	USPAENWLSBEB
				SALLAKCIT	(DWD) ELECT INBOUND REPORTS	USPAENWLSBEB
				SALLAKCIT	(GFJ) INBOUND PROCESS	USPAENWLSBEB
				SALLAKCIT	(LMF) #1 STACK CRACKED**APPLY**	USPAENWLSBEB
				SALLAKCIT	(LMF)*RM* 01/09/92 UZ029 OBT BRACKETS LOOSE C/O	USPAENWLSBEB
				SALLAKCIT	(LMF) APPLY CARBODY HATCH & DOOR'S	USPAENWLSBEB
				SALLAKCIT	(LMF) APPLY STACK COVER	USPAENWLSBEB
				SALLAKCIT	(LMF) C/O LEFT REAR CAM, #11 LOBE PITTED. **FIN APPLY**	USPAENWLSBEB
				SALLAKCIT	(LMF) C/O #12 ASSEMBLY WLS(PPA)	USPAENWLSBEB
				SALLAKCIT	(LMF) MACH INBOUND REPORTS	USPAENWLSBEB
				SALLAKCIT	(LMF) PRESSURE CHECK - CK RPLS **AFTER ASSY C/O*	USPAENWLSBEB

000026

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
OMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE DATE MO DA YR	LOCATION	DETAIL	WORK CODES
UP 001218	01/10/92	01/25/92		SALLAKCIT	(LMF)R. BLOWER LEAKS OIL AT ENG FLANGE GSKT. C/O BLOWER**OUT**	USPAEWMLSOEB
				SALLAKCIT	(LMF)WASH	USPAEWMLSOEB
				SALLAKCIT	HELD 01/10/92 DUE	TRACK OS USPAEWMLSOEB
	02/16/92	02/20/92		LOSANGELE	(AR) R-2 COIL SPRING POCKET ,BROKEN SAFETY PIN HANGER.	USTK
	04/08/92	04/10/92		LOSANGELE	(AM) ELECT.PI	PNPILUQHRYWA
				LOSANGELE	(CW) WASH COMPLETE.	PNPILUQHRYWA
				LOSANGELE	(ES) MACH. PI P.I.DONE.	PNPILUQHRYWA
				LOSANGELE	(ES) CHANGED OUT DIST.VALVE	PNPILUQHRYWA
	05/20/92	05/21/92		LOSANGELE	(MH) B/O FRONT LIGHT SLIDE SWITCH PART #8330135 O.K.	USRM
	05/21/92	05/21/92		LOSSERTRA	(MH)ELECT TP REPAIR B/O HEADLIGHT SLIDE SW.	TPRMH
	06/29/92	07/01/92		LOSANGELE	(ES) BRACKET WELDED. OK.	PHAIRMLUNAAM
				LOSANGELE	(MH) ELECT. AI TO SIGN BLUECARD.	PHAIRMLUNAAM
				LOSANGELE	(BK,FC) BOTTOM DONE, FILTERS DONE, TOP TO FINISH.	PHAIRMLUNAAM
				LOSANGELE	(BK,FC) MACH. AI, COMPLETED MINI. REQUIRMENTS.	PHAIRMLUNAAM
				LOSANGELE	(ES) HAND BRK. CHAINBRACKET UNDER FLOOR BOARD TO WELD.	PHAIRMLUNAAM
				LOSANGELE	(SM,PT) WASH COMPLETE. WASHED OK.	PHAIRMLUNAAM
	08/02/92	08/02/92		LOSANGELE	(CCS) REPORT FUEL LEAK. C/O SITE GLASS & BRACKET. O/K.	USFLWA
	09/28/92	10/06/92		LOSANGELE	(MH) ELECT. INSPECTION REPORTS COMPLETED. TO SIGN BLUECARD. O/K.	PNPIQLUNA
				LOSANGELE	(ACG) UNIT TO WASH INSIDE AND OUTSIDE. O/K.	PNPIQLUNA
				LOSANGELE	(ES) MACH. TO WORK INSP. AND SIGN CARD. O/K.	PNPIQLUNA
	11/10/92	11/11/92		LOSANGELE	(ES) MACH TO REPLACE B/O WINDOW ON ENGR. SIDE. O/K.	USCN

000027

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
OMNT459.FOCUS.MAINTING

LOCOMOTIVE PLACE DATE RELEASE DATE

NUMBER	MO	DA	YR	MO	DA	YR	LOCATION	DETAIL	WORK CODES
UP 001300	02/11/88	02/28/88	SALLAKCIT	(	)	HTO			TIRMWAENELFIFPAI
			SALLAKCIT	(BEB)	C/O	#2TH ACCT GROUNDED FIELD			TIRMWAENELFIFPAI
			SALLAKCIT	(CEP)*RM*	02-08-88	HNK DIC EAST DUE TI			TIRMWAENELFIFPAI
			SALLAKCIT	(CEP)L#2	J BOX SPRING BROKEN				TIRMWAENELFIFPAI
			SALLAKCIT	(CEP)	PRE-MACH TEST OUT				TIRMWAENELFIFPAI
			SALLAKCIT	(CEP)	PROJECTS (05-OK) (99-OK)				TIRMWAENELFIFPAI
			SALLAKCIT	(CEP)	WELD R #2 SANDER BRACKET				TIRMWAENELFIFPAI
			SALLAKCIT	(DTC)	WIRE THERMONICS				TIRMWAENELFIFPAI
			SALLAKCIT	(GEC)	APPLY BAGGIE FILTER HOUSING MOD				TIRMWAENELFIFPAI
			SALLAKCIT	(GEC)	BLMKR TO APPLY GUARDS				TIRMWAENELFIFPAI
			SALLAKCIT	(GEC)	C/O FUEL PUMP ASSY				TIRMWAENELFIFPAI
			SALLAKCIT	(GEC)	C/O THREE YEAR AIR				TIRMWAENELFIFPAI
			SALLAKCIT	(GEC)	CLAMP CONDUIT FOR THERMONICS(WIRE TYES HOLDING CONDUIT)				TIRMWAENELFIFPAI
			SALLAKCIT	(GEC)	HTO				TIRMWAENELFIFPAI
			SALLAKCIT	(GEC)	RE-ALIGN AIR COMPRESSOR (BOLT BROKE & SHIMS OUT)				TIRMWAENELFIFPAI
			SALLAKCIT	(GEC)	RE-ALIGN R2 BRAKE HEAD				TIRMWAENELFIFPAI
			SALLAKCIT	(GEC)	RENEW CAB FLOOR (FIN)				TIRMWAENELFIFPAI
			SALLAKCIT	(GEC)	RENEW REAR CAB DOOR THESHOLD				TIRMWAENELFIFPAI
			SALLAKCIT	(JFC)	PRE-LOAD (M-) (E-OK)				TIRMWAENELFIFPAI
			SALLAKCIT	(REJ)	RUN CONDUIT FOR THERMONICS				TIRMWAENELFIFPAI
			SALLAKCIT	(REJ)	TEST & CARD		CARD	02/27/88	TIRMWAENELFIFPAI
			SALLAKCIT	(REJ)	WORK TH'S WHEELS OK				TIRMWAENELFIFPAI
			SALLAKCIT	(RLV)	APPLY DOORS OVER ENG AIR FILTERS				TIRMWAENELFIFPAI
			SALLAKCIT	(RLV)	BLACKLIGHT ENGINE				TIRMWAENELFIFPAI
			SALLAKCIT	(RLV)	C/O ALL INJ'S				TIRMWAENELFIFPAI
			SALLAKCIT	(RLV)	FIN INSPECTORS REPORTS ELECT OK				TIRMWAENELFIFPAI
			SALLAKCIT	(RLV)	FIN TRI ANNUAL REPORTS ELECT OK				TIRMWAENELFIFPAI
			SALLAKCIT	(RLV)	INSP(M-OK) (E-OK) (CC-OK) (BK-OK)				TIRMWAENELFIFPAI
			SALLAKCIT	(RLV)	PURGE & FILL WITH OIL				TIRMWAENELFIFPAI
			SALLAKCIT	(RLV)	REPIPE SLIDE SELECTOR VALVE				TIRMWAENELFIFPAI
			SALLAKCIT	(RLV)	WORK BOTTON'S				TIRMWAENELFIFPAI
			SALLAKCIT	HELD	02/11/88	3YR INSPECTION			TRACK 06 TIRMWAENELFIFPAI
04/16/88	04/16/88	ALBINA	(DEB)	BRAKE SHOES CHANGED AND ADJUSTED					TKICMI
		ALBINA	(DEB)	CAB SERVICED					TKICMI
		ALBINA	(DEB)	CHANGED BURNT IN BRAKE HEAD					TKICMI
		ALBINA	(DEB)	FLUID LEVELS CHECKED					TKICMI
		ALBINA	(DEB)	FUELED AND SANDED UNIT					TKICMI
		ALBINA	(DEB)	INSPECTED					TKICMI
02/27/89	03/13/89	ALBINA	(JLB)	APPLY MU JUMPER CABLE CAN					AIICWA
		ALBINA	(JLB)	CHECK BELL REPORTED STALLS OUT.					AIICWA
		ALBINA	(JLB)	MECH. INSP. TEST & CARD.					AIICWA
		ALBINA	(JSN)	WASH ENG. & CARBODY.					AIICWA
		ALBINA	(LRS)	ELECT. INSP. TEST & CARD.					AIICWA
		ALBINA	(LRSI)	FRONT SANDERS INOPERATIVE					AIICWA
		ALBINA	(NJZ)	*AI* INSP. DUE 03-01-89					AIICWA
		ALBINA	(NJZ)	SIDE WINDOWS DIFFICULT TO OPEN & CLOSE.					AIICWA

000026

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
DMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE DATE MO DA YR	LOCATION	DETAIL	WORK CODES
UP 001300	03/28/89	04/04/89		ALBINA	(CAC) #2 WHEEL TO C/O ACCT. FLAT.	RHNC
				ALBINA	(DER) #3 WHEEL TO C/O ACCT. FLAT.	RHNC
				ALBINA	(JLB) #1 WHEEL TO C/O ACCT. THIN & ROLLED.	RHNC
				ALBINA	(LJW) #4 WHEEL TO C/O ACCT. FLAT.	RHNC
				ALBINA	(MJZ) *RM* REFER. B/O.	RHNC
	04/11/89	04/11/89		ALBINA	(CAC) ENL. GOV. TO CHG. ACCT. PILOT VALVE BO	GV
	06/02/89	06/07/89		ALBINA	(JLB) APPLY FORM HOLDER IN CAB	PIGRHNC
				ALBINA	(JLB) APPLY 20LB FIRE EX. & BRACKET IN CAB	PIGRHNC
				ALBINA	(JSN) TEST & CARD MACH.	PIGRHNC
				ALBINA	(JSN) WASH UNIT COMPLETE	PIGRHNC
				ALBINA	(LJW) INSP. UNIT FOR FRA DEFECTS	PIGRHNC
				ALBINA	(LRS) TEST & CARD ELECT.	PIGRHNC
	08/11/89	08/13/89		HINKLE	() TAGGED AT ARGO "WON'T GO FORWARD"	CDNLU
				HINKLE	(UH) RVF CONTACTOR TO INSTALL.	CDNLU
				HINKLE	(WAM) WELDED LEFT ELECTRICAL COMPARTMENT DOOR HINGES ON DOOR.	CDNLU
	08/27/89	08/27/89		ALBINA	(DGR) OIL SAMPLE TAKEN	TP
	09/01/89	09/15/89		ALBINA	(JLM) CLEAN EX. MANIFOLDS	PIENLUXSNNW
				ALBINA	(JLM) TEST & CARD-MACH	PIENLUXSNNW
				ALBINA	(JLM)(CAC) REMOVE, CLEAN & REPLACE EX. MANIFOLD'S	PIENLUXSNNW
				ALBINA	(LJW) INSP. UNIT FOR FRA DEFECTS	PIENLUXSNNW
				ALBINA	(LKR) WASH UNIT COMPLETE	PIENLUXSNNW
				ALBINA	(LRS) REPLACE RADIO	PIENLUXSNNW
				ALBINA	(LRS) REPLACE STROBE LIGHT	PIENLUXSNNW
				ALBINA	(LRS) TEST & CARD-ELECT.	PIENLUXSNNW
				ALBINA	(LRS) TEST & REPAIR SANDER'S WHERE NECESSARY	PIENLUXSNNW
	10/23/89	10/23/89		ALBINA	(KME) FRONT HEADLIGHT B/O (CHANGED OUT SWITCH).	LVRH
	10/29/89	10/30/89		ALBINA	(DR)PERFORM LU, GET OIL SAMPLE	TP
				ALBINA	(DR)PERFORM HM	TP
				ALBINA	(DR)REMOVE DEADMAN PEDAL	TP
				ALBINA	(DR)REPAIR JUMP SEAT	TP
	11/10/89	11/11/89		ALBINA	(DGR) DAILY INSPECTION	TPRM
				ALBINA	(DGR) REPAIRED OUTSTANDING DEFECTS	TPRM
	12/15/89	12/21/89		ALBINA	()	PIGLUPJSNMTKIC
				ALBINA	(D-R) MACH. TEST & CARD	PIGLUPJSNMTKIC
				ALBINA	(D-R) REMOVE DEAD MAN PEDAL	PIGLUPJSNMTKIC
				ALBINA	(D-R) WASH UNIT COMPLETE	PIGLUPJSNMTKIC
				ALBINA	(KAR) ELECT. TEST & CARD	PIGLUPJSNMTKIC
				ALBINA	(LJW) INSP. UNIT FOR FRA DEFECTS	PIGLUPJSNMTKIC
				ALBINA	(LRS) COMPLETE ATCS MOD 12-19-89	PIGLUPJSNMTKIC
	01/31/90	02/01/90		ALBINA	(CC)CHANGED THIN BRAKE SHOES	HNLU
				ALBINA	(CC)COMPLETED LU	HNLU
				ALBINA	(CC)COMPLETED HM	HNLU
	02/10/90	02/11/90		ALBINA	(DGR) REPLACED WORN BRAKE SHOES AND ADJUSTED PISTON TRAVEL	TP
				ALBINA	(JLM) REPAIRED REAR SANDERS	TP
	03/08/90	03/12/90		ALBINA	(CMH) ELECT. TEST & CARD	AISNMTKREABLU
				ALBINA	(DGR) ADDED GOV. OIL 1/2 PINT	AISNMTKREABLU

000029

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
OMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE DATE MO DA YR	LOCATION	DETAIL	WORK CODES
UP 001300	03/08/90	03/12/90		ALBINA	(DGR) CLEAN & TEST SANDERS	AI5NMTKREABLU
				ALBINA	(DGR) CLEANED SAND TRAPS AND TESTED	AI5NMTKREABLU
				ALBINA	(DGR) FABRICATED AND APPLIED ENGINE FOOTREST	AI5NMTKREABLU
				ALBINA	(DGR) OPENED AIR COMPRESSOR FLOOR DRAIN AND ENGINE DRAIN	AI5NMTKREABLU
				ALBINA	(J-B) CHANGED ALL FUEL, AIR AND OIL FILTERS	AI5NMTKREABLU
				ALBINA	(J-B) CLEAN UNIT COMPLETE	AI5NMTKREABLU
				ALBINA	(J-B) GREASED COUPLER SHANK WEAR PLATE	AI5NMTKREABLU
				ALBINA	(J-B) GREASED FAN BEARINGS	AI5NMTKREABLU
				ALBINA	(J-B) INSPECTED HANDBRAKE	AI5NMTKREABLU
				ALBINA	(JJM) ADDED ENGINE OIL 6 INCHES	AI5NMTKREABLU
				ALBINA	(JJM) APPLIED BRAKE SHOES ADJUSTED BRAKE PISTON TRAVEL	AI5NMTKREABLU
				ALBINA	(JJM) BLACK LIGHT INSPECTED FOR FUEL LEAKS	AI5NMTKREABLU
				ALBINA	(KAR) REPLACED MAIN GENERATOR BRUSHES	AI5NMTKREABLU
				ALBINA	(LDS) APPLIED HEAD BUMP PROTECTION	AI5NMTKREABLU
				ALBINA	(LDS) APPLIED MOBIL COMMUNICATION PACKAGES	AI5NMTKREABLU
				ALBINA	(LDS) APPLY AJAX WATER COOLER	AI5NMTKREABLU
				ALBINA	(LDS) REPLACED FUEL PUMP BRUSHES	AI5NMTKREABLU
				ALBINA	(LJM) CHANGED AUTOMATIC BRAKE VALVE	AI5NMTKREABLU
				ALBINA	(LJM) INSP. UNIT FOR FRA DEFECTS	AI5NMTKREABLU
				ALBINA	(LJM) MACH. TEST & CARD	AI5NMTKREABLU
	03/28/90	03/29/90		ALBINA	(CHM) REPAIR LOOSE GROUND WIRE ON #4 TH	TPRM
				ALBINA	(JJM) CHANGE OUT EIGHTEEN BRAKE SHOES	TPRM
				ALBINA	(JJM) REPLACE MISSING MAIN RES. HOSE FRONT LEFT	TPRM
	04/06/90	04/07/90		ALBINA	(CHM) CHECKED ALL LIGHTS AND CAB HEATER	TPRM
				ALBINA	(CHM) LOAD TESTED	TPRM
				ALBINA	(CHM) REPAIRED GAUGE LIGHTS	TPRM
				ALBINA	(CHM) REPLACED GROUND LIGHTS	TPRM
				ALBINA	(JJM) CHANGED OUT EIGHT BRAKE SHOES	TPRM
				ALBINA	(JJM) REPAIRED OIL LEAK AT LOAD REGULATOR	TPRM
	04/21/90	04/23/90		ALBINA	(DGR) ADDED 6 INCHES OF ENGINE OIL	RMMMLU
				ALBINA	(DGR) CHANGED BAGGIE AIR INTAKE FILTERS	RMMMLU
				ALBINA	(DGR) CHANGED CAR BODY AIR FILTERS	RMMMLU
				ALBINA	(DGR-JJM) CHANGED WORN BRAKE SHOES AND ADJUSTED PISTON TRAVEL	RMMMLU
				ALBINA	(JJM) ADDED GEAR GREASE TO ALL TH GEAR CASES	RMMMLU
				ALBINA	(JJM) TIGHTENED PIPE BETWEEN OIL FILTER HOUSING AND PUMP	RMMMLU
	04/28/90	04/28/90		ALBINA	(CHM) CHANGED OUT TEST FUSE LIGHT	TPRM
				ALBINA	(CHM) CHECK AND REPAIR ENGINE SPEEDS	TPRM
				ALBINA	(CHM) REPAIR REPORTED HEAD LIGHT PROBLEMS	TPRM
				ALBINA	(JJM) ADD ENGINE LUBE OIL 40 GALS.	TPRM
				ALBINA	(JLB) ADJUST AND CHANGE OUT BRAKE SHOES	TPRM
				ALBINA	(JLB) REWELD TWO SANDING PIPES	TPRM
	05/03/90	05/03/90		ALBINA	(LRS) CVC RELAY REPAIRED-NUT FELL OFF OF CONTACT BLOCK BOTTOM	TPRM
				ALBINA	OF RELAY, NULLIFYING RUNS 7 & 8	TPRM
	05/08/90	05/08/90		ALBINA	(LRS) LOW VOLT GR. IN REAR TRAIN LINE RECEPTCLE—CAUSING THROTTLE	TPLV
				ALBINA	PROBLEMS - REPAIRED	TPLV
	05/30/90	05/31/90		ALBINA	(JJM) CHANGE WORN BRK SHOES AND ADJUST TRAVEL	TPRM

C00030

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
OMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE MO DA YR	LOCATION	DETAIL	WORK CODES
UP 001300	05/30/90	05/31/90		ALBINA	(JJM) CHECK FLUID LEVELS	TPRM
				ALBINA	(JJM) TEST HORN BELL AND WIPER MOTORS	TPRM
				ALBINA	(JJM) TEST SANDERS	TPRM
				ALBINA	(WRR) CLEAN AND SUPPLY CAB	TPRM
				ALBINA	(YKK) CHECK LIGHTS HEATERS RADIO AND REFER	TPRM
	06/09/90	06/13/90		ALBINA	(D-R) **PROJ*** 053A PROJECT TO DO	PIQMRMLUPJSNMMTK
				ALBINA	(D-R) MACH. TEST & CARD	PIQMRMLUPJSNMMTK
				ALBINA	(D_R) TEST & CLEAN SANDERS	PIQMRMLUPJSNMMTK
				ALBINA	(KAR) ELECT. TEST & CARD	PIQMRMLUPJSNMMTK
				ALBINA	(LAW) WASH UNIT COMPLETE	PIQMRMLUPJSNMMTK
				ALBINA	(LJM) INSP. UNIT FOR FRA DEFECTS	PIQMRMLUPJSNMMTK
	06/18/90	06/18/90		ALBINA	(CMH) COMPLETED DAILY AND RUNNING CHECKS	TPCR
				ALBINA	(CMH) REPLACED C VALVE THROTTLE MICRO SWITCH	TPCR
				ALBINA	(CMH) THROTTLE STICKS COMING DOWN(MJZ)	TPCR
	06/23/90	06/23/90		ALBINA	(CMH) CHANGED 4 GAUGE LIGHTS	TP
				ALBINA	(CMH) CHECK ENG SPEEDS	TP
				ALBINA	(CMH) CHECK LIGHTS RADIO HEATERS REFER	TP
				ALBINA	(CMH) TEST LOAD AND DIRECTION	TP -
				ALBINA	(JLB) CHANGED WORN BRK SHOES AND ADJUST TRAVEL	TP -
				ALBINA	(JLB) CHECK FLUID LEVELS	TP
				ALBINA	(JLB) CLEAN AND SUPPLY CAB	TP
				ALBINA	(JLB) TEST BELL AND HORN	TP
				ALBINA	(JLM) (CMH) TEST SANDERS	TP
	06/27/90	06/27/90		ALBINA	(JJM) ADDED 5" ENGINE LUBE OIL	TP
				ALBINA	(JJM) CHANGED OUT 7 BRAKE SHOES	TP
				ALBINA	(JJM) CLEANED AND SUPPLIED CAB	TP
				ALBINA	(JJM) REPAIRED WATER LEAK AT WATER PUMP	TP
	07/07/90	07/07/90		ALBINA	(CMH) CHECKED ALL LIGHTS, FRIDG, AND RADIO.	LU
				ALBINA	(CMH) CLEANED AND SUPPLIED CAB	LU
				ALBINA	(CMH) REPAIRED SANDER RELAY	LU
				ALBINA	(JJM) CHANGED OUT 09 BRAKE SHOES	LU
				ALBINA	(JJM) REPAIRED LOAD REG. OIL LEAK	LU
	07/12/90	07/12/90		ALBINA	(CMH) CHECKED ALL LIGHTS, REFER. RADIO, HEATERS ECT.	TP
				ALBINA	(CMH) CHECKED ENGINE SPEEDS AND LOAD TEST.	TP
				ALBINA	(CMH) REPAIR HEADLIGHT RES. LIGHTWIRE	TP
				ALBINA	(CMH) REPLACE THROTTLE LIGHT	TP
				ALBINA	(JJM) ADD 8" OF ENGINE COOLING WATER	TP
				ALBINA	(JJM) ADD 8" OF ENGINE LUBE OIL	TP
				ALBINA	(JJM) CHANGE OUT 12 BRAKE SHOES	TP
				ALBINA	(JJM) REPAIR REAR MAIN RES. HOSE	TP
				ALBINA	(WRR) CLEANED AND SUPPLIED CAB	TP
				ALBINA	(WRR) CLEANED WINDOWS	TP
	07/19/90	07/19/90		ALBINA	(CMH) CHANGE THREE GAUGE LIGHTS	TP
				ALBINA	(CMH) CHECKED ALL LIGHTS RADIO HEATERS AND FRIDGE	TP
				ALBINA	(CMH) LOAD TESTED AND CHECKED ENGINE SPEEDS	TP
				ALBINA	(JJM) CHANGE OUT AND ADJUST WORN BRAKE SHOES	TP

000031

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
OMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE DATE MO DA YR	LOCATION	DETAIL	WORK CODES
UP 001300	07/19/90	07/19/90		ALBINA	(JJM) CHECK ALL ENGINE FLUID LEVELS	TP
				ALBINA	(JJM) REPAIR FIREMANS REAR WIPER	TP
				ALBINA	(JJM) REPAIR TRAINLINE HOSE REAR	TP
	08/16/90	08/16/90		ALBINA	(KKG) OIL SAMPLE TAKEN	TPTKWA
				ALBINA	(KKG) MAHSED CARBODY & TRUCKS COMPLETE	TPTKWA
				ALBINA	(LJW) LUBRICATED SWIVEL SEAT POSTS & TRACK-ENGR'S & FIREMAN'S	TPTKWA
				ALBINA	(LJW) REPLACED BRAKE SHOES WHERE NECESSARY & ADJUSTED	TPTKWA
	08/25/90	08/27/90		NPLATTE	(EDD) *RM* B/O COMPRESSOR INTERCOOLER	RMEW
				NPLATTE	(EDD) H/P DISCHARGE VALVE NEW	RMEW
				NPLATTE	(RJR) *RM* B/O COMPRESSOR CONTROL SWITCH	RMEW
				NPLATTE	(RJR) *RM* DIC	RMEW
	09/04/90	09/04/90		ALBINA	(LJW) REPAIRED LEFT FRONT ACTUATING LINE-HOLE WORN IN SAME	TPAB
	09/10/90	09/20/90		ALBINA	CLEARANCE.	PISMSNTKWAICLU
				ALBINA	(DBR)(JLB)(KAR) DROP #1 & #2 TRUCKS & ADJUST SIDE BEARING	PISMSNTKWAICLU
				ALBINA	(JLB) TEST UNIT & CARD-MACH.	PISMSNTKWAICLU
				ALBINA	(KAR) TEST UNIT & CARD-ELECT.	PISMSNTKWAICLU
				ALBINA	(LJW) INSP. UNIT FOR FRA DEFECTS	PISMSNTKWAICLU
	09/29/90	09/30/90		ALBINA	(YKK) FRONT HEADLIGHTS BAD ORDER.	TP
				ALBINA	(YKK) SOME OTHER LIGHT'S BURNT OUT.	TP
	10/13/90	10/13/90		ALBINA	(CHM) (JJM) TEST SANDERS	LU
				ALBINA	(CHM) CHECK LIGHTS RADIO HEATERS AND REFER	LU
				ALBINA	(CHM) CHECK LOAD AND DIRECTION	LU
				ALBINA	(CHM) REPAIR FRONT RIGHT # LIGHT	LU
				ALBINA	(JJM) CHANGE WORN BRAKE SHOES AND ADJUST TRAVEL	LU
				ALBINA	(JJM) CHECK FLUID LEVELS	LU
				ALBINA	(JJM) DO LU (TAKE LUBE OIL SAMPLE)	LU
				ALBINA	(KMG) CLEAN AND SUPPLY CAB	LU
				ALBINA	(KMG) FUEL AND SAND UNIT	LU
	10/18/90	10/19/90		ALBINA	(JJM) CHANGED OUT 16 BRAKE SHOES	TP
				ALBINA	(JJM) CHECKED FLUID LEVELS	TP
				ALBINA	(LKR) CLEANED AND SUPPLIED CAB	TP
	10/23/90	10/31/90		ALBINA	(DGR) CHANGED OUT A/C INTERCOOLER	RMACLU
				ALBINA	(DGR) CHANGED OUT 8 BRAKE SHOES	RMACLU
				ALBINA	(DGR) CHECKED FLUID LEVELS	RMACLU
				ALBINA	(DGR) CLEANED AND SUPPLIED CAB	RMACLU
				ALBINA	(KAR) PERFORMED ELECTRICAL CHECKS	RMACLU
	11/20/90	11/21/90		ALBINA	(CHM) CHECK ENGINE SPEEDS LOAD AND DIRECTION	TP
				ALBINA	(CHM) CHECK LIGHTS RADIO HEATERS AND REFER	TP
				ALBINA	(CHM) REPAIR RIGHT GROUND LIGHT	TP
				ALBINA	(CHM) REPAIR SAND LIGHT	TP
				ALBINA	(DEB) CHANGE WORN BRAKE SHOES AND ADJSUT TRAVEL	TP
				ALBINA	(DEB) CHECK HORN BELL AND WIPERS	TP
				ALBINA	(KMG) CHECK FLUID LEVELS	TP
				ALBINA	(KMG) CLEAN AND SUPPLY CAB	TP
	12/01/90	12/02/90		ALBINA	(CCM) CHECKED FRIDGE, LIGHTS HEATERSAND ALL ELECTRICAL	TP
				ALBINA	(CCM) ENGINE SPEEDS AND DIRECTIONAL TEST	TP

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
OMNT459.FOCUS.MAINTING

LOCOMOTIVE	PLACE	DATE	RELEASE	DATE			
NUMBER	MO	DA	YR	MO	DA	YR	WORK CODES
UP 001300	12/01/90	12/02/90	ALBINA	(CCM)	REPLACED FRONT NUMBER LIGHT		TP
			ALBINA	(CCM)	REPLACED TWO GAUGE LIGHTS		TP
			ALBINA	(CMH)	REPAIR FRONT HEADLIGHT CIRCUIT		TP
			ALBINA	(DGR)	CHANGED 14 BRAKE SHOES		TP
			ALBINA	(DGR)	CHECKED ALL FLUID LEVELS		TP
			ALBINA	(DGR)	INSTALLED CREW PAK HOLDER		TP
			ALBINA	(DGR)	REPAIRED SANDERS		TP
			ALBINA	(KMG)	CLEAN CAB, WINDOWS AND SUPPLIED CAB		TP
	12/10/90	12/11/90	ALBINA	(DGR)	CHANGED AIR COMPRESSOR AIR FILTER		PIQMSNWKIKICWC
			ALBINA	(DGR)	CHANGED BAGGIE TYPE AIR FILTERS		PIQMSNWKIKICWC
			ALBINA	(DGR)	CHANGED CAR BODY TYPE AIR FILTERS		PIQMSNWKIKICWC
			ALBINA	(DGR)	CHANGED FUEL FILTERS SPIN ON TYPE		PIQMSNWKIKICWC
			ALBINA	(DGR)	CHANGED OIL FILTERS		PIQMSNWKIKICWC
			ALBINA	(DGR)	CHANGED WORN BRAKE SHOES AND ADJUSTED PISTON TRAVEL		PIQMSNWKIKICWC
			ALBINA	(DGR)	CHECKED FAN BELTS		PIQMSNWKIKICWC
			ALBINA	(DGR)	CHECKED PILOT HEIGHT CLEARANCES		PIQMSNWKIKICWC
			ALBINA	(DGR)	CHECKED SIDE BEARINGS CLEARANCE		PIQMSNWKIKICWC
			ALBINA	(DGR)	CHECKED WHEELS FOR HIGH FLANGES AND TREAD WEAR		PIQMSNWKIKICWC
			ALBINA	(DGR)	GREASED COUPLER WEAR PLATES		PIQMSNWKIKICWC
			ALBINA	(DGR)	INSPECTED SAND TRAPS AND PIPING		PIQMSNWKIKICWC
			ALBINA	(DGR)	LUBRICATED DOOR LATCHES		PIQMSNWKIKICWC
			ALBINA	(DGR)	LUBRICATED FAN BEARINGS		PIQMSNWKIKICWC
			ALBINA	(DGR)	LUBRICATED TRI POD SEATS		PIQMSNWKIKICWC
			ALBINA	(DGR)	OILED CENTER CASTING ON BOTH TRUCKS		PIQMSNWKIKICWC
			ALBINA	(DGR)	REPLACED BUCKEYE FUEL FILLER VENT HOSE FIREMANS SIDE		PIQMSNWKIKICWC
			ALBINA	(DGR)	TESTED AND CARDED		PIQMSNWKIKICWC
			ALBINA	(DGR)	TOOK ENGINE OIL, WATER AND AIR COMPRESSOR OIL SAMPLE		PIQMSNWKIKICWC
			ALBINA	(DGR)	TOOK P2A VALVE OFF AND BLEW OUT AIR LINE		PIQMSNWKIKICWC
			ALBINA	(JLB)	(DGR) STEAMED CLEANED ENGINE ROOM AND MAIN GENERATOR		PIQMSNWKIKICWC
			ALBINA	(JLB)	INSTALLED NEW STYLE ATCS (OBT) BRACKET AND MODIFIED FLOOR		PIQMSNWKIKICWC
			ALBINA	(JLB)(DGR)(KAR)	CHANGED NO. 1 TRACTION MOTOR ACC. FED. HIGH FLANGE		PIQMSNWKIKICWC
			ALBINA	(KAR)	CHECKED ALL LIGHTS		PIQMSNWKIKICWC
			ALBINA	(KAR)	CHECKED ALL SMALL MOTORS		PIQMSNWKIKICWC
			ALBINA	(KAR)	CHECKED HIGH LOW VOLTAGE GRND.		PIQMSNWKIKICWC
			ALBINA	(KAR)	REPAIRED REAR HEAD LHT.		PIQMSNWKIKICWC
			ALBINA	(KAR)	REPLACED HEAD LHT. SWITCH		PIQMSNWKIKICWC
			ALBINA	(KAR)	WASHED AND FILLED BATT. WITH WATER		PIQMSNWKIKICWC
			ALBINA	(KAR)	WORKED MAIN. GEN. AND AUX. GEN.		PIQMSNWKIKICWC
			ALBINA	(KAR)	WORKED TRACTION MOTORS		PIQMSNWKIKICWC
	12/16/90	12/17/90	ALBINA	(KME)	FRONT HEADLIGHT'S NO DIM OR MED.		LVRMLU
			ALBINA	(KME)	REAR HEADLIGHT SWITCH WRONG SWITCH, UPSIDE DOWN.		LVRMLU
	12/29/90	01/04/91	ALBINA	(JLB)	CHECKED BELL; HORN; WIPERS; SANDERS.		RHTK
			ALBINA	(JLB)	CLEANED AND SUPPLIED CAB.		RHTK
			ALBINA	(JLB)(JJM)	CHECKED ALL FLUID LEVELS; ADDED 75 GALS. LUBE OIL;		RHTK
			ALBINA	(JLB)(DGR)	DROPPED NO. 2 TRACTION MOTOR ACC. TO RENEW L-2		RHTK
			ALBINA	(JLB)(JJM)	CHANGED WORN BRAKE SHOES; ADJUSTED PISTON TRAVEL.		RHTK

000036

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
OMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE MO DA YR	LOCATION	DETAIL	WORK CODES
UP 001300	12/29/90	01/04/91		ALBINA	INSIDE BRAKE HEAD.	RMTK
				ALBINA	50 GALS. ENG. WATER.	RMTK
	01/08/91	01/08/91		ALBINA	(LJW) CHGD. & REPLACED NECESSARY BRAKE SHOES	RMLU
				ALBINA	(LJW) CHKD. WATER, OIL, & AIR COMPRESSOR FLUID LEVEL	RMLU
				ALBINA	(LJW) INSP. UNIT FOR FRA DEFECTS	RMLU
				ALBINA	(LJW) OIL SAMPLE TAKEN	RMLU
	01/16/91	01/17/91		ALBINA	(CHM) CHECKED ALL LIGHTS, HEATERS, AND FRIG.	TP
				ALBINA	(CHM) LOAD TEST FOR. AND REV.	TP
				ALBINA	(CHM) REPLACED LEFT # LIGHT.	TP
				ALBINA	(CHM) REPLACED LEFT GROUND LIGHT.	TP
				ALBINA	(KMG) C/O BRAKE SHOES & ADJUST	TP
				ALBINA	(KMG) CHECKED FLUIDS	TP
				ALBINA	(KMG) TEST SANDERS	TP
				ALBINA	(KMG) TEST WIPERS BELL & HORN	TP
				ALBINA	(TLH&KMG) FUELED & SANDED	TP
				ALBINA	(WRF) CLEAN & SUPPLIED CAB	TP
	01/30/91	01/30/91		ALBINA	(JLB) CHANGED BAGGIE AIR FILTERS.	LURMTP
				ALBINA	(JLB) CHANGED WORN BRAKE SHOES, ADJUSTED PISTON TRAVEL.	LURMTP
				ALBINA	(JLB) CHECKED ALL FLUID LEVELS, ADDED 75 GALS. WATER.	LURMTP
				ALBINA	(JLB) CLEANED AND SUPPLIED CAB.	LURMTP
				ALBINA	(JLB) TESTED BELL, HORN, WIPERS, AND SANDERS.	LURMTP
				ALBINA	(KAR) CHECKED ALL LIGHTS, ENG. SPEEDS, LOAD FORWARD AND REVERSE.	LURMTP
	02/09/91	02/10/91		ALBINA	(CHM) CHECKED ALL LIGHTS, RADIO AND FRIG.	TPRM
				ALBINA	(DGR) ADDED ENGINE WATER	TPRM
				ALBINA	(DGR) CHANGED WORN BRAKE SHOES AND ADJUSTED PISTON TRAVEL	TPRM
				ALBINA	(DGR) CHECKED ALL FLUID LEVELS	TPRM
				ALBINA	(DGR) OPENED AIR COMPRESSOR FLOOR DRAIN	TPRM
				ALBINA	(LKR) CLEANED AND SUPPLIED CAB	TPRM
	02/11/91	02/12/91		ALBINA	(JLN/MRR/KME) *DE* EXCESSIVE OIL IN ENGINE "V".	TPDEMA
				ALBINA	(KME/MRR) WASH UNIT.	TPDEMA
	02/14/91	02/14/91		ALBINA	(JLB) TESTED HORN, BELL, WIPERS AND SANDERS.	RMTF
				ALBINA	(JLB)(LJW) APPLIED NEW LT. #4 BRAKE HANGER AND BRAKE HEAD	RMTF
				ALBINA	(JLB)(LJW) CHANGED WORN BRAKE SHOES, ADJUSTED PISTON TRAVEL.	RMTF
				ALBINA	(JLB)(LJW) CHECKED ALL FLUID LEVELS.	RMTF
				ALBINA	(LJW) CLEANED AND SUPPLIED CAB.	RMTF
				ALBINA	BECAUSE BRAKE SHOE WAS OVER RIDING WHEEL.	RMTF
	02/18/91	02/18/91		ALBINA	(DGR) ADDED ENGINE LUBE OIL; 5 INCHES	TPRMLU
				ALBINA	(DGR) ADDED ENGINE WATER	TPRMLU
				ALBINA	(DGR) CHANGED FRONT KNUCKLE ON COUPLER	TPRMLU
				ALBINA	(DGR) CHANGED SAND HOSE RIGHT #4 REAR	TPRMLU
				ALBINA	(DGR) CHANGED WORN BRAKE SHOES AND ADJUSTED PISTON TRAVEL	TPRMLU
				ALBINA	(DGR) CHECKED ALL FLUID LEVELS	TPRMLU
				ALBINA	(KMG) CLEANED AND SUPPLIED CAB	TPRMLU
	02/24/91	02/25/91		ALBINA	(DGR) INSTALLED FUEL FILL CAP.	TP
				ALBINA	(JLB) CHANGED WORN OUT BRAKE SHOES, ADJUSTED PISTON TRAVEL.	TP
				ALBINA	(JLB) CHECKED ALL FLUID LEVELS, ADDED 100 GALS ENG. WATER.	TP

000034

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
OMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE DATE MO DA YR	LOCATION	DETAIL	WORK CODES
UP 001300	02/24/91	02/25/91		ALBINA	(JLB) CLEANED AND SUPPLIED CAB.	TP
				ALBINA	(JLB) REPAIRED MOREMEN FITTING ON RADITION PIPEING	TP
				ALBINA	(JLB) REPAIRED PIPEING AT THERMOSTATE HOUSEING.	TP
				ALBINA	(JLB) TESTED HORN, BELL, WIPERS AND SANDERS.	TP
	03/06/91	03/11/91		SALLAKCIT	MOUNTING HEIGHT DOES NOT EXCEED 32 INCHES	TI EMELWAPATW
				SALLAKCIT	TRANSPONDER TAGS	TI EMELWAPATW
				SALLAKCIT	(***)SPECIAL (29A-**) APPLY TWO AUTOMATIC EQUIPMENT ID (AEI)	TI EMELWAPATW
				SALLAKCIT	(BEB)TEST & CARD CARDED 03/10/91	TI EMELWAPATW
				SALLAKCIT	(DLW)*ST* NO ENGINEERS REPORTS FOUND(DLW)	TI EMELWAPATW
				SALLAKCIT	(EFF)C/O #3 ASSY (HEAD CRACKED)	TI EMELWAPATW
				SALLAKCIT	(EFF)C/O AUTO BRK VALVE(DEF-BP LEAKAGE)	TI EMELWAPATW
				SALLAKCIT	(EFF)C/O FRONT COUPLER (FIN)	TI EMELWAPATW
				SALLAKCIT	(EFF)C/O LOWER MAIN BEARINGS (MILES)	TI EMELWAPATW
				SALLAKCIT	(FCR)MACH TESTOUT	TI EMELWAPATW
				SALLAKCIT	(GWO)APPLY CARBODY FILTERS AFTER WASH	TI EMELWAPATW
				SALLAKCIT	(GWO)APPLY SUNVISORS IN CAB	TI EMELWAPATW
				SALLAKCIT	(GWO)C/O LUBE OIL (OUT)	TI EMELWAPATW
				SALLAKCIT	(GWO)REPLACE CAB SEATS	TI EMELWAPATW
				SALLAKCIT	(GWO)WASH / CLEAN CAB	TI EMELWAPATW
				SALLAKCIT	(DEM)PAINT CAB	TI EMELWAPATW
				SALLAKCIT	(OK)REPAIR AND CHECK RADIO MOUNT & HOUSING, APPLY RADIO & TEST	TI EMELWAPATW
				SALLAKCIT	(ONC)WHEEL TRUE ALL (FLANGE HEIGHT)	TI EMELWAPATW
				SALLAKCIT	(PDB) INBOUND INSPECTION	TI EMELWAPATW
				SALLAKCIT	(RLV)*ST* DIC(DLW)	TI EMELWAPATW
				SALLAKCIT	(RLV)*TI* DUE INSPECTION 03/06/91	TI EMELWAPATW
				SALLAKCIT	(RLV)INSPECT (H-OK) (E-OK) (CC-OK) (B-OK)	TI EMELWAPATW
				SALLAKCIT	(RLV)SPECIAL (02-**) UPDATE =UM SCREEN	TI EMELWAPATW
				SALLAKCIT	(RLV)SPECIAL (50A-**) REMOVE WARNING LIGHT FROM TOP	TI EMELWAPATW
				SALLAKCIT	(RLV)SPECIAL (58A-**) APPLY NEW ON BOARD TERMINAL BRACKET (433)	TI EMELWAPATW
				SALLAKCIT	(RLV)SPECIAL (60A-**) INSPECT ATCS PHOENIX CONNECTOR AND INSURE	TI EMELWAPATW
				SALLAKCIT	(RLV)SPECIAL (88-**) APPLY HEAD BUMP PROTECTION	TI EMELWAPATW
				SALLAKCIT	(RLV)WORK AI INSP /// TRIANNUAL AIR.	TI EMELWAPATW
				SALLAKCIT	(RLV)WORK BRAKES (RE-DO ALL BRAKE RODS / WILL NOT ADJUST)	TI EMELWAPATW
				SALLAKCIT	(RLV)WORK TH'S	TI EMELWAPATW
				SALLAKCIT	(RLV)WORK 3YR AIR (FIN)	TI EMELWAPATW
				SALLAKCIT	HELD 03/06 AI INSPECTION TRACK 05	TI EMELWAPATW
	03/22/91	03/28/91		NLRJENKS	(DLB) PT. PREP.	SRMPTWA
				NLRJENKS	(FH) BLOW	SRMPTWA
				NLRJENKS	(FH) GRIND	SRMPTWA
				NLRJENKS	(FH) MASK	SRMPTWA
				NLRJENKS	(FH) PAPER	SRMPTWA
				NLRJENKS	(FH) PRIME	SRMPTWA
				NLRJENKS	(FH) PT EXT GRAY	SRMPTWA
				NLRJENKS	(FH) PT INT	SRMPTWA
				NLRJENKS	(FH) SCOTCHLITE	SRMPTWA
				NLRJENKS	(FH) TOUCHUP	SRMPTWA

000035

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
OMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE DATE MO DA YR	LOCATION	DETAIL	WORK CODES
UP 001300	03/22/91	03/28/91		MLRJENKS	(FH) WIPE	SGRNPMTWA
				MLRJENKS	(FH) YELLOW	SGRNPMTWA
				MLRJENKS	(MGA) RINSE	SGRNPMTWA
				MLRJENKS	(MGA) SANDBLAST	SGRNPMTWA
	04/11/91	04/11/91		ALBINA	(DEB) CHANGE WORN BRAKE SHOES AND ADJUST TRAVEL	TPRM
				ALBINA	(DEB) CHECK FLUID LEVELS	TPRM
				ALBINA	(DEB) CHECK LIGHTS RADIO HEATERS AND REFER	TPRM
				ALBINA	(DEB) CHECK LOAD SPEEDS AND DIRECTION	TPRM
				ALBINA	(DEB) TEST HORN BELL AND WIPERS	TPRM
				ALBINA	(DEB) TEST SANDERS	TPRM
				ALBINA	(KMG) CLEAN AND SUPPLY CAB	TPRM
				ALBINA	(KMG) WASH EXTERIOR	TPRM
	04/12/91	04/24/91		ALBINA	(JLB) INSTALLED NEW SMALL SECTION RADITOR CORE, LEFT SIDE.	RD
				ALBINA	(JLB) REMOVED LEFT BANK RADITOR.	RD
	04/29/91	04/30/91		ALBINA	(DGR) CHANGED OUT ENGINE AIR INTAKE FILTERS	TP
				ALBINA	(JJM) ADDED 9" OF ENGINE OIL	TP
				ALBINA	(JJM) CHANGED OUT AND ADJUSTED BRAKES	TP
				ALBINA	(JJM) CHECKED ALL OTHER FLUID LEVELS	TP
				ALBINA	(JJM) CLEANED AND SUPPLIED CAB	TP
				ALBINA	(JJM) MECH OUT BOUND CHECKS	TP
				ALBINA	(JJM) TOOK ENGINE OIL SAMPLE	TP
				ALBINA	(JJM)(DGR) APPLIED CARBODY FILTERS	TP
	05/04/91	05/05/91		ALBINA	(DEB) CHECKED ALL LIGHTS	TPLUMH
				ALBINA	(DEB) REPLACED SELECTOR SWITCH KNOB	TPLUMH
				ALBINA	(DGR) ADDED ENGINE WATER 6"	TPLUMH
				ALBINA	(DGR) CHANGED WORN BRAKE SHOES AND ADJUSTED PISTON TRAVEL	TPLUMH
				ALBINA	(DGR) CHECKED ALL FLUID LEVELS	TPLUMH
				ALBINA	(DGR) CHECKED BELL, HORN WIPERS	TPLUMH
				ALBINA	(DGR) TOOK LUBE OIL SAMPLE	TPLUMH
				ALBINA	(DGR) WELDED RIGHT REAR 1/4 SAND PIPE	TPLUMH
				ALBINA	(DGR-LKR) WASHED EXTERIOR CAR BODY	TPLUMH
				ALBINA	(LKR) CLEAN AND SUPPLIED CAB	TPLUMH
	05/10/91	05/11/91		ALBINA	(CHM) CHANGED RIGHT GROUND LIGHT	TPRM
				ALBINA	(CHM) CHECKED ALL FLUID LEVELS	TPRM
				ALBINA	(CHM) CHECKED ALL LIGHTS	TPRM
				ALBINA	(CHM) ENGINE SPEEDS, RADIO, FRIDGE, AND HEATER	TPRM
				ALBINA	(CHM) REPLACED ENGINE RM LIGHT	TPRM
				ALBINA	(JJM) CHANGED OUT 15 BRAKE SHOES	TPRM
				ALBINA	(JJM) REPAIRED SANDERS	TPRM
				ALBINA	(LKR) CLEANED AND SUPPLIED CAB	TPRM
				ALBINA	(LKR) WASHED UNIT	TPRM
	05/21/91	05/21/91		ALBINA	(JJM) CHANGED OUT 14 BRAKE SHOES	TP
				ALBINA	(JJM) CHECKED FLUID LEVELS	TP
				ALBINA	(JJM) CLEANED AND SUPPLIED CAB	TP
				ALBINA	(JJM) REPAIRED RIGHT FRONT SANDER	TP
	05/26/91	05/27/91		ALBINA	(DGR) CHANGED WORN BRAKE SHOES AND ADJUSTED PISTON TRAVEL	TPLU

000030

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
OMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE DATE MO DA YR	LOCATION	DETAIL	WORK CODES
UP 001300	05/26/91	05/27/91		ALBINA	(DGR) CHECKED ALL FLUID LEVELS	TPLU
				ALBINA	(DGR) TOOK LUBE OIL SAMPLE	TPLU
	05/27/91	05/27/91		ALBINA	(DGR) ADDED ENGINE WATER	RM
				ALBINA	(DGR) CHANGE WORN BRAKE SHOES AND ADJUST TRAVEL	TP
	06/01/91	06/02/91		ALBINA	(DGR) CHECK FLUID LEVELS	TP
				ALBINA	(LDS) CHECK LIGHTS RADIO AND HEATERS	TP
	06/10/91	06/18/91		ALBINA	(LKR) CLEAN AND SUPPLY CAB	TP
				ALBINA	(JLB) CHANGED CAR BODY FILTERS.	PIQHRMNASNTKIC
				ALBINA	(JLB) CHANGED SPIN ON FUEL FILTERS.	PIQHRMNASNTKIC
				ALBINA	(JLB) CHANGED WORN BRAKE SHOES, ADJUSTED PISTON TRAVEL	PIQHRMNASNTKIC
				ALBINA	(JLB) CHECKED ALL FLUID LEVELS, ADDED 75 GALS. LUBE OIL.	PIQHRMNASNTKIC
				ALBINA	(JLB) CHECKED CONDITION AND TENSION OF COOLING FAN DRIVE BELTS.	PIQHRMNASNTKIC
				ALBINA	(JLB) CHECKED MANUALLY OPERATION OF SHUTTERS.	PIQHRMNASNTKIC
				ALBINA	(JLB) CHECKED OPERATION OF DOOR LATCHES.	PIQHRMNASNTKIC
				ALBINA	(JLB) CHECKED OPERATION OF EMERGENCY FUEL CUT OFF VALVE.	PIQHRMNASNTKIC
				ALBINA	(JLB) CHECKED OPERATION OF THE ENGINE PROTECTIVE DEVICE / COP	PIQHRMNASNTKIC
				ALBINA	(JLB) CLEANED SUCTION STRAINERS AND CHANGED LUBE OIL FILTERS.	PIQHRMNASNTKIC
				ALBINA	(JLB) ENG. WATER, LUBE OIL, AND AIR COMPRESSOR SAMPLES TAKEN.	PIQHRMNASNTKIC
				ALBINA	(JLB) GREASED COUPLER WEAR PLATE.	PIQHRMNASNTKIC
				ALBINA	(JLB) INSPECTED (MID) HOSES AND VALVES.	PIQHRMNASNTKIC
				ALBINA	(JLB) INSPECTED SAND TRAPS AND HOSES.	PIQHRMNASNTKIC
				ALBINA	(JLB) INSURED THAT INDEPENDENT AND AUTO. BRAKE VALVES ARE PIPES	PIQHRMNASNTKIC
				ALBINA	(JLB) LUBRICATED FAN JACK SHAFT BEARINGS.	PIQHRMNASNTKIC
				ALBINA	(JLB) LUBRICATED TRI-POD SEAT POST.	PIQHRMNASNTKIC
				ALBINA	(JLB) ON BAGGIE AIR FILTERS IN STOCK.	PIQHRMNASNTKIC
				ALBINA	(JLB) UNIT NEEDS FIRST AID, NONE IN STOCK.	PIQHRMNASNTKIC
				ALBINA	(KAR) CHECKED ALARM BELL AND ALARM SYSTEMS	PIQHRMNASNTKIC
				ALBINA	(KAR) CHECKED AUX, GEN. SMALL MOTORS	PIQHRMNASNTKIC
				ALBINA	(KAR) CHECKED HIGH AND LOW VOLTAGES GRNDS.	PIQHRMNASNTKIC
				ALBINA	(KAR) CHECKED HIGH VOLTAGE EQUIP. AND CABS.	PIQHRMNASNTKIC
				ALBINA	(KAR) CHECKED RADIO AND ANTENNA	PIQHRMNASNTKIC
				ALBINA	(KAR) CHECKED WHEEL SLIP AND GRND. RELAY	PIQHRMNASNTKIC
				ALBINA	(KAR) TEST AND CARD	PIQHRMNASNTKIC
				ALBINA	(KAR) WASHED AND FILLED BATT. WITH WATER	PIQHRMNASNTKIC
				ALBINA	(KAR) WORKED LIGHTS	PIQHRMNASNTKIC
				ALBINA	(KAR) WORKED TRACTION MOTORS	PIQHRMNASNTKIC
				ALBINA	BELOW THE FLOOR.	PIQHRMNASNTKIC
				ALBINA	SWITCH.	PIQHRMNASNTKIC
	06/27/91	06/27/91		ALBINA	(DEB) ADD ENGINE OIL	TPRM
				ALBINA	(DEB) ADD ENGINE WATER	TPRM
				ALBINA	(DEB) CHANGE WORN BRAKE SHOES AND ADJUST TRAVEL	TPRM
				ALBINA	(DEB) CHECK FLUID LEVELS	TPRM
				ALBINA	(DEB) CLEAN AND SUPPLY CAB	TPRM
				ALBINA	(DGR) CHANGED BAGGIE TYPE AIR FILTERS	RHRMLU
	07/09/91	07/10/91		ALBINA	(DGR) CHANGED WORN BRAKE SHOES AND ADJUSTED PISTON TRAVEL	RHRMLU
				ALBINA	(DGR) CHECKED ALL FLUID LEVELS	RHRMLU

000037

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
QMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE DATE MO DA YR	LOCATION	DETAIL	WORK CODES
UP 001300	07/09/91	07/10/91		ALBINA	(DGR) CLEANED CAB AND SUPPLIED CAB	RMRMLU
				ALBINA	(DGR) REPLACED UNION ON LEAKING WATER JUMPER LINE	RMRMLU
				ALBINA	(DGR) TOOK LUBE OIL SAMPLE	RMRMLU
				ALBINA	(DGR) WASHED EXTERIOR	RMRMLU
	07/14/91	07/15/91		ALBINA	() CLEAN AND SUPPLIED CAB.	TP
				ALBINA	(JLB) CHANGED ALL WORN BRAKE SHOES, ADJUSTED PISTON TRAVEL.	TP
				ALBINA	(JLB) CHECKED ALL FLUID LEVELS.	TP
				ALBINA	(JLB) TESTED HORN, BELL, WIPERS AND SANDERS.	TP
	07/24/91	07/25/91		ALBINA	(JLB) CHANGED WORN BRAKE SHOES, ADJUSTED PISTON TRAVEL.	TP
				ALBINA	(JLB) CHECKED ALL FLUID LEVELS, ADDED 50 GALS. LUBE OIL.	TP
				ALBINA	(JLB) CLEANED AND SUPPLIED CAB.	TP
				ALBINA	(JLB) RAN UNIT THRU WASH RACK.	TP
				ALBINA	(JLB) TESTED HORN, BELL, WIPERS AND SANDERS.	TP
	08/01/91	08/02/91		ALBINA	(JLB) TESTED HORN, BELL, WIPERS AND SANDERS.	HMLU
				ALBINA	(JLB) WORKED (LJD) (HND) OIL SAMPLE TAKEN, CHANGED CAR BODY FILTERS	HMLU
				ALBINA	(JLB) (JMD) CHANGED WORN BRAKE SHOES, ADJUSTED PISTON TRAVEL.	HMLU
				ALBINA	(KAR) (TLH) CLEANED AND SUPPLIED CAB.	HMLU
				ALBINA	(LJD) CHECKED ALL FLUID LEVELS.	HMLU
				ALBINA	NO BAGGIE FILTERS IN STOCK.	HMLU
	08/24/91	08/29/91		ALBINA	(DGR) LU GOT ON UNIT	RMLUNC
				ALBINA	(LRS) (JLB) (DGR) CHG'D #2 PR. WHEELS ACCT. FLAT	RMLUNC
	09/10/91	09/13/91		ALBINA	(JJM) CHANGED BAG TYPE ENGINE INTAKE FILTERS	PISHSNWATKIC
				ALBINA	(JJM) CHANGED LUBE OIL FILTERS	PISHSNWATKIC
				ALBINA	(JJM) CHANGED OUT CARBODY FILTERS	PISHSNWATKIC
				ALBINA	(JJM) CHANGED OUT FUEL FILL GAUGE	PISHSNWATKIC
				ALBINA	(JJM) CHECKED AIR BOX, RINGS ECT	PISHSNWATKIC
				ALBINA	(JJM) CHECKED BELTS	PISHSNWATKIC
				ALBINA	(JJM) CHECKED BUCKEYE FUEL FILLER	PISHSNWATKIC
				ALBINA	(JJM) CHECKED CRANKCASE	PISHSNWATKIC
				ALBINA	(JJM) CHECKED HORN, BELL, WIPERS, AND SANDERS.	PISHSNWATKIC
				ALBINA	(JJM) CHECKED MU HOSES, ANGLE COCKS ECT.	PISHSNWATKIC
				ALBINA	(JJM) CHECKED PIPING OF INDEP. AND AUTO. VALS FOR SUBDECK	PISHSNWATKIC
				ALBINA	(JJM) CLEANED SUCTION STRAINERS	PISHSNWATKIC
				ALBINA	(JJM) CLEANED UP ENGINE ROOM	PISHSNWATKIC
				ALBINA	(JJM) CLEANED FUEL SIGHT GLASS	PISHSNWATKIC
				ALBINA	(JJM) DOOR LATCHES OILED AND CHECKED	PISHSNWATKIC
				ALBINA	(JJM) GREASE COUPLER SHANK WEAR PLATE	PISHSNWATKIC
				ALBINA	(JJM) INSPECTED SAND TRAPS AND HOSES	PISHSNWATKIC
				ALBINA	(JJM) LUBED COOLING FAN BEARINGS	PISHSNWATKIC
				ALBINA	(JJM) OUT BOUND TEST	PISHSNWATKIC
				ALBINA	(JJM) RECEIVED COMPRESSOR OIL SAMPLES	PISHSNWATKIC
				ALBINA	(JJM) RECEIVED ENGINE WATER, OIL SAMPLES	PISHSNWATKIC
				ALBINA	(JJM) REPLACED FUEL FILTERS	PISHSNWATKIC
				ALBINA	(JJM) TRI-POD SEAT LUBED	PISHSNWATKIC
				ALBINA	(KAR) CHECKED ALARM BELL AND ALARMS SYSTEMS	PISHSNWATKIC
				ALBINA	(KAR) CHECKED ALL LIGHTS	PISHSNWATKIC

000036

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
OMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE DATE MO DA YR	LOCATION	DETAIL	WORK CODES
UP 001300	09/10/91	09/13/91		ALBINA	(KAR) CHECKED ALL SMALL MOTORS	PISMSNWATKIC
				ALBINA	(KAR) CHECKED AUX. GEN.	PISMSNWATKIC
				ALBINA	(KAR) CHECKED GRND. RELAY AND CHARGING CIRCUIT	PISMSNWATKIC
				ALBINA	(KAR) CHECKED HIGH AND LOW VOLTAGE GRNDS.	PISMSNWATKIC
				ALBINA	(KAR) CHECKED HIGH CAB. AND EQUIP.	PISMSNWATKIC
				ALBINA	(KAR) CHECKED RADIO AND ANTENNA	PISMSNWATKIC
				ALBINA	(KAR) CHECKED RER. FOR OPERATION	PISMSNWATKIC
				ALBINA	(KAR) CHECKED WHEEL SLIP SYSTEMS	PISMSNWATKIC
				ALBINA	(KAR) INSPECTED MAIN GEN. PIT	PISMSNWATKIC
				ALBINA	(KAR) REBRUSHED MAIN GEN.	PISMSNWATKIC
				ALBINA	(KAR) TEST AND CARDED	PISMSNWATKIC
				ALBINA	(KAR) WASHED BATT. AND FILLED WITH WATER	PISMSNWATKIC
				ALBINA	(KAR) WORKED TRACTION MOTORS	PISMSNWATKIC
	09/16/91	09/17/91		ALBINA	(KME) P2 CONTACTOR INTERLOCK BLOCK NOT WORKING.	TP
				ALBINA	(JLB) CHANGED WORN BRAKE SHOES, ADJUSTED PISTON TRAVEL	TP
				ALBINA	(JLB) CHECKED ALL FLUID LEVELS.	TP
				ALBINA	(JLB) CLEANED AND SUPPLIED CAB.	TP
				ALBINA	(JLB) TESTED HORN, BELL, WIPERS, AND SANDERS.	TP
				ALBINA	(JLB) TESTED HORN, WIPERS, AND SANDERS.	TP
	09/22/91	09/23/91		ALBINA	(DGR) ADDED ENGINE WATER	RMLU
				ALBINA	(DGR) CHANGED WORN BRAKE SHOES AND ADJUSTED PISTON TRAVEL	RMLU
				ALBINA	(DGR) CHECKED ALL FLUID LEVELS	RMLU
				ALBINA	(DGR) CLEANED AND SUPPLIED CAB	RMLU
				ALBINA	(DGR) TOOK LUBE OIL SAMPLE	RMLU
	09/28/91	09/30/91		ALBINA	(KME) FIRE EXT. IN CAB MISSING.	TPIC
	10/09/91	10/10/91		ALBINA	(JJD) ADDED 12 BAGS OF WATER TREATMENT	TP
				ALBINA	(JJD) ADDED 6" OF WATER TO ENGINE	TP
				ALBINA	(JJD) CHANGED AND ADJUSTED BRAKE SHOES	TP
				ALBINA	(JJD) CHECKED ALL FLUID LEVELS	TP
				ALBINA	(JJD) CLEANED AND SUPPLIED CAB	TP
				ALBINA	(JJD) MECH OUT BOUND TEST	TP
	10/16/91	10/16/91		ALBINA	(JLB) CHANGED WORN BRAKE SHOES, ADJUSTED PISTON TRAVEL	RMLUTP
				ALBINA	(JLB) CHECKED ALL FLUID LEVELS.	RMLUTP
				ALBINA	(JLB) CLEANED AND SUPPLIED CAB.	RMLUTP
				ALBINA	(JLB) TESTED HORN, BELL, AND WIPERS.	RMLUTP
				ALBINA	(JLB) WORKED (LUB) OIL SAMPLE TAKEN.	RMLUTP
	10/25/91	10/26/91		ALBINA	(CHM) CHECKED ALL LIGHTS, HEATERS, FRIG, RADIO	TPRMMH
				ALBINA	(CHM) TESTED ENGINE SPEEDS AND DIRECTIONS	TPRMMH
				ALBINA	(LKR) CLEANED AND SERVICED CAB	TPRMMH
				ALBINA	(WRH) CHANGE ADJUST BRAKE SHOES	TPRMMH
				ALBINA	(WRH) CHECK FLUIDS	TPRMMH
				ALBINA	(WRH) CHECKED SANDERS	TPRMMH
				ALBINA	(WRH) PERFORMED "HH"	TPRMMH
	11/05/91	11/06/91		ALBINA	(JJD) CHANGED WORN BRAKE SHOES, ADJUSTED PISTON TRAVEL	TPLV
				ALBINA	(JJD) CHECKED ALL FLUID LEVELS.	TPLV
				ALBINA	(JJD) CLEANED AND SUPPLIED CAB.	TPLV

000033

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
OMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE DATE MO DA YR	LOCATION	DETAIL	WORK CODES
UP 001300	11/05/91	11/06/91		ALBINA	(LRS) REPAIRED THE HEAD LIGHT RESISTOR.	TPLV
	11/19/91	11/20/91		ALBINA	(JLB) CHANGED WORN BRAKE SHOES, ADJUSTED PISTON TRAVEL	TPSV
				ALBINA	(JLB) CHECKED ALL FLUID LEVELS.	TPSV
				ALBINA	(JLB) CLEANED AND SUPPLIED CAB.	TPSV
				ALBINA	(JLB) TESTED HORN, BELL, WIPERS AND SANDERS.	TPSV
	11/28/91	11/29/91		ALBINA	(CHM) CHECK LIGHTS RADIO HEATERS AND REFER	SURMLU
				ALBINA	(DEB) CHANGE WORN BRAKE SHOES AND ADJUST TRAVEL	SURMLU
				ALBINA	(JLM) TAKE LUBE OIL SAMPLE	SURMLU
				ALBINA	(KMG) CLEAN AND SUPPLY CAB	SURMLU
	12/04/91	12/05/91		ALBINA	(JJM) ADDED ENGINE COOLING WATER	TP
				ALBINA	(JJM) ADDED 9" OF ENGINE OIL	TP
				ALBINA	(JJM) CHANGED AND ADJUSTED BRAKE SHOES	TP
				ALBINA	(JJM) CHECKED FLUID LEVELS	TP
				ALBINA	(JJM) CLEANED AND SUPPLIED CAB	TP
				ALBINA	(JJM) REPAIRED ENGINEERS CAB SEAT	TP
	12/10/91	12/11/91		ALBINA	(DGR) ADDED ENGINE WATER	TPSV
				ALBINA	(DGR) CHANGED WORN BRAKE SHOES AND ADJUSTED PISTON TRAVEL	TPSV
				ALBINA	(DGR) CHECKED ALL FLUID LEVELS	TPSV
				ALBINA	(DGR) CLEANED AND SUPPLIED CAB	TPSV
				ALBINA	(DGR) FUELED AND SANDED	TPSV
	12/14/91	01/08/92		ALBINA	(LDS) CHECK AND RENEW ALL LIGHTS	PIQHRNSNWKATKIC
				ALBINA	(LDS) CHECK COVERS FOR ALL PROPER STENCILING	PIQHRNSNWKATKIC
				ALBINA	(LDS) CHECK REVERSER HANDLE INTERLOCK	PIQHRNSNWKATKIC
				ALBINA	(LDS) CHECK TRACTION MOTORS FOR PROPER BRUSH LENGTH AND EQUIPMENT	PIQHRNSNWKATKIC
				ALBINA	(LDS) CHECKED ALARM BELLS	PIQHRNSNWKATKIC
				ALBINA	(LDS) CLEAN AND NEUTRALIZE BATTERIES	PIQHRNSNWKATKIC
				ALBINA	(LDS) REPLACE ALL FUSES	PIQHRNSNWKATKIC
				ALBINA	(LDS) TEST FOR AND CLEAR ALL LOW AND HIGH VOLTAGE GROUNDS	PIQHRNSNWKATKIC
				ALBINA	(JJM) ADDED GOV OIL	PIQHRNSNWKATKIC
				ALBINA	(JJM) ADDED LUBE OIL	PIQHRNSNWKATKIC
				ALBINA	(JJM) CHANGED OUT WATER SIGHT GLASS	PIQHRNSNWKATKIC
				ALBINA	(JJM) CHECKED BRAKE SHOES AND ADJUSTED	PIQHRNSNWKATKIC
				ALBINA	(JJM) CLEANED AND SUPPLIED CAB	PIQHRNSNWKATKIC
				ALBINA	(JJM) DRAINED FUEL FROM TANK AND REPAIRED GAUGE	PIQHRNSNWKATKIC
				ALBINA	(JJM) DRAINED WATER, ADDED TREATMENT, AND REFILLED	PIQHRNSNWKATKIC
				ALBINA	(JJM) INSPECTION OF SAND TRAPS	PIQHRNSNWKATKIC
				ALBINA	(JJM) SUPPLIED FIRST AID KIT	PIQHRNSNWKATKIC
				ALBINA	(JJM)(LDS) OUTBOUND CHECKS	PIQHRNSNWKATKIC
				ALBINA	(JJM)(LDS) REPAIRED LEFT REAR SAND TRAP	PIQHRNSNWKATKIC
				ALBINA	(JJM)(LDS) WASHED TRUCKS AND CARBODY	PIQHRNSNWKATKIC
				ALBINA	(WRH) CHANGED BAG TYPE AIR FILTERS	PIQHRNSNWKATKIC
				ALBINA	(WRH) CHANGED LUBE OIL FILTERS	PIQHRNSNWKATKIC
				ALBINA	(WRH) CHANGED OUT CARBODY FILTERS	PIQHRNSNWKATKIC
				ALBINA	(WRH) CHECKED AND LUBED ALL DOOR HINGES	PIQHRNSNWKATKIC
				ALBINA	(WRH) CHECKED AND LUBED TRI POD SEAT	PIQHRNSNWKATKIC
				ALBINA	(WRH) CHECKED AUTO AND INDEP VALVES FOR PROPER PIPING	PIQHRNSNWKATKIC

000040

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
OMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE MO DA YR	DATE MO DA YR	LOCATION	DETAIL	WORK CODES
UP 001300	12/14/91	01/08/92			ALBINA	(WRH) CHECKED BRAKE RIGGING	PIQHRMSNWKATKIC
					ALBINA	(WRH) CHECKED BUCKEYE FILL AND VENT	PIQHRMSNWKATKIC
					ALBINA	(WRH) CHECKED FIRE EXTINGUISHER	PIQHRMSNWKATKIC
					ALBINA	(WRH) CHECKED FUEL TANK BOLTS	PIQHRMSNWKATKIC
					ALBINA	(WRH) CHECKED MU HOSES	PIQHRMSNWKATKIC
					ALBINA	(WRH) GREASED COUPLER SHANK	PIQHRMSNWKATKIC
					ALBINA	(WRH) INSPECTED TOP DECK	PIQHRMSNWKATKIC
					ALBINA	(WRH) LUBE FAN BEARING	PIQHRMSNWKATKIC
					ALBINA	(WRH) REPLACED FUEL FILTERS	PIQHRMSNWKATKIC
	01/18/92	01/19/92			ALBINA	(WRH) TOOK LUBE OIL, WATER AND COMPRESSOR SAMPLES	PIQHRMSNWKATKIC
					ALBINA	(CHM) CHECK ALL LIGHTS.	TP
					ALBINA	(CHM) LOAD TEST UNIT.	TP
					ALBINA	(CHM) TEST FRIG.	TP
					ALBINA	(CHM) TEST RADIO.	TP
					ALBINA	(WRH) ADJUSTED BRAKE TRAVEL	TP
					ALBINA	(WRH) CHECKED BELL	TP
					ALBINA	(WRH) CHECKED BRAKE SHOES	TP -
					ALBINA	(WRH) CHECKED SANDERS	TP -
					ALBINA	(WRH) CHECKED WIPERS	TP
	01/22/92	01/22/92			ALBINA	(DGR) ADDED ENGINE WATER	TP
					ALBINA	(DGR) CHANGED FRONT AND REAR TRAIN LINE HOSES	TP
					ALBINA	(DGR) CHANGED WORN BRAKE SHOES AND ADJUSTED PISTON TRAVEL	TP
					ALBINA	(DGR) CHECKED ALL FLUID LEVELS	TP
					ALBINA	(DGR) CLEANED AND SUPPLIED CAB	TP
	01/30/92	01/31/92			ALBINA	(JJM) ADDED ENGINE OIL 6"	TP
					ALBINA	(JJM) CHANGED AND ADJUSTED BRAKE SHOES	TP
					ALBINA	(JJM) CHECKED ENGINE FLUID LEVELS	TP
					ALBINA	(JJM) CLEANED AND SUPPLIED CAB	TP
					ALBINA	(LDS) ELECTRICAL CHECKS	TP
	02/02/92	02/03/92			ALBINA	(CHM) LOAD TEST UNIT.	TP
					ALBINA	(CHM) TEST ALL CAB HEATERS.	TP
					ALBINA	(WRH) TEST HORN, BELL, AND WIPERS.	TP
					ALBINA	(WRH) TEST SANDERS.	TP
	02/06/92	02/06/92			ALBINA	(JLB) CHANGED WORN BRAKE SHOES, ADJUSTED PISTON TRAVEL	TPSV
					ALBINA	(JLB) CHECKED ALL FLUID LEVELS.	TPSV
					ALBINA	(JLB) CLEANED AND SUPPLIED CAB.	TPSV
	02/11/92	02/11/92			ALBINA	(JLB) (DGR) (LRS) CHANGED DRAFT GEAR AND COUPLER.	USTPSVCD
	02/16/92	02/17/92			ALBINA	(LDS) CLEANED AND SUPPLIED CAB	SVTP
					ALBINA	(LDS) TESTED ATCS FOR PROPER OPERATION	SVTP
					ALBINA	(LDS) TESTED LIGHTS FOR PROPER OPERATION	SVTP
					ALBINA	(LDS) TESTED RADIO FOR PROPER OPERATION	SVTP
					ALBINA	(LDS) TESTED WATER COOLER FOR PROPER OPERATION	SVTP
	02/22/92	02/23/92			ALBINA	(LDS) REPLACED OBT WITH ONE WITH A WORKING KEYBOARD	TP
					ALBINA	(LDS) TESTED ATCS SYSTEM FOR PROPER OPERATION	TP
	03/07/92	03/08/92			ALBINA	(JJM) CHANGE L#1 BRAKE HEAD ACCT. B/O	TP
					ALBINA	(JJM) CHANGE WORN BRAKE SHOES AND ADJUST TRAVEL	TP

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
DMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE DATE MO DA YR	LOCATION	DETAIL	WORK CODES
UP 001300	03/07/92	03/08/92		ALBINA	(JJM) CHECK FLUID LEVELS	TP
				ALBINA	(LKR) CLEAN AND SUPPLY CAB	TP
				ALBINA	(YKK) CHECK LIGHTS RADIO HEATERS AND REFER	TP
				ALBINA	(YKK) REPAIR HEADLIGHT WIRING	TP
	03/12/92	03/17/92		ALBINA	(JLB) CHANGED BAGGIE AND CAR BODY AIR FILTERS.	PHAIAMRMSNTKICW
				ALBINA	(JLB) CHANGED FUEL FILTERS.	PHAIAMRMSNTKICW
				ALBINA	(JLB) CHANGED LUBE OIL FILTERS AND CLEANED SUCTION STRAINERS.	PHAIAMRMSNTKICW
				ALBINA	(JLB) CHANGED WORN BRAKE SHOES, ADJUSTED PISTON TRAVEL.	PHAIAMRMSNTKICW
				ALBINA	(JLB) CHECKED ALL FLUID LEVELS.	PHAIAMRMSNTKICW
				ALBINA	(JLB) CHECKED CONDITION OF COOLING FAN BELTS.	PHAIAMRMSNTKICW
				ALBINA	(JLB) CHECKED OPERATION OF CAB DOOR LATCHES.	PHAIAMRMSNTKICW
				ALBINA	(JLB) CLEANED FUEL SYSTEM SIGHTS GLASSES.	PHAIAMRMSNTKICW
				ALBINA	(JLB) GREASED COUPLER WEAR PLATE.	PHAIAMRMSNTKICW
				ALBINA	(JLB) INSPECTED BUCKEYE FUEL FILLERS AND VENT HOSES.	PHAIAMRMSNTKICW
				ALBINA	(JLB) INSPECTED CONDITION OF (MID HOSES ON BOTH FRONT AND REAR OF	PHAIAMRMSNTKICW
				ALBINA	(JLB) INSPECTED CONDITION OF FIRST AID KIT.	PHAIAMRMSNTKICW
				ALBINA	(JLB) INSPECTED CONDITION OF THE HAND BRAKE.	PHAIAMRMSNTKICW
				ALBINA	(JLB) INSPECTED SAND TRAPS AND HOSES FOR DEFECTS.	PHAIAMRMSNTKICW
				ALBINA	(JLB) INSPECTED UNIT FOR SIDE BEARING CLEARANCE.	PHAIAMRMSNTKICW
				ALBINA	(JLB) INSURED FREENESS OF BRAKE SLACK ADJUSTERS.	PHAIAMRMSNTKICW
				ALBINA	(JLB) INSURED THAT INDEPENDENT AND AUTOMATIC BRAKE VALVES ARE	PHAIAMRMSNTKICW
				ALBINA	(JLB) INSURED 20#FIRE EXT. ARE IN WORKING ORDER.	PHAIAMRMSNTKICW
				ALBINA	(JLB) LUBE OIL, ENG. WATER SAMPLES TAKEN.	PHAIAMRMSNTKICW
				ALBINA	(JLB) LUBRICATED COOLING FAN JACK SHAFT.	PHAIAMRMSNTKICW
				ALBINA	(JLB) LUBRICATED TRI-POD SEAT POSTS.	PHAIAMRMSNTKICW
				ALBINA	(JLB) REPLACED AIR COMPRESSOR AIR FILTER.	PHAIAMRMSNTKICW
				ALBINA	(JLB) REPLACED REAR TRAIN LINE HOSE.	PHAIAMRMSNTKICW
				ALBINA	(JLB) STEAMED CLEANED ENGINE ROOM.	PHAIAMRMSNTKICW
				ALBINA	(JLB) TEST AND CARD.	PHAIAMRMSNTKICW
				ALBINA	(JLB) TESTED HORN, BELL, WIPERS AND SANDERS.	PHAIAMRMSNTKICW
				ALBINA	(LDS) CHECK REVISION OF THE OBT SOFTWARE.	PHAIAMRMSNTKICW
				ALBINA	(LDS) CONVERT RADIO POWER FROM 12VDC TO 72VDC.	PHAIAMRMSNTKICW
				ALBINA	(LDS) MEG HIGH VOLTAGE SYSTEM (2-MEG).	PHAIAMRMSNTKICW
				ALBINA	(LDS) REPLACE O.B.T.	PHAIAMRMSNTKICW
				ALBINA	(LDS) TEST AND CARD UNIT.	PHAIAMRMSNTKICW
				ALBINA	(LDS) UP-GRADE RADIO	PHAIAMRMSNTKICW
				ALBINA	(YKK) CHECK ALL TRACTION MOTOR BRUSHES.	PHAIAMRMSNTKICW
				ALBINA	(YKK) CHECK AND CLEAR ALL LOW VOLTAGE GROUNDS.	PHAIAMRMSNTKICW
				ALBINA	(YKK) CHECK AUX-GEN OUTPUT VOLTAGE.	PHAIAMRMSNTKICW
				ALBINA	(YKK) CHECK AUX-GEN REFERENCE VOLTAGE.	PHAIAMRMSNTKICW
				ALBINA	(YKK) CHECK AUXILIARY GENERATOR BRUSHES.	PHAIAMRMSNTKICW
				ALBINA	(YKK) CHECK GROUND RELAY OPERATION.	PHAIAMRMSNTKICW
				ALBINA	(YKK) CHECK MAIN GENERATOR BRUSHES.	PHAIAMRMSNTKICW
				ALBINA	(YKK) CHECK OPERATION OF ALL LIGHTS.	PHAIAMRMSNTKICW
				ALBINA	(YKK) CHECK OPERATION OF REVERSER INTERLOCK.	PHAIAMRMSNTKICW
				ALBINA	(YKK) CHECK OPERATION OF THE ALARM BELL.	PHAIAMRMSNTKICW

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
OMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE MO DA YR	LOCATION	DETAIL	WORK CODES
UP 001300	03/12/92	03/17/92		ALBINA	(YKK) CHECK REMOVABLE COVERS FOR (DANGER-600-VOLTS).	PMAIAHRMSNTKICMA
				ALBINA	(YKK) INSPECT ALL T.M. LEADS, BOOTS, CLAMPS AND GROUND STRAPS.	PMAIAHRMSNTKICMA
				ALBINA	(YKK) REPLACE ALL MISSING FUSES.	PMAIAHRMSNTKICMA
				ALBINA	(YKK) REPLACE CAB HEATER MOTOR BRUSHER.	PMAIAHRMSNTKICMA
				ALBINA	(YKK) REPLACE FUEL PUMP MOTOR BRUSHES.	PMAIAHRMSNTKICMA
				ALBINA	(YKK) TEST OPERATION OF ALL CAB HEATERS.	PMAIAHRMSNTKICMA
				ALBINA	(YKK) WASH AND FILL BATTERY.	PMAIAHRMSNTKICMA
				ALBINA	UNIT. REPLACED AS NECESSARY.	PMAIAHRMSNTKICMA
				ALBINA	VENTED BELOW THE FLOOR.	PMAIAHRMSNTKICMA
	03/22/92	03/22/92		ALBINA	(DGR) ADDED OIL TO CRANK CASE	TPSVRM
				ALBINA	(DGR) CHANGED AND ADJUSTED BRAKE SHOES	TPSVRM
				ALBINA	(DGR) CHECKED FLUID LEVELS	TPSVRM
				ALBINA	(DGR)(YKK) CLEANED AND SUPPLIED CAB	TPSVRM
				ALBINA	(YKK) CHANGED OUT OBT	TPSVRM
	04/04/92	04/05/92		ALBINA	(WRH) CHECKED ADJUSTED AND CHANGED BRAKE SHOES	TP
				ALBINA	(WRH) CHECKED FLUIDS	TP
				ALBINA	(WRH) CHECKED SANDERS	TP
				ALBINA	(YKK) CHECKED LIGHTS, HORN, BELL, REEFER RADIO WIPERS	TP
	04/07/92	04/08/92		ALBINA	(DGR) REPLACED HOSE -- WATER PUMP TO EX. TANK	TPRML
	04/17/92	04/18/92		ALBINA	(JJM) CHECKED ALL FLUID LEVELS	SVTPRM
				ALBINA	(JJM)(WRH) C/O BRAKE SHOES AND ADJUSTED	SVTPRM
				ALBINA	(LKR) CLEANED AND SUPPLIED CAB	SVTPRM
				ALBINA	(YKK) ELECTRICAL CHECKS	SVTPRM
	04/25/92	04/26/92		ALBINA	(WRH) CHANGED AND ADJUSTED BRAKES	TP
				ALBINA	(WRH) CHECKED FLUID LEVELS	TP
				ALBINA	(WRH) PERFORMED L.U.	TP
	04/30/92	05/01/92		ALBINA	(JJM) ADDED WATER TREATMENT	RHMLU
				ALBINA	(JJM) CHANGED AND ADJUSTED BRAKE SHOES	RHMLU
				ALBINA	(JJM) CHECKED FLUID LEVELS	RHMLU
				ALBINA	(JJM) CLEANED AND SUPPLIED CAB	RHMLU
				ALBINA	(JJM) LU DONE	RHMLU
				ALBINA	(JJM) MM DONE	RHMLU
	05/05/92	05/06/92		ALBINA	(JJM) ADDED ENGINE WATER 8"	TPSVMA
				ALBINA	(JJM) ADDED 6" OF ENGINE OIL	TPSVMA
				ALBINA	(JJM) CHANGED AND ADJUSTED BRAKE SHOES	TPSVMA
				ALBINA	(JJM) CHECKED FLUID LEVELS	TPSVMA
				ALBINA	(JJM) CLEANED AND SUPPLIED CAB	TPSVMA
				ALBINA	(JJM)(DGR) WASHED CARBODY	TPSVMA
	05/21/92	05/26/92		ALBINA	(/) REMOVE BRAKE RIGGING.	USRMLUTK
				ALBINA	(JLM/KME) REMOVE & REPLACE LEFT #7 BRAKE HEAD.	USRMLUTK
				ALBINA	(DGR) CHANGED WORN BRAKE SHOES ADJUSTED PISTON TRAVEL.	USRMLUTK
				ALBINA	(DGR) CHECKED ALL FLUID LEVELS.	USRMLUTK
				ALBINA	(DGR) REPLACE PEDESTAL LINERS, LEFT&RIGHT.	USRMLUTK
				ALBINA	(JLB) CLEANED AND SUPPLIED CAB.	USRMLUTK
				ALBINA	(JLB)(DGR) REPLACE BRAKE RIGGING.	USRMLUTK
	06/06/92	06/06/92		ALBINA	(JJM) CHANGE WORN BRAKE SHOES AND ADJUST TRAVEL	SVTPSRM

000043

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
CHNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE DATE MO DA YR	LOCATION	DETAIL	WORK CODES
UP 001300	06/06/92	06/06/92		ALBINA	(JJM) CHECK FLUID LEVELS	SVTPSORM
				ALBINA	(JJM) CHECK FOR WATER LEAKS(NOTHING FOUND) SEE RM	SVTPSORM
				ALBINA	(JJM) CLEAN AND SUPPLY CAB	SVTPSORM
				ALBINA	(JJM) RUNNING CHECKS	SVTPSORM
				ALBINA	(YKK) CHECK LIGHTS RADIO REFER	SVTPSORM
	06/10/92	06/11/92		ALBINA	(JLM) CHANGE WORN BRAKE SHOES AND ADJUST TRAVEL	SVTP
				ALBINA	(JLM) CHECK FLUID LEVELS	SVTP
				ALBINA	(KMG) CLEAN AND SUPPLY CAB	SVTP
				ALBINA	(SR) CHECK LIGHTS RADIO REFER	SVTP
	06/17/92	06/22/92		ALBINA	AND HOOK UP.	PMFIGNLRMLUSN
				ALBINA	PROPER OPERATION (4.12)	PMFIGNLRMLUSN
				ALBINA	PROPERLY INSTALLED	PMFIGNLRMLUSN
				ALBINA	REPLACED ALL MUFFLERS	PMFIGNLRMLUSN
				ALBINA	THAT ALL LEADS AND BOOTS ARE OK AND ALL FELTS ON COVERS ARE	PMFIGNLRMLUSN
				ALBINA	WATER. ALSO SPRAYED CONNECTIONS WITH BATTERY SAVER.	PMFIGNLRMLUSN
				ALBINA	(LDS) CHECKED HIGH VOLTAGE PANELS AND REPLACED B.O. DECALS	PMFIGNLRMLUSN
				ALBINA	(LDS) CHECKED LIGHTS AND REPLACED BURNED BULBS	PMFIGNLRMLUSN
				ALBINA	(LDS) CHECKED DBT FOR CORRECT REVISION AND TESTED SYSTEM FOR	PMFIGNLRMLUSN
				ALBINA	(LDS) CHECKED REVERSER FOR PROPER OPERATION AND TESTED INTERLOCK	PMFIGNLRMLUSN
				ALBINA	(LDS) CHECKED TRACTION MOTORS FOR PROPER BRUSH LENGTH AND INSURED	PMFIGNLRMLUSN
				ALBINA	(LDS) INSPECTED BATTERIES FOR PROPER INSTALLATION AND FILLED WITH	PMFIGNLRMLUSN
				ALBINA	(LDS) MEG HIGH VOLTAGE FOR LEAKAGE (10 MEGOHM)	PMFIGNLRMLUSN
				ALBINA	(LDS) REPLACED TWO B.O. MAIN REV BLOWDOWN AND REPAIRED ONE UNIT	PMFIGNLRMLUSN
				ALBINA	(LDS) TEST LOW VOLTAGE SYSTEM FOR GROUNDS (OK)	PMFIGNLRMLUSN
				ALBINA	(LDS) TESTED ALARM BELL FOR PROPER OPERATION	PMFIGNLRMLUSN
				ALBINA	(LDS) TESTED RADIO AND ANTENNA FOR PROPER OPERATION ALSO MOUNTING	PMFIGNLRMLUSN
				ALBINA	(LDS) UNIT HAS NO SPARE FUSE BOX	PMFIGNLRMLUSN
				ALBINA	(JJM) APPLIED 10 PSI INTO WATER SYSTEM AND CHECKED FOR H2O LEAKS	PMFIGNLRMLUSN
				ALBINA	(JJM) CHECKED AND LUBED ALL DOOR HINGES AND LATCHES	PMFIGNLRMLUSN
				ALBINA	(JJM) CHECKED AND LUBED ALL SEATS, MADE REPAIRS TO FM SEAT	PMFIGNLRMLUSN
				ALBINA	(JJM) CHECKED FIRE EXTINGUISHERS	PMFIGNLRMLUSN
				ALBINA	(JJM) CHECKED FIRST AID KIT	PMFIGNLRMLUSN
				ALBINA	(JJM) CHECKED FUEL LINES FOR LEAKS WITH BLACK LIGHT	PMFIGNLRMLUSN
				ALBINA	(JJM) CHECKED MU HOSES	PMFIGNLRMLUSN
				ALBINA	(JJM) CHECKED OUT TOP DECK, HEADS, CRABS, RACK, ECT.	PMFIGNLRMLUSN
				ALBINA	(JJM) CLEANED OUT STACK RETENTION BINS	PMFIGNLRMLUSN
				ALBINA	(JJM) FOUND WATER LEAK @ #6 ASSEMBLY REPT' ON REFERRAL MAINT.	PMFIGNLRMLUSN
				ALBINA	(JJM) GREASED COUPLER SHANK	PMFIGNLRMLUSN
				ALBINA	(JJM) TOOK FLUID SAMPLES	PMFIGNLRMLUSN
				ALBINA	(JLB) CHANGED AIR COMPRESSOR AIR INTAKE FILTER.	PMFIGNLRMLUSN
				ALBINA	(JLB) CHANGED ALL AIR FILTERS	PMFIGNLRMLUSN
				ALBINA	(JLB) CHANGED BAGGIE AND CAR BODY AIR FILTERS.	PMFIGNLRMLUSN
				ALBINA	(JLB) CHANGED LUBE OIL FILTERS.	PMFIGNLRMLUSN
				ALBINA	(JLB) CLEANED FUEL SYSTEM SIGHT GLASSES.	PMFIGNLRMLUSN
				ALBINA	(JLB) LUBRICATED COOLING FAN JACK SHAFT.	PMFIGNLRMLUSN
				ALBINA	(WRH) LU	PMFIGNLRMLUSN

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
DMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE DATE MO DA YR	LOCATION	DETAIL	WORK CODES
UP 001300	06/26/92	06/30/92		HINKLE	() *SA* HOLD AT SLC FOR THE RETENTION TANK MOD. (JRL/DMA)	USMIRNEW
				HINKLE	(CAS) *RM*#6 CYL WATER LEAKS	USMIRNEW
				HINKLE	(JAM/DLH/CAS/AGS) CO #6 ASSY (WATER LEAK) NUMBERS IN COMPUTER	USMIRNEW
	06/30/92	07/01/92		ALBINA	(JLB) CHANGED WORN BRAKE SHOES, ADJUSTED PISTON TRAVEL	TPSVLU
				ALBINA	(JLB) CLEANED AND SUPPLIED CAB.	TPSVLU
				ALBINA	(JLB) PERFORMED (LD) OIL SAMPLE TAKEN	TPSVLU
				ALBINA	(JLB) TESTED HORN, BELL, WIPERS AND SANDERS.	TPSVLU
	07/04/92	07/05/92		ALBINA	(DGR) CHANGE WORN BRAKE SHOES AND ADJUST TRAVEL	TP
				ALBINA	(DGR) CHECK FLUID LEVELS	TP
				ALBINA	(LKR) CLEAN AND SUPPLY CAB	TP
				ALBINA	(YKK) CHECK LIGHTS RADIO REFER	TP
	07/13/92	07/14/92		ALBINA	(JLB) (DGR) (CHD) DROPPED #1 TRUCK, ACCT. NO SIDE BEARING CLEARANCE.	USSGRNTHKV
				ALBINA	(JLB) (DGR) (YKK) REMOVED #4 TRACTION MOTOR AND REPAIRED TRACTION	USSGRNTHKV
				ALBINA	MOTOR LEADS AND REINSTALLED.	USSGRNTHKV
	07/29/92	07/29/92		ALBSERTRK	(TLH) CLEAN AND SUPPLY CAB	TPSV
				ALBSERTRK	(MRH) CHANGE WORN BRAKE SHOES AND ADJUST TRAVEL	TPSV
				ALBSERTRK	(MRH) CHECK FLUID LEVELS	TPSV
				ALBSERTRK	(YKK) CHECK LIGHTS RADIO AND REFER	TPSV
	08/04/92	08/04/92		ALBINA	(KME) #LU*	SVSQ LU
				ALBINA	(KME) CHANGED OUT 15 BRAKE SHOES.	SVSQ LU
	08/08/92	08/09/92		ALBSERTRK	(JLM) *RM*	SVTPSMMH
	08/27/92	08/28/92		ALBSERTRK	(JLB) CHANGED WORN BRAKE SHOES, ADJUSTED PISTON TRAVEL	LUTKSV
				ALBSERTRK	(JLB) CHECKED ALL FLUID LEVELS.	LUTKSV
				ALBSERTRK	(JLB) (JMD) REPLACED LT. #2 INSIDE BRAKE HEAD AND BRAKE STRAPS.	LUTKSV
	09/01/92	09/01/92		ALBSERTRK	(JLB) CHANGED WORN BRAKE SHOES, ADJUSTED PISTON TRAVEL	TPSV
				ALBSERTRK	(JLB) CHECKED ALL FLUID LEVELS.	TPSV
				ALBSERTRK	(JLB) CLEANED AND SUPPLIED CAB.	TPSV
				ALBSERTRK	(JLB) TESTED HORN, BELL, WIPERS AND SANDERS.	TPSV
	09/14/92	09/14/92		POCATELLO	() NO SIDE BEARING CLEARANCE RIGHT REARTRUCK	PMPIEM RMLUPJ
				POCATELLO	() RM TO SLC AFTER INSP. FOR MODS	PMPIEM RMLUPJ
				POCATELLO	(JEW) #10 ROCKER ARM STUD BROKEN REPLACED	PMPIEM RMLUPJ
				POCATELLO	(JEW) CHECK & SIGN OFF INSPECTOR'S WORK REPORT	PMPIEM RMLUPJ
				POCATELLO	(JEW) DO SPCL 009 RADIO MODS PER LDI 7200 THRU 7203 & FREQ LIST	PMPIEM RMLUPJ
				POCATELLO	(JEW) DO SPCL 036 FRA CHECK LIST	PMPIEM RMLUPJ
				POCATELLO	(JEW) DO SPCL 090 ENGINEER'S INSPECTION DECAL	PMPIEM RMLUPJ
				POCATELLO	(JEW) ENGINE OIL/WATER & AIR COMPRESSOR SAMPLES	PMPIEM RMLUPJ
				POCATELLO	(JEW) PI, EM, SQ 9/11	PMPIEM RMLUPJ
				POCATELLO	(JEW) RUN PACKET (DNH)	PMPIEM RMLUPJ
				POCATELLO	(SRW) RM TO SLC AFTER INSP. FOR MODS	PMPIEM RMLUPJ
	09/15/92	09/20/92		SALLAKCIT	(***INBOUND PROCESS	PMPIEM RMLUPJ
				SALLAKCIT	(BA) *ST*PROJECT WORK - 013 MOD	PMPIEM RMLUPJ
				SALLAKCIT	(BA) *ST*RETENTION TANK MOD (GGC)	PMPIEM RMLUPJ
				SALLAKCIT	(BA) APPLY RETENTION TANK & WELD BRACKETS	PMPIEM RMLUPJ
				SALLAKCIT	(BA) FLUSH & FILL FUEL TANK WITH FUEL	PMPIEM RMLUPJ
				SALLAKCIT	(BA) PIPE RETENTION TANK	PMPIEM RMLUPJ
				SALLAKCIT	(EFF)PUMP FUEL OUT	PMPIEM RMLUPJ

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
OMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE DATE MO DA YR	LOCATION	DETAIL	WORK CODES
UP 001300	09/15/92	09/20/92		SALLAKCIT	(EFF)STEAM FUEL TANK - ON STEAM 9:30 PM 09/16/92	PMPJLUPJ
				SALLAKCIT	(GFJ) MECH TEST OUT	PMPJLUPJ
				SALLAKCIT	(GFJ)DRAIN WATER FROM FUEL TANK	PMPJLUPJ
				SALLAKCIT	(JMN)START & CHECK	PMPJLUPJ
				SALLAKCIT	(HJL)*ST* CHANGED OUT AIR COMPRESSOR OIL	PMPJLUPJ
				SALLAKCIT	HELD 09/15/92 DUE	TRACK 05 PMPJLUPJ
	09/25/92	09/27/92		ALBSERTRK	(DEB) CLEAN AND SUPPLY CAB	SVTP
				ALBSERTRK	(DGR) CHANGE WORN BRAKE SHOES AND ADJUST TRAVEL	SVTP
				ALBSERTRK	(DGR) CHECK FLUID LEVELS (ADD ENG WATER)	SVTP
				ALBSERTRK	(LJP) CHECK LIGHTS RADIO HEATERS AND REFER	SVTP
	10/29/92	10/29/92		ALBSERTRK	(CLB) FRONT PILOT PLATE LOWERED ACCT. HIGH	MM
				ALBSERTRK	(TLB) WASTE WATER DRAINED FROM RETENTION TANK	MM
	10/30/92	10/30/92		ALBINA	(KLB) REPLACED GASKETS TO SEPARATOR POT--TIGHTENED HOSE CLAMPS	MAOL
				ALBINA	(SRL) WASHED MAIN GENERATOR PIT & AREA AROUND	MAOL
	11/05/92	11/05/92		ALBSERTRK	(KAR) REPAIRED BURNED WIRE TO HEADLIGHT RESISTOR	SVEL
	11/16/92	11/17/92		ALBSERTRK	(JLB) APPLIED NEW TRAIN LINE HOSE.	TPSV
				ALBSERTRK	(JLB) CHANGED WORN BRAKE SHOES.	TPSV
				ALBSERTRK	(JLB) CHECKED ALL FLUID LEVELS.	TPSV
	12/07/92	12/07/92		ALBINA	(CAS) MACH. TEST & CARD	PMPIDMLUMATKSN
				ALBINA	(DAH) WASH UNIT COMPLETE	PMPIDMLUMATKSN
				ALBINA	(REB) ELECT. TEST & CARD	PMPIDMLUMATKSN
	12/15/92	12/16/92		ALBSERTRK	(JLB) CHANGED WORN BRAKE SHOES, ADJUSTED PISTON TRAVEL	SVTP
				ALBSERTRK	(JLB) CHECKED ALL FLUID LEVELS, ADDED 100 GALS LUBE OIL	SVTP

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
OMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE DATE MO DA YR	LOCATION	DETAIL	WORK CODES
UP 001307	01/01/70	11/11/91		ALBINA	(JLB) REPLACED B.O. ENGINEERS SEAT.	CD
	05/21/88	05/21/88		POCATELLO	() GR/WS	MI
				POCATELLO	() WHITE LAB	MI
	05/22/88	06/10/88		SALLAKCIT	**** POSITIVE FEED FOR THERMONICS HAS BEEN	TISIABFFPIEWELLU
				SALLAKCIT	**** TAKEN CARE OF AT TB. ****	TISIABFFPIEWELLU
				SALLAKCIT	TO CLEAR CALL POWER CONTROL AT 688-3636	TISIABFFPIEWELLU
				SALLAKCIT	(***)*SI* 08-16-87 SRR KEEP IN ALBINA OR FOR SWT & LOCAL SERVICE	TISIABFFPIEWELLU
				SALLAKCIT	(BEJ)APPLY CARBODY AIR FILTERS WHEN AVAILABLE****N.I.S. ***	TISIABFFPIEWELLU
				SALLAKCIT	(BEJ)MECH TEST OUT (DWD)	TISIABFFPIEWELLU
				SALLAKCIT	(BEJ)SPECIALS (05-JES) (54-JES) (79-****)	TISIABFFPIEWELLU
				SALLAKCIT	(DTC)UNHOOK FROM LOAD BOX AFTER CHECKS	TISIABFFPIEWELLU
				SALLAKCIT	(DTC)WIRE THERMONICS**** CONDUIT IN PLACE NEED CONDULETS T17 2EA*	TISIABFFPIEWELLU
				SALLAKCIT	(DWD)HOOK TO LOAD BOX	TISIABFFPIEWELLU
				SALLAKCIT	(DWD)TEST & CARD	TISIABFFPIEWELLU
				SALLAKCIT	(JES)WASH AND COVER	TISIABFFPIEWELLU
				SALLAKCIT	(JRM)ELECT TEST OUT(DWD)	TISIABFFPIEWELLU
				SALLAKCIT	(MM)INSPECT (M-DWD) (E-PDB) (CC-PDB) (BM-PDB)	TISIABFFPIEWELLU
				SALLAKCIT	(PDB)W/BRAKES	TISIABFFPIEWELLU
				SALLAKCIT	(PDB)W/TM'S	TISIABFFPIEWELLU
				SALLAKCIT	(RLV)*ST* C/O THIN BRAKE SHOES(LER)	TISIABFFPIEWELLU
				SALLAKCIT	(RLV)*ST* DEAD & DRAINED(LER)	TISIABFFPIEWELLU
				SALLAKCIT	(RLV)*TI* DUE INSPECTION 05/17/88	TISIABFFPIEWELLU
				SALLAKCIT	(RLV)BLACKLITE INJECTORS	TISIABFFPIEWELLU
				SALLAKCIT	(RLV)FILL W/OIL	TISIABFFPIEWELLU
				SALLAKCIT	(TCT)APPLY PCS MOD	TISIABFFPIEWELLU
				SALLAKCIT	(TCT)C/O ALL INJECTORS & LASH ADJUSTERS	TISIABFFPIEWELLU
				SALLAKCIT	(TCT)C/O FUEL PUMP (NEED FUEL PUMP)	TISIABFFPIEWELLU
				SALLAKCIT	(TCT)C/O REFER (KNOCKING)	TISIABFFPIEWELLU
				SALLAKCIT	(TCT)FIN INSPECTION SHEETS(E-OK)	TISIABFFPIEWELLU
				SALLAKCIT	(TCT)MAKE AND APPLY CLAMPS TO THERMONIC CONDUITS.	TISIABFFPIEWELLU
				SALLAKCIT	(TCT)PIPE INJECTORS	TISIABFFPIEWELLU
				SALLAKCIT	(TCT)WORK AIR	TISIABFFPIEWELLU
				SALLAKCIT	(TLT)CAB FLOOR	TISIABFFPIEWELLU
				SALLAKCIT	(2ND)PRE-LOAD (M-DWD) (E-DWD)	TISIABFFPIEWELLU
				SALLAKCIT	HELD 05/22 3YR INSPECTION	TRACK 05 TISIABFFPIEWELLU
	06/15/88	06/15/88		HINKLE	(JRC) HOLD FOR JRC INSPECTION	JB
				HINKLE	(JWB) WAS SET OUT AT GIBBON HOT BOX	JB
	11/16/88	11/17/88		ALBINA	(LDS) #1 PR WHEELS TO CHG. 2 1/2" FLAT	RHMC
	02/17/89	02/23/89		HINKLE	() NEED TO CHECK FOR OIL OUT STACK	MILURNAB
				HINKLE	(ALL)WASH CARBODY	MILURNAB
				HINKLE	(HAM)ADJUST BRAKE PISTON TRAVEL	MILURNAB
				HINKLE	(TJB) I GOT A OIL SAMPLE HAS A LOT OF WATER IN THE OIL.	MILURNAB
				HINKLE	(TJB) THE OIL VIS. IS (850) —————	MILURNAB
				HINKLE	(TJB) 824 FILTER HOUSING COVER COMING FROM SLC ON A UNIT	MILURNAB
				HINKLE	(WAM)DUE LU AND MM	MILURNAB
				HINKLE	(WAM)W.F.L REPORT—MAIN RESERVOIR FILTER HOUSING BUSTED	MILURNAB

000047

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
OMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE DATE	LOCATION	DETAIL	WORK CODES
UP 001307	03/13/89	03/17/89		ALBINA	(DER) #3 PR. WHEELS TO CHG. FLAT	PIQMLURHAWMC
				ALBINA	(JLB) SANDER CONTROL RELAYS BO--FRONT, TO BE CHGD	PIQMLURHAWMC
				ALBINA	(JLB) MACH TEST & CARD	PIQMLURHAWMC
				ALBINA	(LRS) ELECT TEST & CARD	PIQMLURHAWMC
	06/11/89	06/22/89		ALBINA	(CAM) DEAD BATTERIES.	AIBALVNCMALU
				ALBINA	(DER) WORK AI (MACHINIST)	AIBALVNCMALU
				ALBINA	(JEB) REPAIR REPORTED DEFECTS	AIBALVNCMALU
				ALBINA	(JEB) TRIPS CCP (CHECK FOR REASON)	AIBALVNCMALU
				ALBINA	(JSN) C/O #2, 3, 4 WHEELS ACCT. FEDERAL FLATS (LRS) (CAC)	AIBALVNCMALU
				ALBINA	(LAK) CLEAN CAB	AIBALVNCMALU
				ALBINA	(LAK) WASH LOCOMOTIVE	AIBALVNCMALU
				ALBINA	(LRS) REPAIR B/O WARNING LIGHT	AIBALVNCMALU
				ALBINA	(LRS) WORK AI (ELECTRICIAN)	AIBALVNCMALU
				ALBINA	(JEB) CLEAN OUT SANDERS & CHECK OPERATION	AIBALVNCMALU
				ALBINA	(JEB) REPOSITION WASTE BASKET & BRACKET IN CAB	AIBALVNCMALU
				ALBINA	(JSN) #4 PR. WHEELS TO CHG. FLAT (LRS) (JEB)	AIBALVNCMALU
				ALBINA	(LRS) REBRUSH MAIN GEN.	AIBALVNCMALU
	07/25/89	07/25/89		ALBINA	(LJM) ENG. HAS CCP--TRIPPING LOW OIL BUTTON	WCEN-
				ALBINA	(LRS) (LJM) (JEB) CHG'D #1 PR. WHEELS ACCT. FLAT	WCEN
	08/21/89	08/26/89		ALBINA	(WAG) CELLER PACK	LU
				ALBINA	(1ST) GET LUBE OIL SAMPLE	LU
	09/21/89	09/28/89		ALBINA	(CHD) ELECT. TEST & CARD	PIQMLUTKMW SN
				ALBINA	(JLB) INSP. UNIT FOR FRA DEFECTS	PIQMLUTKMW SN
				ALBINA	(JLB) MACH. TEST & CARD	PIQMLUTKMW SN
				ALBINA	(JLM) COOLING FAN BELTS TO CHANGE--BO	PIQMLUTKMW SN
				ALBINA	(KLR) WASH UNIT COMPLETE	PIQMLUTKMW SN
	11/15/89	11/15/89		ALBINA	(J-M) CHECK GEAR GREASE & SUPPORT OIL--TAKE OIL SAMPLE	LU
	11/18/89	11/19/89		ALBINA	(WAG) REPAIRED REAR DOOR LATCH	TPIC
	12/12/89	12/18/89		ALBINA	(J-M) PI INSP. MECH. TEST & CARD.	PIENLUBA
				ALBINA	(KAR) PI INSP. ELECT. TEST & CARD.	PIENLUBA
				ALBINA	(D-R) WASH UNIT COMPLETE	PIENLUBA
				ALBINA	(J-M) REMOVE DEAD MAN PEDAL	PIENLUBA
				ALBINA	(KLA) COMPLETE ATCS MOD	PIENLUBA
				ALBINA	(LJM) INSP. UNIT FOR FRA DEFECTS	PIENLUBA
	01/23/90	01/29/90		POCATELLO ()	*RM* BATTS NEED REPLACED	RNDSBAMH
				POCATELLO ()	*RM* OIL OUT STACK	RNDSBAMH
				POCATELLO (JEW)	WASHED UNIT OIL OUT STACK DIDNT LOOK BAD	RNDSBAMH
	01/29/90	02/01/90		POCATELLO (MCH)	CHECKED ENGINE BLOWERS OK. PRESSURED ENGINE OK.	COLTOS
				POCATELLO (MCH)	RANG ENGINE CHECKED OUT NO DEFECT FOR OIL .	COLTOS
				POCATELLO (MCH)	SHUTTERS STUCK OPEN--WON'T CLOSE--RUNNING COLD.	COLTOS
				POCATELLO (RHL)	PUT ON LOAD BOX.	COLTOS
	03/22/90	03/23/90		POCATELLO (RHL)	PAST DUE PI--GM 03-20-90.	PIQMW
				POCATELLO (RHL)	PI TEST AND CARD	PIQMW
				POCATELLO (RHL)	REPAIR FRONT CUT LEVERS	PIQMW
				POCATELLO (RHL)	WASH COMPLETE	PIQMW
	03/27/90	03/28/90		ALBINA	(CHM) LIGHTS CHECKED OK	TP

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
OMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	LOCATION	DETAIL	WORK CODES
UP 001307	03/27/90	03/28/90	ALBINA	(CHM) LOADS OK BOTH DIRECTIONS	TP
			ALBINA	(JJM) ALL FLUID LEVELS CHECKED OK	TP
			ALBINA	(JJM) CHANGED OUT WORN BRK. SHOES AND ADJUSTED TRAVEL	TP
			ALBINA	(JJM) SANDERS CHECKED OK	TP
	04/06/90	04/07/90	ALBINA	(CHM) CHECKED ALL LIGHTS AND CAB HEATERS	TP
			ALBINA	(CHM) LOAD TESTED	TP
			ALBINA	(CHM) REPLACED FOUR GAUGE LIGHTS	TP
			ALBINA	(CHM) REPLACED TWO REAR HEADLIGHTS	TP
			ALBINA	(JJM) ADD ENGINE COOLING WATER TO ENGINE	TP
			ALBINA	(JJM) ADDED 30 GALS. ENGINE LUBE OIL	TP
			ALBINA	(JJM) REPAIR REAR WIPER ENG. SIDE	TP
			ALBINA	(JJM) REPAIR WRECK DAMAGE ON REAR PIN LIFTING MECH.	TP
	04/13/90	04/14/90	ALBINA	(CHM) REPAIRED HEADLIGHT WIRING AND CHANGED BULB	LU
			ALBINA	(JJM) ADDED ENGINE WATER	LU
			ALBINA	(JJM) CHANGE OUT WORN BRK. SHOES AND ADJUST TRAVEL	LU
			ALBINA	(JJM) TAKE LUBE OIL SAMPLE	LU
			ALBINA	(JLB) DO LU	LU -
			ALBINA	(JLB) DO LU	LU -
	04/24/90	04/24/90	ALBINA	(JLM) RIGHT REAR STEPS KNOCKED OFF ONE SIDE & INSIDE SILL BENT IN.	ADLU
	04/29/90	04/29/90	ALBINA	(CHM) CHECKED LIGHTS, REFER AND RADIO	TP
			ALBINA	(CHM) CLEAN SUPPLIED CAB	TP
			ALBINA	(CHM) REPLACED REAR HEADLIGHT BULBS	TP
			ALBINA	(DGR) REPLACED WORN BRK SHOES AND ADJUSTED TRAVEL	TP
	05/01/90	05/02/90	ALBINA	(CHM) REPLACED GROUND LIGHT	TP
			ALBINA	(CHM) REPLACED RADIO	TP
			ALBINA	(CHM) REPLACED 4 GAUGE LIGHTS	TP
			ALBINA	(CHM) TESTED ENGINE SPEEDS AND LOAD	TP
			ALBINA	(CHM) TESTED LIGHTS, CAB HEATERS AND RADIO	TP
			ALBINA	(JJM) CHANGED WORN BRK SHOES AND ADJUSTED TRAVEL	TP
			ALBINA	(JJM) CHECKED FLUID LEVELS	TP
			ALBINA	(WRR) CLEAN AND SUPPLY CAB	TP
	05/07/90	05/07/90	ALBINA	(D-R) (JMC) COOLING FAN BELTS REPLACED ACCT. BROKEN	TPCF
	05/15/90	05/16/90	ALBINA	(CHM) C/O B/O "A" VALVE THROTTLE SWITCH	LU
			ALBINA	(CHM) C/O B/O REAR HEADLIGHT	LU
			ALBINA	(CHM) CHECK LOAD AND THROTTLE	LU
			ALBINA	(CHM) CHECK RADIO, LIGHTS, HEATERS	LU
			ALBINA	(JJM) CHECK FLUID LEVELS	LU
			ALBINA	(JJM) DO LU	LU
			ALBINA	(JJM) REPAIR FRONT SANDERS	LU
			ALBINA	(JJM) REPLACE WORN BRK SHOES AND ADJUST PISTON TRAVEL	LU
			ALBINA	(WRR) CLEAN AND SUPPLY CAB	LU
	05/20/90	05/20/90	ALBINA	(CHM) REPLACED LEFT REAR HEAD LIGHT	TP
			ALBINA	(CHM) REPLACED RIGHT FRONT NUMBER LIGHT	TP
			ALBINA	(CHM) REPLACED RIGHT REAR NUMBER LIGHT	TP
			ALBINA	(CHM) TESTED CAB HEATERS AND REFER	TP
			ALBINA	(CHM) TESTED ENGINE SPEED AND LOAD	TP

000049

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
OMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE DATE MO DA YR	LOCATION	DETAIL	WORK CODES
UP 001307	05/20/90	05/20/90		ALBINA	(DGR) APPLIED 9 BRAKE SHOES AND ADJUSTED PISTON TRAVEL	TP
				ALBINA	(DGR) CLEANED AND SUPPLIED CAB	TP
				ALBINA	(DGR) TESTED SANDERS	TP
	05/23/90	05/23/90		ALBINA	(CHM) CHECK LIGHTS RADIO HEATERS AND REFER	TP
				ALBINA	(CHM) CHECK LOAD AND DIRECTION	TP
				ALBINA	(JJM) CHANGE WORN BRK SHOES AND ADJUST TRAVEL	TP
				ALBINA	(JJM) CHECK ALL FLUID LEVELS	TP
				ALBINA	(JJM) CHECK SANDER OPERATION	TP
				ALBINA	(JJM) REPAIR REPORTED DEFECTS	TP
				ALBINA	(WRR) CLEAN AND SUPPLY CAB	TP
	05/31/90	05/31/90		ALBINA	(JLB) CHANGED LEFT NO.1 BRAKE HEAD	TPTK
				ALBINA	(JLB) CHANGED WORN OUT BRAKE SHOES	TPTK
	06/07/90	06/07/90		ALBINA	(DGR) CLEANED AND SUPPLIED CAB	LU
				ALBINA	(DGR) REPOSITIONED AJAX WATER COOLER AND BOLTED DOWN	LU
				ALBINA	(JLB) CHANGED WORN BRAKE SHOES AND ADJUSTED PISTON TRAVEL	LU
	06/16/90	06/17/90		ALBINA	(KME) REPLACE B/D REAR AIR HOSE'S.	TPAB
				ALBINA	(YKK) REPAIR HEADLIGHTS.	TPAB
	06/22/90	07/03/90		ALBINA	EX. STACK & REPLACE	AITKICMNSNEXLU
				ALBINA	(DGR) REPLACE COOLING FAN BELTS ACCT. BROKEN	AITKICMNSNEXLU
				ALBINA	(JLB) MACH. TEST & CARD	AITKICMNSNEXLU
				ALBINA	(JLB)(DGR) REMOVE EX. MANIFOLD'S-CLEAN & REPLACE; CLEAN FALSE	AITKICMNSNEXLU
				ALBINA	(KAR) ELECT. TEST & CARD	AITKICMNSNEXLU
				ALBINA	(KAR) REBRUSH MAIN GEN.	AITKICMNSNEXLU
				ALBINA	(KAR) REPLACE RADIO ACCT. BO	AITKICMNSNEXLU
				ALBINA	(KMG) WASH UNIT COMPLETE-CARBODY & TRUCKS	AITKICMNSNEXLU
				ALBINA	(LJW) INSP. UNIT FOR FRA DEFECTS	AITKICMNSNEXLU
	07/06/90	07/06/90		ALBINA	(KMG) CLEANED AND SUPPLIED CAB	TP
				ALBINA	(KMG) WASHED CARBODY AND TRUCKS	TP
				ALBINA	(KRR) MADE ELECTRICAL CHECKS	TP
				ALBINA	(LJW) ADDED 6" OF ENGINE LUBE OIL	TP
				ALBINA	(LJW) CHANGED OUT 10 BRAKE SHOES	TP
	07/16/90	07/17/90		ALBINA	(JLM) FILLED WITH 10 INCHS OF ENGINE OIL	TP
				ALBINA	(PWR) CLEANED CAB	TP
				ALBINA	(PWR) SERVICED CAB WITH WATER AND SUPPLIES	TP
				ALBINA	(YKK) CHECKED UNIT ELECTRICALLY	TP
	07/27/90	07/27/90		ALBINA	(DEB) CHANGE WORN BRAKE SHOES AND ADJUST TRAVEL	TP
				ALBINA	(DEB) CHECK FLUID LEVELS	TP
				ALBINA	(DEB) CHECK LIGHTS RADIO HEATERS AND REFER	TP
				ALBINA	(DEB) CHECK LOAD, SPEEDS AND DIRECTION	TP
				ALBINA	(DEB) CLEAN AND SUPPLY CAB	TP
				ALBINA	(DEB) REPAIR REPORTED DEFECTS	TP
				ALBINA	(DEB) TEST AIR BRAKE SYSTEM	TP
				ALBINA	(DEB) TEST BELL HORN AND WIPERS	TP
	08/03/90	08/03/90		ALBINA	(DEB) FUEL AND SAND UNIT	TP
				ALBINA	(JLM) CHANGE WORN BRAKE SHOES AND ADJUST TRAVEL	TP
				ALBINA	(JLM) CHECK FLUID LEVELS	TP

000050

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
OMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE MO DA YR	LOCATION	DETAIL	WORK CODES
UP 001307	08/03/90	08/03/90		ALBINA	(JLM) CHECK LIGHTS RADIO AND REFER	TP
				ALBINA	(JLM) REPAIR REAR DOOR LATCH	TP
				ALBINA	(WRR) CLEAN AND SUPPLY CAB	TP
	08/09/90	08/09/90		ALBINA	(JJM) ADJUSTED REFER	TP
				ALBINA	(JJM) CHANGED OUT 4 BRAKE SHOES AND ADJUSTED	TP
				ALBINA	(JJM) CHECKED ALL FLUID LEVELS	TP
				ALBINA	(JJM) CLEANED AND SUPPLIED CAB	TP
				ALBINA	(KAR) CHECKED ALL LIGHTS SWITCHES HEATERS ECT	TP
	08/19/90	08/22/90		ALBINA	(DGR) CHANGE OUT 9 BRAKE SHOES	RMD
				ALBINA	(DGR) CHECKED ALL FLUID LEVELS	RMD
				ALBINA	(DGR) CLEAN AND SUPPLY CAB	RMD
				ALBINA	(DGR, JJM) REPLACE FRONT ELECTRICAL MU PLUG AND HOUSING	RMD
				ALBINA	(DGR, JJM) STRAIGHTEN FRONT LEFT HAND RAIL AND STANSIONS	RMD
	08/25/90	08/26/90		ALBINA	(CHM) DIRECTIONAL LOAD AND ENGINE SPEED CHECKS	TP
				ALBINA	(CHM) CHECKED ALL LIGHTS, FRIDGE, HEATERS, AND GAUGE LIGHTS	TP
				ALBINA	(JJM) CHANGED OUT FIVE BRAKE SHOES	TP
				ALBINA	(JJM) CLEANED AND SUPPLIED CAB	TP
				ALBINA	(JJM) REPAIRED REAR SANDERS	TP
				ALBINA	(JJM) WASHED CARBODY AND TRUCKS	TP
	08/31/90	08/31/90		ALBINA	(YKK/KME) REAR HEADLIGHT'S BURNING OUT.	TPLV
	09/14/90	09/15/90		ALBINA	(YKK) CHANGED OUT RVR CONTACTOR .	TPRV
				ALBINA	(YKK) LOAD CHECKED OK.	TPRV
	10/01/90	10/04/90		ALBINA	(DEVD) WELDED SANDPIPE LEFT FRONT TRUCK REAR SANDER	PIGNLUEL
				ALBINA	(DGR) CHANGED AIR COMPRESSOR AIR FILTERS	PIGNLUEL
				ALBINA	(DGR) CHANGED BAGGIE TYPE AIR FILTERS	PIGNLUEL
				ALBINA	(DGR) CHANGED CAR-BODY FILTERS	PIGNLUEL
				ALBINA	(DGR) CHANGED OUT FUEL FILTERS	PIGNLUEL
				ALBINA	(DGR) CHANGED OUT OIL FILTERS	PIGNLUEL
				ALBINA	(DGR) CHECKED SANDERS AND HOSES	PIGNLUEL
				ALBINA	(DGR) CHECKED SIDE BEARING CLEARANCE	PIGNLUEL
				ALBINA	(DGR) LUBE FAN BEARINGS AND CHECKED BELT CONDITION AND TENSION	PIGNLUEL
				ALBINA	(DGR) LUBED COUPLER WEAR PLATES	PIGNLUEL
				ALBINA	(DGR) LUBED DOOR LATCHES	PIGNLUEL
				ALBINA	(DGR) LUBED ENGINEER AND FIREMAN'S SEAT POST	PIGNLUEL
				ALBINA	(DGR) TOOK AIR COMPRESSOR OIL SAMPLE	PIGNLUEL
				ALBINA	(DGR) TOOK ENGINE WATER SAMPLE	PIGNLUEL
				ALBINA	(DGR) TOOK OIL SAMPLE	PIGNLUEL
				ALBINA	(KAR) CHANGED OUT GS CONTACTOR	PIGNLUEL
				ALBINA	(KAR) CHARGED BATTERIES	PIGNLUEL
				ALBINA	(KAR) CHECKED ALL ALARMS	PIGNLUEL
				ALBINA	(KAR) TEST AND CARD	PIGNLUEL
				ALBINA	(KAR) WASHED AND FILLED BATTERIES	PIGNLUEL
				ALBINA	(KAR) WORKED ALL LIGHTS	PIGNLUEL
				ALBINA	(KAR) WORKED ALL SMALL MOTORS	PIGNLUEL
				ALBINA	(KAR) WORKED TRACTION MOTORS	PIGNLUEL
	10/09/90	10/10/90		ALBINA	(DGR) WASHED CARBODY & TRUCKS	TP

000031

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
OMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE DATE MO DA YR	LOCATION	DETAIL	WORK CODES
UP 001307	10/09/90	10/10/90		ALBINA	(JLB) CHANGED R2 BRAKE (INSIDE) ACCT. BURNED IN	TP
	10/16/90	10/17/90		ALBINA	(DGR) WASHED CARBODY & TRUCKS COMPLETE	TPWA
	10/21/90	10/22/90		ALBINA	(JLM) CHANGE OUT ENGR'S SEAT.	TPICLV
				ALBINA	(YKK) REPAIR ENGR'S HEATER.	TPICLV
	11/02/90	11/03/90		ALBINA	(CHM) CHECK LIGHTS RADIO AND HEATERS	TP
				ALBINA	(CHM) CHECK LOAD AND DIRECTION	TP
				ALBINA	(CHM) TEST SANDERS	TP
				ALBINA	(JJM) CHANGE WORN BRAKE SHOES AND ADJUST TRAVEL	TP
				ALBINA	(JJM) CHECK FLUID LEVELS	TP
				ALBINA	(JJM) CHECK HORN BELL AND WIPERS	TP
				ALBINA	(JJM) INSPECT UNIT FOR DEFECTS	TP
				ALBINA	(JJM) TEST AIR BRAKES	TP
				ALBINA	(KMG) CLEAN AND SUPPLY CAB	TP
	11/07/90	11/13/90		ALBINA	BOTTOM WINDOW BEARINGS REPLACED	TPIC
				ALBINA	(JMC) SLIDING CAB WINDOWS HAD BOTTOM TRACK REPLACED &	TPIC
	11/17/90	11/19/90		ALBINA	(KWE) REPAIR CAB ENGR'S MAIN CAB HEATER (NO HEAT ON LOW)	LULV
				ALBINA	(KWE) REPLACE WIPER BLADES.	LULV
				ALBINA	(YKK) REPAIR REAR HEADLIGHTS.	LULV
	11/19/90	11/20/90		ALBINA	(KWE/YKK) CHANGE OUT CARBODY & BLOWER FILTER'S.	MMWA
				ALBINA	(KWE) CHANGE OUT FUEL FILTER'S.	MMWA
				ALBINA	(KWE) EX. MANIFOLD PLUGS CLEANED (REAR MAINFOLD CLEANED OUT OK.	MMWA
				ALBINA	(WRR) WASH UNIT.	MMWA
				ALBINA	FRONT MANIFOLD PLUGGED ABLE TO GET ABOUT 5" UP CLEAN OUT PORT)	MMWA
	11/22/90	11/24/90		ALBINA	(CHM) (JJM) REPAIR DEFECTS ON ENGR'S REPT.	TP
				ALBINA	(CHM) CHECK LIGHTS RADIO HEATERS AND REFER	TP
				ALBINA	(JJM) CHANGE WORN BRAKE SHOES AND ADJUST TRAVEL	TP
				ALBINA	(JJM) CHECK FLUID LEVELS	TP
				ALBINA	(KMG) CLEAN AND SUPPLY CAB	TP
	11/29/90	11/30/90		ALBINA	(JLM) ENGR'S SEAT WON'T TURN FREE.	TPIC
	12/08/90	12/08/90		ALBINA	(CHM) CHANGE 2 GAGE LIGHTS	LU
				ALBINA	(CHM) CHECK LIGHTS RADIO HEATERS AND REFER	LU
				ALBINA	(CHM) CHECK LOAD SPEEDS AND DIRECTION	LU
				ALBINA	(CHM) CLEAN AND SUPPLY CAB	LU
				ALBINA	(DEB) ADD GOV. OIL	LU
				ALBINA	(DEB) CHANGE WORN BRAKE SHOES AND ADJUST TRAVEL	LU
				ALBINA	(DEB) CHECK FLUID LEVELS	LU
				ALBINA	(DEB) CHECK HORN BELL AND WIPERS	LU
				ALBINA	(DEB) DO LU (TAKE LUBE OIL SAMPLE)	LU
				ALBINA	(KMG) SAND AND FUEL UNIT	LU
				ALBINA	(TLH) CLEAN WINDOWS AND SAND	LU
	12/19/90	12/28/90		ALBINA	STOCK.	PISHMASNTKICSI
				ALBINA	(JLB) CHANGED OIL FILTERS; FUEL FILTERS; AIR COMPRESSOR AIR	PISHMASNTKICSI
				ALBINA	(JLB) CHECKED AIR COMPRESSOR GOVERNOR PSI. SETTING.	PISHMASNTKICSI
				ALBINA	(JLB) CHECKED ALL FLUID LEVELS.	PISHMASNTKICSI
				ALBINA	(JLB) CHECKED CONDITION OF CRANKCASE AND PEE PIPES.	PISHMASNTKICSI
				ALBINA	(JLB) CHECKED CONDITION OF PISTON AND LINERS.	PISHMASNTKICSI

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
OMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE DATE MO DA YR	LOCATION	DETAIL	WORK CODES
UP 001307	12/19/90	12/28/90		ALBINA	(JLB) CHECKED CONDITION OF RADITION COOLING FAN BELTS.	PISHWASNTKICSI
				ALBINA	(JLB) CHECKED MANUALLY OPERATION OF SHUTTERS.	PISHWASNTKICSI
				ALBINA	(JLB) CHECKED OPERATION OF BELL; HORN; WINDSHEILD WIPERS.	PISHWASNTKICSI
				ALBINA	(JLB) CHECKED OPERATION OF CAB DOOR LATCHES.	PISHWASNTKICSI
				ALBINA	(JLB) CHECKED OPERATION OF ENG. COP. SWITCH.	PISHWASNTKICSI
				ALBINA	(JLB) CHECKED OPERATION OF FUEL CUT OFF VALVE.	PISHWASNTKICSI
				ALBINA	(JLB) CHECKED OPERATION OF M. U. HOSES AND VALVES.	PISHWASNTKICSI
				ALBINA	(JLB) CHECKED OPERATION OF SAND TRAPES AND HOSES.	PISHWASNTKICSI
				ALBINA	(JLB) CHECKED THAT THIS UNIT HAS A FULL FIRST AID KIT.	PISHWASNTKICSI
				ALBINA	(JLB) CLEANED AND CHEAKED OPERATION OF ALL SANDERS.	PISHWASNTKICSI
				ALBINA	(JLB) CLEANED AND SUPPLIED CAB.	PISHWASNTKICSI
				ALBINA	(JLB) CLEANED FUEL SIGHT GLASSES.	PISHWASNTKICSI
				ALBINA	(JLB) CLEANED OIL SUCTION STRAINERS AND CHEAKED O-RINGS	PISHWASNTKICSI
				ALBINA	(JLB) ENG. WATER; LUBE OIL; AIR COMPRESSOR OIL SAMPLES TAKEN.	PISHWASNTKICSI
				ALBINA	(JLB) GREASED COOLING FAN JACK SHAFT.	PISHWASNTKICSI
				ALBINA	(JLB) INSPECTED BUCKEYE FUEL FILLER AND VENT HOSE.	PISHWASNTKICSI
				ALBINA	(JLB) INSPECTED CYLINDER HEAD MECHANISM.	PISHWASNTKICSI
				ALBINA	(JLB) INSPECTED FUEL SYSTEM WITH FUEL PUMP RUNNING FOR LEAKES.	PISHWASNTKICSI
				ALBINA	(JLB) LUBRICATED TRIPOD SEAT TUBE.	PISHWASNTKICSI
				ALBINA	(JLB) LUBRICATED AND CHEAKED OPERATION OF THE HAND BRAKE.	PISHWASNTKICSI
				ALBINA	(JLB) MODIFIED FLOOR AND INSTALLED (ATCS) (OBT) BRACKET.	PISHWASNTKICSI
				ALBINA	(JLB) REMOVED P2A VALVE AND BLEW MOISTURE FROM AIR SYSTEM.	PISHWASNTKICSI
				ALBINA	(JLB) STEAM CLEANED ENG. AND AIR COMPRESSOR ROOMS.	PISHWASNTKICSI
				ALBINA	(JLB) UNPLUGGED AIR COMPRESSOR ROOM DRAIN.	PISHWASNTKICSI
				ALBINA	(JLB) (LDS) TEST AND CARD.	PISHWASNTKICSI
				ALBINA	(KAR) CHECKED ALL SMALL MOTORS	PISHWASNTKICSI
				ALBINA	(KAR) CHECKED AUX. GEN. BRUSHES	PISHWASNTKICSI
				ALBINA	(KAR) CHECKED HIGH AND LOW VOLTAGES FOR GRNDS.	PISHWASNTKICSI
				ALBINA	(KAR) CHECKED HIGH VOLTAGE CAB.	PISHWASNTKICSI
				ALBINA	(KAR) CHECKED MAIN GEN. AND REPLACED SOME BRUSHES SPRINGS	PISHWASNTKICSI
				ALBINA	(KAR) CHECKED WHEEL SLIP SYSTEMS	PISHWASNTKICSI
				ALBINA	(KAR) TESTED ALARM SYTEMS	PISHWASNTKICSI
				ALBINA	(KAR) WASHED AND FILLED BATT. WITH WATER	PISHWASNTKICSI
				ALBINA	(KAR) WORKED ALL LIGHTS	PISHWASNTKICSI
				ALBINA	(KAR) WORKED TRACTION MOTORS	PISHWASNTKICSI
				ALBINA	(KAR) TESTED RADIO	PISHWASNTKICSI
				ALBINA	(LJM) CHANGED CAR BODY AIR FILTERS; NO BLOWER AIR FILTERSIN	PISHWASNTKICSI
				ALBINA	(LJM) CHANGED WORN BRAKE SHOES AND ADJUSTED PISTON TRAVEL.	PISHWASNTKICSI
				ALBINA	(LJM) GREASED COUPLER SHANKS.	PISHWASNTKICSI
				ALBINA	FILTER.	PISHWASNTKICSI
	01/01/91	01/02/91		ALBINA	(CHM) CHECK LIGHTS RADIO HEATERS AND REFER	LU
				ALBINA	(CHM) REPAIR WARNING LIGHT	LU
				ALBINA	(DEB) CHANGE WORN BRAKE SHOES AND ADJUST TRAVEL	LU
				ALBINA	(DEB) CHECK FLUID LEVELS	LU
				ALBINA	(DEB) DO LU (TAKE LUBE OIL SAMPLE)	LU
				ALBINA	(LDS) CLEAN AND SUPPLY CAB	LU

000053

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
QMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE DATE MO DA YR	LOCATION	DETAIL	WORK CODES
UP 001307	01/12/91	01/14/91		ALBINA	(DGR) CHANGED WORN BRAKE SHOES AND ADJUSTED PISTON TRAVEL	RMSN
				ALBINA	(DGR) CHECKED ALL FLUID LEVELS	RMSN
				ALBINA	(DGR) CHECKED HORN, BELL, WIPERS AND SANDERS	RMSN
				ALBINA	(DGR) CLEANED AND SUPPLIED CAB	RMSN
				ALBINA	(DGR) REPLACED COPPER AIR PIPE FOR L-1 SAND TRAP	RMSN
	01/14/91	01/15/91		ALBINA	(JJM) ADDED 10" OF ENGINE OIL	TPDE
				ALBINA	(JJM) APPLIED NEW RESERVOIR BLOW DOWNS R & L SIDES	TPDE
				ALBINA	(JJM) CHANGED FRONT MR HOSE	TPDE
				ALBINA	(JJM) CHANGED OUT 3 BRAKE SHOES AND ADJUSTED	TPDE
				ALBINA	(JJM) CLEANED AND SUPPLIED CAB	TPDE
				ALBINA	(JJM) REMOVED APPROX. 20 GALS WATER CONDIN. FROM MR'S	TPDE
				ALBINA	(JJM) REMOVED BOTH 1&2 MAIN RES. AUTO BLOW DOWNS	TPDE
	01/21/91	01/24/91		ALBINA	(DGR) REPAIRED RIGHT FRONT BRAKE HEAD	LUELRV
				ALBINA	(KAR) CHANGED RVF CONTACTOR ACCOUNT OF BURNT CONTACTOR	LUELRV
				ALBINA	(KAR) 050A REMOVED WARNING LIGHT	LUELRV
	01/30/91	01/30/91		ALBINA	(JLB) CHANGED WORN OUT BRAKE SHOES; ADJUSTED PISTON TRAVEL	TP
				ALBINA	(JLB) CHECKED ALL FLUID LEVELS.	TP
				ALBINA	(JLB) CLEANED AND SUPPLIED CAB; ALSO WASHED WINDOWS.	TP
				ALBINA	(JLB) TESTED HORN; BELL; WIPERS; AND SANDERS.	TP
				ALBINA	(KAR) CHECKED ALL LIGHTS; ALSO ENG. SPEEDS LOAD FORWARD AND REVERSE.	TP
	02/02/91	02/03/91		ALBINA	(CHM) CHECKED FRIG, HEATERS, LIGHTS, ENGINE SPEEDS AND DIRECTIONAL	TP
				ALBINA	(CHM) REPLACED ENGINE ROOM LIGHTS	TP
				ALBINA	(CHM) REPLACED FUSE TEST LIGHT	TP
				ALBINA	(CHM) REPLACED LEFT GROUND LIGHT	TP
				ALBINA	(CHM) REPLACED RIGHT NUMBER LIGHTS	TP
				ALBINA	(DGR) ADDED AIR COMPRESSOR OIL	TP
				ALBINA	(DGR) CHANGED WORN BRAKE SHOES AND ADJUSTED PISTON TRAVEL	TP
				ALBINA	(DGR) CHECKED ALL FLUID LEVELS	TP
				ALBINA	(DGR) CHECKED SANDERS, HORN, BELL, AND WIPERS	TP
				ALBINA	(DGR) UNPLUGGED FRONT AND REAR SANDERS	TP
				ALBINA	(LKRO) CLEANED AND SUPPLIED CAB	TP
	02/07/91	02/08/91		ALBINA	() CHANGE OUT BAGGIE AIR FILTER'S**N.O.H.**	NM
				ALBINA	() CHANGE OUT FUEL FILTER'S**N.O.H.**	NM
				ALBINA	(JLM) CHANGE OUT CARBODY FILTER'S	NM
	02/19/91	02/19/91		ALBINA	(DGR) CHANGED BAGGIE TYPE AIR FILTERS	LU
				ALBINA	(DGR) CHANGED SPIN ON FUEL FILTERS	LU
				ALBINA	(DGR) CHANGED WORN BRAKE SHOES AND ADJUSTED PISTON TRAVEL	LU
				ALBINA	(DGR) CHECKED ALL FLUID LEVELS	LU
				ALBINA	(DGR) CLEANED AND SUPPLIED CAB	LU
				ALBINA	(DGR) TESTED SANDERS, BELL, WIPERS AND HORN	LU
				ALBINA	(DGR) TOOK LUBE OIL SAMPLE	LU
	02/26/91	02/26/91		ALBINA	(DGR) REPLACED LT#1 BRAKE STRAPS AND SLACK ADJUSTER.	TKTP
				ALBINA	(JLB) CLEANED AND SUPPLIED CAB.	TKTP
				ALBINA	(JLB) REPLACED RT. #2 BRAKE HEAD, AND BRAKE STRAPS ALSO REPLACED	TKTP
				ALBINA	(JLB) (DGR) CHANGED WORN BRAKE SHOES, ADJUSTED PISTON TRAVEL	TKTP

000054

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
QHNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE DATE	LOCATION	DETAIL	WORK CODES
UP 001307	02/26/91	02/26/91		ALBINA	(JLB)(DGR) CHECKED ALL FLUID LEVELS, ADDED 100 GALS. LUBE OIL.	TKTP
				ALBINA	(JLB)(DGR) TESTED HORN, BELL, WIPERS AND SANDERS.	TKTP
				ALBINA	SLACK ADJUSTER.	TKTP
	03/02/91	03/03/91		ALBINA	(CMH) CHANGE ALL NUMBER LIGHT BULBS	TP
				ALBINA	(CMH) CHECK LIGHTS RADIO HEATERS AND REFER	TP
				ALBINA	(CMH) CHECK LOAD SPEEDS AND DIRECTION	TP
				ALBINA	(DGR) CHANGE WORN BRAKE SHOES AND ADJUST TRAVEL	TP
				ALBINA	(DGR) CHECK FLUID LEVELS	TP
				ALBINA	(DGR) CHECK HORN BELL AND WIPERS	TP
				ALBINA	(DGR) TEST SANDERS	TP
				ALBINA	(LKR) CLEAN AND SUPPLY CAB	TP
	03/07/91	03/07/91		ALBINA	(DEB) CHANGE ALL BRAKE SHOES AND ADJUST TRAVEL	TPRM
				ALBINA	(DEB) CHECK FLUID LEVELS	TPRM
				ALBINA	(JHM) REPLACE CAB FIRE EXT.	TPRM
				ALBINA	(KMG) CLEAN AND SUPPLY CAB	TPRM
				ALBINA	(YKK) CHECK LIGHTS RADIO HEATERS AND REFER	TPRM
				ALBINA	(YKK) REPLACE FRONT HEADLIGHT BULB	TPRM
	03/12/91	03/12/91		ALBINA	(DGR) CHANGED ALL WORN BRAKE SHOES AND ADJUSTED PISTON TRAVEL	LURN
				ALBINA	(DGR) CHECKED ALL FLUID LEVELS	LURN
				ALBINA	(DGR) CHECKED SANDERS, BELL, HORN AND WIPERS	LURN
				ALBINA	(DGR) REPLACED BROKEN #4 REAR RIGHT SAND TRAP	LURN
				ALBINA	(DGR) TOOK LUBE OIL SAMPLE	LURN
	03/15/91	03/15/91		ALBINA	(KWE/MRR) WASH CARBODY.	TPMWRM
				ALBINA	(JLB) CHANGED WORN BRAKE SHOES, ADJUSTED PISTON TRAVEL	TPMWRM
				ALBINA	(JLB) CHECKED ALL FLUID LEVELS.	TPMWRM
				ALBINA	(JLB) CLEANED AND SUPPLIED CAB.	TPMWRM
				ALBINA	(JLB) TESTED HORN, BELL, WIPERS AND SANDERS.	TPMWRM
	03/21/91	03/21/91		ALBINA	(JLM) CHANGE WORN BRAKE SHOES AND ADJUST TRAVEL	TPRM
				ALBINA	(JLM) CHECK FLUID LEVELS	TPRM
				ALBINA	(JLM) CHECK HORN BELL AND WIPERS	TPRM
				ALBINA	(JLM)(YKK) CLEAN AND SUPPLY CAB	TPRM
				ALBINA	(KMG) SAND AND FUEL UNIT	TPRM
				ALBINA	(YKK) CHECK LIGHTS RADIO HEATERS AND REFER	TPRM
				ALBINA	(YKK) CHECK LOAD SPEEDS AND DIRECTION	TPRM
	03/30/91	04/03/91		ALBINA	(CMH) REPLACED HEATER MOTOR FIREMANS SIDE	PIQHRMLUMASNTKIC
				ALBINA	(DGR) APPLIED NEW CREW PACK HOLDER IN CAB	PIQHRMLUMASNTKIC
				ALBINA	(DGR) CARDED UNIT	PIQHRMLUMASNTKIC
				ALBINA	(DGR) CHANGED ALL BRAKE SHOES AND ADJUSTED PISTON TRAVELS	PIQHRMLUMASNTKIC
				ALBINA	(DGR) CHANGED BAG TYPE AIR FILTERS	PIQHRMLUMASNTKIC
				ALBINA	(DGR) CHANGED CAR BODY AIR FILTERS	PIQHRMLUMASNTKIC
				ALBINA	(DGR) CHANGED FUEL SPIN ON FILTERS	PIQHRMLUMASNTKIC
				ALBINA	(DGR) CHANGED LUBE OIL FILTERS	PIQHRMLUMASNTKIC
				ALBINA	(DGR) CHECKED ALL FLUID LEVELS	PIQHRMLUMASNTKIC
				ALBINA	(DGR) CHECKED COUPLER HEIGHTS	PIQHRMLUMASNTKIC
				ALBINA	(DGR) CHECKED FAN BELT TENSIONS AND CONDITIONS	PIQHRMLUMASNTKIC
				ALBINA	(DGR) CHECKED SIDE BEARING CLEARANCES	PIQHRMLUMASNTKIC

000050

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
OMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE DATE	LOCATION	DETAIL	WORK CODES
UP 001307	03/30/91	04/03/91		ALBINA	(DGR) CHECKED SNOW FLOW HEIGHT CLEARANCES	PIQHRMLUMASNTKIC
				ALBINA	(DGR) CLEANED AND SUPPLIED CAB	PIQHRMLUMASNTKIC
				ALBINA	(DGR) CLEANED FUEL SIGHT GLASSES	PIQHRMLUMASNTKIC
				ALBINA	(DGR) GREASED COUPLER SHANK WEAR PLATES	PIQHRMLUMASNTKIC
				ALBINA	(DGR) GREASED FAN BEARINGS	PIQHRMLUMASNTKIC
				ALBINA	(DGR) INSPECTED SAND TRAPS AND PIPING FOR HOLES AND DEFECTS	PIQHRMLUMASNTKIC
				ALBINA	(DGR) LUBRICATED ALL DOOR HINGES AND LATCHES	PIQHRMLUMASNTKIC
				ALBINA	(DGR) LUBRICATED TRIPOD SEAT POST AND PIVOTS	PIQHRMLUMASNTKIC
				ALBINA	(DGR) MADE VISUAL INSPECTION OF BUCKEYE FUEL FILLER VENT HOSE	PIQHRMLUMASNTKIC
				ALBINA	(DGR) REPLACED MR HOSE ON REAR LEFT	PIQHRMLUMASNTKIC
				ALBINA	(DGR) STEAM CLEANED CAR BODY, TRUCKS AND ENGINE COMPARTMENT	PIQHRMLUMASNTKIC
				ALBINA	(DGR) TESTED SANDERS, BELL, AND WIPERS	PIQHRMLUMASNTKIC
				ALBINA	(DGR) TOOK LUBE OIL, WATER AND AIR COMPRESSOR OIL SAMPLE	PIQHRMLUMASNTKIC
				ALBINA	(KAR) CHECKED ALARM BELL AND ALARM SYSTEMS	PIQHRMLUMASNTKIC
				ALBINA	(KAR) CHECKED CHARGING CIRCUIT AUX. GEN.	PIQHRMLUMASNTKIC
				ALBINA	(KAR) CHECKED GRND. RELAY	PIQHRMLUMASNTKIC
				ALBINA	(KAR) CHECKED HIGH VOLTAGE AND LOW VOLTAGE GRNDS.	PIQHRMLUMASNTKIC
				ALBINA	(KAR) CHECKED HIGH VOLTAGE EQUIP. AND CAB.	PIQHRMLUMASNTKIC
				ALBINA	(KAR) CHECKED LIGHTS	PIQHRMLUMASNTKIC
				ALBINA	(KAR) CHECKED MAIN GEN. AND AUX. GEN.	PIQHRMLUMASNTKIC
				ALBINA	(KAR) CHECKED RADIO AND ANTENNA	PIQHRMLUMASNTKIC
				ALBINA	(KAR) CHECKED WHEEL SLIP SYSTEMS	PIQHRMLUMASNTKIC
				ALBINA	(KAR) CLEANED CAB WINDOWS	PIQHRMLUMASNTKIC
				ALBINA	(KAR) WASHED AND FILLED BATT. WITH WATER , GREASED BATT. TERMS.	PIQHRMLUMASNTKIC
				ALBINA	(KAR) WORKED ALL SMALL MOTORS	PIQHRMLUMASNTKIC
				ALBINA	(KAR) WORKED TRACTION MOTORS	PIQHRMLUMASNTKIC
				ALBINA	(KAR) TEST AND CARDED	PIQHRMLUMASNTKIC
	04/08/91	04/08/91		ALBINA	(JLB) CHANGED WORN BRAKE SHOES, ADJUSTED PISTON TRAVEL	TP
				ALBINA	(JLB) CHECKED ALL FLUID LEVELS.	TP
				ALBINA	(JLB) TESTED HORN, BELL, WIPERS AND SANDERS.	TP
	04/14/91	04/14/91		ALBINA	(CHH) CHECK LIGHTS RADIO HEATERS AND REFER	TP
				ALBINA	(CHH) CHECK LOAD SPEED AND DIRECTION	TP
				ALBINA	(DGR) CHANGE WORN BRAKE SHOES AND ADJUST TRAVEL	TP
				ALBINA	(DGR) CHECK FLUID LEVELS	TP
				ALBINA	(DGR) CHECK HORN BELL AND WIPERS	TP
				ALBINA	(DGR) TEST SANDERS	TP
				ALBINA	(LKR) CLEAN AND SUPPLY CAB	TP
	04/29/91	04/30/91		ALBINA	(KWE) P CONTACTOR BURNT UP.	HURV
				ALBINA	(KWE) START & CHECK.	HURV
	05/08/91	05/09/91		ALBINA	(DEB) CHANGE WORN BRAKE SHOES AND ADJUST TRAVEL	TP
				ALBINA	(DEB) CHECK FLUID LEVELS	TP
				ALBINA	(DEB) CHECK HORN BELL AND WIPERS	TP
				ALBINA	(DEB) CHECK LIGHTS RADIO HEATERS AND REFER	TP
				ALBINA	(DEB) CHECK LOAD SPEEDS AND DIRECTION	TP
				ALBINA	(DEB) CHECK SANDERS	TP
				ALBINA	(DEB) REPLACE L. #2 PEDESTAL LINER BOLTS	TP

000056

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
OMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE DATE MO DA YR	LOCATION	DETAIL	WORK CODES
UP 001307	05/08/91	05/09/91		ALBINA	(DEB) REPLACE R. FRONT M. RES. HOSE	TP
				ALBINA	(DEB) REPLACE 1 FRONT AND 1 REAR HEADLIGHT BULB	TP
	05/18/91	05/18/91		ALBINA	(CMH) CHECK LIGHTS RADIO HEATERS AND REFER	RHMHU
				ALBINA	(CMH) CHECK LOAD SPEEDS AND DIRECTION	RHMHU
				ALBINA	(CMH) CLEAN AND SUPPLY CAB	RHMHU
				ALBINA	(CMH) FILLED BATTERIES ACCT. LOW	RHMHU
				ALBINA	(DEB) CHANGE WORN BRAKE SHOES AND ADJUST TRAVEL	RHMHU
				ALBINA	(DEB) CHECK FLUID LEVELS	RHMHU
				ALBINA	(DEB) CHECK HORN BELL AND WIPERS	RHMHU
				ALBINA	(DEB) CHECK SANDERS (NOTE RM)	RHMHU
				ALBINA	(DEB) DO LU (TAKE LUBE OIL SAMPLE)	RHMHU
				ALBINA	(DEB) DO MH	RHMHU
	06/15/91	06/20/91		SALLAKCIT	TRANSFONDER TAGS	TIRHEWALTWC
				SALLAKCIT	MOUNTING HEIGHT DOES NOT EXCEED 32 INCHES ABOVE CAB FLOOR	TIRHEWALTWC
				SALLAKCIT	(***SPECIAL (049-***)) END/GE MONTEROZATION MOD	TIRHEWALTWC
				SALLAKCIT	(BK)*RM* 05/18/91 DP500 FRONT TRUCK L REAR SANDER NEEDS OVERHAUL	TIRHEWALTWC
				SALLAKCIT	(BK)*RM* 06/11/91 DP500 BATTERIES BO, BATTERIES BOX CHECKT OUT OK	TIRHEWALTWC
				SALLAKCIT	(BK)*ST* ENGINE DEAD	TIRHEWALTWC
				SALLAKCIT	(BK)*TI* DUE INSPECTION 06/14/91	TIRHEWALTWC
				SALLAKCIT	(BK)*SPECIAL (029A-***)) APPLY TWO AUTOMATIC EQUIPMENT ID (AED)	TIRHEWALTWC
				SALLAKCIT	(BK)*TEST & CARD CARD 06/17/91	TIRHEWALTWC
				SALLAKCIT	(BK)*WORK ELECT INBOUND INSP	TIRHEWALTWC
				SALLAKCIT	(BK)*WORK MACH INBOUND INSP	TIRHEWALTWC
				SALLAKCIT	(GMD)TAKE & ENTER WHEEL SIZES	TIRHEWALTWC
				SALLAKCIT	(JEA)C/O (#1-JEA)(#3-JEA)(#4-JEA) WHEELS(HIGH FLANGES)	TIRHEWALTWC
				SALLAKCIT	(JRM)C/O #2 WHEEL & SAVE (HIGH FLANGE ALSO)	TIRHEWALTWC
				SALLAKCIT	(OK)*SPECIAL (060A-***)) INSPECT ATCS PHOENIX CONNECTOR AND INSURE	TIRHEWALTWC
				SALLAKCIT	(PDB) INBOUND PROCESS	TIRHEWALTWC
				SALLAKCIT	(PIT)*ST* NO ENGINEER REPORT FOUND	TIRHEWALTWC
				SALLAKCIT	(REW)W/TMS	TIRHEWALTWC
				SALLAKCIT	(REW)WASH/CLEAN CAB	TIRHEWALTWC
				SALLAKCIT	HELD 06/15/91 DUE TI 06/14/91	TRACK OS TIRHEWALTWC
	07/02/91	07/03/91		ALBINA	(DGR) CHANGED WORN BRAKE SHOES AND ADJUSTED PISTON TRAVEL	TP
				ALBINA	(DGR) CHECKED ALL FLUID LEVELS	TP
				ALBINA	(DGR) CLEANED AND SUPPLIED CAB	TP
	07/14/91	07/15/91		ALBINA	() CLEANED AND SUPPLIED CAB.	TPRM
				ALBINA	(JLB) CHANGED WORN BRAKE SHOES, ADJUSTED PISTON TRAVEL	TPRM
				ALBINA	(JLB) CHECKED ALL FLUID LEVELS, ADDED 50 GALS. ENG. WATER.	TPRM
				ALBINA	(JLB) TESTED HORN, BELL, WIPERS AND SANDERS.	TPRM
	07/17/91	07/23/91		ALBINA	(KAR) BATTERIES REPLACED ACCT. BO—BOTH SIDES	BARM
	07/25/91	08/06/91		ALBINA	(DGR)(KAR) REPLACED LARGE SECTION RADIATOR CORE LEFT FRONT	RD
	08/23/91	08/23/91		ALBINA	(DEB) CHANGE WORN BRAKE SHOES AND ADJUST TRAVEL	TP
				ALBINA	(DEB) CHECK HORN BELL AND WIPERS	TP
				ALBINA	(DEB) CHECK LIGHTS RADIO & REFER	TP
				ALBINA	(DEB) CHECK LOAD SPEEDS AND DIRECTION	TP
				ALBINA	(KMG) CHECK FLUID LEVELS (ADD ENGINE OIL)	TP

000037

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
OHNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE DATE MO DA YR	LOCATION	DETAIL	WORK CODES			
UP 001307	08/23/91	08/23/91	08/23/91	ALBINA	(KMG) CLEAN AND SUPPLY CAB	TP			
				08/27/91	08/28/91	ALBINA	(CMH) CHANGE 7 GAUGE LIGHT BULBS	TP	
	09/07/91	09/09/91		ALBINA	(CMH) CHECK LIGHTS RADIO HEATERS AND REFER	TP			
				ALBINA	(DEB) CHANGE WORN BRAKE SHOES AND ADJUST TRAVEL	TP			
				ALBINA	(DEB) CHECK FLUID LEVELS	TP			
				ALBINA	(WRH) (CMH) MAKE OUTBOUND TESTS	TP			
				ALBINA	(WRH) CHECK HORN BELL AND WIPERS	TP			
				ALBINA	(WRR) CLEAN AND SUPPLY CAB	TP			
				ALBINA	(KME) REPT. OBT BAD ORDER.	TPFFLU			
				ALBINA	(B-H) FUEL FILTERS CHG'D ACCT. LIGHT LOAD	TPFFLU			
				ALBINA	(B-H) LU COMPLETED & OIL SMP. TAKEN	TPFFLU			
				09/17/91	09/20/91		ALBINA	(JJM) ADDED WATER TREATMENT CONCENTRATE	PIGMSNTKICWA
	ALBINA	(JJM) CHANGED BAG TYPE AIR INTAKE FILTERS(ONE ON EACH SIDE N.I.S)	PIGMSNTKICWA						
	ALBINA	(JJM) CHANGED LUBE OIL FILTERS	PIGMSNTKICWA						
	ALBINA	(JJM) CHANGED OUT CARBODY FILTERS	PIGMSNTKICWA						
	ALBINA	(JJM) CHANGED OUT COMPRESSOR AIR INTAKE FILTERS	PIGMSNTKICWA						
	ALBINA	(JJM) CHANGED OUT FUEL FILTERS	PIGMSNTKICWA						
	ALBINA	(JJM) CHECK OPERATION AND LUBE CAB DOOR LATCHES	PIGMSNTKICWA						
	ALBINA	(JJM) CHECKED AND REPAIRED MU AIR HOSES	PIGMSNTKICWA						
	ALBINA	(JJM) CHECKED AUTO AND INDEPENDENT PIPING	PIGMSNTKICWA						
	ALBINA	(JJM) CHECKED BELTS AND TENSION	PIGMSNTKICWA						
	ALBINA	(JJM) CHECKED BUCKEYE FUEL FILL	PIGMSNTKICWA						
	ALBINA	(JJM) CHECKED FIRST AID KIT	PIGMSNTKICWA						
	ALBINA	(JJM) CLEANED AND SUPPLIED CAB	PIGMSNTKICWA						
	ALBINA	(JJM) GREASE COUPLER SHANK WEAR PLATE	PIGMSNTKICWA						
	ALBINA	(JJM) INSPECTED SAND TRAPS	PIGMSNTKICWA						
	ALBINA	(JJM) OUT BOUND CHECKS	PIGMSNTKICWA						
	ALBINA	(JJM) REPAIRED FIREMANS SEAT,LUBE SEAT SUPPORT	PIGMSNTKICWA						
	ALBINA	(JJM) TOOK COMPRESSOR, ENGINE OIL, AND WATER SAMPLES	PIGMSNTKICWA						
	ALBINA	(KAR) CHECK OPERATION OF WHEEL SLIP	PIGMSNTKICWA						
	ALBINA	(KAR) CHECKED ALARM BELL AND ALARM SYSTEMS	PIGMSNTKICWA						
	ALBINA	(KAR) CHECKED ALL LIGHTS	PIGMSNTKICWA						
	ALBINA	(KAR) CHECKED HIGH AND LOW VOLTAGE GRNDS.	PIGMSNTKICWA						
	ALBINA	(KAR) CHECKED HIGH CAB. AND EQUIP.	PIGMSNTKICWA						
	ALBINA	(KAR) CHECKED OPERATION OF WHEEL SLIP	PIGMSNTKICWA						
	ALBINA	(KAR) CHECKED RADIO AND ANTENNA	PIGMSNTKICWA						
	ALBINA	(KAR) CHECKED REV. FOR OPERATION	PIGMSNTKICWA						
	ALBINA	(KAR) CHECKED TH BRUSHES	PIGMSNTKICWA						
	ALBINA	(KAR) INSPECT MAIN GEN.	PIGMSNTKICWA						
	ALBINA	(KAR) OUT BOUND CHECKS	PIGMSNTKICWA						
	ALBINA	(KAR) WASHED AND FILLED BATT. WITH WATER	PIGMSNTKICWA						
	ALBINA	(KAR) WORKED TRACTION MOTORS	PIGMSNTKICWA						
	09/28/91	09/28/91					ALBINA	(CMH) CHECKED LIGHTS, HEATERS, FRIDGE, ECT.	LU
							ALBINA	(JJM) ADDED GEAR GREASE TO TH GEAR CASES	LU
							ALBINA	(JJM) CHANGED OUT AND ADJUSTED BRAKE SHOES	LU
				ALBINA	(JJM) CHECKED FLUID LEVELS	LU			

000038

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
OMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE DATE MO DA YR	LOCATION	DETAIL	WORK CODES
UP 001307	09/28/91	09/28/91		ALBINA	(JJM) CLEANED AND SUPPLIED CAB	LU
				ALBINA	(JJM) TOOK LUBE OIL SAMPLE	LU
	10/12/91	10/13/91		ALBINA	(CHM) CHECK LIGHTS RADIO HEATERS AND REFER	TP
				ALBINA	(DGR) CHANGE WORN BRAKE SHOES AND ADJUST TRAVEL	TP
				ALBINA	(DGR) CHECK FLUID LEVELS	TP
				ALBINA	(DGR) INSPECT UNIT	TP
	10/19/91	10/20/91		ALBINA	(CHM) CHECK LIGHTS RADIO HEATERS AND REFER	LU
				ALBINA	(CHM) CHECK LOAD SPEEDS AND DIRECTION	LU
				ALBINA	(DEB) CLEAN AND SUPPLY CAB	LU
				ALBINA	(WRH) CHANGE WORN BRAKE SHOES AND ADJUST TRAVEL	LU
				ALBINA	(WRH) CHECK FLUID LEVELS	LU
				ALBINA	(WRH) CHECK HORN BELL AND WIPERS	LU
				ALBINA	(WRH) DO LU (TAKE LUBE OIL SAMPLE)	LU
				ALBINA	(WRH) TEST SANDERS	LU
	10/26/91	10/27/91		ALBINA	(CHM) CHECKED ALL LIGHTS	TP
				ALBINA	(CHM) TESTED RADIO	TP
				ALBINA	(CHM) CHECKED FRIG.	TP
				ALBINA	(LKR) CLEANED RESUPPLIED CAB	TP
				ALBINA	(WRH) CHECKED ADJUSTED CHANGED BRAKE SHOES	TP
				ALBINA	(WRH) CHECKED FLUID LEVELS	TP
	10/31/91	11/01/91		ALBINA	(JLB) CHANGED WORN BRAKE, ADJUSTED PISTON TRAVEL	HMTF
				ALBINA	(JLB) CHECKED ALL FLUID LEVELS.	HMTF
				ALBINA	(JLB) CLEANED AND SUPPLIED CAB.	HMTF
				ALBINA	(JLB) FASTENED ENG. SEAT TO PEDESTAL BRACKET.	HMTF
				ALBINA	(JLB) TESTED HORN, BELL, WIPERS AND SANDERS.	HMTF
				ALBINA	(JLB) WORKED (LUB OIL SAMPLE TAKEN	HMTF
				ALBINA	(JLB) WORKED (MHO), CHANGED CAR BODY AND BAGGIE AIR FILTERS.	HMTF
	11/08/91	11/08/91		ALBINA	(JJM) CHANGED OUT ENGINEERS SEAT	SVTP
				ALBINA	(JJM) CHANGED OUT FIREMANS BROKEN WINDOW	SVTP
				ALBINA	(JJM) CHECKED ALL FLUID LEVELS.	SVTP
				ALBINA	(JJM) REPAIRED AWNING	SVTP
				ALBINA	(JJM) REPAIRED REPORTED VIBRATING	SVTP
				ALBINA	(JLB) CHANGED WORN BRAKE SHOES, ADJUSTED PISTON TRAVELS.	SVTP
				ALBINA	(JLB) CHECKED ALL FLUID LEVELS.	SVTP
				ALBINA	(JLB) TESTED HORN, BELL, WIPERS AND SANDERS.	SVTP
				ALBINA	(TLH) LEANED AND SUPPLIED CAB.	SVTP
				ALBINA	(TLH) CLEANED AND SUPPLIED CAB.	SVTP
	11/22/91	11/22/91		ALBINA	(JLB) CHANGED WORN BRAKE SHOES, ADJUSTED PISTON TRAVEL.	TPSV
				ALBINA	(JLB) CHECKED ALL FLUID LEVELS.	TPSV
				ALBINA	(JLB) CLEANED AND SUPPLIED CAB.	TPSV
				ALBINA	(JLB) TESTED HORN, BELL, WIPERS AND SANDERS.	TPSV
	11/26/91	11/27/91		ALBINA	(DGR) CHANGED BRAKE SHOES AND ADJUSTED PISTON TRAVEL	TPSV
				ALBINA	(DGR) CHECKED ALL FLUID LEVELS	TPSV
				ALBINA	(DGR) CLEANED AND SUPPLIED CAB	TPSV
				ALBINA	(DGR) REPLACED FIREMANS SIDE CAB AWNING	TPSV
	12/08/91	12/10/91		ALBINA	(DGR) CHANGED WORN BRAKE SHOES AND ADJUSTED PISTON TRAVEL	LUTK

000039

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
OMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE DATE MO DA YR	LOCATION	DETAIL	WORK CODES
UP 001307	12/08/91	12/10/91		ALBINA	(DGR) CHECKED ALL FLUID LEVELS	LUTK
				ALBINA	(DGR) CLEANED AND SUPPLIED CAB	LUTK
				ALBINA	(DGR) TOOK LUBE OIL SAMPLE	LUTK
				ALBINA	(JLB) (DGR) CHANGED RGT #3 INSIDE BRAKE HEAD.	LUTK
	12/15/91	12/16/91		ALBINA	(CHM) CHECKED FRIG. AND RADIO	TPSV
				ALBINA	(CHM) REPLACE FIREMAN CAB LIGHT	TPSV
				ALBINA	(CHM) REPLACE LEFT-REAR HEADLIGHT	TPSV
				ALBINA	(CHM) TESTED ALL LIGHTS	TPSV
				ALBINA	(JLB) CHECKED ALL FLUID LEVELS.	TPSV
				ALBINA	(JLB) CLEANED AND SUPPLIED CAB.	TPSV
				ALBINA	(JLB) TESTED HORN, BELL, WIPERS AND SANDERS.	TPSV
				ALBINA	(JLB) (LJM) CHANGED WORN BRAKE SHOES, ADJUSTED PISTON TRAVEL.	TPSV
	12/20/91	01/07/92		ALBINA	(JJM) ADDED LUBRICANT TO CENTER CASTING SHIMS	PISMTKICRASNMA
				ALBINA	(JJM) BLEW OUT P2A AND PIPING TO REMOVE WATER, REAPPLIED P2A	PISMTKICRASNMA
				ALBINA	(JJM) CHANGED OUT BAGGI TYPE ENGINE AIR INTAKE FILTERS	PISMTKICRASNMA
				ALBINA	(JJM) CHANGED OUT CARBODY FILTERS	PISMTKICRASNMA
				ALBINA	(JJM) CHANGED OUT COMPRESSOR AIR INTAKE FILTERS	PISMTKICRASNMA
				ALBINA	(JJM) CHANGED OUT FUEL FILTERS	PISMTKICRASNMA
				ALBINA	(JJM) CHANGED OUT LUBE OIL FILTERS	PISMTKICRASNMA
				ALBINA	(JJM) CHECKED AND LUBED HANDBRAKE, AND APPLIED TAG.	PISMTKICRASNMA
				ALBINA	(JJM) DRAINED WATER FROM ENGINE, ADDED WATER TREATMENT CONC'NTRT	PISMTKICRASNMA
				ALBINA	(JJM) MACH. TEST & CARD	PISMTKICRASNMA
				ALBINA	(JJM) REMOVED P2A FOR WINTER TIME BLOW OUT	PISMTKICRASNMA
				ALBINA	(JJM) SANDER'S CLEANED & TESTED	PISMTKICRASNMA
				ALBINA	(KAR) CHECKED ALARMS BELL AND ALARM SYSTEMS	PISMTKICRASNMA
				ALBINA	(KAR) CHECKED ALL LIGHTS	PISMTKICRASNMA
				ALBINA	(KAR) CHECKED ALL SMALL MOTORS AND AUX. GEN. FOR BRUSHES	PISMTKICRASNMA
				ALBINA	(KAR) CHECKED AND CLEAN GEN. PIT	PISMTKICRASNMA
				ALBINA	(KAR) CHECKED HIGH AND LOW GRNDS.	PISMTKICRASNMA
				ALBINA	(KAR) CHECKED HIGH VOLTAGE CAB. AND EQUIP.	PISMTKICRASNMA
				ALBINA	(KAR) CHECKED OUT HEATER SIDEMALL	PISMTKICRASNMA
				ALBINA	(KAR) WASHED AND FILLED BATT. WITH WATER	PISMTKICRASNMA
				ALBINA	(KAR) WORKED MAIN GEN. AND REPLACED ALL BRUSHES	PISMTKICRASNMA
				ALBINA	(KAR) WORKED TRACTION MOTORS	PISMTKICRASNMA
				ALBINA	(LRS) ELECT. TEST & CARD	PISMTKICRASNMA
				ALBINA	(WRH) CHECKED FIRE EXTINGUISHERS	PISMTKICRASNMA
				ALBINA	(WRH) CHECKED AND LUBED TRIPOD MOUNT AND LUBED	PISMTKICRASNMA
				ALBINA	(WRH) CHECKED AND REPAIRED BUCKEYE FUEL FILLER AND VENT	PISMTKICRASNMA
				ALBINA	(WRH) CHECKED AND REPAIRED DOOR LATCHES	PISMTKICRASNMA
				ALBINA	(WRH) CHECKED FUEL INJECTORS AND FUEL LINES WITH BLACKLIGHT.	PISMTKICRASNMA
				ALBINA	(WRH) CHECKED FUEL TANK BOLTS FOR TIGHTNESS	PISMTKICRASNMA
				ALBINA	(WRH) CHECKED MU HOSES	PISMTKICRASNMA
				ALBINA	(WRH) COOLING SYSTEM AND FUEL PUMP RUNNING	PISMTKICRASNMA
				ALBINA	(WRH) GREASED COUPLER SHANK WEAR PLATE	PISMTKICRASNMA
				ALBINA	(WRH) INSPECTED BRAKE RIGGING, OVERRIDING BRAKE SHOES ECT.	PISMTKICRASNMA
				ALBINA	(WRH) INSPECTED PISTON RINGS, LINERS FOR SCORING WITH PRESSURE ON	PISMTKICRASNMA

000060

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
OMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE DATE MO DA YR	LOCATION	DETAIL	WORK CODES
UP 001307	12/20/91	01/07/92		ALBINA	(WRH) INSPECTED TOP DECK SUPPORT ASSEMBLY	FISHTKICRASNWA
				ALBINA	(WRH) INSURED AUTO, AND INDEP. VALVES PROPERLY VENTED	FISHTKICRASNWA
				ALBINA	(WRH) MADE CRANKCASE INSPECTION	FISHTKICRASNWA
	01/11/92	01/12/92		ALBINA	(WRH) TOOK LUBE OIL, ENGINE WATER, AND COMPRESSOR OIL SAMPLES	FISHTKICRASNWA
				ALBINA	(CHH) CHECKED ALL LIGHTS.	TPLU
				ALBINA	(CHH) TESTED RADIO & FRIG.	TPLU
				ALBINA	(DGR) CHANGED WORN BRAKE SHOES AND ADJUSTED PISTON TRAVEL	TPLU
				ALBINA	(DGR) CHECKED ALL FLUID LEVELS	TPLU
				ALBINA	(WRH) PERFORMED L.U.	TPLU
	01/17/92	01/17/92		ALBINA	(LDS) TESTED LIGHTS FOR PROPER OPERATION	TPSVAB
				ALBINA	(LDS) TESTED OBT FOR PROPER OPERATION	TPSVAB
				ALBINA	(LDS) TESTED RADIO FOR PROPER OPERATION	TPSVAB
				ALBINA	(JLB) CHANGED WORN BRAKE SHOES, ADJUSTED PISTON TRAVEL.	TPSVAB
				ALBINA	(JLB) CHECKED ALL FLUID LEVELS.	TPSVAB
				ALBINA	(JLB) CLEANED AND SUPPLIED CAB.	TPSVAB
				ALBINA	(JLB) EXTENDED FRONT AND REAR TRAIN LINE HOSES.	TPSVAB
				ALBINA	(JLB) TESTED HORN, BELL, WIPERS AND SANDERS.	TPSVAB
	01/21/92	01/22/92		ALBINA	(DGR) CHANGED WORN BRAKE SHOES AND ADJUSTED PISTON TRAVEL	TP -
				ALBINA	(DGR) CHECKED ALL FLUID LEVELS	TP
				ALBINA	(DGR) CLEANED AND SUPPLIED CAB	TP
	01/31/92	02/01/92		ALBINA	(CHH) CHECK LIGHTS RADIO HEATERS AND REFER	LU
				ALBINA	(CHH) CHECK LOAD SPEEDS AND DIRECTION	LU
				ALBINA	(LKR) CLEAN AND SUPPLY CAB	LU
				ALBINA	(WRH) CHANGE WORN BRAKE SHOES AND ADJUST TRAVEL	LU
				ALBINA	(WRH) CHECK FLUID LEVELS.	LU
				ALBINA	(WRH) CHECK HORN BELL AND WIPERS	LU
				ALBINA	(WRH) DO LU (TAKE OIL SAMPLE)	LU
				ALBINA	(WRH) REPAIR BROKEN SAND PIPE	LU
				ALBINA	(WRH) TEST SANDERS	LU
	02/05/92	02/06/92		ALBINA	(JLB) CHANGED WORN BRAKE, ADJUSTED PISTON TRAVEL.	TPSV
				ALBINA	(JLB) CHECKED ALL FLUID LEVELS.	TPSV
				ALBINA	(JLB) CLEANED AND SUPPLIED CAB.	TPSV
	02/16/92	02/17/92		ALBINA	(LDS) TESTED ATCS FOR PROPER OPERATION	SVTP
				ALBINA	(LDS) TESTED LIGHTS FOR PROPER OPERATION	SVTP
				ALBINA	(LDS) TESTED RADIO FOR PROPER OPERATION	SVTP
				ALBINA	(LDS) TESTED WATER COOLER FOR PROPER OPERATION	SVTP
				ALBINA	(JLB) CHANGED WORN BRAKE SHOES, ADJUSTED PISTON TRAVEL.	SVTP
				ALBINA	(JLB) CHECKED ALL FLUID LEVELS.	SVTP
				ALBINA	(JLB) CLEANED AND SUPPLIED CAB.	SVTP
				ALBINA	(JLB) TESTED HORN, BELL, WIPERS AND SANDERS.	SVTP
	02/22/92	02/24/92		ALBINA	(DGR) ADDED ENGINE LUBE OIL 6 INCHES	HMLUTPSU
				ALBINA	(DGR) CHANGED BAGGIE TYPE AIR FILTERS	HMLUTPSU
				ALBINA	(DGR) CHANGED CAR BODY TYPE AIR FILTERS	HMLUTPSU
				ALBINA	(DGR) CHANGED WORN BRAKE SHOES AND ADJUSTED PISTON TRAVEL	HMLUTPSU
				ALBINA	(DGR) CHECKED ALL FLUID LEVELS	HMLUTPSU
				ALBINA	(DGR) CLEANED AND SUPPLIED CAB	HMLUTPSU

000061

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
OMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE DATE MO DA YR	LOCATION	DETAIL	WORK CODES
UP 001307	02/22/92	02/24/92	02/26/92	ALBINA	(DGR) TOOK LUBE OIL SAMPLE	KMLUTPSV
				ALBINA	(LDS) LOAD TESTED UNIT FOR POWER IN BOTH DIRECTIONS	TPSVABNL
	02/26/92	02/27/92		ALBINA	(LDS) REPLACED RVF BECAUSE COIL WEAK	TPSVABNL
				ALBINA	(LDS) TESTED ATCS SYSTEM FOR PROPER OPERATION	TPSVABNL
				ALBINA	(LDS) TESTED COOLER FOR PROPER OPERATION	TPSVABNL
				ALBINA	(LDS) TESTED LIGHTS AND REPLACED BURNT BULBS	TPSVABNL
				ALBINA	(LDS) TESTED RADIO FOR PROPER OPERATION	TPSVABNL
				ALBINA	(JJM) CHANGED AND ADJUSTED BRAKE SHOES	SVABSN
	02/27/92	02/27/92		ALBINA	(JJM) CHECKED ALL FLUID LEVELS	SVABSN
				ALBINA	(JJM) CLEANED AND SUPPLIED CAB	SVABSN
				ALBINA	(JJM) REPAIRED FRONT LEFT WINDOW WIPER	SVABSN
				ALBINA	(JJM) REPAIRED LEFT FRONT SANDER	SVABSN
				ALBINA	(JJM) REPIPED AUTOMATIC BV EXHAUST	SVABSN
				ALBINA	(DGR) CHECKED ALL FLUID LEVELS	TPSV
	03/04/92	03/05/92		ALBINA	(DGR) CLEANED AND SUPPLIED CAB	TPSV
				ALBINA	(DGR) REPLACED WORN BRAKE SHOES AND ADJUSTED PISTON TRAVEL	TPSV
	03/08/92	03/09/92		ALBINA	(DGR) REPLACED REAR DOOR LATCHES AND CATCHES	TP
				ALBINA	(JJM) CHANGED AND ADJUSTED BRAKE SHOES	LUSVIC
	03/13/92	03/14/92		ALBINA	(JJM)(WRH)(YHK) OUTBOUNDTEST	LUSVIC
				ALBINA	(WRH) ADDED GREASE TO T.M. GEAR CASES	LUSVIC
				ALBINA	(WRH) CHECKED ENGINE FLUID LEVELS	LUSVIC
				ALBINA	(WRH) TOOK LUBE OIL SAMPLE	LUSVIC
				ALBINA	(YHK) CHANGED HEADLIGHT	LUSVIC
				ALBINA	(YHK) ELECTRICAL CHECKS	LUSVIC
	03/19/92	03/19/92		ALBINA	(DGR) CHANGED WORN BRAKE SHOES AND ADJUSTED PISTON TRAVEL	TPSV
				ALBINA	(DGR) CHECKED ALL FLUID LEVELS	TPSV
				ALBINA	(DGR) CLEANED AND SUPPLIED CAB	TPSV
				ALBINA	(LKR) CLEAN AND SUPPLY CAB	TP
	03/28/92	03/28/92		ALBINA	(WRH) CHANGE WORN BRAKE SHOES AND ADJUST TRAVEL	TP
				ALBINA	(WRH) CHECK FLUID LEVELS	TP
				ALBINA	(YKK) CHECK LIGHTS RADIO HEATERS AND REFER	TP
				ALBINA	(CHM) CHECK ALL TRACTION MOTOR BRUSHES.	PNPFIHLSUNWATKIC
	04/01/92	04/07/92		ALBINA	(CHM) CHECK COMPRESSOR GOVERNOR OPERATION (ON AT 120, OFF AT 130).	PNPFIHLSUNWATKIC
				ALBINA	(CHM) CHECK FOR AND CLEAR ALL LOV VOLTAGE GROUNDS.	PNPFIHLSUNWATKIC
				ALBINA	(CHM) CHECK GROUND RELAY OPERATION.	PNPFIHLSUNWATKIC
				ALBINA	(CHM) CHECK OPERATION OF ALARM BELL.	PNPFIHLSUNWATKIC
				ALBINA	(CHM) CHECK OPERATION OF ALL CAB HEATERS.	PNPFIHLSUNWATKIC
				ALBINA	(CHM) CHECK OPERATION OF ALL LIGHTS.	PNPFIHLSUNWATKIC
				ALBINA	(CHM) CHECK OPERATION OF EMERGENCY FUEL CUT-OFF VALVE CONTROLS.	PNPFIHLSUNWATKIC
				ALBINA	(CHM) CHECK OPERATION OF REFRIGERATOR.	PNPFIHLSUNWATKIC
				ALBINA	(CHM) CHECK OPERATION OF REVERSER HANDLE INTERLOCK.	PNPFIHLSUNWATKIC
				ALBINA	(CHM) CHECK OPERATION OF WHEEL-SLIP SYSTEM.	PNPFIHLSUNWATKIC
				ALBINA	(CHM) CHECK REMOVABLE ELECTRICAL COVERS FOR (DANGER-600-VOLTS).	PNPFIHLSUNWATKIC
				ALBINA	(CHM) CHECK THE REVISION OF THE DBT SOFTWARE (04.12).	PNPFIHLSUNWATKIC
				ALBINA	(CHM) ELECT. TEST AND CARD.	PNPFIHLSUNWATKIC
				ALBINA	(CHM) INSPECT TRACTION MOTOR LEADS, BOOTS, CLAMPS AND GROUND STRAPS	PNPFIHLSUNWATKIC

000062

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
OMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE DATE	LOCATION	DETAIL	WORK CODES
UP 001307	04/01/92	04/07/92		ALBINA	(CHM) INSURE ALL FUEL CUT-OFF CONTROLS ARE LABELED.	PNPQMLUSNWATKIC
				ALBINA	(CHM) INSURE ALL TRACTION MOTOR COVERS HAVE FELTS APPLIED.	PNPQMLUSNWATKIC
				ALBINA	(CHM) INSURE RADIO POWER SUPPLY IS 72V NOT 12V.	PNPQMLUSNWATKIC
				ALBINA	(CHM) INSURE UNIT HAS UPGRADE RADIO.	PNPQMLUSNWATKIC
				ALBINA	(CHM) HEG HIGH VOLTAGE SYSTEM.	PNPQMLUSNWATKIC
				ALBINA	(CHM) RE-MOUNT ATCS CIRCUIT BREAKER.	PNPQMLUSNWATKIC
				ALBINA	(CHM) REPLACE ALL MISSING FUSES IN SPARE FUSE RACK.	PNPQMLUSNWATKIC
				ALBINA	(CHM) REPLACE GAUGE LIGHT DIMMER.	PNPQMLUSNWATKIC
				ALBINA	(CHM) TEST THROTTLE SEQUENCE FOR OPERATION.	PNPQMLUSNWATKIC
				ALBINA	(CHM) TEST UNIT LOAD IN FOR. AND REV.	PNPQMLUSNWATKIC
				ALBINA	(CHM) WASH AND FILL BATTERY.	PNPQMLUSNWATKIC
				ALBINA	(CHM) INSURE OPERATION OF THERMIONIC DRAIN VALVES.	PNPQMLUSNWATKIC
				ALBINA	(DGR) CHECKED ALL FLUID LEVELS	PNPQMLUSNWATKIC
				ALBINA	(DGR) CHECKED CONDITION AND TENSION OF COOLING FAN BELTS	PNPQMLUSNWATKIC
				ALBINA	(DGR) CHECKED PILOT HEIGHT CLEARANCES	PNPQMLUSNWATKIC
				ALBINA	(DGR) CHECKED SAND TRAPS AND PIPING FOR CONDITION	PNPQMLUSNWATKIC
				ALBINA	(DGR) CHECKED SIDE BEARING CLEARANCES	PNPQMLUSNWATKIC
				ALBINA	(DGR) CHECKED SPARK ARRESTOR RETENTION BINS	PNPQMLUSNWATKIC
				ALBINA	(DGR) GREASED COUPLER SHANK WEAR PLATES	PNPQMLUSNWATKIC
				ALBINA	(DGR) LUBRICATED CENTER TRUCK CASTINGS	PNPQMLUSNWATKIC
				ALBINA	(DGR) LUBRICATED COOLING FAN BEARINGS	PNPQMLUSNWATKIC
				ALBINA	(DGR) LUBRICATED TRIPOD SEATPOST AND PIVOTS	PNPQMLUSNWATKIC
				ALBINA	(DGR) LUBRICATED WINDOW SLIDES	PNPQMLUSNWATKIC
				ALBINA	(DGR) TESTED SANDERS AND WIPERS	PNPQMLUSNWATKIC
				ALBINA	(DGR) WASHED ENGINE ROOM INTERIOR	PNPQMLUSNWATKIC
				ALBINA	(WRH) CHANGED BAGGIE TYPE AIR FILTERS	PNPQMLUSNWATKIC
				ALBINA	(WRH) CHANGED CAR BODY TYPE AIR FILTERS	PNPQMLUSNWATKIC
				ALBINA	(WRH) CHANGED FUEL FILTERS	PNPQMLUSNWATKIC
				ALBINA	(WRH) CHANGED LUBE OIL FILTERS	PNPQMLUSNWATKIC
				ALBINA	(WRH) CHECKED FOR LOOSE FUEL TANK BOLTS	PNPQMLUSNWATKIC
				ALBINA	(WRH) CHECKED MU AIR HOSES	PNPQMLUSNWATKIC
				ALBINA	(WRH) INSPECTED BUCKEYE FUEL FILLER VENT HOSES	PNPQMLUSNWATKIC
				ALBINA	(WRH) INSPECTED TOP DECK SUPPORT ARM ASSEMBLY	PNPQMLUSNWATKIC
				ALBINA	(WRH) LUBRICATED DOOR HINGES AND LATCHES	PNPQMLUSNWATKIC
	04/11/92	04/12/92		ALBINA	(WRH) TOOK ENGINE LUBE OIL, WATER AND AIR COMPRESSOR SAMPLES	PNPQMLUSNWATKIC
				ALBINA	(DGR) CHANGE WORN BRAKE SHOES AND ADJUST TRAVEL	SVTP
				ALBINA	(DGR) CHECK FLUID LEVELS	SVTP
				ALBINA	(LKR) CLEAN AND SUPPLY CAB	SVTP
				ALBINA	(YKK) CHECK LIGHTS RADIO HEATERS AND REFER	SVTP
	04/16/92	04/17/92		ALBINA	(JLB) CHANGED WORN BRAKE SHOES, ADJUSTED PISTON TRAVEL.	SVTP
				ALBINA	(JLB) CHECKED ALL FLUID LEVELS.	SVTP
				ALBINA	(JLB) TESTED HORN, BELL, WIPERS AND SANDERS.	SVTP
	04/21/92	04/21/92		ALBINA	(WRH) CHANGE WORN BRAKE SHOES AND ADJUST TRAVEL	TP
				ALBINA	(WRH) CHECK FLUID LEVELS	TP
				ALBINA	(WRR) CLEAN AND SUPPLY CAB	TP
				ALBINA	(YKK) CHECK LIGHTS RADIO HEATERS AND REFER	TP

000066

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
OMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE DATE MO DA YR	LOCATION	DETAIL	WORK CODES
UP 001307	04/25/92	04/26/92		ALBINA	(WRH) CHECKED BRAKES ADJUSTED TRAVEL	TP
				ALBINA	(WRH) CHECKED FLUIDS	TP
				ALBINA	(WRH) PERFORMED L.U.	TP
	05/06/92	05/06/92		ALBINA	(JJM) CHANGED OUT AND ADJUSTED BRAKE SHOES	LURF
				ALBINA	(JJM) CHANGED OUT OBT	LURF
				ALBINA	(JJM) CHECKED FLUID LEVELS	LURF
				ALBINA	(JJM) CLEANED AND SUPPLIED CAB	LURF
				ALBINA	(JJM) LU	LURF
				ALBINA	(WRH) ADJUSTED BRAKES AS NEEDED	TPSV
	05/10/92	05/11/92		ALBINA	(WRH) CHANGED BRAKE SHOES AS NEEDED	TPSV
				ALBINA	(WRH) CHECKED FLUIDS	TPSV
				ALBINA	(YKK) CHECKED LIGHTS REEFER RADIO	TPSV
				SALLAKCIT	(DTC)ELECT TEST OUT	USRHHAGEMNA
	05/18/92	05/21/92		SALLAKCIT	(JEA)*** MECHANICAL MAINTENANCE	USRHHAGEMNA
				SALLAKCIT	(JEA)*RM** 05/12/92 OPS00 AUXGEN DRIVE OUT DIC EAST	USRHHAGEMNA
				SALLAKCIT	(JEA)*ST* DEAD & DRAINED(RAP)	USRHHAGEMNA
				SALLAKCIT	(JEA)AFTER CARBODY FILTERS AFTER WASH	USRHHAGEMNA
				SALLAKCIT	(JEA)REMOVE BLOWER	USRHHAGEMNA
				SALLAKCIT	(JEA)WASH	USRHHAGEMNA
				SALLAKCIT	(JWN) INBOUND PROCESS	USRHHAGEMNA
				SALLAKCIT	(LMF)ALIGN AUX GEN	USRHHAGEMNA
				SALLAKCIT	(LMF)APPLY HATCH COVER	USRHHAGEMNA
				SALLAKCIT	(LMF)C/O BAGGIES	USRHHAGEMNA
				SALLAKCIT	(LMF)C/O PTO DEF ***APPLY***	USRHHAGEMNA
				SALLAKCIT	(SRH) ELECT INBOUND TEST OUT	USRHHAGEMNA
				SALLAKCIT	(SRH) HACH INBOUND TEST OUT.	USRHHAGEMNA
				SALLAKCIT	(SRH)START & CHECK	USRHHAGEMNA
				SALLAKCIT	HELD 05/18/92 DUE	TRACK 05 USRHHAGEMNA
	05/26/92	05/27/92		HINKLE	(WAM/IND) **RF**L #3 JOURNAL HOT	USRFTK
				HINKLE	(WAM/IND) CHECK LATERAL ON ALL BOXES	USRFTK
				HINKLE	(WAM/IND) CHECK SIDE BEARINGS	USRFTK
				HINKLE	(WAM/IND) LUBRICATE CENTER CASTINGS	USRFTK
				HINKLE	(WAM/IND) WELDED LEFT #3 SANDER BRACKET & PIPE.	USRFTK
	06/02/92	06/03/92		ALBINA	(WRH) CHANGE WORN BRAKE SHOES AND ADJUST TRAVEL	TP
				ALBINA	(WRH) CHECK FLUID LEVELS	TP
				ALBINA	(WRH) CHECK HORN BELL AND WIPERS	TP
				ALBINA	(WRR) CLEAN AND SUPPLY CAB	TP
				ALBINA	(YKK) APPLY RADIO	TP
				ALBINA	(YKK) CHECK LIGHTS RADIO REFER	TP
				ALBINA	(YKK) CHECK LOAD SPEEDS AND DIRECTION	TP
	06/07/92	06/08/92		ALBINA	(JLM) *LU*	LU
	06/10/92	06/10/92		ALBINA	(KMG) CLEAN AND SUPPLY CAB	TP
				ALBINA	(WRH) CHANGE WORN BRAKE SHOES AND ADJUST TRAVEL	TP
				ALBINA	(WRH) CHECK FLUID LEVELS	TP
	06/20/92	06/26/92		ALBINA	(YKK) CHECK LIGHTS RADIO REFER	TP
				ALBINA	() AIR COMPRESSOR, LUBE OIL, AND ENG.COOLING WATER SAMPLES	PHAIAMSQSNWALUTK

000064

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
OMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE DATE MO DA YR	LOCATION	DETAIL	WORK CODES
UP	001307	06/20/92	06/26/92	ALBINA	(CHM) CHECK ALL TRACTION MOTOR BRUSHES.	PMIAHMSQSNWALUTK
				ALBINA	(CHM) CHECK AUX GENERATOR VOLTAGE.	PMIAHMSQSNWALUTK
				ALBINA	(CHM) CHECK AUXILIARY GENERATOR BRUSHES.	PMIAHMSQSNWALUTK
				ALBINA	(CHM) CHECK FOR AND CLEAR ALL LOW VOLTAGE GROUNDS.	PMIAHMSQSNWALUTK
				ALBINA	(CHM) CHECK LOAD METER.	PMIAHMSQSNWALUTK
				ALBINA	(CHM) CHECK MAIN GENERATOR BRUSHES.	PMIAHMSQSNWALUTK
				ALBINA	(CHM) CHECK OPERATION OF ALL LIGHTS AND REPLACE AS NECESSARY.	PMIAHMSQSNWALUTK
				ALBINA	(CHM) CHECK OPERATION OF COMPRESSOR GOVERNOR.	PMIAHMSQSNWALUTK
				ALBINA	(CHM) CHECK OPERATION OF REFRIGERATOR.	PMIAHMSQSNWALUTK
				ALBINA	(CHM) CHECK OPERATION OF REVERSER HANDLE INTERLOCK.	PMIAHMSQSNWALUTK
				ALBINA	(CHM) CHECK OPERATION OF THE ALARM BELL.	PMIAHMSQSNWALUTK
				ALBINA	(CHM) CHECK REMOVABLE COVERS FOR (DANGER-600-VOLTS).	PMIAHMSQSNWALUTK
				ALBINA	(CHM) CHECK THE REVISION OF THE OBT SOFTWARE (C4.12).	PMIAHMSQSNWALUTK
				ALBINA	(CHM) INSPECT TRACTION MOTOR LEADS, BOOTS, CLAMPS AND GROUND STRAPS	PMIAHMSQSNWALUTK
				ALBINA	(CHM) INSURE ALL TRACTION MOTOR COVERS HAVE FELTS APPLIED.	PMIAHMSQSNWALUTK
				ALBINA	(CHM) INSURE UNIT HAS STANDARD RADIO.	PMIAHMSQSNWALUTK
				ALBINA	(CHM) MAKE DIRECTIONAL TEST.	PMIAHMSQSNWALUTK
				ALBINA	(CHM) MAKE POWER TEST.	PMIAHMSQSNWALUTK
				ALBINA	(CHM) MAKE THROTTLE SEQUENCE TEST.	PMIAHMSQSNWALUTK
				ALBINA	(CHM) MEG HIGH VOLTAGE SYSTEM (10-MEG).	PMIAHMSQSNWALUTK
				ALBINA	(CHM) REPLACE ALL MISSING FUSES IN SPARE FUSE RACK.	PMIAHMSQSNWALUTK
				ALBINA	(CHM) REPLACE CAB HEATER MOTOR BRUSHES.	PMIAHMSQSNWALUTK
				ALBINA	(CHM) REPLACE FUEL PUMP MOTOR BRUSHES.	PMIAHMSQSNWALUTK
				ALBINA	(CHM) TEST GROUND RELAY SYSTEM.	PMIAHMSQSNWALUTK
				ALBINA	(CHM) TEST MAIN RESERVOIR DRAIN VALVES.	PMIAHMSQSNWALUTK
				ALBINA	(CHM) TEST OPERATION OF ALL CAB HEATERS.	PMIAHMSQSNWALUTK
				ALBINA	(CHM) TEST OPERATION OF EMERGENCY FUEL CUT-OFF CONTROLS.	PMIAHMSQSNWALUTK
				ALBINA	(CHM) TEST WHEEL-SLIP SYSTEM.	PMIAHMSQSNWALUTK
				ALBINA	(CHM) VERIFY UNIT RADIO POWER IS 72VDC NOT 12VDC.	PMIAHMSQSNWALUTK
				ALBINA	(CHM) WASH AND FILL ALL BATTERYS.	PMIAHMSQSNWALUTK
				ALBINA	(DGR) ADDED ENGINE COOLING WATER TREATMENT.	PMIAHMSQSNWALUTK
				ALBINA	(DGR) INSPECTED SANDHOSES, PIPES AND TRAPS.	PMIAHMSQSNWALUTK
				ALBINA	(DGR) INSPECTED UNIT FOR SIDE BEARING CLEARANCE.	PMIAHMSQSNWALUTK
				ALBINA	(JLB) CHANGED AIR COMPRESSOR AIR INTAKE FILTER.	PMIAHMSQSNWALUTK
				ALBINA	(JLB) CHANGED ALL FUEL FILTERS.	PMIAHMSQSNWALUTK
				ALBINA	(JLB) CHANGED BAGGIE AND CAR BODY AIR FILTERS.	PMIAHMSQSNWALUTK
				ALBINA	(JLB) CHANGED LUBE OIL FILTER AND CLEANED LUBE OIL SUCTION	PMIAHMSQSNWALUTK
				ALBINA	(JLB) CHANGED WORN BRAKE SHOES, ADJUSTED PISTON TRAVEL.	PMIAHMSQSNWALUTK
				ALBINA	(JLB) CHECKED CONDITION OF COOLING FAN -V- BELTS.	PMIAHMSQSNWALUTK
				ALBINA	(JLB) CHECKED CONDITION OF CRANKCASE AND PEE-PIPES.	PMIAHMSQSNWALUTK
				ALBINA	(JLB) CHECKED CONDITION OF FIRE EXTINGUISHERS.	PMIAHMSQSNWALUTK
				ALBINA	(JLB) CHECKED CONDITION OF M.U. HOSES.	PMIAHMSQSNWALUTK
				ALBINA	(JLB) CHECKED CONDITION OF PISTON AND LINERS.	PMIAHMSQSNWALUTK
				ALBINA	(JLB) CHECKED OPERATION OF CAB DOOR LATCHES.	PMIAHMSQSNWALUTK
				ALBINA	(JLB) CHECKED OPERATION OF ENGINE DEVICE /COP SWITCH.	PMIAHMSQSNWALUTK
				ALBINA	(JLB) CHECKED OPERATION OF HAND BRAKE.	PMIAHMSQSNWALUTK

000065

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
OMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE DATE MO DA YR	LOCATION	DETAIL	WORK CODES
UP 001307	06/20/92	06/26/92		ALBINA	(JLB) CLEANED FUEL SYSTEM SIGHT GLASSES.	PMAIAMSSSNMALUTK
				ALBINA	(JLB) GREASED COUPLER CARRIER IRON.	PMAIAMSSSNMALUTK
				ALBINA	(JLB) INSPECTED BRAKE SHOES FOR SIGNS OF OVER RIDEING WHEEL.	PMAIAMSSSNMALUTK
				ALBINA	(JLB) INSPECTED CONDITION OF FIRST AID KIT.	PMAIAMSSSNMALUTK
				ALBINA	(JLB) INSPECTED OPERATION OF BUCKEYE FUEL FILLER AND VENT HOSES.	PMAIAMSSSNMALUTK
				ALBINA	(JLB) INSPECTED TOP DECK AND SUPPORT ARMS.	PMAIAMSSSNMALUTK
				ALBINA	(JLB) INSURED FREENESS OF SLACK ADJUSTER.	PMAIAMSSSNMALUTK
				ALBINA	(JLB) INSURED THAT INDEPENTENT AND AUTOMATIC BRAKE VALVES ARE	PMAIAMSSSNMALUTK
				ALBINA	(JLB) LUBICATED COOLING FAN JACK SHAFT.	PMAIAMSSSNMALUTK
				ALBINA	(JLB) LUBICATED TRI-POD SEAT POSTS.	PMAIAMSSSNMALUTK
				ALBINA	(JLB) MANNUALLY CHECKED OPERATION OF THE SHUTTERS.	PMAIAMSSSNMALUTK
				ALBINA	(TLH) CLEAN AND SUPPLY CAB.	PMAIAMSSSNMALUTK
				ALBINA	STRAINERS.	PMAIAMSSSNMALUTK
				ALBINA	TAKEN.	PMAIAMSSSNMALUTK
				ALBINA	VENTED BELOW THE FLOOR.	PMAIAMSSSNMALUTK
	07/01/92	07/01/92		ALBINA	(JLB) CHANGED WORN BRAKE SHOES, ADJUSTED PISTON TRAVEL.	TPSV
				ALBINA	(JLB) CHECKED ALL FLUID LEVELS.	TPSV-
				ALBINA	(JLB) CLEANED AND SUPPLIED CAB.	TPSV-
				ALBINA	(JLB) TESTED HORN, BELL, WIPERS AND SANDERS.	TPSV
	07/18/92	07/18/92		ALBINA	(LKR) CLEAN AND SUPPLY CAB	SVSQLU
				ALBINA	(WRH) CHANGE WORN BRAKE SHOES AND ADJUST TRAVEL	SVSQLU
				ALBINA	(WRH) CHECK FLUID LEVELS	SVSQLU
				ALBINA	(WRH) DO LU (TAKE OIL SAMPLE)	SVSQLU
				ALBINA	(YKK) CHECK LIGHTS RADIO AND REFER	SVSQLU
	07/23/92	07/29/92		ALBSERTRK	(KGB) CHANGED BO BRAKE SHOES, ADJ. CLY TRAVEL	SVTPSQ
				ALBSERTRK	(KGB) CHANGED LOW WATER, LOW OIL SHUTDOWN ACC. BO	SVTPSQ
				ALBSERTRK	(KGB) STRAIGHTEN RT FT CUT LEVER	SVTPSQ
	08/07/92	08/07/92		ALBSERTRK	(DEB) CHANGED L#1 BRAKE HEAD ACCT. BURNT IN	TPSVSQ
				ALBSERTRK	(LDS) OK FOR SERVICE	TPSVSQ
	08/12/92	08/15/92		ALBSERTRK	(KGB) DO LU (TAKE LUBE OIL SAMPLE)	SVMMLU
				ALBSERTRK	(KGB) DO MH	SVMMLU
				ALBSERTRK	(LKR) CLEAN AND SUPPLY CAB	SVMMLU
				ALBSERTRK	(LP) CHECK LIGHTS RADIO AND REFER	SVMMLU
				ALBSERTRK	(LP) RUNNING CHECKS	SVMMLU
				ALBSERTRK	(WRH) CHANGE WORN BRAKE SHOES AND ADJUST TRAVEL	SVMMLU
				ALBSERTRK	(WRH) CHECK FLUID LEVELS	SVMMLU
				ALBSERTRK	(WRH) DO RUNNING CHECKS	SVMMLU
	08/22/92	08/23/92		ALBSERTRK	(JLM) CHANGED OUT FRONT SAND TRAP.	TPSVSN
	09/01/92	09/02/92		ALBSERTRK	(JLB) CHANGED WORN BRAKE SHOES, ADJUSTED PISTON TRAVEL.	TPSV
				ALBSERTRK	(JLB) CHECKED ALL FLUID LEVELS.	TPSV
				ALBSERTRK	(JLB) CLEANED AND SUPPLIED CAB.	TPSV
				ALBSERTRK	(JLB) TESTED HORN, BELL, WIPERS AND SANDERS.	TPSV
	09/03/92	09/03/92		ALBSERTRK	(DEB) CHANGE WORN BRAKE SHOES AND ADJUST TRAVEL	SVTP
	09/11/92	09/12/92		ALBSERTRK	(DEB) CHECK LIGHTS RADIO AND REFER	SVSQRLU
				ALBSERTRK	(KGB) CHANGE WORN BRAKE SHOES AND ADJUST TRAVEL	SVSQRLU
				ALBSERTRK	(KGB) CHECK FLUID LEVELS	SVSQRLU

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
OMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE DATE MO DA YR	LOCATION	DETAIL	WORK CODES
UP 001307	09/11/92	09/12/92		ALBSERTRK (KGB)	DO LU (TAKE LUBE OIL SAMPLE)	SUSORMLU
	09/26/92	10/12/92		ALBSERTRK (LKR)	CLEAN AND SUPPLY CAB	SUSORMLU
				SALLAKCIT	MOUNTING	PNPIQMRNPJ
				SALLAKCIT	HEADS NEED REPLACED	PNPIQMRNPJ
				SALLAKCIT (***)*RM*	08/07/92 DP500S BLOWDOWNS ARE NOT WORKING	PNPIQMRNPJ
				SALLAKCIT (***)*RM*	08/22/92 DP500 RADIATOR LEAD REPAIR AT PI	PNPIQMRNPJ
				SALLAKCIT (***)*NOT	INBOUND INSPECTED BY ELECT AT PIT	PNPIQMRNPJ
				SALLAKCIT (***)*SPECIAL (008A-***)	WINTER WEATHER PREPARATION INSTRUCTIONS	PNPIQMRNPJ
				SALLAKCIT (***)*SPECIAL (009A-***)	WINTER WETHER PREPARATION MOD	PNPIQMRNPJ
				SALLAKCIT (***)*SPOT	FOUR C	PNPIQMRNPJ
				SALLAKCIT (BA)	FUEL TANK ON STEAM AT 10:30 AM 10/08/92 - OFF 10:30 AM 10/09	PNPIQMRNPJ
				SALLAKCIT (BA)	PUMP FUEL OUT	PNPIQMRNPJ
				SALLAKCIT (CAF)	SPOT FOUR A	PNPIQMRNPJ
				SALLAKCIT (CAF)	SPOT FOUR B	PNPIQMRNPJ
				SALLAKCIT (EFF)	SPOT FIVE	PNPIQMRNPJ
				SALLAKCIT (EFF)	SPOT SIX (TSEST AND CARD)	PNPIQMRNPJ
				SALLAKCIT (EFF)	SPOT TWO(WASH)	PNPIQMRNPJ
				SALLAKCIT (EFF)	TEST & CARD CARDED / /	PNPIQMRNPJ
				SALLAKCIT (GND)*PI*	DUE INSPECTION 09/24/92	PNPIQMRNPJ
				SALLAKCIT (GND)*QM*	QUARTERLY MAINTENANCE	PNPIQMRNPJ
				SALLAKCIT (GND)*SPECIAL (009-***)	REPAIR AND UPGRADE RADIO WIRING AND	PNPIQMRNPJ
				SALLAKCIT (GND)*SPOT	THREE(ELECT)	PNPIQMRNPJ
				SALLAKCIT (IST)	TOP DECK COVERS ROBBED FOR UP 1364	PNPIQMRNPJ
				SALLAKCIT (PA)	APPLY RETENTION TANK & WELD	PNPIQMRNPJ
				SALLAKCIT (PA)	PIPE RETENTION TANK	PNPIQMRNPJ
				SALLAKCIT (PA)	SPECIAL (013-***) APPLICATION OF RETENTION TANKS TO MP15 LOC	PNPIQMRNPJ
				SALLAKCIT (REJ)*RM*	09/12/92 DP500(L#3 OUTSIDE-SRH)(L#4 INSIDE-REJ) BRAKE	PNPIQMRNPJ
				SALLAKCIT HELD	09/26/92 DUE PI 09/24/92 TRACK 10	PNPIQMRNPJ
	10/30/92	10/31/92		ALBSERTRK (JJH)	CHECK SANDERS	TPSV
				ALBSERTRK (JLH)	CHANGE WORN BRAKE SHOES AND ADJUST TRAVEL	TPSV
				ALBSERTRK (JLH)	CHECK FLUID LEVELS	TPSV
				ALBSERTRK (KAR)	CHECK LIGHTS RADIO HEATERS AND REFER	TPSV
				ALBSERTRK (LKR)	CLEAN AND SUPPLY CAB	TPSV
	11/07/92	11/12/92		ALBSERTRK (JB)	CHANGED R-7 BRAKE HEAD (JM)	UMTKSV
	12/09/92	12/11/92		ALBINA (JJR)	DUE LU	PNPIEMLUMASNTK
				ALBINA (LJM)	DUE EM	PNPIEMLUMASNTK
				ALBINA (LJM)	DUE PI INSP.	PNPIEMLUMASNTK
				ALBINA (LJM)	MACH TO TEST & CARD	PNPIEMLUMASNTK
				ALBINA (LKR)	NEEDS ENGINE "VEE" WASHED.	PNPIEMLUMASNTK
				ALBINA (RER)	ELECT TO TEST & CARD.	PNPIEMLUMASNTK
				ALBINA (JJK)	RETORQUED EX. BASE BOLTS	PNPIEMLUMASNTK
				ALBINA (LJM)	CLEAN & TEST SANDERS	PNPIEMLUMASNTK
				ALBINA (LKR)	WASH CARBODY & ENG.	PNPIEMLUMASNTK
	12/17/92	12/18/92		ALBSERTRK (ACS)	CHANGED WORN BRAKE SHOES, ADJUSTED PISTON TRAVEL.	SUTP
				ALBSERTRK (JLB)	CHECKED ALL FLUID LEVELS.	SUTP
	12/24/92	12/24/92		ALBSERTRK (KEB)	HAND BRAKE REPAIRED	SUTK

000067

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
OMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE DATE MO DA YR	LOCATION	DETAIL	WORK CODES
UP 002359	07/18/90	07/18/90		ARMSTRGYD	(TWB) CHANGED OUT GOVERNOR, OLD-1843330, NEW-764828	LUTSGV
				ARMSTRGYD	(TWB) ENGINE GOVERNOR, "A" VALVE BO	LUTSGV
	07/26/90	07/27/90		ARMSTRGYD	(TWB) REPORTED KICKING O/S (PEL)	RMEW
	08/03/90	08/03/90		NLRRAMP	(ALL) MAKE IB INSP & WR (BLM)	PIQWAPJ
				NLRRAMP	(ALL) RUN TEST & OB (BLM)	PIQWAPJ
				NLRRAMP	(JMA) AIR TEST OB	PIQWAPJ
				NLRRAMP	(MGH) INSP WORKED (SCR)	PIQWAPJ
				NLRRAMP	(MGH) MAKE RPL INSP UNDER WATER PRESSURE	PIQWAPJ
				NLRRAMP	(OJ.) WASHED ENG & CARBODY	PIQWAPJ
				NLRRAMP	(OK.) SPCL 001: CLEAN CAB RADIO MOD	PIQWAPJ
	11/03/90	11/06/90		FTWORTH	(DLG) DUE PI SM	PISHRFMEXPJLT
				FTWORTH	(DLG) RF: KICKING GOV. BUTTON	PISHRFMEXPJLT
				FTWORTH	(DLG) RM: SER. # FOR AUX. GEN. SEND TO J. KRAMER, LATA I623777	PISHRFMEXPJLT
				FTWORTH	(DLG) SEE 2A FORM	PISHRFMEXPJLT
				FTWORTH	(EG) PROJ 029A (TRANSPONDERS)	PISHRFMEXPJLT
				FTWORTH	(EHF) CHECK SANDERS	PISHRFMEXPJLT
				FTWORTH	(JAP) WASH	PISHRFMEXPJLT
				FTWORTH	(OC) RM: AIR BOX DRAIN PIPE TOO SHORT	PISHRFMEXPJLT
				FTWORTH	(PAB) LOAD TEST	PISHRFMEXPJLT
				FTWORTH	(PAB) ONLY GET 1604 HORSES.	PISHRFMEXPJLT
				FTWORTH	(RES) PROJ 030A (LOCOTEMP INSPECTION)	PISHRFMEXPJLT
				FTWORTH	(RMS) CHG # 4 INJ @ LEAKING (LPD) 4465 SER NO.	PISHRFMEXPJLT
				FTWORTH	***** OR CALL 8271-3056.....	PISHRFMEXPJLT
				FTWORTH	----- CARDED 1-4-90	PISHRFMEXPJLT
				FTWORTH	----- TAKE OIL SAMPLE BEFORE LOAD TESTING.	PISHRFMEXPJLT
	02/03/91	02/03/91		HOUSTON	(HV) REPLACED REAR TRAIN LINE HOOK	PIQWATSAB
				HOUSTON	(HV) REPLACED RIGHT FRONT WIPER MOTOR	PIQWATSAB
				HOUSTON	(HV) WASHED ENGINE	PIQWATSAB
	05/09/91	05/10/91		ARMSTRGYD	(TWB) AUX. GEN. DRIVE SHAFT GUARD NOT SECURED	AILUTS
				ARMSTRGYD	(TWB) DUE ANGL INSPECTION	AILUTS
				ARMSTRGYD	(TWB) FRONT HEAD LIGHT BO	AILUTS
				ARMSTRGYD	(TWB) LEFT #1-2-BINDER BOLTS LOOSE	AILUTS
				ARMSTRGYD	(TWB) LEFT #4 JURNAL BOX DRAIN PLUG BO	AILUTS
				ARMSTRGYD	(TWB) LEFT OIL COOLER WATER COUPLING LEAKING	AILUTS
				ARMSTRGYD	(TWB) MAIN RES. AIR GUAGE IN AIR COMP. ROOM BO	AILUTS
				ARMSTRGYD	(TWB) REAR HAND HOLDS NOT PAINTED	AILUTS
				ARMSTRGYD	(TWB) RIGHT #1-3-4-BINDER BOLTS LOOSE	AILUTS
				ARMSTRGYD	(TWB) RIGHT FRONT CENTER WINSHEILD CRACKED	AILUTS
				ARMSTRGYD	(TWB) WATER SIGHT GLASS DIRTY	AILUTS
	08/08/91	08/08/91		FTWORTH	(DLG) CHECK SANDERS	PIQWASNEL
				FTWORTH	(DLG) WASH	PIQWASNEL
				FTWORTH	***** WHEEL REPORT OK	PIQWASNEL
				FTWORTH	*****PI QM*****	PIQWASNEL
	10/16/91	10/17/91		ARMSTRGYD	(EJH) CHECK FOR POSSIBLE GEAR CASE DAMAGE. (EJH)	TSAD
				ARMSTRGYD	(RDH) R#4 BINDER BOLTS MISSING. (EJH)	TSAD
				ARMSTRGYD	(RDH) RIGHT #1 BRAKE RIGGING BENT. REPAIRED. (EJH)	TSAD

000068

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
OMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE DATE	LOCATION	DETAIL	WORK CODES
UP 002359	10/16/91	10/17/91		ARMSTRGYD	(RDO) RIGHT BOTTOM EDGE OF FRONT SNOWPLOW BENT . (EJH)	TSAD
	11/08/91	11/09/91		FTWORTH	(BJ) RM: DB, FIRE IN ELECTRICAL CABINET	PIEWRMELWASNTW
				FTWORTH	(BJ) RM: REVERSER IS STICKING	PIEWRMELWASNTW
				FTWORTH	(JG) TURN LT 2 WHEEL ACCT. GOUGE IN WHEEL	PIEWRMELWASNTW
				FTWORTH	(RDN) REAR STANTION BROKEN	PIEWRMELWASNTW
				FTWORTH	(SUE) WASH (JAP)	PIEWRMELWASNTW
				FTWORTH	(WLG) RM: EDT ANT. IS B/O	PIEWRMELWASNTW
				FTWORTH	(WLG) RM: RADIO ANT. IS B/O	PIEWRMELWASNTW
				FTWORTH	(WLG) RM: RADIO NEEDS LOCKED DOWN	PIEWRMELWASNTW
				FTWORTH	(WLS) CROSSING BELL B/O	PIEWRMELWASNTW
				FTWORTH	(WS) REAR CROSSING CHAIN MISSING	PIEWRMELWASNTW
				FTWORTH	***** DUE PI EM *****	PIEWRMELWASNTW
				FTWORTH	JL) CHECK SANDERS	PIEWRMELWASNTW
	02/09/92	02/09/92		FTWORTH	(ALA) CHECK SANDERS	PMPIDHNASN
				FTWORTH	(CC) ENG. RT. FRT. WIPER NEEDS ADJUSTED	PMPIDHNASN
				FTWORTH	(ERD) FUEL LINES LEAK AT BOTTOM CENTER OF FUEL TANK	PMPIDHNASN
				FTWORTH	(HRR) FRT. & REAR KNUCKLES THIN	PMPIDHNASN
				FTWORTH	(PAC) WASH	PMPIDHNASN
				FTWORTH	***** DUE PI EM INSPECTION *****	PMPIDHNASN
	04/24/92	04/26/92		NLRAMP	(ALL) TK = SHIM OUT OF PLACE TOP OF L-2 JRL BOX	USRMENWITK
				NLRAMP	(FJC) REPAIRED S/R	USRMENWITK
				NLRAMP	(TWC) EW = ENG. GOVERNOR OVER-FILLED WITH OIL	USRMENWITK
				NLRAMP	(TWC) TK = BOLT BROKEN IN SIDE BEARING CLIP, L-SIDE OF #1 TRUCK	USRMENWITK
	08/12/92	08/12/92		HOUSTON	(CM) REPLACED FIRE EXT. IN CAB	USPIGHTSOTWAIC
				HOUSTON	(CM) REPLACED FIRST AID KIT	USPIGHTSOTWAIC
				HOUSTON	(CM) STRAIGHTENED R CAB MIRROR BRACKET	USPIGHTSOTWAIC
				HOUSTON	(HV) CLEANED WATER SIGHT GLASS	USPIGHTSOTWAIC
				HOUSTON	(HV) WASHED ENGINE	USPIGHTSOTWAIC
	11/14/92	11/15/92		HOUSTON	(BB) MADED 009 MOD.	PMPISMTSCDPJWA
				HOUSTON	(GP) APPLIED BRAKE AWAY SPRINGS TO SAFETY CHAINS	PMPISMTSCDPJWA
				HOUSTON	(GP/LL) MADED 008A 009A MOD.	PMPISMTSCDPJWA
				HOUSTON	(GP/LL) WASHED ENGINE	PMPISMTSCDPJWA
				HOUSTON	(HL) REPAIRED MAGNET VALVE TO SHUTTER CYL.	PMPISMTSCDPJWA
				HOUSTON	(LC) MADED 090 MOD.	PMPISMTSCDPJWA
				HOUSTON	(LL) CLEANED FUEL SIGHT GLASS	PMPISMTSCDPJWA

000069

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
OMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE DATE MO DA YR	LOCATION	DETAIL	WORK CODES
UP 002360	05/29/90	06/02/90		ARMSTRGYD	(HRM) REPT. KICKING GROUND RELAY. (TDA)	ELGR
	08/16/90	08/18/90		ARMSTRGYD	(JCB) INSP CARDED	PIGRMLUTSFLQWL
				ARMSTRGYD	(JCB) CAB & ENGINE ROOM FIRE EXTINGUISHER SEALS B.O. (JCB)	PIGRMLUTSFLQWL
				ARMSTRGYD	(JCB) FRONT COUPLER LOM. (JCB)	PIGRMLUTSFLQWL
				ARMSTRGYD	(JCB) FRONT PILOT BELOW FEDERAL LIMITS. (JCB)	PIGRMLUTSFLQWL
				ARMSTRGYD	(JCB) L. & R. OIL COOLER DRESSER COUPLINGS LEAKING. (JCB)	PIGRMLUTSFLQWL
				ARMSTRGYD	(JCB) LEFT EXPANSION TANK COUPLING LEAKING. (JCB)	PIGRMLUTSFLQWL
				ARMSTRGYD	(JCB) RIGHT FRONT FUEL TANK SIGHT GLASS LEAKING. (JCB)	PIGRMLUTSFLQWL
	11/15/90	11/15/90		NLRRAMP	() SPCL 002:=UM UPDATE	PISHRMPJWALTEML
				NLRRAMP	(EEB) AIR TEST OB	PISHRMPJWALTEML
				NLRRAMP	(EFJ) RM:FURNISH SER # FOR AUX GEN TO J KRAMER 8271-3056	PISHRMPJWALTEML
				NLRRAMP	(FC) ENG RUNS HOT—REPAIRED TEMP. CONTROLLER—	PISHRMPJWALTEML
				NLRRAMP	(FC) SPCL 030A:LOCOTEMP FAN CONTROLLER INSP & UPGRADE	PISHRMPJWALTEML
				NLRRAMP	(JAP) SPCL 036A:CAB DOOR GRABIRON MOD	PISHRMPJWALTEML
				NLRRAMP	(PAN) INSP WORKED (FC)	PISHRMPJWALTEML
				NLRRAMP	(PAN) LOAD TESTED (FC)	PISHRMPJWALTEML
				NLRRAMP	(PAN) MAKE RPL INSP UNDER WATER PRESSURE	PISHRMPJWALTEML
				NLRRAMP	(PAN) RM:KICKING LOW WATER BUTTON	PISHRMPJWALTEML
				NLRRAMP	(PAN) WASHED ENG & CARBODY	PISHRMPJWALTEML
				NLRRAMP	(MEW) MAKE IB INSP & MR (MLB)	PISHRMPJWALTEML
				NLRRAMP	(MEW) RUN TEST & OB (FC)	PISHRMPJWALTEML
	02/15/91	02/16/91		ARMSTRGYD	() CLEAN & VACUUM CAB. (TDA)	PIGRMEWTKWATSLU
				ARMSTRGYD	() UNIT DUE QUARTERLY INSPECTION. (TDA)	PIGRMEWTKWATSLU
				ARMSTRGYD	(DLM) PAINT REAR PIN LIFTER GRABIRON "WHITE". (JCB)	PIGRMEWTKWATSLU
				ARMSTRGYD	(JCB) UNIT DUE QUARTERLY INSPECTION. (TDA)	PIGRMEWTKWATSLU
				ARMSTRGYD	(MED) CLEAN & VACUUM CAB. (TDA)	PIGRMEWTKWATSLU
				ARMSTRGYD	(TFM) "DANGER 600 VOLT" STICKER MISSING FROM CABINET. (JCB)	PIGRMEWTKWATSLU
				ARMSTRGYD	(TFM) CHANGE GOVERNOR OIL. (JCB)	PIGRMEWTKWATSLU
				ARMSTRGYD	(TFM) LEFT FRONT BOTTOM OF SNOWPLOW BENT IN. (JCB)	PIGRMEWTKWATSLU
				ARMSTRGYD	(TFM) REPLACE ENGINEER CAB SEAT PIN. (JCB)	PIGRMEWTKWATSLU
	05/17/91	05/18/91		NLRRAMP	ANNUAL INSP	AIAMPJWA
				NLRRAMP	(EW) TEST AIR	AIAMPJWA
				NLRRAMP	(EW) WORK AIR	AIAMPJWA
				NLRRAMP	(JMB) WATER TEST	AIAMPJWA
				NLRRAMP	(MED) CARD (MLB)	AIAMPJWA
				NLRRAMP	(MED) MAKE IB INSP & MR (MLB)	AIAMPJWA
				NLRRAMP	(MLB) 002=UPDATE THE =UM SCREEN	AIAMPJWA
				NLRRAMP	(WRM) MAKE RPL INSP UNDER PRESSURE	AIAMPJWA
				NLRRAMP	(WRM) RUN TEST OB—FINISH FORMS (MLB)	AIAMPJWA
				NLRRAMP	(WRM) WASH ENGINE & CARBODY	AIAMPJWA
				NLRRAMP	(WRM) WORK INSP (MLB)	AIAMPJWA
	07/06/91	07/06/91		NLRRAMP	SUPPORTING BRACKET TO PREVENT BREAKAGE AGAIN.	RFWL
				NLRRAMP	(HLR) RF WL= WATER LEAKS, BROKEN PIPE AT WATER DUMP VALVE. NEEDS	RFWL
	08/16/91	08/16/91		FTWORTH	(BJR) WASH	PIGRWASH
				FTWORTH	(DC) CHECK SANDERS	PIGRWASH
				FTWORTH	***** BLUE CARD ON UNIT.	PIGRWASH

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
OMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE DATE MO DA YR	LOCATION	DETAIL	WORK CODES
UP 002360	08/16/91	08/16/91		FTWORTH	*****PI QM*****	PIQMWASH
	11/15/91	11/16/91		HOUSTON	(CM) REPLACED REAR KNUCKLE	PIENRFTSWACWABE
				HOUSTON	(CM) REPLACED RIGHT FRONT WINDOW	PIENRFTSWACWABE
				HOUSTON	(MS) CHANGED LEFT MAIN RESERVOIR DRAIN	PIENRFTSWACWABE
				HOUSTON	(MS) CHANGED RADIATOR CAP	PIENRFTSWACWABE
				HOUSTON	(MS) CLEANED FUEL SIGHT GLASS	PIENRFTSWACWABE
				HOUSTON	(MS) WASHED ENGINE	PIENRFTSWACWABE
	01/23/92	01/24/92		ARMSTRGYD	(SHL) CHANGED RIGHT WATER PUMP. (RLR)	USWLMF
				ARMSTRGYD	(SHL) REPORTED RIGHT WATER PUMP B/O.	USWLMF
	02/17/92	02/17/92		NLRRAMP	HANGER.....	PNPQMRMPJ
				NLRRAMP	RM IS: RADIO NEEDS LOCKED DOWN AND MICROPHONE NEEDS	PNPQMRMPJ
				NLRRAMP	(MED) RT & OB MADE (RLS)	PNPQMRMPJ
				NLRRAMP	(MED) WATER TESTED	PNPQMRMPJ
				NLRRAMP	(MED) WORKED INSP (RLS)	PNPQMRMPJ
				NLRRAMP	(MEM) CARDED (HLH)	PNPQMRMPJ
				NLRRAMP	(MEM) MADE IB & MR (HLH)	PNPQMRMPJ
	05/14/92	05/14/92		FTWORTH	(BLD) RM:SP: DUE SNOWPLOW MOD.	PHAIAMRNSPICELCD
				FTWORTH	(CLK) EW:ML: REPORTED WATER LEAKS AT EXPANSION JOINTS ON PIPE	PHAIAMRNSPICELCD
				FTWORTH	(JGL) TW: #R2 WHEEL HAS 22 FLANGE HEIGHT - 40 RIM THICKNESS	PHAIAMRNSPICELCD
				FTWORTH	(LWT) TK: CHECK BRAKE RIGGING - OLD REPORT STATES BRK. HD. WORN	PHAIAMRNSPICELCD
				FTWORTH	(MAT) CD: REPORTED ENGR' MIRROR NEEDS REPLACING	PHAIAMRNSPICELCD
				FTWORTH	(MAT) IC: CAB SEAT NOT SECURE	PHAIAMRNSPICELCD
				FTWORTH	(OK) AI AM DUE	PHAIAMRNSPICELCD
				FTWORTH	(RDN) SP: FRONT SNOWPLOW, LEFT BOTTOM NEEDS REPAIR	PHAIAMRNSPICELCD
				FTWORTH	(RTH) EL: REPORTED THROTTLE STICKS FROM NOTCH TO NOTCH	PHAIAMRNSPICELCD
				FTWORTH	***** *** REPORT	PHAIAMRNSPICELCD
				FTWORTH	***** FROM WATER TANK TO ENG. BLOCK	PHAIAMRNSPICELCD
				FTWORTH	***** TW: #1, 3, 4 WHEELS HAVE 21 FLANGE HEIGHT- SEE WHEEL	PHAIAMRNSPICELCD
	08/14/92	08/15/92		FTWORTH	(CG) *LM* ADD 14 (80Z) BAGS OF BORATES TO COOLING WATER UNIT	PNPQMTWASH
				FTWORTH	(JG) TURN #'S 1,3,4 WHEELS FOR HIGH FLANGES	PNPQMTWASH
				FTWORTH	***** INSPECTION WORKED ***** 2ND	PNPQMTWASH
				FTWORTH	***** PI QM *****	PNPQMTWASH
	11/11/92	11/11/92		HOUSTON	(CM) MOD 090	PNPISHRFLUPJCWNA
				HOUSTON	(CM) REPAIRED FRONT DOOR LOCK	PNPISHRFLUPJCWNA
				HOUSTON	(CM) REPLACED FIRST AID KIT	PNPISHRFLUPJCWNA
				HOUSTON	(CM) REPLACED R & L MIDDLE CAB GLASSES	PNPISHRFLUPJCWNA
				HOUSTON	(HV) APPLIED BRAKE AWAY SPRINGS TO SAFETY CHAINS	PNPISHRFLUPJCWNA
				HOUSTON	(HV) CLEANED FUEL SIGHT GLASS.	PNPISHRFLUPJCWNA
				HOUSTON	(HV) CLEANED VEE AT STACKS.	PNPISHRFLUPJCWNA
				HOUSTON	(HV) FILLED GOVERNOR W/OIL	PNPISHRFLUPJCWNA
				HOUSTON	(HV) MOD 008A	PNPISHRFLUPJCWNA
				HOUSTON	(HV) MOD 009A	PNPISHRFLUPJCWNA
				HOUSTON	(HV) REPLACED R. REAR MAIN RES. HOSE	PNPISHRFLUPJCWNA
				HOUSTON	(HV) STRAIGHTENED FRONT UPRIGHT BOTTOM BRACKET	PNPISHRFLUPJCWNA
				HOUSTON	(HV) WASHED ENGINE	PNPISHRFLUPJCWNA
				HOUSTON	(JG) REPLACED "C" THROTTLE SWITCH	PNPISHRFLUPJCWNA

UNION PACIFIC RAILROAD
 LOCOMOTIVE MAINTENANCE HISTORY
 FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
 TIME PERIOD: 1988 - 1992
 OMNT459.FOCUS.MAINTING

LOCOMOTIVE PLACE DATE RELEASE DATE

NUMBER	MO DA YR	MO DA YR	LOCATION	DETAIL
--------	----------	----------	----------	--------

UP 002360	11/11/92	11/11/92	HOUSTON	(KG) MOD 053
	12/28/92	12/28/92	POCATELLO	(JEW) ARR SERVICE PIT OFF LINE OUT OF WATER(FILLED)
			POCATELLO	(JEW) NEEDS ALL SEATS C/O ARR NO ARMREST
			POCATELLO	(JEW) NEEDS OBT APPLIED
			POCATELLO	(JEW) REPORTED-TRIPPED LOW WATER-RESTARTED-OUT OF WATER
			POCATELLO	(JEW) RM-NEEDS ANTENA FOR ATCS MODS-NOT APPLIED
			POCATELLO	(JEW) RUN PACKET (RHL)

WORK CODES

PNPISMRFLUPJCWA
 USUFWLEWELOBPJRI
 USUFWLEWELOBPJRI
 USUFWLEWELOBPJRI
 USUFWLEWELOBPJRI
 USUFWLEWELOBPJRI
 USUFWLEWELOBPJRI

000072

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
OMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE MO DA YR	LOCATION	DETAIL	WORK CODES
UP 003243	01/01/70	03/24/92		NPLSERTK	(***) *** DUE, DONE ON 03/24/92 AT SLC	PMHMCMSI
				NPLSERTK	(FMP) **RF** BRAKES NOT RELEASING,	PMHMCMSI
				NPLSERTK	(FMP) RIGHT 1 BRAKE ADJUSTER PIN MISSING, REPLACED	PMHMCMSI
	12/31/87	01/06/88		SALLAKCIT	() PROJECTS (05-***).	MMADEWLT
				SALLAKCIT	(DLG)*ST* ENGINE OIL LOW.(DTC)	MMADEWLT
				SALLAKCIT	(DLG)*ST* FUEL BYPASSING.(DTC)	MMADEWLT
				SALLAKCIT	(DLG)C/O FUEL FILTERS	MMADEWLT
				SALLAKCIT	(GGJ)*ST* FRONT AX.(DTC)	MMADEWLT
				SALLAKCIT	(GGJ)*ST* FRONT PILOT BENT OUT (STOPS & HANDRAILS BENT).(DTC)	MMADEWLT
				SALLAKCIT	(MMH)*MM* 46 DAY MAINTENANCE DUE.	MMADEWLT
				SALLAKCIT	(DEM)WASH	MMADEWLT
				SALLAKCIT	HELD 12/31 DUE	TRACK OS MMADEWLT
	01/24/88	01/28/88		NPLATTE	() *RM* CCS CONDUIT WIRING	RMRFADWA
				NPLATTE	(EDD) REPAIR SNOW PLOW, MOUNTING BOLTS SHEARED<SDK>	RMRFADWA
				NPLATTE	(EDD) WELD PILOT TO POCKET BRACE, L SIDE<SDK>	RMRFADWA
				NPLATTE	(HEC) *RM* WHEEL SLIP	RMRFADWA
				NPLATTE	(HEC) #2 PROBABLE CAUSE OF WHL SLIP	RMRFADWA
				NPLATTE	(HEC) CCS CONDUIT WRNG REPAIRED	RMRFADWA
				NPLATTE	(HEC) REBRUSHED #2,4 TH'SSHORT BRUSHES	RMRFADWA
				NPLATTE	(JEB) CCS TO TEST<HEC>	RMRFADWA
				NPLATTE	(JEB) S&C OK	RMRFADWA
				NPLATTE	(JHC) WASHED OAS COMPL	RMRFADWA
				NPLATTE	(RLD) REPLACE BARS AFTER SNOW PLOW REPAIRED<HEC>	RMRFADWA
				NPLATTE	(EEH) FRT TRAIN LINE PIPES TO APPLY <EDD>	RMRFADWA
	02/08/88	03/04/88		NLRJENKS	() GRAY	TIRFWAFIEPPTTS
				NLRJENKS	() TOUCH UP	TIRFWAFIEPPTTS
				NLRJENKS	(DWN) PAINT INT	TIRFWAFIEPPTTS
				NLRJENKS	(DWN) PAPER	TIRFWAFIEPPTTS
				NLRJENKS	(DWN) PRIME	TIRFWAFIEPPTTS
				NLRJENKS	(DWN) RINSE	TIRFWAFIEPPTTS
				NLRJENKS	(DWN) SANDBLAST	TIRFWAFIEPPTTS
				NLRJENKS	(DWN) SCOTCHLITE	TIRFWAFIEPPTTS
				NLRJENKS	(DWN) YELLOW	TIRFWAFIEPPTTS
				NLRJENKS	(FH) BLOW	TIRFWAFIEPPTTS
				NLRJENKS	(FH) GRIND	TIRFWAFIEPPTTS
				NLRJENKS	(FH) MASK	TIRFWAFIEPPTTS
				NLRJENKS	(FH) WIPE	TIRFWAFIEPPTTS
	03/24/88	03/26/88		NPLATTE	(EDD) HAD 7LB PRESSURE CAP	RFCOTW
				NPLATTE	(EDD) NO WL FOUND	RFCOTW
				NPLATTE	(EDD) SINK STOPPERS LK <EDD>	RFCOTW
				NPLATTE	(KAB) *ST* WT FLG<RAW>	RFCOTW
				NPLATTE	(KAB) REPAIR A/C LOCKER DOOR AT ACCESSORY RACK<SDK>	RFCOTW
				NPLATTE	(SDK) *RF* LD BOXED OK NO DEFECTS FOUND AT HINKLE.	RFCOTW
				NPLATTE	(SDK) *RF* REP DIES, LD WTR.	RFCOTW
				NPLATTE	(SDK) #2 COOLING FAN FUSES BLOWN, NEW<SDK>	RFCOTW
				NPLATTE	(SDK) S/C OK<SDK>	RFCOTW

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
OMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE DATE MO DA YR	LOCATION	DETAIL	WORK CODES
UP 003243	06/08/88	06/09/88		POCATELLO	(JEW) PAST DUE PI DIC POC (KFB)	PIQM
	08/25/88	08/27/88		SALLAKCIT	() *RM* CCP&DIC	MI
				SALLAKCIT	() *ST* AIR COMP ROOM OILY	MI
				SALLAKCIT	() *ST* CLEAN EDUCTOR TUBES	MI
				SALLAKCIT	() *ST* OOS	MI
				SALLAKCIT	() *12-13-14-15-16 FLASHCOCK TUBES (CRACKED WELD AT HEAD POT)	MI
				SALLAKCIT	() C/O #9 ROCKERS (ROLLERS BAD)	MI
				SALLAKCIT	() PRESSURE CHECK - CK RPLS	MI
				SALLAKCIT	() START & CHECK	MI
				SALLAKCIT	() WASH	MI
				SALLAKCIT	(BPC)C/O #7 ASSY (SCORED PISTON AND LINER)	MI
				SALLAKCIT	*****SEND DIC TO NLR XC*****	MI
				SALLAKCIT	HELD 08/25 DUE	TRACK 05 MI
	10/11/88	10/14/88		NLRJENKS	(DB) 8 HOUR LOADTEST MADE	PISHXCXGAGACRDWA
				NLRJENKS	(REP) FINAL AIRTEST MADE	PISHXCXGAGACRDWA
				NLRJENKS	(SCL) OUTBOUND MADE & WORKED	PISHXCXGAGACRDWA
				NLRJENKS	(SCL) PI INSP., MADE	PISHXCXGAGACRDWA
				NLRJENKS	(SCL) XC COMPLETE ENGINE CHANGE MADE	PISHXCXGAGACRDWA
	11/17/88	11/26/88		NPLATTE	(***) SEND TO NLR ON RELEASE REPAINT NUMBERS ON REAR OF UNIT(GIP)	RFCDELAG
				NPLATTE	(DET) S&C OK	RFCDELAG
				NPLATTE	(HEC) ALT CIRC GRNDED(HEC)	RFCDELAG
				NPLATTE	(HEC) GRIDS READ LOW(HEC)	RFCDELAG
				NPLATTE	(HEC)*RF* GROUND RELAY ACTION.	RFCDELAG
				NPLATTE	(MRH) BATT CHG ASSY TO FIN(HEC)	RFCDELAG
				NPLATTE	(MRH) NO BATT CHG(DET)	RFCDELAG
				NPLATTE	(MRH) TH'S ARE MET BUT OK-STILL HITS LOW-LOAD BOX	RFCDELAG
				NPLATTE	(MRH) WIRING & CABLING DONE	RFCDELAG
				NPLATTE	(MRH) WIRING ON AUX GEN WIRING OPEN HV WIRING IN GEN PIT (RWJ)	RFCDELAG
				NPLATTE	(PST) BOILERMAKERS TO COVER & TRY OUTSIDE (MRH)	RFCDELAG
				NPLATTE	(PST) HAND RAILS APPLIED	RFCDELAG
				NPLATTE	(RAS) ABOVE "D" CONTACTORS, CARBODY ROOF HAS BIG CRACK ALL WAY	RFCDELAG
				NPLATTE	(RAS) AUX GEN NEW & ALIGNED--WASHERS WELDED(RAS)	RFCDELAG
				NPLATTE	(RLD) AUX GEN UNHOOKED & OUT (MRH)	RFCDELAG
				NPLATTE	(RLD) C/O AUX FAILED 6V TEST(HEC)	RFCDELAG
				NPLATTE	(RLD)*ST* AUX GEN B/O - NO A.C. OUTPUT. (DMS)	RFCDELAG
				NPLATTE	ACROSS ALLOWING WATER & OIL IN ON CABLES ETC: NEEDS WELDED (MRH)	RFCDELAG
	01/14/89	01/18/89		SALLAKCIT	ARE PIPED BELOW CAB FLOOR.....	PIQM
				SALLAKCIT	TOP FRONT BOLT MISSING AND HOLDING BRACKET BROKEN	PIQM
				SALLAKCIT	(BA) *ST* PI INSP	PIQM
				SALLAKCIT	(BA) INSP(M-OK)(E-OK)(CC-OK)(B-OK)	PIQM
				SALLAKCIT	(BA) WORK BRAKES	PIQM
				SALLAKCIT	(BA) WORK TH'S	PIQM
				SALLAKCIT	(EFF) TEST & CARD	PIQM
				SALLAKCIT	(EFF) WORK TEST OUT	PIQM
				SALLAKCIT	(GMD)*SPCL*04*INSPECT TO INSURE AUTO & INDP BRAKE VALVE EXHAUSTS	PIQM
				SALLAKCIT	(GMD)*SPCL*12*CK 'GN' & 'GP' TEST PANEL BINDING POST TIGHTNESS	PIQM

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
OMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE DATE MO DA YR	LOCATION	DETAIL	WORK CODES
UP 003243	01/14/89	01/18/89		SALLAKCIT	(GWO)*ST* L. MAIN RES THERMONIC INOPERATIVE *NEW*	PIGM
				SALLAKCIT	(GWO)*ST* RF WINDOW WIPER B/O	PIGM
				SALLAKCIT	(GWO)WORK AIR	PIGM
				SALLAKCIT	(JRB)*SPCL*35*APPLY M.U. JUMPER CABLE 'CAN' TO EACH END OF LOCO	PIGM
				SALLAKCIT	(JRB)WASH	PIGM
				SALLAKCIT	(JRB)WORK BHK WHITE SHEETS	PIGM
				SALLAKCIT	HELD 01/14	PI DUE
	04/18/89	04/20/89		NPLATTE	(AJG) WASHED COMPLETE	TRACK 01 PIGM
				NPLATTE	(DET) CCS AIR TEST TO DO (WRD)	AIRWATS
				NPLATTE	(DET) TEST & CARD TO DO (WRD) CARDED 04/20	AIRWATS
				NPLATTE	(JES)*ST* TS DONE	AIRWATS
				NPLATTE	(JPG) ALL FILTERS NEW	AIRWATS
				NPLATTE	(JPG)*RM* SHOP FOR AI MACH AND ELECT DONE	AIRWATS
				NPLATTE	(JPG)076 MOD DONE	AIRWATS
	07/20/89	07/21/89		FTWORTH	GROUNDED--TO RENEW	PIGMWASNLVEL
				FTWORTH	(JAP) WASH	PIGMWASNLVEL
				FTWORTH	(KH) L.V. GRD. IN LOCAL CONTROL CIRCUIT--WATER DRAIN VALVE	PIGMWASNLVEL
				FTWORTH	(KH) CHECK SANDERS	PIGMWASNLVEL
				FTWORTH	(OK) PI GM	PIGMWASNLVEL
				FTWORTH	(3RD) ELECT. R/O OK	PIGMWASNLVEL
	10/17/89	10/20/89		NPLATTE	(AJS) CHANGE OIL FILTERS & FILL WITH OIL	PIENMAPJLMTSPAOT
				NPLATTE	(AJS) REPAIR FRONT LATCHES ON L-2 TOP DECK LID	PIENMAPJLMTSPAOT
				NPLATTE	(AJS) REPRESSURE (EDD)	PIENMAPJLMTSPAOT
				NPLATTE	(DEL) *WA* WASH UNIT THROUGH WASH HOUSE	PIENMAPJLMTSPAOT
				NPLATTE	(DLB) SPAH1 WIRE TO MULTI-PLEX GROUNDED*** NO GRNDS IN INTERFACE	PIENMAPJLMTSPAOT
				NPLATTE	(EDD) OIL & FLTRS NEW	PIENMAPJLMTSPAOT
				NPLATTE	(JAB) *LM* RED LAB - CHANGE LUBE OIL FILTERS**FILTERS OUT TO WASH	PIENMAPJLMTSPAOT
				NPLATTE	(JAB) *LM* RED LAB - CHANGE LUBE OIL**OIL OUT**	PIENMAPJLMTSPAOT
				NPLATTE	(JAB) *LM* RED LAB - WATER LEAKS (FREE WATER)	PIENMAPJLMTSPAOT
				NPLATTE	(JAB) #15 ASSY CRABS BROKEN & LIFTED (KLS)	PIENMAPJLMTSPAOT
				NPLATTE	(JAB) CHECK MAIN BEARINGS	PIENMAPJLMTSPAOT
				NPLATTE	(JAK) EMULSIFIED OIL & TRIPS CCP (MRH)*****.6" VACUUM*****	PIENMAPJLMTSPAOT
				NPLATTE	(JAK) NEEDS LOAD BOXED AGAIN (MRH)	PIENMAPJLMTSPAOT
				NPLATTE	(KLS) *ISC*RADIATION PIPE CLAMP NEEDS WELDED RIGHT SIDE (DET)	PIENMAPJLMTSPAOT
				NPLATTE	(KLS) *PJ* 014 REMOVE DEAD MAN PEDAL*DONE*	PIENMAPJLMTSPAOT
				NPLATTE	(KLS) *SM* PI DUE 10/16**DONE*	PIENMAPJLMTSPAOT
				NPLATTE	(KLS) ALL FILTERS NEW	PIENMAPJLMTSPAOT
				NPLATTE	(KLS) MACH & ELECT INSP DONE	PIENMAPJLMTSPAOT
				NPLATTE	(MRH) CARDED 10-20	PIENMAPJLMTSPAOT
	12/03/89	12/06/89		SALLAKCIT	(DND)*ST* TURBO PUMP TRIP BREAKER (LER)	RFHNEWALT
				SALLAKCIT	(JEA)C/O TURBO LUBE PUMP (NTR TRIPS BREAKER)	RFHNEWALT
				SALLAKCIT	(LMF)*EW* DEAD AND DRAINED (LER)	RFHNEWALT
				SALLAKCIT	(LMF)*MM* 46 DAY MAINTENANCE	RFHNEWALT
				SALLAKCIT	(LMF)*ST* REPORTED POWER ASSEMBLYS B/O (LER)	RFHNEWALT
				SALLAKCIT	(LMF)C/O FILLER NECK & APPLY 20 PSI PRESS. CAP	RFHNEWALT
				SALLAKCIT	(LMF)PRESS CK CK RPL'S	RFHNEWALT

000075

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
QWNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE DATE MO DA YR	LOCATION	DETAIL	WORK CODES
UP 003243	12/03/89	12/06/89		SALLAKCIT	(LMF)REPAIR WATER LEAKS F Y PIPE-WATER SIGHT GLASS-OILCOOLER EAR	RFHMEWALT
				SALLAKCIT	(PDB)*RF* ARR, VGS DIC, FROM YND THRU, SAME	RFHMEWALT
				SALLAKCIT	(PDB)START & CHECK	RFHMEWALT
				SALLAKCIT	(PDB)TRIPS TURBO LUBE PUMP BKR (C/O WEAK BREAKER)	RFHMEWALT
				SALLAKCIT	HELD 12/03/89 DUE	TRACK OS RFHMEWALT
	12/22/89	12/22/89		NORPLTSE	() SHUTTER MAG VALVE INOP(DJR)	LULVCOOP
				NORPLTSE	(AJS) LUBE OIL DRAINED DOWN // OVERFULL OIL	LULVCOOP
				NORPLTSE	(AJS) LUBE OIL DRAINED DOWN ACCT OVERFULL	LULVCOOP
				NORPLTSE	(DJR) WARNING LITE NEW	LULVCOOP
				NORPLTSE	(MGS) X-BELL VALVE IN CAB NEEDS REPLACED (MRH)	LULVCOOP
				NORPLTSE	(MRH) BOTH SHUTTER CYL'S-NEW	LULVCOOP
				NORPLTSE	(MRH) HORN VALVE IN A/C ROOM B/O TO C/O (C/O-NEW)	LULVCOOP
				NORPLTSE	(MRH) S&C OK	LULVCOOP
				NORPLTSE	(MRH) SHUTTER MAG VALVE INOPERATIVE	LULVCOOP
				NORPLTSE	(PJT)*WASH COMPLETE (OAS)	LULVCOOP
	12/31/89	01/01/90		NPLATTE	(HOD) S/C OK	OSMA
				NPLATTE	(HOD) ST OAS	OSMA
				NPLATTE	(HJF) ENGINE CHKS GOOD, NO DEFECTS FOUND (HJF)	OSMA
				NPLATTE	(PJT) WASH UNIT	OSMA
	01/20/90	01/21/90		NPLATTE	() *PJ* 053 ATCS WORKORDER MOD	PIQMBNCPDELEXPJ
				NPLATTE	() CCS AIR TEST.(TLL)	PIQMBNCPDELEXPJ
				NPLATTE	() HACH/ELECT T/C.(TLL)	PIQMBNCPDELEXPJ
				NPLATTE	() *IBC* COMP CONT MAG VALVE B/O (DJR)**REBUILT CK ON T/C**	PIQMBNCPDELEXPJ
				NPLATTE	(***) *PJ* 053 ATCS WORKORDER MOD	PIQMBNCPDELEXPJ
				NPLATTE	(DET) CARDED 01/21	PIQMBNCPDELEXPJ
				NPLATTE	(DET) CCS AIR TEST.(TLL)	PIQMBNCPDELEXPJ
				NPLATTE	(DET) HACH/ELECT T/C.(TLL)	PIQMBNCPDELEXPJ
				NPLATTE	(DET)*IBC* COMP CONT MAG VALVE B/O (DJR)**REBUILT CK ON T/C**	PIQMBNCPDELEXPJ
				NPLATTE	(JHC) WASH UNIT	PIQMBNCPDELEXPJ
				NPLATTE	(SVT) *ST* TOILET SERVICED	PIQMBNCPDELEXPJ
				NPLATTE	(TLL) *BM* CCS MAG VALVE DUE CHANGE (EHB).	PIQMBNCPDELEXPJ
				NPLATTE	(TLL) *PJ* 008 APPLY GRAB IRONS TO MD BOX	PIQMBNCPDELEXPJ
				NPLATTE	(TLL) *PJ* 084 PERMANET INSTALATION ROT. **ROT# 22003**	PIQMBNCPDELEXPJ
				NPLATTE	(TLL) DUE PI/OM INSP **ALL FILTERS NEW**	PIQMBNCPDELEXPJ
				NPLATTE	(TLL) HORN B/O.(TLL) **NEW**	PIQMBNCPDELEXPJ
				NPLATTE	(TLL)*IBC* ENGINEER'S WIPER NEEDS ORIFICE IN AIR LINE (DJR)	PIQMBNCPDELEXPJ
				NPLATTE	(TLL)*IBC* EXP JOINT BETWEEN #1 & #2 SECTIONS LEAK (DJR)**NEW**	PIQMBNCPDELEXPJ
				NPLATTE	(TLL)*IBC* LEFT FRONT SANDER PLUGGED (DJR)	PIQMBNCPDELEXPJ
				NPLATTE	(TLL)*IBC* OIL LEAK AT 4-BOLT FLG FROM SCAVENGER PUMP	PIQMBNCPDELEXPJ
				NPLATTE	(TLL)*IBC* WATER LEAKS AT TEMP SWITCH WATER MANIFOLD (DJR)	PIQMBNCPDELEXPJ
	02/26/90	03/01/90		NPLATTE	(DJR) FIREMAN'S WIPER HOSE LEAKS	TWALPAFIPJICCD
				NPLATTE	(DJR) S&C OK	TWALPAFIPJICCD
				NPLATTE	(DLB) *PJ* 053 ATCS SER # MCP 159 LDB 418 PWR SUPPLY 11890615	TWALPAFIPJICCD
				NPLATTE	(DLB) ATCS TO FINISH	TWALPAFIPJICCD
				NPLATTE	(EDD) *ST* PRESSURIZED WATER SYSTEM(DAC)	TWALPAFIPJICCD
				NPLATTE	(EEH) 10 ASSY'S MLKS	TWALPAFIPJICCD

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
OMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE DATE MO DA YR	LOCATION	DETAIL	WORK CODES
UP 003243	02/26/90	03/01/90		NPLATTE	(KLS) *ST* WHEEL TRUE #3 SHELL(DAC) FORM 25005	TWMLPAFIPJICCD
	03/23/90	03/25/90		NPLATTE	(RAS) FIREMAN'S DOOR HARD TO OPEN	TWMLPAFIPJICCD
				SALLAKCIT	(BEB) START & CHECK	SORMOSEWALT
				SALLAKCIT	(JEA) WASH CARBODY	SORMOSEWALT
				SALLAKCIT	(JRB) ELECT TESTOUT	SORMOSEWALT
				SALLAKCIT	(JRB) MACH TESTOUT	SORMOSEWALT
				SALLAKCIT	(JRB) PRESSURE CHECK - CK RPLS	SORMOSEWALT
				SALLAKCIT	(LMF) *RM* 03/22 UP076 OIL OUT STACK	SORMOSEWALT
				SALLAKCIT	(LMF) C/OIL SEPERATOR FILTER	SORMOSEWALT
				SALLAKCIT	(LMF) CK TOP DECK COVER SEALS	SORMOSEWALT
				SALLAKCIT	(LMF) TORQUE HEAD SAVER FRAMES	SORMOSEWALT
				SALLAKCIT	(LMF) WASH	SORMOSEWALT
				SALLAKCIT	(M.JL) *ST* BRAKE SHOES WORN(M.JL)	SORMOSEWALT
				SALLAKCIT	(M.JL) *ST* BRAKE TRAVEL LONG(M.JL)	SORMOSEWALT
				SALLAKCIT	(PIT) *ST* RADIO MISSING(M.JL)	SORMOSEWALT
				SALLAKCIT	***** UNIT IDLED IN PROVO FOR 87 HOURS*****	SORMOSEWALT
				SALLAKCIT	HELD 03/23/90 DUE	TRACK 05 SORMOSEWALT
	03/31/90	03/31/90		POCATELLO	(RHL) FRONT CUT LEVERS TO LONG	ABCDTK
				POCATELLO	(RHL) LEFT # 1 BRAKE HEAD BROKEN	ABCDTK
	04/09/90	04/10/90		SALLAKCIT	(***) *SPCL*002*UPDATE THE UM SCREEN OF THE LOCO MANAGEMENT STYSTH	SBTW
				SALLAKCIT	(***) *SPCL*045*REPLACE MANUAL 3-WAY VALVE WITH AMOT	SBTW
				SALLAKCIT	(***) *SPCL*096*APPLY TSM LOCOTEMP RADIATOR FAN CONTROL SYSTEM	SBTW
				SALLAKCIT	(BEJ) ETO	SBTW
				SALLAKCIT	(BEJ) MTO	SBTW
				SALLAKCIT	(JRB) *ST* SHELLING L & R #2&3	SBTW
				SALLAKCIT	(PIT) *ST* LUBE OIL LOW	SBTW
				SALLAKCIT	(PPA) START & CHECK	SBTW
				SALLAKCIT	(SPT) *ST* L AND R AUTO DRAINS CUTOUT	SBTW
				SALLAKCIT	(SPT) *ST* WORK BRAKES	SBTW
				SALLAKCIT	HELD 04/09 AI 4-23-90	TRACK 08 SBTW
	04/21/90	04/22/90		POCATELLO	(RHL) AI TEST AND CARD	AIWA
				POCATELLO	(RHL) DUE AI 04-22-90.	AIWA
				POCATELLO	(RHL) MACHINIST DONE ALL BUT RUNNING CHECKSELECT TO DO YET	AIWA
				POCATELLO	(RHL) WASH COMPLETE	AIWA
	06/22/90	06/22/90		POCATELLO	(RHL) CHECK MANAUL TRANS.	RFNLELLT
				POCATELLO	(RHL) LOAD BOX 45 MINS HAS FULL HORSE POWER	RFNLELLT
				POCATELLO	(RHL) RF-LOADING 100AMPS.	RFNLELLT
				POCATELLO	(RHL) TRACK TEST	RFNLELLT
	07/23/90	07/24/90		NLRRAMP	(ALL) MAKE IB INSP & MR (HBL)	PIGRHMCWPJWAWCTW
				NLRRAMP	(BJH) RM: CAB DOOR GLASS CRACKED	PIGRHMCWPJWAWCTW
				NLRRAMP	(CR) INSP WORKED (WCC)	PIGRHMCWPJWAWCTW
				NLRRAMP	(CR) MAKE RPL INSP UNDER WATER PRESSURE	PIGRHMCWPJWAWCTW
				NLRRAMP	(CR) RUN TEST & OB (HBL)	PIGRHMCWPJWAWCTW
				NLRRAMP	(CSC) SPCL 002: UM UPDATE	PIGRHMCWPJWAWCTW
				NLRRAMP	(JMA) AIR TEST OB	PIGRHMCWPJWAWCTW
				NLRRAMP	(JMA) SPCL 037: REPLACE ABV EXHAUST PIPE	PIGRHMCWPJWAWCTW

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
OMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE DATE MO DA YR	LOCATION	DETAIL	WORK CODES
UP 003243	07/23/90	07/24/90		NLRRAMP	(OJ) WASHED ENG & CARBODY	PIQMRMCHPJWAMCTV
				NLRRAMP	(REG) CHANGE #6 TH A/C MDV. (HDS)	PIQMRMCHPJWAMCTV
				NLRRAMP	(TBK) TO TURN #4,5,6, WHEELS	PIQMRMCHPJWAMCTV
	09/16/90	09/17/90		NPLATTE	(DLG) *ST* #6 T.M. AIR DUCT B/O—NEW	TMTK
				NPLATTE	(RAS) *ST* LEFT REAR FUEL TANK ANGER BOLT LOOSE	TMTK
	10/22/90	10/23/90		NLRRAMP	PI SM	PISMPJWAGULT
				NLRRAMP	(BJB) 016 SPCL - APPLY REAR KNUCKLE BRACKETS	PISMPJWAGULT
				NLRRAMP	(JDB) WATER TESTED	PISMPJWAGULT
				NLRRAMP	(HDS) IB & MR MADE (JCF)	PISMPJWAGULT
				NLRRAMP	(HDS) OB & CARDED (HLJ)	PISMPJWAGULT
				NLRRAMP	(NG) AIR TESTED	PISMPJWAGULT
				NLRRAMP	(NG) AIR WORKED	PISMPJWAGULT
				NLRRAMP	(NG) FORMS WORKED (JCW)	PISMPJWAGULT
				NLRRAMP	(NG) INSP WORKED (JCW)	PISMPJWAGULT
				NLRRAMP	(PWP) B/O GOV & GOV HARNESS—NEW GOV. SER. #840791	PISMPJWAGULT
				NLRRAMP	(PWP) LOAD TESTED	PISMPJWAGULT
	01/10/91	01/10/91		FTWORTH	(CLK) CHECK SANDERS	EMOLTKCDWASN
				FTWORTH	(FB) EW: R/AFTERCOOLER CRACKED	EMOLTKCDWASN
				FTWORTH	(GKB) WASH	EMOLTKCDWASN
				FTWORTH	(LPI) CD: THERMONICS B/O LEFT MAIN RES DRAIN BD (RMS)	EMOLTKCDWASN
				FTWORTH	(LPI) CD: WIPER BLADE LOOSE ON WIPER (RMS)	EMOLTKCDWASN
				FTWORTH	(TR) OL: OIL LEAK AT OVERSPEED TRIP HOUSING	EMOLTKCDWASN
				FTWORTH	(TR) OL: OIL LEAK AT SCAVANGER PUMP PIPE FLANGE	EMOLTKCDWASN
	01/20/91	01/22/91		NLRRAMP	() CHANGE OUT GROUNDED #1 GRID BLOWER	PIQMRFR
				NLRRAMP	() LOAD TESTED	PIQMRFR
				NLRRAMP	() RF= KICKING GROUND RELAY	PIQMRFR
				NLRRAMP	(AES) WATER TESTED	PIQMRFR
				NLRRAMP	(AES) WORKED INSP (JRB)	PIQMRFR
				NLRRAMP	(AES) WORKED RT/OB (JRB)	PIQMRFR
				NLRRAMP	(GAL) CARDED ()	PIQMRFR
				NLRRAMP	(GAL) MADE IB INSP & MR (JRB)	PIQMRFR
				NLRRAMP	(LW) WASHED UNIT	PIQMRFR
				NLRRAMP	(RDH) CHG 2 GRD GRIDS A-5077***** A-5076	PIQMRFR
				NLRRAMP	(RGM) WORKED AIR	PIQMRFR
	01/25/91	01/25/91		ARMSTRGYD	(TWB) ARRIVED DEAD AND DRAINED	EWEL
				ARMSTRGYD	(TWB) REBRUSHED FUEL PUMP MOTOR	EWEL
				ARMSTRGYD	(TWB) STARTED, SELF LOADED FOR 1 HOUR NO OTHER DEFECTSNOTED	EWEL
				ARMSTRGYD	(TWB) WATER PRESSURE, BARRED,	EWEL
	02/14/91	02/15/91		HINKLE	AND HIPOTS CLEAR. *****NOTE***** REAR SLIP RINGS NEEDS	RFGRM
				HINKLE	NEW BRUSHES NIS HKL PLACED ON REFERRAL	RFGRM
				HINKLE	REINSULATED CABLE HARNESS CLEANED MAIN GEN. UNIT HEGS	RFGRM
				HINKLE	(JSS) ARRIVED HKL WITH GROUND RELAY TRIPPED	RFGRM
				HINKLE	(S&H) CABLE HARNESS IN MAIN GEN ROOM GROUNDED, REPAIRED GROUND	RFGRM
	02/26/91	03/05/91		POCATELLO	() CHK SPCL 096 TSM TEMPERATURE CONTROL SYSTEM	ADPJLUMIICAS
				POCATELLO	(JEW) AX DAMAGE	ADPJLUMIICAS
				POCATELLO	(JEW) DD SPCL 058A NEW STYLE DBT BRACKET & ALL ATCS RELATED MODS	ADPJLUMIICAS

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
OMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE DATE	LOCATION	DETAIL	WORK CODES
UP 003243	02/26/91	03/05/91		POCATELLO	<JEW> DO MECHANICAL INSPECTION	ADPJLUMIICAS
				POCATELLO	<JEW> ENGINE OIL SAMPLE	ADPJLUMIICAS
				POCATELLO	<JEW> KEEP TRACK OF MANHOURS 1ST SHIFT=24_ 2ND SHIFT=___	ADPJLUMIICAS
				POCATELLO	<JEW> REPLACE F SNOWPLOW	ADPJLUMIICAS
				POCATELLO	<MCH> CHK SPCL 002A NEW STYLE CAB SEATS	ADPJLUMIICAS
				POCATELLO	<MCH> DO SPCL 050A REMOVAL OF WARNING LIGHT & DISCONNECT BREAKER	ADPJLUMIICAS
				POCATELLO	<MCH> DO SPCL 060A INSURE PHOENIX NO HIGHER THAN 32"	ADPJLUMIICAS
				POCATELLO	<MCH> RIGHT AFTERCOOLER PIPE MISSING NONE ON HAND 712-5047	ADPJLUMIICAS
	04/11/91	04/11/91		HOUSTON	REPT. GOVERNOR FAILURE	ENRFFI
				HOUSTON	(LL) CHANGED #6 INJECTOR ACCOUNT STUCK.	ENRFFI
	04/22/91	04/27/91		SALLAKCIT	CONTROL VALVE ON FUEL SYSTEM	TIPJRDWEMELWALT
				SALLAKCIT	SYSTEM	TIPJRDWEMELWALT
				SALLAKCIT	<BA> WIT #1&6 WHEEL'S (FLANGE & HIGH FLANGED)	TIPJRDWEMELWALT
				SALLAKCIT	<GWO>*ST* CLEAN EDUCTOR TUBES	TIPJRDWEMELWALT
				SALLAKCIT	<GWO>*ST* ENGINE OIL LOW	TIPJRDWEMELWALT
				SALLAKCIT	<GWO>*ST* REFRIGERATOR IS NOT RUNNING (REMOVED)	TIPJRDWEMELWALT
				SALLAKCIT	<GWO>*#14 HEAD HAS CRACKED LIFTER HOLE(WATER)	TIPJRDWEMELWALT
				SALLAKCIT	<GWO>APPLY DYNAVANES & EDUCTOR HATCH	TIPJRDWEMELWALT
				SALLAKCIT	<GWO>C/O LEFT RADIATER(LEAKS)	TIPJRDWEMELWALT
				SALLAKCIT	<GWO>CONNECT WDV	TIPJRDWEMELWALT
				SALLAKCIT	<GWO>HOOK UP HORN PIPE	TIPJRDWEMELWALT
				SALLAKCIT	<GWO>SPECIAL (36A-***) APPLY NEW STYLE CAB DOOR GRAB IRONS	TIPJRDWEMELWALT
				SALLAKCIT	<GWO>W/TMS	TIPJRDWEMELWALT
				SALLAKCIT	<JRA>APPLY RAD FAN HATCH	TIPJRDWEMELWALT
				SALLAKCIT	<JRA>C/O 7-8-9-16 PEEPIPES	TIPJRDWEMELWALT
				SALLAKCIT	<JRA>FIN AIR	TIPJRDWEMELWALT
				SALLAKCIT	<JRA>PIPE #14 ASSY	TIPJRDWEMELWALT
				SALLAKCIT	<JRA>PIPE ALL INJECTORS & BLACKLIGHT FOR LEAKS	TIPJRDWEMELWALT
				SALLAKCIT	<JRA>REMOVE & CLEAN DIODE BANKS ***DIODES OUT*** TO REBUILD	TIPJRDWEMELWALT
				SALLAKCIT	<JRA>REMOVE DYNAVANES	TIPJRDWEMELWALT
				SALLAKCIT	<JRA>SPECIAL (45-***) REPLACE MANUAL 3-WAY VALVE WITH 'AMOT'	TIPJRDWEMELWALT
				SALLAKCIT	<JRA>TEST & CARD CARDED 04/26/91	TIPJRDWEMELWALT
				SALLAKCIT	<JRB>*ST* FULL NEGATIVE LOW VOLTAGE GROUND	TIPJRDWEMELWALT
				SALLAKCIT	<JRB>*ST* WORK BRAKES	TIPJRDWEMELWALT
				SALLAKCIT	<JRB>C/O INJECTORS & VALVE BRIDGES	TIPJRDWEMELWALT
				SALLAKCIT	<JRB>REMOVE RAD HATCH	TIPJRDWEMELWALT
				SALLAKCIT	<JRM>ELECT TESTOUT	TIPJRDWEMELWALT
				SALLAKCIT	<JRM>QUALIFY MODULES	TIPJRDWEMELWALT
				SALLAKCIT	<KGP>MECH INBOUND REPORT	TIPJRDWEMELWALT
				SALLAKCIT	<KGP>RESTORE CAB & APPLY NEW REEFER.	TIPJRDWEMELWALT
				SALLAKCIT	<OEM>PAINT CAB	TIPJRDWEMELWALT
				SALLAKCIT	<OK1>SPECIAL (96-***) APPLY TSM LOCOTEMP RADIATOR FAN CONTROL	TIPJRDWEMELWALT
				SALLAKCIT	<REJ> INBOUND PROCESS	TIPJRDWEMELWALT
				SALLAKCIT	<REJ>*TI* DUE TI INSPECTION ON 04/21/91	TIPJRDWEMELWALT
				SALLAKCIT	<REJ>ELECT INBOUND REPORT	TIPJRDWEMELWALT
				SALLAKCIT	<RLV>MACH TESTOUT	TIPJRDWEMELWALT

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
DMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE DATE	LOCATION	DETAIL	WORK CODES
UP 003243	04/22/91	04/27/91		SALLAKCIT	HELD 04/22/91 DUE TI 04/21/91	TRACK 05 TIPJRDTHWELMAL
	06/08/91	06/09/91		SALLAKCIT	IMPACT DAMAGE HELPER ENG'S COLLIDED WITH APLA7 07 6/5/91 AT	SS ADDG
				SALLAKCIT	SUMMITT CA	SS ADDG
				SALLAKCIT	() *AD*APPLY ALL LABOR AND MATERIAL TO W/O 90601 JOB# 037	SS ADDG
				SALLAKCIT	(BA) *ST* FRONT PILOT BENT LEFT SIDE	SS ADDG
				SALLAKCIT	(BEB) INBOUND PROCESS	SS ADDG
				SALLAKCIT	(DND) *ST* CHECK ALARM BELL CIRCUIT	SS ADDG
				SALLAKCIT	(DND) START & CHECK	SS ADDG
				SALLAKCIT	(GGC) *ST* ADJUST BRAKE TRAVEL (GGC)	SS ADDG
				SALLAKCIT	(MLJ) *ST* REPT: AX DAMAGE DRAW BARS CRACKED	SS ADDG
				SALLAKCIT	HELD 06/08/91 DUE PI 07/27/91	TRACK 05 SS ADDG
	07/20/91	07/22/91		NPLATTE	(DET) S&C OK	RHEWEXWILT
				NPLATTE	(LDP) *RM* RIGHT TURBO AIR DUCT CRACKED	RHEWEXWILT
				NPLATTE	(LDP) *ST* LEFT TURBO AIR DUCT IS CRACKED ON BOTTOM	RHEWEXWILT
				NPLATTE	(LDP) *ST* RIGHT TURBO AIR DUCT IS CRACKED	RHEWEXWILT
				NPLATTE	(LDP) *ST* SMALL EXP. JOINT IS CRACKED**HDF**	RHEWEXWILT
				NPLATTE	(PJT) WASH ENG	RHEWEXWILT
	07/28/91	07/30/91		HOUSTON	(HV) APPLIED R. FRONT BOTTOM SAND PIPE RUBBER BOOT	PIGHEWOTWA
				HOUSTON	(HV) CLEANED FUEL SIGHT GLASS	PIGHEWOTWA
				HOUSTON	(HV) REPAIRED OIL LINE UNDER L. WATER PUMP	PIGHEWOTWA
				HOUSTON	(HV) WASHED ENGINE	PIGHEWOTWA
				HOUSTON	(HV) WIRED WATER DRAIN VALVE	PIGHEWOTWA
				HOUSTON	(JF) REPLACED FIRST AID KIT	PIGHEWOTWA
				HOUSTON	(JF) REPLACED R & L SLIDER WINDOW	PIGHEWOTWA
				HOUSTON	(MS) REPLACED LEFT FRONT WIPER BLADE	PIGHEWOTWA
				HOUSTON	(MS) WELDED GEN. ROOM FLOOR PLATE	PIGHEWOTWA
	08/19/91	08/19/91		SALLAKCIT	(***) INBOUND PROCESS	WUTW
				SALLAKCIT	(BA) *ST* #4 & #6 WHEELS MISMATCHED (RP)	WUTW
				SALLAKCIT	(BA) SHIM #6 WHEEL'S (RM)	WUTW
				SALLAKCIT	HELD 08/19/91 DUE	TRACK 06 WUTW
	10/04/91	10/04/91		NPLSERTK	(ROM) INDUCTOR TUBE CHANGED	LUNWEX
	10/17/91	10/17/91		POCATELLO	() LOAD TEST	OLMLULT
				POCATELLO	() OIL LEAK AT OIL COOLER	OLMLULT
				POCATELLO	() WASH	OLMLULT
				POCATELLO	() WATER LEAK ABOVE OIL COOLER	OLMLULT
				POCATELLO	(MCM) ENG OIL SAMPLE	OLMLULT
				POCATELLO	(MCM) LOAD TEST	OLMLULT
				POCATELLO	(MCM) OIL LEAK AT OIL COOLER	OLMLULT
				POCATELLO	(MCM) WASH	OLMLULT
				POCATELLO	(MCM) WATER LEAK ABOVE OIL COOLER. REPLACED WATER LINE.	OLMLULT
				POCATELLO	(MCM) WATER LEAK ABOVE OIL COOLER	OLMLULT
	10/27/91	10/29/91		POCATELLO	(FMP) TOILET SERVICED	PISMBHTSLUPJMI
				POCATELLO	(JEW) CCS MAG. VALVE C/O	PISMBHTSLUPJMI
				POCATELLO	(JEW) CHK SPCL 0096 TSM TEMPERATURE RADIATOR FAN CONTROL SYSTEM	PISMBHTSLUPJMI
				POCATELLO	(JEW) DO SPCL 021 APPLY LOCTITE TO OBT BRACKET BALL	PISMBHTSLUPJMI
				POCATELLO	(JEW) DO SPCL 059A REMOVE REVA MCP & REPLACE W/REVB MCP	PISMBHTSLUPJMI

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
OMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE DATE MO DA YR	LOCATION	DETAIL	WORK CODES
UP 003243	10/27/91	10/29/91		POCATELLO	(JEW) ENG OIL & WATER SAMPLE	FISMBNTSLUPJMI
				POCATELLO	(JEW) OBT BRACKET BROKEN. TO C/O.	FISMBNTSLUPJMI
				POCATELLO	(JEW) RIGHT #3 BRAKE HEAD BROKEN.	FISMBNTSLUPJMI
				POCATELLO	(MCM) C/O REAR ANGLE COCK LEAKING CHECK LEAKAGE	FISMBNTSLUPJMI
				POCATELLO	(MCM) CHECK UNLOADER FOR STICKINGBILDS AIR SLOW	FISMBNTSLUPJMI
				POCATELLO	(MCM) CHK SPCL 036A BOLT ON CAB DOOR HANDHOLDS INSTEAD OF WELDED	FISMBNTSLUPJMI
				POCATELLO	(MCM) DUE PI, SM, BM, 10/26/91	FISMBNTSLUPJMI
				POCATELLO	(MCM) OIL LEAKS AT MAIN LUBE PUMP	FISMBNTSLUPJMI
				POCATELLO	(MCM) RIGHT SHUTTER CYL TO C/O	FISMBNTSLUPJMI
	12/08/91	12/11/91		NPLATTE	(DEL) AIR BOXES TO WASH	TCMLLTWPEWELNIWA
				NPLATTE	(EDD) *ST* CHECK TURBO ALSO	TCMLLTWPEWELNIWA
				NPLATTE	(EDD) *ST* WON'T START **CHECK PARTS SAVER FOR BEING PLUGGED	TCMLLTWPEWELNIWA
				NPLATTE	(EDD) BOTH AFTERCOOLERS LK (EDD)	TCMLLTWPEWELNIWA
				NPLATTE	(EDD) CHECK AIR FLTR HSG FOR FORIEGN MATERIAL (EDD) NEEDS CLEANED	TCMLLTWPEWELNIWA
				NPLATTE	(EDD) CHECK VALVES NEW	TCMLLTWPEWELNIWA
				NPLATTE	(EDD) TURBO & SOAKBACK FLTRS NEW	TCMLLTWPEWELNIWA
				NPLATTE	(EDD) TURBO NEW TO FINISH (TLL)	TCMLLTWPEWELNIWA
				NPLATTE	(JHC) WASH ENG ROOM	TCMLLTWPEWELNIWA
				NPLATTE	(JPG) *ST* DIC INTO NOP	TCMLLTWPEWELNIWA
				NPLATTE	(JPG) OIL LK AT HOT OIL SENSOR (JPG)	TCMLLTWPEWELNIWA
				NPLATTE	(JPG) START AND CK OK	TCMLLTWPEWELNIWA
				NPLATTE	(JPG) TURBO LOAD. DONE	TCMLLTWPEWELNIWA
				NPLATTE	(TLL) C/O RIGHT WATER PUMP LEAKING. (TLL) **C/O AGAIN/LEAKS H2O**	TCMLLTWPEWELNIWA
				NPLATTE	(TLL) C/O TURBO-BO BRGS (EDD) ** NEW BACK LASH OK ** (TLL)	TCMLLTWPEWELNIWA
				NPLATTE	(TLL) DYNAVANES TO APPLY (EDD)	TCMLLTWPEWELNIWA
				NPLATTE	(TLL) ENGINE CHECKS TO DO	TCMLLTWPEWELNIWA
				NPLATTE	(TLL) RESEAL "Y" PIPE MARMON JOINTS LEAKING. (TLL)	TCMLLTWPEWELNIWA
				NPLATTE	(TLL) TURBO TO COVER	TCMLLTWPEWELNIWA
	02/02/92	02/05/92		HINKLE	CHECK DYN BKS WHEN TEST AND CARD.	PHQHRMCSP
				HINKLE	() DUE CS	PHQHRMCSP
				HINKLE	() DUE PI INSP.	PHQHRMCSP
				HINKLE	() DUE OH	PHQHRMCSP
				HINKLE	() LEFT REAR FUEL TANK BOLTS NEED TIGHTENED.	PHQHRMCSP
				HINKLE	() T & C FOR ELECT.	PHQHRMCSP
				HINKLE	(CAS) RESEAL LEFT SHUTTER CYL (LEAKING)	PHQHRMCSP
				HINKLE	(MFC) RM: 1-28-92 BO DYNL REPAIRED S25 INTERLOCK BLOCK	PHQHRMCSP
	02/14/92	02/16/92		NPLATTE	(CMF) WASHED ENG ROOM	USEXWILTRD
				NPLATTE	(HJF) EXHAUST LEAKS LEG GASKETS #8 AND 16 CYL-NEW GASKET (HJF)	USEXWILTRD
				NPLATTE	(RJR) NEW RADIO	USEXWILTRD
				NPLATTE	(RJR) S & C OK	USEXWILTRD
	02/23/92	02/23/92		NPLATTE	(CMF) *ST* WASH UNIT (EXHAUST LEAKS)	USEXOLLT WI
				NPLATTE	(DET) S&C OK	USEXOLLT WI
				NPLATTE	(VEP) *ST* HOT OIL SENSOR LEAKING OIL (VEP)	USEXOLLT WI
				NPLATTE	(VEP) *ST* PARTSAVER GASKET BLOWN (RESEALED VEP)	USEXOLLT WI
				NPLATTE	(VEP) *ST* PISTON COOLING PUMP LEAKS AT BOLT HEADS	USEXOLLT WI
				NPLATTE	(VEP) *ST* 1/4" LINE BELOW L WATER PUMP LEAKS	USEXOLLT WI

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
OMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE DATE MO DA YR	LOCATION	DETAIL	WORK CODES
UP	003243	03/25/92	03/25/92	NPLSERTK	() *25005* L2-3-4-5 J BOXES LEAKING	USMI
				NPLSERTK	() *25005* R-4 WHEEL HAS 3" SHELL, WILL TRUE	USMI
				NPLSERTK	() *25005* R2-3 J BOXES LEAKING	USMI
				NPLSERTK	(JPG) START AND CK OK ITEMS TO DO	USMI
				NPLSERTK	(PST) *ST* L#2-3-4-5 J-BOXES LEAKING **RETORQUED*	USMI
				NPLSERTK	(PST) *ST* R#2-3 J-BOXES LEAKING **RETORQUED**	USMI
				NPLSERTK	(PST) BOTH SINK STOPPERS LK(JFG)	USMI
				NPLSERTK	(PST) RECHECK J-BOX OIL LEVELS WHEN UNIT IS ON THE WHEEL TRUE#FUL	USMI
				NPLSERTK	(PST) 4 BOLT FLG OFF SCAV PUMP LKS (JFG)	USMI
				NPLSERTK	(SDK) C/O #6TH THIN & FLANGE(VEP) NEW(SDK)	USMI
				NPLSERTK	(VEP) *ST* R#4 WHEEL 3" SHELL, WILL TRUE	USMI
	04/14/92	04/15/92		ALBINA	(JLB) CHANGED WORN BRAKE SHOES, ADJUSTED PISTON TRAVEL.	TPSV
				ALBINA	(JLB) CHECKED ALL FLUID LEVELS.	TPSV
				ALBINA	(JLB) MADE MACHINICAL TRIP INSPECTION.	TPSV
	04/17/92	04/24/92		HINKLE	(ALL) WASHED ENGINE ROOM, ENGINE SUMP, AND AIR-COMP. ROOM.	PHAIAMRFLUCSTSEW
				HINKLE	(ALL) WASHED HANDRAILS, AND WALKWAYS.	PHAIAMRFLUCSTSEW
				HINKLE	(CAS/AGS) #9 ASSY B.O.	PHAIAMRFLUCSTSEW
				HINKLE	(CAS/AGS) FINISH #9 ASSY	PHAIAMRFLUCSTSEW
				HINKLE	(DLH) DUE LU	PHAIAMRFLUCSTSEW
				HINKLE	(DLH) TEST AND CARD FOR MACHINIST	PHAIAMRFLUCSTSEW
				HINKLE	(JWB/AJS) #9 TOP BRNG IN. REST TO FINISH.	PHAIAMRFLUCSTSEW
				HINKLE	(HAM) CHANGE LUBE FILTERS	PHAIAMRFLUCSTSEW
				HINKLE	(MFC) T & C FOR ELECTRICIANS.	PHAIAMRFLUCSTSEW
				HINKLE	(RLW) LOAD BOXED OK	PHAIAMRFLUCSTSEW
				HINKLE	(RLW) RUNNING TO DRY WATER FROM ENG CRANKCASE	PHAIAMRFLUCSTSEW
				HINKLE	(RLW) TRIPS CRANKCASE BUTTON IN LOADBOX, CHECKED WITH MANOMETER &	PHAIAMRFLUCSTSEW
				HINKLE	(YEP) WATER IN LUBE OIL-OIL DRAINED	PHAIAMRFLUCSTSEW
				HINKLE	(YES) DUE AI INSP.	PHAIAMRFLUCSTSEW
				HINKLE	///// HAS POSITIVE CRANKCASE PRESSURE. NEED TO ROLL ENGINE.	PHAIAMRFLUCSTSEW
	05/06/92	05/09/92		NPLATTE	(AJS) *ST* #4 LEG GASKET BO(MANIFOLD OUT)GAG)*GASKET NIS*	USMPWLEXEMLTOL
				NPLATTE	(AJS) PARTS SAVER OUT(PLUGGED)AT VAT(GAG)	USMPWLEXEMLTOL
				NPLATTE	(GAG) ON CLOCK 05/07/1200 ***712-7401***	USMPWLEXEMLTOL
				NPLATTE	(GAG) *ST* LEFT WATER PUMP LEAKS	USMPWLEXEMLTOL
				NPLATTE	(HJG) OFF CLOCK 05/08/1030 -712-7401 HERE 5-8-92 STK S1702*****	USMPWLEXEMLTOL
				NPLATTE	(MRH) *ST* TURBO BURP NOTCH 7 LOAD BX.	USMPWLEXEMLTOL
				NPLATTE	(MRH) WS10 MODULE GONE	USMPWLEXEMLTOL
				NPLATTE	(RAS) #11 & #14 VALVE KEEPERS B/O (MRH)	USMPWLEXEMLTOL
				NPLATTE	(RAS) NEEDS TOP DECK EXT'S TIGHTENED (MRH)	USMPWLEXEMLTOL
				NPLATTE	(RAS) TOP OFF ENG OIL (MRH)	USMPWLEXEMLTOL
				NPLATTE	(RJR) S & C OK	USMPWLEXEMLTOL
	07/21/92	08/04/92		NPLATTE	FITTING	PHPIGMWACSTRTCDB
				NPLATTE	FRAME (HOOD)	PHPIGMWACSTRTCDB
				NPLATTE	FULL OF WATER (SDK)	PHPIGMWACSTRTCDB
				NPLATTE	GRID CKT STILL GRD, L SIDE UNHOOKED---D-CONT LOCKER WAS	PHPIGMWACSTRTCDB
				NPLATTE	SIDE OF ENGINE-MARKED ** TURBO C/O **	PHPIGMWACSTRTCDB
				NPLATTE	(***) *RF* KICKS LOW WTR AND GOV BUTTON (NO ROAD FAILURE ON FILE)	PHPIGMWACSTRTCDB

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
QMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE DATE MO DA YR	LOCATION	DETAIL	WORK CODES
UP	003243	07/21/92	08/04/92	NPLATTE	(***) 1ST AID KIT EMPTY (MRH)	PNPIQWACSTRTCDB
				NPLATTE	(AJS) BRANCH PIPE TO APPLY (EDD)	PNPIQWACSTRTCDB
				NPLATTE	(AJS) GRIDS UNCOVERED (AJS) C/O #2 GRID BLWR, GRD	PNPIQWACSTRTCDB
				NPLATTE	(AJS) KNUCKLE BRACKETS ON FUEL TANK NEED REMOVED	PNPIQWACSTRTCDB
				NPLATTE	(AJS) PART SAVER APPLIED TO TIGHTEN (EDD)	PNPIQWACSTRTCDB
				NPLATTE	(DET) CARDED 08/03/92	PNPIQWACSTRTCDB
				NPLATTE	(DET) L/S MRAD BLOWS ALL TIME (MRH)	PNPIQWACSTRTCDB
				NPLATTE	(DET) STILL GR IN LOAD BOX (MRH)	PNPIQWACSTRTCDB
				NPLATTE	(DET) TURBO LOAD TO DO. (TLL)	PNPIQWACSTRTCDB
				NPLATTE	(DJR) *RM* PULSE TAPE DOES NOT RECORD ABOVE 3TH NOTCH	PNPIQWACSTRTCDB
				NPLATTE	(DJR) CONDUIT & WIRE LOOSE TO DIRT BLOWER GEN ROOM	PNPIQWACSTRTCDB
				NPLATTE	(DJR) DYNAMIC BRAKE CUTOFF SWITCH NOT SEALED	PNPIQWACSTRTCDB
				NPLATTE	(DLB) #2 GRID BLOWER NEW.	PNPIQWACSTRTCDB
				NPLATTE	(DLB) #5 TH CKT GROED, VERIFIED (RLD)	PNPIQWACSTRTCDB
				NPLATTE	(DLB) C/O #1 TH, THIN FLANGE (DLB)	PNPIQWACSTRTCDB
				NPLATTE	(DLB) C/O #2 TH GRD ARM, VERIFIED (SDK)	PNPIQWACSTRTCDB
				NPLATTE	(DLB) L1 AND R1 GRIDS NEW.	PNPIQWACSTRTCDB
				NPLATTE	(EDD) EXHAUST MANIFOLD BLOW OUT TO DO. (TLL)	PNPIQWACSTRTCDB
				NPLATTE	(EDD) L FRONT PILOT BENT FORWARD & KNEE BRACE IS BROKEN AWAY FROM	PNPIQWACSTRTCDB
				NPLATTE	(EDD) LEFT #3-4 WHEELS PED SHOES B/O. (HOO)	PNPIQWACSTRTCDB
				NPLATTE	(EDD) PARTS SAVER TO APPLY. (TLL)	PNPIQWACSTRTCDB
				NPLATTE	(HOO) *PJ* 001 SUMMERIZATION	PNPIQWACSTRTCDB
				NPLATTE	(HOO) *PJ* 036 FRA LIST	PNPIQWACSTRTCDB
				NPLATTE	(HOO) AIR COMPRESSOR AIR FILTER HOUSING LOOSE, BOLTS GONE	PNPIQWACSTRTCDB
				NPLATTE	(HOO) AUX GEN SHAFT COVER TOO SHORT & LOOSE	PNPIQWACSTRTCDB
				NPLATTE	(HOO) C/O R SHUTTER CYL. LEAKING AIR. (HOO)	PNPIQWACSTRTCDB
				NPLATTE	(HOO) CLIP ON FRONT MU COVER MISSING	PNPIQWACSTRTCDB
				NPLATTE	(HOO) FRONT CROSSWALK LIGHT COVER CRACKED & BOLTS MISSING	PNPIQWACSTRTCDB
				NPLATTE	(HOO) LEFT MAIN RES AUTO DRAIN B/O	PNPIQWACSTRTCDB
				NPLATTE	(HOO) LEFT REAR WIPER B/O	PNPIQWACSTRTCDB
				NPLATTE	(HOO) LEFT 1 & 2 PED SHOE LOOSE BOLTS	PNPIQWACSTRTCDB
				NPLATTE	(HOO) NO DATES ON FIRE EXTINGUISHERS	PNPIQWACSTRTCDB
				NPLATTE	(HOO) OIL LEAK ON QUARTER INCH LINE BELOW LEFT WATER PUMP-FLARE	PNPIQWACSTRTCDB
				NPLATTE	(HOO) REAR CROSSWALK STEP GONE-LAYING ON WALKWAY REAR OF UNIT	PNPIQWACSTRTCDB
				NPLATTE	(HOO) REFRIGERATOR B/O (NEW 7-23-92.)	PNPIQWACSTRTCDB
				NPLATTE	(HOO) RIGHT FRONT FUEL TANK BOLTS NEED TIGHTENED	PNPIQWACSTRTCDB
				NPLATTE	(HOO) RIGHT REAR HANDRAIL UP RIGHT BENT-MARKED.	PNPIQWACSTRTCDB
				NPLATTE	(HOO) RIGHT REAR SAND HOSE OUT OF CLAMP	PNPIQWACSTRTCDB
				NPLATTE	(HOO) RIGHT SIDE SPOOL GASKET LEAKS-MARKED	PNPIQWACSTRTCDB
				NPLATTE	(HOO) RIGHT 2 BRAKE SHOE OVERRIDING WHEEL	PNPIQWACSTRTCDB
				NPLATTE	(HOO) SPOT 2	PNPIQWACSTRTCDB
				NPLATTE	(HOO) SPOT 3	PNPIQWACSTRTCDB
				NPLATTE	(HOO) TH4 CARBODY CABLE CLAMP LOOSE	PNPIQWACSTRTCDB
				NPLATTE	(HOO) TOP DECK LIDS LEAKING AT CORNERS	PNPIQWACSTRTCDB
				NPLATTE	(HOO) WATER INGEN ROOM SUMP	PNPIQWACSTRTCDB
				NPLATTE	(JHC) WASHED OFF WALK WAYS.	PNPIQWACSTRTCDB

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
OMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE DATE MO DA YR	LOCATION	DETAIL	WORK CODES
UP 003243	07/21/92	08/04/92		NPLATTE	(MJF) AIR DUCTS / STACK / SEPERATOR / AUX SHAFT TO APPLY. (TLL)	PNFIQHWACSTRTCDB
				NPLATTE	(MJF) C/O TURBO, SEALS B/O. (HOO)	PNFIQHWACSTRTCDB
				NPLATTE	(MJF) ENGINE SETTINGS TO DO. (TLL)	PNFIQHWACSTRTCDB
				NPLATTE	(MJF) TURBO FILTER CHECK VALVES TO C/O. (TLL)	PNFIQHWACSTRTCDB
				NPLATTE	(MJF) TURBO NEW TO TORQUED. (TLL)	PNFIQHWACSTRTCDB
				NPLATTE	(MJF) TURBO UNCOVERED. (TLL)	PNFIQHWACSTRTCDB
				NPLATTE	(MJF) TURBO UNPIPED. (TLL)	PNFIQHWACSTRTCDB
				NPLATTE	(MRH) ENGINE, ENGINE ROOM & SUMP OILY (NEEDS WASHED.)	PNFIQHWACSTRTCDB
				NPLATTE	(MRH) WASH	PNFIQHWACSTRTCDB
				NPLATTE	(RAS) REFER NEW STILL NOT COOLING (DET) NEW 08/03/92 (RAS)	PNFIQHWACSTRTCDB
				NPLATTE	(RLD) LV GROUND + AUTO DRAIN TIMER CKT **STILL SPOT 5/MRH**	PNFIQHWACSTRTCDB
				NPLATTE	(RLD) REPLACE RUBBER COUPLING ON L1 AX ALT (DLB)	PNFIQHWACSTRTCDB
				NPLATTE	(RLD) SHIM #3 WHEELS (DLB)	PNFIQHWACSTRTCDB
				NPLATTE	(RMA) SPOT 1	PNFIQHWACSTRTCDB
				NPLATTE	(SDK) GRID CKT STILL GROED (SD) BB3 CARBODY LEADS GROED (SDK)	PNFIQHWACSTRTCDB
				NPLATTE	(TBF) CARBODY DOOR LATCH AT START STATION NEEDS ATT (MRH)	PNFIQHWACSTRTCDB
				NPLATTE	(TBF) L/S AIR DOOR LATCHES NEED ATT (MRH)	PNFIQHWACSTRTCDB
				NPLATTE	(TBF) TOILET ROOM FLOOR HAS PLATE IN FRT OF TOILET-NEEDS ATT (MRH)	PNFIQHWACSTRTCDB
				NPLATTE	(TBF) TOILET ROOM STEP BROKE LOOSE ON ONE END (MRH)	PNFIQHWACSTRTCDB
				NPLATTE	(TLL) BOLTS MISSING AND LOOSE ON PANEL COVERS FRONT GEN ROOM	PNFIQHWACSTRTCDB
				NPLATTE	(TLL) BOLTS MISSING LEFT & RIGHT GRID COVERS	PNFIQHWACSTRTCDB
				NPLATTE	(TLL) COVER ON BACK OF CONTROL PANEL UNDER RADIO NOT ON PROPER	PNFIQHWACSTRTCDB
				NPLATTE	(TLL) REAR X OVER NEEDS ATTEN	PNFIQHWACSTRTCDB
				NPLATTE	(TLL) TURBO DRIVE GEAR NOT C/O. (ONLY 55,478 MILES)	PNFIQHWACSTRTCDB
				NPLATTE	(VEP) #2 GRID BLWR UNCOVERED (RAS)	PNFIQHWACSTRTCDB
				NPLATTE	(VEP) GRIDS TO COVER AGAIN (AJS)	PNFIQHWACSTRTCDB
				NPLATTE	(VEP) L3 GRID AND #2 GRID BLOWER GRD (SDK) (NEW VEP)	PNFIQHWACSTRTCDB
				NPLATTE	(VEP) MODULE BACK COVER OFF (AJS)	PNFIQHWACSTRTCDB
				NPLATTE	(VEP) TURBO GAUGES ARE B/O-NEED C/O BEFORE TURBO LOAD (MRH)	PNFIQHWACSTRTCDB
				NPLATTE	***** BATTERY VOLT 70.2	PNFIQHWACSTRTCDB
				NPLATTE	***** CCS DONE - MS#144784. EB#144191. GARY MCCANDLESS	PNFIQHWACSTRTCDB
				NPLATTE	***** HORN MAG VALVE COVER LOOSE	PNFIQHWACSTRTCDB
				NPLATTE	***** KICKS GR IN LOAD BOX (MRH) **RAINING**	PNFIQHWACSTRTCDB
				NPLATTE	***** OIL & AIR LEAK AT JUNCTION OF TURBO AIR DUCT & TURBO, LEFT	PNFIQHWACSTRTCDB
				NPLATTE	***** PI/QM INSP WORK REDUCED INSP	PNFIQHWACSTRTCDB
				NPLATTE	***** SCREW MISSING COVER TO SHUTTER CONTROL COIL	PNFIQHWACSTRTCDB
				NPLATTE	***** IBC BY DRT RDK *****	PNFIQHWACSTRTCDB
	08/07/92	08/07/92		NPLATTE	(LDP) *PJ*001 SUMMERIZATION	USRFTSELEWELLT
				NPLATTE	(LDP) *PJ*036 FRA CHECK LIST	USRFTSELEWELLT
				NPLATTE	(LDP) *ST* L TURBO AIR DUCT GASKET BLOWN OUT.	USRFTSELEWELLT
				NPLATTE	(RJR) S & C OK	USRFTSELEWELLT
				NPLATTE	(SDK) *RF* WHEEL SLIP IN POWER WIRE OFF WS RESISTOR (SDK)	USRFTSELEWELLT
	08/16/92	08/17/92		HINKLE	(CAS) CHANGE LUBE OIL & FILTERS	USRMWPA
				HINKLE	(RMR) LOADBOXED 40 MIN., CHECKED OKAY.	USRMWPA
				HINKLE	(TJS-CAS) #12 POWER ASSY LEAKING WATER CHANGED OUT ASSY.	USRMWPA
				HINKLE	(TJS) RM:8-15-92. #4 POWER ASSY LEAKING WATER.	USRMWPA

UNION PACIFIC RAILROAD
LOCOMOTIVE MAINTENANCE HISTORY
FOR LOCOMOTIVE: UP2359 UP1213 UP1300 UP1307 UP1218 UP2360 UP3243
TIME PERIOD: 1988 - 1992
OMNT459.FOCUS.MAINTING

LOCOMOTIVE NUMBER	PLACE MO DA YR	DATE MO DA YR	RELEASE DATE	LOCATION	DETAIL	WORK CODES
UP 003243	08/31/92	08/31/92		LOSANGELE	(GM) #14 WATER JUMPER B/O TO C/O.	USRFML
				LOSANGELE	(GM) RF UNIT DEAD REPORT USING WATER.	USRFML
	10/25/92	10/27/92		FTWORTH	(BLD) NEW WHEEL REPORT AND COMPONENTS IN COMPUTER *****	PNPIEMRMCSCWCPAPJ
				FTWORTH	(GG) #13 ASSY. HAS BROKEN RINGS WITH PIECES MISSING (AAA)	PNPIEMRMCSCWCPAPJ
				FTWORTH	(LBG) CHANGE 1,2,&3 WHEELS FOR THIN RIMS (RGR)(RBH)	PNPIEMRMCSCWCPAPJ
				FTWORTH	(LG) CHECK SANDER	PNPIEMRMCSCWCPAPJ
				FTWORTH	(MD) CHANGE 4,5,&6 WHEELS FOR THIN RIMS (EDH)(ENT)	PNPIEMRMCSCWCPAPJ
				FTWORTH	(RM) WASH	PNPIEMRMCSCWCPAPJ
				FTWORTH	(SMP) RM: PLEASE FURNISH TURBO SERIAL NUMBER AND TYPE TO JIM	PNPIEMRMCSCWCPAPJ
				FTWORTH	(SMP) 009A MOD - WINTERIZATION	PNPIEMRMCSCWCPAPJ
				FTWORTH	***** KRAMER OMAHA 8-271-3056 OR I623777.	PNPIEMRMCSCWCPAPJ
				FTWORTH	WORKED PI EM CS INSP.*****	PNPIEMRMCSCWCPAPJ
	11/19/92	11/20/92		NPLSERTK	(DJT) ENG REPORTS DROPS LOAD IN NOTCH #6-#8	USELLT
	12/15/92	12/15/92		NPLSERTK	BOX # 207264— SW # 207124— BY W.C. MILLS	LUMMCSFF
	12/29/92	12/29/92		NPLATTE	(EDD) ENG CHECKS OK	USELPJEMLT
				NPLATTE	(EDD) OSO MOD DONE	USELPJEMLT
				NPLATTE	(FCM) ALSO CHECK WIRING AT STA CONTACTOR LOOKS LIKE OPEN WIRING	USELPJEMLT
				NPLATTE	(FCM) POSITIVE COIL WIRE TO FPCR FOUND OFF (FCM)	USELPJEMLT
				NPLATTE	(FCM) STARTERS B/O MONT START	USELPJEMLT
				NPLATTE	(RRW) S&C'D	USELPJEMLT

000035

PHELPS DUNBAR, L.L.P.
3040 POST OAK BLVD., SUITE 900
HOUSTON, TEXAS 77056
713/ 626-1386 TELEPHONE
713/ 626-1388 FAX

GENERAL ASBESTOS SERVICE LIST OF FAX NUMBERS

From: Mark Schaffer

Date: March 2, 1998

of pages: 4

Bailey, Mel	214/210-2500
Barrett, Davis	214/969-1751
Bashline, J.D.	713/527-9437
Beane, Jerry	214/651-4330
Black, Larry	512/476-5382
Brown, Laura Sanders	601/960-8613
Brown, Phil	214/698-8084
Don Bush	214/750-3551
Conant, A.B.	214/999-5747
Cozort, William	713/783-7157
Crouch, Herbert	214/953-3154
Dailey, John	210/495-1774
Devin, Clayton	214/747-0942
Dougall, Tom	803/252-1068
Downey, Josephine	214/760-7332
Drummond, Robert	214/651-4330
Duesler, Thomas	409/838-6950
Elliston, Gary	214/210-2500
Ferguson, Richard	713/961-5438
Ferrell, Melissa	713/525-6295
Fields, Vic	512/327-3879
Fisher, David	409/598-7712
Fitzgerald, Debra	214/953-3154
Foley, James T.	903/593-1099
Forman, Richard	601/960-8613
Garza, Bernardo	713/650-6338
Gault, William	956/544-0607
Getz, Floyd	903/533-0002
Gilbert, Mark	214/741-7548
Green, Charles	214/672-2020
Harmon, Frank	713/658-1921
Harris, James	409/833-4240

PD5:82480.1

RECEIVED TIME MAR. 2. 6:01PM

Hendrix, Mark	214/712-4402 ✓
Hermes, Kathy	214/210-2500 ✓
Hill, John L.	713/223-3717 ✓
Hull, Susan	214/855-4300 ✓
Johnson, Ned	713/961-5438 ✓
Kelly, Patricia	956/428-2954 ✓
Lancaster, John	214/953-5822 ✓
Landin, David	804/788-8218 ✓
Livingston, David	281/876-3599 ✓
Livingston, Stephen	214/969-1751 ✓
Lowrance, David	817/338-4599 ✓
McGregor, Beth	713/783-7157 ✓
McMurry, Stan	214/740-8800 ✓
Miltenberger, Lewis	817/820-0373 ✓
Moir, Peter	214/953-6503 ✓
Myers, Michael	210/731-6499 ✓
Nunnally, Russell	214/740-1499 ✓
Pevsner, Joseph	214/969-1751 ✓
Phifer, Elizabeth	214/760-7332 ✓
Pletcher, Anthony	512/883-0210 ✓
Powers, James	713/767-1799 ✓
Rambin, Neil	214/651-4330 ✓
Rhea, William	512/477-5267 ✓
Riley, James M.	713/651-0220 ✓
Serafin, Russell	713/615-5890 ✓
Sheiness, Marc A.	713/609-7985 ✓
Skepnek, William	913/331-0303 ✓
Stewart, Allen	214/520-1181 ✓
Summers, Robert	512/327-4694 ✓
Thackston, Robert	214/855-4300 ✓
Thompkins, James	713/599-0777 ✓
Truncale, Michael	409/838-6959 ✓
Unger, John	713/225-9945 ✓
Walker, James	210/978-7790 ✓
Wall, Kenneth	713/525-6295 ✓
Ward, John T.	713/525-6295 ✓
Wewers, Eric	214/210-2500 ✓
Wolcott, Craig	713/655-9212 ✓
Wright, Dawn	214/969-1751 ✓
Zaden, Jamshyd	817/820-0373 ✓