

A U T O M O T I V E D A T A B O O K B U L L E T I N #2-921
November 20, 1992

		FRONT FMSI NO.	SYSTEM F/R	REAR FMSI NO.
<u>ALFA ROMEO</u>				
1991, 164		7469-D590** (Notes #4 & 14)	D/D	7144-D228**
1991, Spider		7273-D384**	D/D	735-D30**
<u>AUDI</u>				
1993, 90		7352-D419**	D/D	7144-D228**
1992, 80, 90		7143-D290**	D/D	7144-D228**
1992, 100		7434-D555**	D/D	7309-D228**
<u>BUICK</u>				
1993, Century		7136-D215**	D/N	1394-S636
1993, LeSabre		7384-D505**	D/N	1394-S636
1993, Park Avenue		7384-D505**	D/N	1394-S636
1993, Regal		7265-D376**	D/D	7266-D377**
<u>CADILLAC</u>				
1993, Allante		7384-D505**	D/D	7387-D508**
1993, Brougham		7384-D505**	D/BH	2134BTT-S652
	OR		/BH	2073AT-S653
<u>CHEVROLET</u>				
1993, Beretta		7385-D506**	D/BH	2164-553
1993, Corsica		7385-D506**	D/BH	2164-553
1993, Lumina		7265-D376**	D/D	7266-D377**
<u>CHEVROLET TRUCK</u>				
Astro Van	1993	7214A-D52	D/BH	2117BTT-S651
Astro Van 4WD	1993	7259-D369**	D/BH	2117BTT-S651
C10	1993	7259-D369**	D/N	1404A-S654
			/BH	2073AT-S653
G10	1993	7214A-D52	D/BH	2073AT-S653
K10	1993	7259-D369**	D/N	1404A-S654
			/BH	2073AT-S653
S10	1993	7070A-D202	D/BH	2117BTT-S651
T10	1993	7070A-D202	D/BH	2117BTT-S651
C20	1993	7260-D370**	D/BH	2073AT-S653
			/BH	2042BT-S655
G20	1993	7214A-D52	D/BH	2073AT-S653
K20	1993	7260-D370**	D/BH	2073AT-S653
			/BH	2042BT-S655
C30	1993	7260-D370**	D/BH	2157AT-S656
C30 DRW	1993	7339-D459**	D/BH	2157AT-S656
			D/D	7081A-D149
G30	1993	7280A-D392	D/BH	2042BT-S655
			D/BH	2157AT-S656
K30	1993	7260-D370**	D/BH	2157AT-S656
K30 DRW	1993	7339-D459**	D/BH	2157AT-S656
P30	1993	7280A-D392	D/BH	2042BT-S655
			D/BH	2157AT-S656
P30 DRW	1993	7081A-D149	D/BH	2157AT-S656
			D/BH	2157AT-S656
			D/D	7081-D543**

SEE DISCLAIMER AT END OF BULLETIN

FMSI® and FMS® are registered trademarks of the Friction Materials Standards Institute, Inc.

Copyright© by Friction Materials Standards Institute, Inc.

		FRONT FMSI NO.	SYSTEM F/R	REAR FMSI NO.
<u>CHEVROLET TRUCK (con't)</u>				
W4S042 Flat Low	1990-87		/N	1454-S668 (Notes #6 & 16)
W5S042	1991-88		/N	1455-S669 (Notes #7 & 17)
<u>CHRYSLER</u>				
1993, Concorde		7470A-D591 (Notes #5 & 15)	D/D	7438A-D559
1993, LeBaron		7403A-D521	D/N	1444-S657
1993, New Yorker 5TH Avenue	OR	7404A-D522	D/D	7438A-D559
		7403A-D521	D/N	1444-S657
1993, New Yorker Salon	OR	7403A-D521	/D	7438A-D559
			D/N	1444-S657
1993, Town & Country	OR	7403A-D521	/D	7438A-D559
		7404A-D522	D/BH	2168T-538
	OR		D/	
<u>DODGE (See Comments)</u>				
1993, Colt Vista		7365-D484**	D/N	1415-610*
	OR		/D	7272-D383**
1993, Colt Vista 4WD		7365-D484**	D/N	1445-S658*
	OR		/D	7272-D383**
1993, Daytona		7403A-D521	D/N	1449-520*
	OR	7404A-D522	D/D	7438A-D559
1993, Dynasty		7403A-D521	D/N	1444-S657*
	OR		/D	7438A-D559
1993, Shadow		7403A-D521	D/N	1365-519
1993, Spirit		7403A-D521	D/N	1444-S657*
	OR	7404A-D522	D/D	7438A-D559
1993, Stealth 2WD		7412-D530**	D/D	7272-D383**
1993, Caravan		7403A-D521	D/BH	2168T-538
	OR	7404A-D522	D/	
1993, Caravan 4WD		7403A-D521	D/BH	2025T-446*
	OR	7404A-D522	D/	
1993, Grand Caravan		7403A-D521	D/BH	2168T-538
	OR	7404A-D522	D/	
1993, Grand Caravan 4WD		7403A-D521	D/BH	2025T-446*
	OR	7404A-D522	D/	
1993, Intrepid		7470A-D591	D/N	1456-S657* (Note #8)
	OR		/D	7438A-D559
<u>DODGE TRUCK</u>				
Caravan C/V	1993	7403A-D521	D/BH	2168T-538
	OR	7404A-D522	D/	
Extended Caravan C/V	1993	7403A-D521	D/BH	2168T-538
	OR	7404A-D522	D/	
Ram 50	1993	7241-D349**	D/N	1370-524*
Power Ram 50	1993	7241-D349**	D/N	1370-524*
B150	1993	7179A-D269**	D/BH	2025T-446*
B250	1993	7179A-D269**	D/BH	2025T-446*
B350	1993	7179A-D269**	D/BH	2146AT-357
	OR		/BH	2140AT-358
D150	1993	7179A-D269**	D/BH	2025T-446*
D150S	1993	7179A-D269**	D/BH	2025T-446*
D250	1993	7179A-D269**	D/BH	2146AT-357
D350	1993	7179A-D269**	D/BH	2146AT-357
	OR		/BH	2140AT-358
W150	1993	7179A-D269**	D/BH	2025T-446*

NOVEMBER 20, 1992

		FRONT	SYSTEM	REAR
		FMSI NO.	F/R	FMSI NO.
<u>DODGE TRUCK (con't)</u>				
W250	1993	7179A-D269**	D/BH	2146AT-357
W350	1993	7081A-D149	D/BH	2146AT-357
	OR		/BH	2140AT-358
<u>EAGLE</u>				
1993, Summit Wagon		7365-D484**	D/N	1415-610*
	OR		/D	7272-D383**
1993, Summit Wagon 4WD		7365-D484**	D/N	1445-S658*
	OR		/D	7272-D383**
1993, Talon		7365-D484**	D/D	7415-D533**
1993, Talon 4WD		7412-D530**	D/D	7415-D533**
1993, Vision		7470A-D591	D/D	7438A-D559
<u>FORD (See Corrections)</u>				
1993, Mustang GT 5.0L		7379A-D431	D/	
<u>GMC TRUCK</u>				
Safari Van	1993	7214A-D52	D/BH	2117BTT-S651
Safari Van 4WD	1993	7259-D369**	D/BH	2117BTT-S651
C1500	1993	7259-D369**	D/N	1404A-S654
	OR		/BH	2073AT-S653
G1500	1993	7214A-D52	D/BH	2073AT-S653
K1500	1993	7259-D369**	D/N	1404A-S654
	OR		/BH	2073AT-S653
S15	1993	7070A-D202	D/BH	2117BTT-S651
T15	1993	7070A-D202	D/BH	2117BTT-S651
C2500	1993	7260-D370**	D/BH	2073AT-S653
	OR		/BH	2042BT-S655
G2500	1993	7214A-D52	D/BH	2073AT-S653
K2500	1993	7260-D370**	D/BH	2073AT-S653
	OR		/BH	2042BT-S655
C3500	1993	7260-D370**	D/BH	2157AT-S656
C3500 DRW	1993	7339-D459**	D/BH	2157AT-S656
	OR	7081A-D149	D/D	7081A-D149
G3500	1993	7280A-D392	D/BH	2042BT-S655
	OR	7081A-D149	D/BH	2157AT-S656
K3500	1993	7260-D370**	D/BH	2157AT-S656
K3500 DRW	1993	7339-D459**	D/BH	2157AT-S656
P3500	1993	7280A-D392	D/BH	2042BT-S655
	OR	7081A-D149	D/BH	2157AT-S656
P3500 DRW	1993	7081A-D149	D/BH	2157AT-S656
	OR	7081-D543**	D/D	7081-D543**
W4S042 Flat Low	1990-87		/N	1454-S668
W5S042	1991-88		/N	1455-S669
<u>HONDA</u>				
1993, Accord Coupe		7345-D465**	D/N	1429-S627*
	OR		/D	7418-D537**
1993, Accord Sedan		7345-D465**	D/N	1429-S627*
	OR		/D	7418-D537**
1993, Accord Station Wagon		7382-D503**	D/N	1429-S627*
	OR		/D	7418-D537**
1993, Prelude SR		7382-D503**	D/D	7418-D537**
<u>INFINITI</u>				
1993, J30		7467-D587**	D/D	7468-D588**
		(Notes #2 & 11)		(Notes #3 & 12)
1993-90, Q45		7366-D486**	D/D	7363-D481**

		FRONT FMSI NO.	SYSTEM F/R	REAR FMSI NO.
<u>INFINITI (con't)</u>				
1992, G20		7342-D462**	D/D	7421-D540**
1992, M30		7282-D441**	D/D	7360-D479**
<u>ISUZU (Commercial)</u>				
Truck NPR Flat Low	1990-87		/N	1454-S668
NRR	1991-88		/N	1455-S669
<u>JAGUAR</u>				
1989-88, XJ6		7296-D407**	D/D	7297-D408**
	OR		/D	7466-D586**
				(Notes #1 & 10)
<u>JEEP</u>				
1993-92, Grand Cherokee		7358A-D477	D/BH	2174TT-S670*
				(Notes #9 & 18)
1993, Cherokee 4x2		7122A-D203	D/BH	2168T-538
1993, Cherokee 4x4		7358A-D477	D/BH	2168T-538
1993, Wrangler		7358A-D477	D/BH	2168T-538
<u>OLDSMOBILE</u>				
1993, Bravada		7070A-D202	D/BH	2117BTT-S651
1993, Cutlass Supreme		7265-D376**	D/D	7266-D377**
1993, Ninety Eight		7384-D505**	D/N	1394-S636
1993, 88 Royale		7384-D505**	D/N	1394-S636
<u>PLYMOUTH</u>				
1993, Acclaim		7403A-D521	D/N	1444-S657*
	OR	7404A-D522	D/D	7438A-D559
1993, Colt Vista		7365-D484**	D/N	1415-610*
	OR		/D	7272-D383**
1993, Colt Vista 4WD		7365-D484**	D/N	1445-S658*
	OR		/D	7272-D383**
1993, Laser		7365-D484**	D/D	7415-D533
1993, Laser 4WD		7412-D530**	D/D	7415-D533
1993, Sundance		7403A-D521	D/N	1365-519
1993, Voyager		7403A-D521	D/BH	2168T-538
	OR	7404A-D522	D/	
1993, Voyager 4WD		7403A-D521	D/BH	2025T-446*
	OR	7404A-D522	D/	
1993, Grand Voyager		7403A-D521	D/BH	2168T-538
	OR	7404A-D522	D/	
1993, Grand Voyager 4WD		7403A-D521	D/BH	2025T-446*
	OR	7404A-D522	D/	
<u>PONTIAC</u>				
1993, Bonneville		7384-D505**	D/N	1394-S636
1993, Grand Prix		7265-D376**	D/D	7266-D377**
<u>SATURN</u>				
1993, Coupe		7386-D507**	D/N	1437-S637*
	OR		/D	7387-D508**
1993, Sedan		7386-D507**	D/N	1437-S637*
	OR		/D	7387-D508**
<u>TOYOTA (See Comments)</u>				
1992, Pickup; Long Bed		7320-D589**	D/N	1358-505*
		(Note #13)		

C O M M E N T S

Existing lining used with new shoe:

<u>Lining</u>	<u>Assembly</u>	<u>Application</u>
7320	7320-D589	1992 Toyota Pickup Long Bed Front

Existing shoe with new lining:

<u>Shoe</u>	<u>Assembly</u>	<u>Application</u>
S657	1456-S657	1993 Dodge Intrepid Rear

C O R R E C T I O N S

Ford - Bulletin #1-921 incorrectly listed Mustang GT 5.0L front as 7379A-D421. The correct listing is 7379A-D431.

DISC BRAKE LINING ASSIGNMENTS

Note #1	<u>FMSI 7466</u> 35.0 x 12.9 x 88.0 (1.38 x .508 x 3.47)	7466-D586 4 IM
Note #2	<u>FMSI 7467</u> 41.9 x 14.8 x 127.0 (1.65 x .583 x 5.00)	7467-D587 4 IM
Note #3	<u>FMSI 7468</u> 33.8 x 14.9 x 97.3 (1.33 x .587 x 3.83)	7468-D588 4 IM
Note #4	<u>FMSI 7469</u> 43.9 x 18.4 x 113.3 (1.73 x .724 x 4.46)	7469-D590 4 IM
Note #5	<u>FMSI 7470A</u> 44.5 x 13.0 x 128.5 44.5 x 11.2 x 147.7 (1.75 x .512 x 5.06) (1.75 x .441 x 5.81)	7470A-D591 2 - 12 2 - 12

DRUM BRAKE LINING ASSIGNMENTS

Note #6	<u>FMSI 1454</u> 11.81 - 2.95 x .300 x 11.60	1454-S668 4 - 48
Note #7	<u>FMSI 1455</u> 12.60 - 4.72 x .508 x 13.17	1455-S669 4 64
Note #8	<u>FMSI 1456</u> 220.0 - 40.4 x 5.3 x 225.6 (8.66 - 1.59 x .209 x 8.88)	1456-S657 4 Bonded
Note #9	<u>FMSI 2174TT</u> 254.0 - 44.5 x 4.6 x 214.0 254.0 - 44.5 x 6.1 x 277.0 (10.00 - 1.75 x .181 x 8.43) (10.00 - 1.75 x .240 x 10.91)	2174TT-S670 2 Bonded 2

DISC BRAKE SHOE ASSIGNMENTS

Note #10	<u>FMS D586</u> 89.7 x 5.2 (3.53 x .205)	7466-D566	Jaguar
Note #11	<u>FMS D587</u> 139.2 x 5.6 (5.48 x .220)	7467-D587	Infiniti
Note #12	<u>FMS D588</u> 108.6 x 5.1 (4.28 x .201)	7468-D588	Infiniti
Note #13	<u>FMS D589</u> 116.2 x 5.6 (4.57 x .220)	7320-D589	Toyota
Note #14	<u>FMS D590</u> 129.8 x 5.7 (5.11 x .224)	7469-D590	Alfa Romeo
Note #15	<u>FMS D591</u> 165.1 x 5.3 165.1 x 4.7 (6.50 x .209) (6.50 x .185)	7470A-D591	Chrysler Dodge Eagle

DRUM BRAKE SHOE ASSIGNMENTS

Note #16	<u>FMS S668</u> 300.0 x 75.0 (11.81 x 2.95)	1454-S668	Chevrolet Truck GMC Truck Isuzu
Note #17	<u>FMS S669</u> 320.0 x 120.0 (12.60 x 4.72)	1455-S669	Chevrolet Truck GMC Truck Isuzu
Note #18	<u>FMS S670</u> 254.0 x 44.5 (10.00 x 1.75)	2174TT-S670	Jeep

The data shown in this bulletin has been supplied by sources considered to be reliable. While we believe that such information is correct, the Institute cannot and does not accept any responsibility or liability for errors or omissions, or harm resulting therefrom.

The data shown in this bulletin indicates dimensions only and in no way refers to quality of any materials that may be embodied in the product or particular application involved, and moreover SINCE FIELD CONDITIONS AND OTHER FACTS MAY NECESSARILY VARY FROM ONE APPLICATION TO ANOTHER, FRICTION MATERIALS SUPPLIERS AND INSTALLERS SHOULD RELY ULTIMATELY AND SOLELY UPON THEIR OWN EXPERTISE AND JUDGMENT AS TO QUALITY AND DIMENSIONAL SIZE. Under no circumstances should replacement items be used when they do not appear to fit, nor be "forced" to fit, nor be modified in the field instead of obtaining a proper sized item from a supplier. If such items are modified in the field to fit, the Institute specifically disclaims all liability and responsibility for any harm resulting therefrom.

If any error or omission is noted in this bulletin, it should be reported immediately to the Friction Materials Standards Institute, Inc., 588 Monroe Turnpike, Monroe, Connecticut 06468.