

MAKING NOTES

JOB NAME: 01YE69BDPR

INSTRUCTIONS = PRESSING =
VAT
DATE
TIME
RELEASED BY
PRESS 2 91 92 93
NO. OF CAKES 32 42 32 32
PRESS WITH AGITATION
WASH TO 2000 OHMS 35-74 F WATER
TEST AFTER 2 HOURS
LOAD ON 4 CARS

RECORD
1ST 2ND 3RD 4TH 5TH
PRESSLOAD
STARTED
CAKES USED
WATER ON
HRS. WASHED
OHMS
HRS. WASHED
OHMS
HRS. WASHED
OHMS
CAKE CONDITION
NO CARS LOADED
EXPLAIN LOSSES

SAMPLES
DELIVER TO

SAMPLED BY
RELEASED BY

= DRYING =
(EXTRUDED) DRY 12 HOURS AT 240 DEG F
(NOT EXTRUDED) DRY 14 HOURS AT 240 F

ADDITIONAL DRYING HOURS REQUIRED

SAMPLES 1 ENV
DELIVER TO CTL

NO CARS PULLED
SAMPLED BY
RELEASED BY

NO DRUMS
LUMP WGT

= GRINDING =
MILL MIKROATOMIZE SCREEN RPM
MAX. TEMP DEG F
SET ROOF BLAST GATE AT "9" FOR HIGH
AIR FLOW

EXPLAIN LOSSES

SAMPLE WITHOUT MIXING
SAMPLES 1 ENV
DELIVER TO CTL

DATE MIXED
SAMPLED BY
RELEASED BY

1502

41

300

292

0.00 *

2.92 +

0.12 ✓

3.17 +

0.12 ✓

3.14 +

0.12 ✓

3.08 +

0.12 ✓

3.31 +

0.12 ✓

3.12 +

0.12 ✓

3.23 *

0.12 ✓

3.01 +

0.12 ✓

2.92 +

0.12 ✓

3.02 +

0.12 ✓

3.04 +

0.12 -

0.95 +

0.12 -

33.47 *