

UNION CARBIDE CORPORATION
SOUTH CHARLESTON PLANT
Safety and Health Department
South Charleston, West Virginia 25303

August 19, 1987

TO: J. C. Ketcham

CC: S. W. Drake*
M. J. Shoger*

Re: SHARE Inspection Results


Dear Jan:

You will find attached a copy of the findings from the SHARE inspection held August 19, 1987. Thank you for the cooperation of your staff and hourly folke in making the audit meaningful.

The program goals are that the following items be satisfied by your department:

1. All deficiencies must be addressed within ninety (90) days of the inspection; and
2. An update is sent to the SHARE coordinator and your APM each thirty (30) days after the inspection until completion. You can use a copy of this report and the spaces below in summarizing your completion progress.

I trust that you will find this program worth supporting to continue to maintain and improve our plant facilities and safety. If you have any questions or need help in understanding the requirements/specifications contained within, please contact me at your earliest convenience.



S. B. Kovach
SHARE Coordinator

PROGRESS UPDATE

	30 Days (Sep. 19, 1987)	60 Days (Oct. 19, 1987)	90 Days (Nov. 19, 1987)
% Complete	_____	_____	_____
Signature	_____	_____	_____

Send copy of update to: S. W. Drake - Bldg. 82-3
S. B. Kovach - Bldg. 109-2

SBK/yc
1658A

Attachment

*Copy of letter only

UCC 008476

SOUTH CHARLESTON PLANT SAFETY/HEALTH AUDIT TEAM'S REPORT

Page 1 of 2

Department Title Process Adducts Dept. No. 109 Location 36 N. structure Date of Inspection 8-19-87

Inspector Sub-mitting Report H H Price Phone No. 2953 Inspection Responsibility Insulation Date of Report 8-19-87

Item No.	Description of Substandard Condition	Item Tagged (✓)	Corrective Action Plan		
			Action Steps or Explanation	Date Correct	Shop Ord Number
1N1	Exposed Ins West end structure ground floor up in Rack	✓	Patch & Seal		
1N2	Exposed Ins in Rack 1st Floor in between 9615 & 9614 & Enline Length structure	✓	Patch & Seal		
* 1N3	Exposed Asbestos N. 9775	✓	Strip & Replace		
* 1N4	No 5 Still Cols and Lined	✓	Strip & Replace Insulate w/ 504		
* 1N5	Exposed ins West of N. 4 & 5 Reactors along Walkway N. & S.	✓	Patch & Seal		

SOUTH CHARLESTON PLANT SAFETY/HEALTH AUDIT TEAM'S REPORT

Page 2002

Department Title Offide Adducts Dept. No. 169 Location 36 N. Structure Date of Inspection 5/18/82

Inspector Submitting Report HH Price Phone No. 7953 Inspection Responsibility Insulation Date of Report 5/19/82

Item No.	Description of Substandard Condition	Item Tagged (✓)	Corrective Action Plan		
			Action Steps or Explanation	Date Correct	Shop Ord. Number
1N6	Exposed Ins. on side structure End Land.	✓	Strip Part of Metal to Patch		
* 1N7	Rack Back N. End of Bridge Unbestos (Ins Laying in Rack)	✓	Strip & Reinsulate		
* 1N8	Exposed Ins. in Rack East of West Between River & Structure in Bad Shape	✓	Patch & Seal		
1N9	Exposed ins on Landing at N. S. Rack East End Structure	✓	Patch & Seal		
* 1N10	Exposed Asbestos Walkway Rt side going Pipe Rack East of structure End Land	✓	Seal & Patch		

* Asbestos.