

**ABERDEEN RAIL CAR REPORT**  
**SURFACE TRANSPORTATION DEPT.**

AS OF 7/15/82

| LIMITS | LOCATION           | LOADED<br>VCM      | EMPTY<br>HOPPERS | LOADED<br>HOPPERS | OTHER<br>LOADS | TOTAL      |
|--------|--------------------|--------------------|------------------|-------------------|----------------|------------|
| 63     | IN PLANT           | <u>10</u> <u>0</u> | <u>16</u>        | <u>33</u>         | <u>2</u>       | <u>61</u>  |
| 25     | MONROE LEAD        | <u>39</u>          | <u>10</u>        | <u>2</u>          | <u>0</u>       | <u>51</u>  |
| 20     | BINFORD            |                    |                  | <u>20</u>         |                | <u>20</u>  |
|        | ICG DOWNTOWN       |                    |                  |                   |                |            |
|        | TEXICO TRACK       |                    |                  |                   |                |            |
|        | SLSF ACROSS BRIDGE |                    |                  |                   |                |            |
|        | STRONG             |                    |                  |                   |                |            |
| 30     | PRAIRIE            |                    | <u>2 (CMPD)</u>  | <u>14</u>         |                | <u>16</u>  |
| 50     | EGYPT              |                    |                  | <u>46</u>         |                | <u>46</u>  |
| 25     | AMORY              |                    |                  | <u>1</u>          |                | <u>1</u>   |
|        | OTHER              |                    |                  |                   |                |            |
| 213    | TOTALS             | * <u>49</u>        | <u>28</u>        | <u>116</u>        | <u>2</u>       | <u>195</u> |

EMPTY HOPPERS  
BY PRODUCT ON  
MONROE LEAD

PVC 2  
DB 4  
COMP 4

→ 4 empties are N/A - were not delivered  
by BN RR - should be available  
for 7/16 switch.

\* 6 loaded vcm enroute