

MONITORING SHIFT REPORT

MONITOR YOUNG

SHIFT 12A

DATE 12/24

OVA CALIBRATION 1.0

BACKGROUND 5ppm

OVA NO. I

PERMIT TO ENTER BLDG. 1 WITH OVA

FOREMAN

TIME 3:05

PERMIT TO ENTER BLDG. 111, 115, 127 WITH OVA

FOREMAN

TIME

BLDG. 1

Point No.	RESULTS OF INVESTIGATING CAUSE FOR ALARMS GREATER THAN 3 PPM.
1	No Source found - disappeared while looking for leak.
5	#2 poly inspection plate leaking @ GASKET - TIGHTENED
4	Poly, bottom valve plugged - emitted some fumes while unplugging
6	#81 poly leaking @ 2" Burp line rupture disc - hoses

NUMBER OF RADIO PAGE CALLS TO INVESTIGATE A ALARM (1)

SOURCE OF EMISSION	Tag No.	GC PPM	OVA PPM	Time Found	Person Notified	Action Taken
#21 poly 2" Ruptured disc emitting fumes	AT	73	200	0305	6013	W/o to Repair

BLDG. 111

POINT	RESULT OF INVESTIGATING CAUSE FOR ALARMS OVER 3 PPM
	Bldg down for Holidays

NUMBER OF RADIO PAGE CALLS TO INVESTIGATE A ALARM

SOURCE OF EMISSION	Tag No.	GC PPM	OVA PPM	Time Found	Person Notified	Action Taken
Bldg down for Holidays						

BLDG. 115

TAG	RESULTS OF INVESTIGATING CAUSE FOR ALARMS GREATER THAN 3 PPM.
PT 10	Ls system still getting some reading - ON PT 10 115 NO SOURCE FOUND
	NO OF PAGE CALLS TO INVESTIGATE A ALARM

BLDG. 127

TAG	RESULTS OF INVESTIGATING CAUSE FOR ALARMS GREATER THAN 3 PPM.
	No Alarms No Leaks
	NO OF PAGE CALLS TO INVESTIGATE A ALARM