

ABD00344806

CONOCO CHEMICALS — ABERDEEN PVC PLANT
DOSIMETRY CARD (A)

SAMPLE No 0111 ^A

Hazard: VCM (✓) Lead () Noise () () Date 11/8/79

Name Larry Frize S.S. # 416-74-1049 Shift C

Department vinyl Job Class Chief operator - large reactors

	Start	Stop
Instrument No. 209	Time 645 AM (1 PPM) 7:50 AM (X PPM)	
Noise Cell No.	Airflow	

Analyst: Analysis Date:

Hazard		TWA Exposure	
VCM	PEL: 1 PPM	0.3	PPM
Noise	Over () Under () 115 dBA	% of PEL	
Lead (Micrograms)	TOT: PEL: > Per M ³	Per M ³	

ABD00344807

CONOCO CHEMICALS — ABERDEEN PVC PLANT
DOSIMETRY DATA CARD (B)SAMPLE NO 0111^AHazard: VCM ☒ Lead () Noise () _____ () Date 11/8/79

Time Clock (Lead Sampling Only) : IN: _____ AM() PM() OUT: _____ AM() PM()

List areas you spent most time in and estimate amount of time (nearest hour is sufficient) spent.

Area	Time	Area	Time
Rx area	8 hrs	Bagging area	2 hrs
Dryer area	2 "		

List most likely causes of possible overexposure to the hazard.

1. Rx area
2. _____
3. _____

Check respiratory protection you used:

(☒) None () Dust Mask () Air-line Respirator () Scott Air-pak

Signature

Benny Frye

Please complete and return to guard