

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	01/31/2024	Time	15:50
Inspection Due	2016-10-29T00:00:00Z	Operator Representative	PEMCO, LLC		
Operator Info	PEMCO, LLC P.O. Box 1047 Skiatook, OK 74070 Phone: 918-521-3086	Inventory ID	OS4226000		
		API Well No			
		Lease Name	DANIEL		
		Well ID	75		
Location	NW 33 23N 11E	Status	Inactive	Well Type	Enhanced Recovery
Latitude	36.433021	Longitude	-96.138896		
Inspection Reason	Requested By Compliance Staff	Responsible Company at Time of Inspection	PEMCO, LLC		
Inspect No.		Date Last MIT		Last Test Result	
Casing	4.5	Tubing		USDW	
Monitoring Device Elected	N	Tubings		Annulus	AUTHORIZED
Monitoring Device		Fittings	N	N	Max Pressure 258
FLM Canister Pressure		Actual Pressure			Max Volume
Lease Status	Active	Determined?			Max Inj Units Barrels Per Month
Barrel Monitor Hooked Up?	N	Static Fluid Level			
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	N	Injection Rate (bpd)			
Injecting	N				
Inspection Comments	Unable to locate well. Inspector observed what appeared to be a well location at the GPS listed in the UIC database, but no well was present. EPA inspector met the operator at the location, to the best of the operator's knowledge, there has been no well at the location as long as he has owned the lease. There is a nearby well #75 but the operator and BIA show the well to be a temporarily abandoned producer.				
Inspector Signature					
Supervisor Signature (acting)					

Appendix 1

Photograph Log 1 Photo



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.433021, -96.138896		
City: Avant	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010280

Orientation: N

Date of Photo: 01/31/2024

Time of Photo: 3:50 PM

Latitude: 36.433021

Longitude: -96.138896

Photographer: Matthew Allen

Description: This was the GPS location from the UIC database for well OS4266000. There appears to be an abandoned/restored well location. At the time of the inspection, I was unable to locate the well. Well possibly plugged or misidentified.