

### **III. General Information**

#### **A. Clothing**

Wear shirts and long pants at all times.

#### **B. Smoking**

Smoke only in approved areas. "Strike anywhere" matches are prohibited. No smoking in stairwells, elevators, bridges and on roofs.

#### **C. Pedestrians**

Use walkways where provided. Do not take shortcuts through operating areas.

#### **D. Vehicles on Plant Roads**

All plant traffic regulations must be observed.

#### **E. Running**

Running is not permitted.

#### **F. Conduct**

Horseplay, fighting, gambling, possession of firearms, drinking alcoholic beverages, or using illegal drugs will bar those involved from the site.

#### **G. Equipment**

Contractor shall provide the equipment necessary for safe performance of his work. All tools and equipment brought onto the site for use are subject to inspection and approval by the Remington Administrator. Remington equipment may be used only with approval from the Remington Administrator.

#### **H. Permission to start work**

Contractor shall insure that his employees are properly identified and have been instructed in the boundaries of their work areas. No work shall begin until the Remington Administrator has granted permission.

#### **I. Safety Instructions**

Maintain an educational program to assure the inclusion of safety instructions as a part of job assignment.

#### **J. Orderliness**

Scrap, trash, and other wastes go in designated

containers. Work areas must be cleaned up continually as the job progresses, with cords and hoses routed across walkways in a manner that will present no tripping hazard. All materials, tools, and equipment must be stored in a stable position (tied, stacked, or chocked) to prevent rolling or falling. A safe accessway to all work areas must be maintained.

#### **K. Inspections**

A work area check is to be made daily at the beginning of each shift, to insure safe conditions\*, and at the end to be sure that all flames are extinguished. All applicable federal, state and/or local safety codes must be followed.

#### **L. Chemicals**

Contractor shall insure that his employees have been informed of any hazardous chemicals present and have taken protective measures in accordance with OSHA standard 1910.1200. All chemicals for use at the plant must be approved by the Remington Administrator.

#### **M. Spill Prevention**

No oil or foreign substance may be dumped in plant sumps, trenches or sewers.

### **IV. Personal Protection**

#### **A. Head — Scalp**

Approved hard hats in good condition are required in all areas where overhead work is being performed. "Bump" caps are not acceptable. Metal hard hats shall not be permitted.

#### **B. Eyes and Ears**

##### **1. Types of Eye Protection**

\*Possession of a valid permit, stable shoring, safe access and egress etc.