

Region 6 - Enforcement & Compliance Assurance Division
INSPECTION REPORT

Inspection Date(s):	11/05/2019	
Media Program:	Water	
Regulatory Program(s)	Brine - CWA	
Company Name:	Jerry Langley Oil Company, LLC	
Facility Name:	Fagg Lease	
Facility Physical Location:	33.346447, -92.791775	
(city, state, zip code)	Smackover, Arkansas 71762	
Mailing address:	100 E. 7th St.	
(city, state, zip code)	Smackover, Arkansas 71762	
County/Parish:	Union County	
Facility Phone Number	870-725-3042	
Facility Contact:	Jerry Langley	
	jloc58@yahoo.com	
FRS Number:	N/A	
Identification/Permit Number:	N/A	
Media Identifier Number:	N/A	
NAICS:	21111	
SIC:	1311	
Personnel participating in inspection:		
Kent W. Sanborn	EPA 6 ECDWE	Environmental Engineer
EPA Lead Inspector Signature/Date		
	Kent W. Sanborn	Date
Supervisor Signature/Date		12 DEC 2019
	Guy Tidmore	Date

Section I – INTRODUCTION

PURPOSE OF THE INSPECTION

EPA Region 6 inspector K.W. Sanborn visited the Jerry Langley Oil Company, LLC oil and gas facility located at latitude 33.346447 and longitude -92.791775 near Smackover, Arkansas on 11/05/2019 for an unannounced inspection. There were no representatives of Jerry Langley Oil Company, LLC present for the inspection. The inspection was conducted by authority of the Clean Water Act and the Safe Drinking Water Act to determine compliance with the Environmental Protection Agency (EPA) regulations.

FACILITY DESCRIPTION

This facility is a tank battery located on the Fagg lease.

Section II - OBSERVATIONS

During the inspection, I observed that the secondary containment area berms had a drain pipe located within it and it was leaking. I saw some oil inside the containment area during the inspection. The secondary containment berms were inadequate to provide secondary containment.

Section III – AREAS OF CONCERN

The secondary containment was not adequate and oil staining was present during the inspection. A drainage pipe was present during the inspection in the secondary containment berms.

Section IV – FOLLOW UP

EPA water enforcement will conduct a follow up inspection in approximately 6 months.

Section V – LIST OF APPENDICES

N/A