

~~11/16~~ - File
December 19, 1979

Mr. Stanley Bryniarski
Eaton Corporation
Brake Division - Research
21220 W. 8 Mile Road
Southfield, Michigan 48075

Dear Stan:

Subject: Dynamometer Test 693-551C

Attached is a copy of our Test No. 6-955 which we ran using 693-551C from batch number 46609.

Please note that the peak recovery pressure was well below the FMVSS 121 limit of 82 psi.

Regards,

John J. Brown
Account Manager

/kb

attach.

Bcc: HBecker
ADIndelicato
RPearce
AFSchmaltz/RLCutler/file

SC1 02729