

August 12, 1998

This is the first Automotive Data Book Bulletin since printing the 1998 Automotive Data Book.

		FRONT FMSI NO.	SYSTEM F/R	REAR FMSI NO.
<u>BMW</u>				
1997, 318i			/D	7631-D763** (Notes #8 & #21)
<u>DODGE (See Comments)</u>				
1998, Neon			/D	7438-D759** (Note #17)
<u>DODGE TRUCK</u>				
Ram Van B1500	1998(late)	7627-D758**	D/BH	2025T-446*
		(Notes #4 & #16)		
Ram Van B2500	1998(late)	7535-D655**	D/BH	2025T-446*
Ram Van B3500	1998(late)	7535-D655**	D/BH	2171T-583*
<u>FORD</u>				
1998, Contour		7630-D762**	D/	(Notes #7 & #20)
<u>FORD TRUCK</u>				
F250	1999-98	7625-D756**	D/D	7626-D757**
		(Notes #2 & #14)		(Notes #3 & #15)
F350	1999-98	7625-D756**	D/D	7626-D757**
<u>HONDA</u>				
1998, Accord		7632-D764**	D/	(Notes #9 & #22)
<u>ISUZU</u>				
1998, Amigo			/N	1503-S735* (Notes #10 & #23)
<u>LEXUS</u>				
1998, ES300		7581-D707**	D/D	7223-D325**
1998, GS300		7495-D619**	D/D	7452-D572**
1998, LS400		7544-D665**	D/D	7491-D613**
1998, SC300		7357-D718**	D/D	7452-D572**
1998, SC400		7451-D571**	D/D	7452-D572**
<u>MAZDA (See Comments)</u>				
1998, 626		7624-D755**	D/	(Notes #1 & #13)
1998, B2500			/BH	2185T-S704* (Note #12)
	OR		/BH	2184T-S705* (Note #11)

SEE DISCLAIMER AT END OF BULLETIN

FMSI® and FMS® are registered trademarks of the Friction Materials Standards Institute, Inc.

Copyright© by Friction Materials Standards Institute, Inc.

	FRONT FMSI NO.	SYSTEM F/R	REAR FMSI NO.
<u>MAZDA (cont'd)</u>			
1998, B3000		/BH	2185T-S704*
	OR	/BH	2184T-S705*
1998, B4000		/BH	2185T-S704*
	OR	/BH	2184T-S705*

MERCEDES

1998, ML320	7628-D760** D/D (Notes #5 & #18)	7629-D761** (Notes #6 & #19)
-------------	-------------------------------------	---------------------------------

MERCURY

1998, Mystique	7630-D762** D/
----------------	----------------

MITSUBISHI

1998, 3000GT	7412-D530** D/D	7272-D383**
1998, 3000GT-VR4	7413-D531** D/D	7510-D631**
1998, Diamante	7412-D530** D/D	7591-D724**
1998, Eclipse	7365-D484** D/N	1445-S658*
	OR 7412-D530** D/D	7272-D383**
1998, Galant	7365-D484** D/N	1445-S658*
	OR /D	7272-D383**
1998, Mirage	7483-D602** D/N	1415-S677*
1998, Montero	7412-D530** D/D	7447-D567**
1998, Montero Sport	7412-D530** D/N	1499-S728*
	OR /D	7602-D733**

PLYMOUTH

1998, Neon	/D	7438-D759**
------------	----	-------------

COMMENTSExisting lining used with new shoe:

<u>Lining</u>	<u>Assembly</u>	<u>Application</u>
7438	7438-D759	1998 Dodge, Plymouth Neon Rear

Existing shoe with new lining:

<u>Shoe</u>	<u>Assembly</u>	<u>Application</u>
S704	2185T-S704	1998 Mazda B Series Pick-Ups Rear
S705	2184T-S705	1998 Mazda B Series Pick-Ups Rear

DISC BRAKE LINING ASSIGNMENTS

Note #1	<u>FMSI 7624</u>	7624-D755
	51.3 x 16.0 x 131.6	2 IM
	51.3 x 15.0 x 131.6	2
	(2.02 x .630 x 5.18)	
	(2.02 x .591 x 5.18)	
Note #2	<u>FMSI 7625</u>	7625-D756
	46.7 x 17.8 x 168.4	4 IM
	(1.84 x .700 x 6.63)	
Note #3	<u>FMSI 7626</u>	7626-D757
	44.5 x 17.4 x 135.9	4 IM
	(1.75 x .685 x 5.35)	

DISC BRAKE LINING ASSIGNMENTS (cont'd)


Note #4	<u>FMSI 7627</u>	7627-D758
	43.4 x 15.8 x 157.7	4 IM
	(1.71 x .622 x 6.21)	
Note #5	<u>FMSI 7628</u>	7628-D760
	50.5 x 16.6 x 119.6	2 IM
	45.0 x 15.6 x 144.3	2
	(1.99 x .654 x 4.71)	
	(1.77 x .614 x 5.68)	
Note #6	<u>FMSI 7629</u>	7629-D761
	38.6 x 16.0 x 123.4	4 IM
	(1.52 x .630 x 4.86)	
Note #7	<u>FMSI 7630</u>	7630-D762
	53.6 x 19.5 x 110.0	4 IM
	(2.11 x .768 x 4.33)	
Note #8	<u>FMSI 7631</u>	7631-D763
	29.0 x 16.3 x 88.9	4 IM
	(1.14 x .642 x 3.50)	
Note #9	<u>FMSI 7632</u>	7632-D764
	46.5 x 16.8 x 123.4	4 IM
	(1.83 x .661 x 4.86)	


DRUM BRAKE LINING ASSIGNMENTS

Note #10	<u>FMSI 1503</u>	1503-S735
	295.0 - 45.2 x 5.8 x 282.7	Bonded
	(11.61 - 1.78 x .228 x 11.13)	
Note #11	<u>FMSI 2184T</u>	2184T-S705
	10.0 - 2.50 x .181 x 8.45	2 - 16
	10.0 - 2.50 x .245 x 9.82	2 Bonded
	(Note: mixed attachment)	
Note #12	<u>FMSI 2185T</u>	2185T-S704
	228.6 - 44.5 x 4.3 x 155.7	2 - 16
	228.6 - 44.5 x 6.9 x 223.0	2 Bonded
	(9.00 - 1.75 x .171 x 6.13)	
	(9.00 - 1.75 x .271 x 8.78)	

DISC BRAKE SHOE ASSIGNMENTS

		
	Inner	Outer
Note #13	<u>FMS D755</u>	7624-D755
	131.6 x 6.0	Mazda
	131.6 x 5.0	
	(5.18 x .236)	
	(5.18 x .201)	

Note #14				
	<u>FMS D756</u>			7625-D756
	193.3	x 6.1		Ford Truck
	(7.61	x .240)		

Note #15				
	<u>FMS D757</u>			7626-D757
	158.8	x 5.7		Ford Truck
	(6.25	x .224)		

Note #16				
	<u>FMS D758</u>			7627-D758
	188.5	x 6.0		Dodge Truck
	(7.42	x .238)		

Note #17				
	<u>FMS D759</u>			7438-D759
	133.7	x 6.3		Dodge
	(5.26	x .248)		Plymouth

Note #18				
			Inner	Outer
	<u>FMS D760</u>			7628-D760
	188.0	x 7.1		Mercedes
	188.0	x 6.1		
	(7.40	x .280)		
	(7.40	x .240)		

Note #19				
	<u>FMS D761</u>			7629-D761
	140.2	x 6.2		Mercedes
	(5.52	x .244)		

DISC BRAKE SHOE ASSIGNMENTS (cont'd)

Note #20				
	<u>FMS D762</u>			
	156.5	x 5.6		
	(6.16	x .220)		
				7630-D762
				Ford
				Mercury

Note #21				
	<u>FMS D763</u>			
	123.2	x 5.2		
	(4.85	x .205)		
			Inner	Outer
				7631-D763
				BMW

Note #22				
	<u>FMS D764</u>			
	137.9	x 6.1		
	(5.43	x .240)		
				7632-D764
				Honda

DRUM BRAKE SHOE ASSIGNMENTS

Note #23				
	<u>FMS S735</u>			
	295.0	x 46.0		
	(11.61	x 1.81)		
				1503-S735
				Isuzu

CLUTCH FACING APPLICATIONS BY MODELCHRYSLER

1994-85, Chrysler

8082
(Note #25)FORD

1995-90, Ford

7005
(Note #24)FORD TRUCK1995, F150, F250, F350 5.8L 11027
(Note #27)GEO

1995-89, GEO

8083
(Note #26)

CLUTCH FACING APPLICATIONS BY MODEL (cont'd)MAZDA

1995-90, Mazda	7005
1995-81, Mazda	8082

MERCURY

1995-81, Mercury	8082
------------------	------

MITSUBISHI

1994-85, Mitsubishi	8082
---------------------	------

NISSAN

1990-88, Nissan	8082
-----------------	------

TOYOTA

1995-86, Toyota	8083
-----------------	------

CLUTCH FACING ASSIGNMENTS

Note #24	<u>FMSI 7005</u>					
	200.0	x	130.0	x	3.8	12 Gr A Str - 12
	(7.87	x	5.12	x	.150)	
Note #25	<u>FMSI 8082</u>					
	215.0	x	140.0	x	3.5	12 Gr A Str - 12
	(8.46	x	5.51	x	.138)	
Note #26	<u>FMSI 8083</u>					
	212.0	x	140.0	x	3.5	12 Gr A Str - 12
	(8.35	x	5.51	x	.138)	
Note #27	<u>FMSI 11027</u>					
	11.54	x	8.39	x	.132	40 DGAP - 40

The data shown in this bulletin has been supplied by sources considered to be reliable. While we believe that such information is correct, the Institute cannot and does not accept any responsibility or liability for errors or omissions, or harm resulting therefrom.

The data shown in this bulletin indicates dimensions only and in no way refers to quality of any materials that may be embodied in the product or particular application involved, and moreover, SINCE FIELD CONDITIONS AND OTHER FACTS MAY NECESSARILY VARY FROM ONE APPLICATION TO ANOTHER, FRICTION MATERIALS SUPPLIERS AND INSTALLERS SHOULD RELY ULTIMATELY AND SOLELY UPON THEIR OWN EXPERTISE AND JUDGMENT AS TO QUALITY AND DIMENSIONAL SIZE. Under no circumstances should replacement items be used when they do not appear to fit, nor be "forced" to fit, nor be modified in the field instead of obtaining a proper sized item from a supplier. If such items are modified in the field to fit, the Institute specifically disclaims all liability and responsibility for any harm resulting therefrom.

If any error or omission is noted in this bulletin, it should be reported immediately to the Friction Materials Standards Institute, Inc., 588 Monroe Turnpike, Monroe, Connecticut 06468.