

UNION-MANAGEMENT MEETING
JUNE 18, 1964

Present:

L. Sandro
S. Capoferri
C. Streck
A. DiPietro

R. C. Amos
R. E. Grimmie

OLD BUSINESS

1. Subject: Objectionable fumes and smoke in dowtherm area. Union states that dust and fumes are very bad and getting worse. Union requests more air circulation in this area.

Action: Management stated that maintenance will continue to upgrade area and most valves and dowtherm pumps will be repacked on the 4th of July shutdown.

2. Subject: Dust collector throwing dust in parking area.

Action: Management stated that bags have been replaced in dust collector and the cyclone will be checked to see if it can be improved.

*Sixth
Unit
12500*

*in
Baffling
the
offline
all
others*

*4. Subject:
Material
are here
This week
Repacked all
an valve*

3. Subject: No. 2 Line to be checked for bonus over down time.

Action: Management said that any downtime less than 15 minutes is not counted off standard. The overall incentive payment is not majorly affected regardless of whether it is counted off standard or not.

4. Subject: Union stated that mud in prehardeners continues to present safety hazard. Also duck boards between No. 3 and No. 4 prehardeners need repair. In addition there are many leaking steam valves as well as many obsolete pipes and valves both in and outside of prehardeners.

Action: Management agreed the prehardeners should be cleaned more often. Mr. Grimmie to set up a cleaning schedule. Steam valves to be repaired at 4th of July shutdown. Obsolete piping will be removed at first opportunity.

*Tie in line
on bottom
try making
pipe over
#3 zone
sheet*

Weitzman

Sadeke - ble

- 70

June 18, 1964

Page 2

5. Subject: Exhaust duct on spray booth on the integrated line needs replacing or cleaning.

Action: Management stated that this will be done.

6. Subject: Union requested that sheet metal rack be moved to maintenance shop closer to shear.

Action: Management said that there was no room for rack in maintenance shop but would investigate designing a vertical rack which would take less space.

NEW BUSINESS

1. Subject: Hole in floor by scrap dock.

Action: Management stated that this would be repaired.

2. Subject: Union stated that dryer and integrated line lift trucks throwing excessive smoke.

Action: Management stated that the truck would be checked and repaired.

3. Subject: L.P. tanks left around plant creating a safety hazard.

Action: Mr. Amos agreed and told Mr. Grimmie to instruct all shift supervisors that tanks must be placed where they belong on each shift.

Letter for record

JTW

Load Dock

Truck Dock

Bar wires & lights

A. DePietro

R. E. Grimmie

Scotly Knot - Repairs

Cape machine

and Forman washing

C 16