

ABERDEEN CHEMICAL PLANT—DOSIMETRY RECORD

No 001034

Name NEW VCM (NMPR. SPEC) - CONTIN. MONITOR POINT Shift _____ Date 11-11-98

Social Security No. _____ Job Code _____

Instrument No. <u>2556</u>	Start	Stop
	Time <u>11:08</u> AM () PM (X) <u>5:48</u> AM (X) PM ()	
Airflow _____		

HAZARD	SAMPLE CONCENTRATION (Time Weighted Average)	Sample Time
VCM	<u>10.1</u> - PPM	
Lead	-Micrograms/M ³	PEL: -Micrograms/M ³
Total Dust	-Milligrams/M ³	

Analyst [Signature]
Analysis Date 11-12-98

Hazard: VCM () Lead () Dust () _____

No 001034

1. I came to work at _____ AM () PM ()

Firewatch Work?
Yes / No (Circle One)

2. I left work at _____ AM () PM ()

3. I did the regular work of a (enter Job Class) _____

4. I used a respirator during the following jobs (check one)

	None	Dust Mask	Air-Line Resp.	Scott Air-Pak	3 M Air Hat

5. The following unusual events may have caused me to be overexposed:

6. Other comments and information (Use reverse side of card)

Signature _____

Please complete and return to Guard