



UNION CARBIDE CORPORATION
CHEMICALS AND PLASTICS

P.O. BOX 8004, SOUTH CHARLESTON, W. VA. 25303

671 Report

March 14, 1980

Mr. Andrew J. Kolarsky
U. S. Environmental Protection Agency
Region III
Wheeling Field Office
303 Methodist Building
Wheeling, West Virginia 26003

Subject: EPA Vinyl Chloride
Regulations: Semi-Annual
Report

Ref.: Section 61.70

Dear Mr. Kolarsky:

Attached is information as required by Section §61.70
f the vinyl chloride regulations.

Please note that there was no production requiring
vinyl chloride during the report period. There was, however,
some inactive storage of the material.

Very truly yours,

J. L. Worstell
Environmental Protection
Coordinator

JLW/pl

Attachment

cc: Mr. C. G. Beard, II - WVAPCC
Mr. P. W. Schaul - EPA
~~Mr. J. R. Solce~~ - UCC

UCC 102326

(I) Vinyl Chloride Concentrations in Vents: 61.70(c)(1), 61.64, 61.65

There are no vents to the atmosphere. All venting is routed to the Island Powerhouse for incineration.

Control Device (Incineration, Island Powerhouse): The continuous monitor shows that the vinyl chloride concentration in the vent from the control device is always well below 10 ppm.

There was no production involving the use of vinyl chloride during the report period.

UCC 102327

JRS

bc:

Mr. D. A. Baehl
Mr. R. N. Bates
Mr. R. T. Kramer
Mr. J. L. Palmer
Mr. L. C. Stewart
Mr. P. D. Wegrzynowicz
Mr. R. N. Wheeler
Mr. H. L. Wise