

QUEBEC ASBESTOS MINING ASSOCIATION

C/O Asbestos Corporation Ltd.
Thetford Mines, Que.
July 18, 1967.

Mr. G. F. Brink,
" R. S. Coleman,
" R. Dodds-Hebron,
" J. O. Eby, ←
" J. G. Hoffarth,
" R. J. Merrill,
" D. O. Poirier,
" J. P. Wiser

Dear Sir:

There will be a meeting of the Q.A.M.A. Uniform, Classification and Grading Committee meeting in the Engineering Building of Canadian Johns-Manville, Asbestos, Quebec, at 9.30 a.m. on Tuesday, August 1st. There will be golf in the afternoon for those who wish to play.

May I remind you again of my request of July 6th for a listing of the number of grades that you feel would be classified better under a list other than Q.S. Test.

Yours very truly,



W.H. Foster,
Chairman,

Uniform, Classification & Grading Comm.

WHF/dd.

c.c. Mr. P. Filtean,
M. Messel

July 20, 1967.

Recommended Procedure for Random Production Q.S. Testing by Fibre Inspector

1. Taking of Sample

1.1. All Companies except C.J.M.

All Companies, except C.J.M., take production bagging samples from the pressure-packed bags. The Fibre Inspector would watch this sampling and, if satisfied with procedure, would take part of this bagging sample for shipment to Sherbrooke Laboratory. If the Fibre Inspector is not satisfied with sampling procedure, he would take his own sample from the pressure-packed bags as they come from production following "Testing Procedure for Chrysotile Asbestos Fibre" - Sampling A-1.

This sample will be held by the Inspector to ensure that the production is on grade. If it is on grade and accepted by the Company concerned the Fibre Inspector will ship the sample to Sherbrooke. If the Company declare the fibre off-grade the Fibre Inspector will discard the sample and take another later.

1.2 C.J.M.

This Company takes a loose fibre sample from an automatic sampler ahead of bagging. At the moment, subject to review, it is proposed that the Fibre Inspector take a portion of this loose sample but the Sherbrooke procedure will vary as below:-

2. Sherbrooke Laboratory Procedure

2.1 All Companies except C.J.M.

2 passes in Johnson's Conditioner
Quebec Standard Test (for Q.S. Fibres only, S.U. for P.V. Fibres, etc.)

2.2 C.J.M. Fibre

3 Passes
2 passes in Johnson's Conditioner
Q.S. Test (for Q.S. Fibres only, S.U. for P.V. fibres, etc.)

WHF/dd.

(EXCEPT 3) no standard procedure