

FILE NAME: Talc (TALC)

DATE: 1978 June 20

DOC#: TALC487

DOCUMENT DESCRIPTION: Naval Memo - Review of Tremolite Talc
Containing Asbestos Fibers

Naval Specdltr

File 5137-1

NAV 5010155 (Rev. 7-73)

USE FOR URGENT
LETTERS ONLY

DO NOT CLEAR TYPE IN
COMMUNICATIONS OFFICE

CLASSIFICATION ☒ REGULAR ☐ REGISTERED ☐ AIR ☐ CERTIFIED ☐ SPECIAL DELIVERY		CLASSIFICATION Unclassified	DATE JUN 20 1978	INSTRUCTIONS 1. Message type abbreviations are permissible. 2. Encl. addresses must be appropriate for window envelopes or bulk mailing, as indicated. Include distribution rules when known. Use distribution lists as guides for window envelope addresses. 3. Give priority to processing, routing, and action required. Avoid time-consuming controls. 4. In order to speed processing, a ready index to this special window envelope, of NAV 145A, Speedletter Envelope, is provided for unclassified speedletters where bulk mailing is not used. Other window envelopes also may be used. In bulk mail, speedletters should be placed on top of regular correspondence.
IN REPLY, REFER TO 185-Ser 486 /5100				

Commander
Naval Sea Systems Command (SEA 0730)
Washington, D. C. 20362

STANDARD REFERENCES AND ENCLOSURES, IF ANY, TEXT AND SIGNATURE BLOCK

FOR OFFICIAL USE ONLY

Subj: Review of Tremolite Talc containing asbestos fibers on Mare Island Naval Shipyard

Ref: (a) PONECON between R. D. Patterson, SEA 0730, and A. E. Leveque, Code 185, NAVSHIPYDMARE, of 7 June 1978
 (b) PONECON between R. D. Patterson, SEA 0730, and A. E. Leveque, Code 185, NAVSHIPYDMARE, of 16 June 1978

Encl: (1) Report of Review of Talc, containing asbestiform, used on Mare Island Naval Shipyard
 (2) Field Information Memo #74-92, U. S. Department of Labor, OSEA

1. During a telephone conversation (reference a), Mare Island Safety Office reported that through microscopic evaluation, Talc used in production facilitating processes appeared to contain asbestos fibers. In a telephone conversation (reference b), the Safety Director, Mare Island Naval Shipyard, reported the findings and actions taken to NAVSEA. Enclosure (1) is results of the survey and enclosure (2) is background information pertaining to Tremolite and asbestiform requirements.

2. Actions taken.

a. A hold was placed on all Talc used in production facilitating processes to determine possible asbestiform contamination.

COPIES TO

All Naval Shipyards
 BUED (Code 55)
 NAVSEA O&F

Commander
Mare Island Naval Shipyard
Vallejo, California 94592

NYC/5100
 100
 185
 130
 300
 303

ADDRESS REPLY AS
 SHOWN AT LEFT OR RE-
 PLY HEREON AND RETURN

CLASSIFICATION

Unclassified

FOR OFFICIAL USE ONLY

CRMCM-HT-TALC-000272

SUT0020

1543