

8/28/87

CATALYTIC CRACKING/GAS
DAILY TURNAROUND GUIDES

ERII's
Operations 3
B & R Maint. 4
Shell Maint. 0

SAFETY

Several lights have been installed or repaired on the slurry structure and at the Gas Fract/Treater areas.

Just a reminder. Remember that operators must wear the organic respirators when sampling processes for Benzene.

LIR

GENERAL

CPS is having problems with boiler 8610. If they request it, we need to stop using all 300 psi steam being used in the main fract, strippers and in any process lines. Continue to use steam for the terry turbine and steam air decoking.

LIR

BOARD

Environmental says we do not have to call them for opacity violations. Please collect and put the computer opacity printouts in the pouch. Good old Rudy Choir will collect all the data and report to Environmental.

The expander train cannot withstand pumping the blower. Some of the bolts are already broken. Therefore, do not deliberately do anything which is likely to pump it.

LIR

GENERAL OPERATOR

Correction: There is a fuel tank located next to the steam air decoking compressor. Please use this fuel to keep the compressors running.

LIR

LAM 018445

DPMC-12110

FRACT & TETS

All hands are continuing to do a good job. Keep up the good work.

When draining or venting, be sure to use the organic vapor respirator for protection against Benzene. Continue with the steam and wash steps. Use either tanks, S-352, S-354 or S-350 for the decontamination tanks. Strive for getting the isolation blinds installed.

We've had one FR-II on the Fract., with R. Bishop injuring his knee. I don't have the full details at this time, but wish him well. The lighting problems is being taken care of as a result.

Doc L

LAM 018446

DPMC-12111