

INDUSTRIAL HYGIENE-MONITORING FOR ASBESTOSTO: R. F. Painter, Trlr. 5583
511Computer Ref. W-10757
CC: C. W. Carman, 725-105 D. R. Paugh, 511-2009 E. J. Tawney, 5583
G. F. Hurley, 701-334 H. L. Robinson, 701-401 R. G. Rowe, M.D., 75
L. R. Noble, 511-2149 E. C. Shipley, 511-2009PERSON MONITORED R. E. TempletonLocation Bldg. 777 - Room 111 Date 8/18/80

EXPOSURE RESULTS

	Conc.	Sampling Time	Comments
Sample 1	6.3 5 $\mu\text{m}/\text{cm}^3$ fibers	42 minutes	A.M. - Wetting and bagging insulation
2			
3	3.9 "	149 minutes	P.M. - Wetting and bagging insulation and cleaning up area
4			
5			
6			

Time-Weighted Average Concentration (TWA) 2.8 fibers > 5 $\mu\text{m}/\text{cm}^3$
Ceiling Concentration _____

ALLOWABLE EXPOSURE

TWA 2 fibers > 5 $\mu\text{m}/\text{cm}^3$ OSHA UCC Other
Ceiling _____ OSHA UCC Other

COMMENTS

More water needs to be used in keeping the insulation wetted. Disposable dust respirators should be worn while in the stripping area and until the cleanup is completed.

WORK BY

Ruth Clise

APPROVED BY

George Hurley

8-19-80 11 AM

On 2 occasions to visit the area DRC noticed they were not wearing respirators & were not sufficiently wetting the asbestos to be stripped. She told them several times.

I called Jimmy Tawney who said he would see that they wore them.

JH

8-19 PM

Still not wearing DRC

P-20 2:30 Still not wearing resp.
Working outside.

FILE COPYTO: R. F. Painter, Trlr. 5583
511

Computer Ref. W-1075

CC: C. W. Carman, 725-105 D. R. Paugh, 511-2009 E. J. Tawney, 5583
 G. F. Hurley, 701-334 H. L. Robinson, 701-401 R. G. Rowe, M.D., 7
 L. R. Noble, 511-2149 E. C. Shipley, 511-2009 R. J. Sexton, M.D.,
 512

PERSON MONITORED R. E. TempletonLocation Bldg. 777 - Room 111 Date 8/18/80

EXPOSURE RESULTS

	Conc.	Sampling Time	Comments
Sample 1	6.3 5 $\mu\text{m}/\text{cm}^3$ fibers	42 minutes	A.M. - Wetting and bagging insulation
2	.		
3	3.9 "	149 minutes	P.M. - Wetting and bagging insulation and cleaning up area
4			
5			
6			

Time-Weighted Average Concentration (TWA) 2.8 fibers > 5 $\mu\text{m}/\text{cm}^3$
 Ceiling Concentration _____

ALLOWABLE EXPOSURE

TWA 2 fibers > 5 $\mu\text{m}/\text{cm}^3$ OSHA UCC Other
 Ceiling _____ OSHA UCC Other

COMMENTS

More water needs to be used in keeping the insulation wetted. Disposable dust respirators should be worn while in the stripping area and until the cleanup is completed.

WORK BY

Ruth Clise

APPROVED BY

George Hurley