

SC

12559

6 STORIES

GENE C
MANUEL P
PAT W
MIKE W
JIM NIDIFF

12/17/82
12/18/82
12/19/82
12/20/82
12/21/82
12/22/82
12/23/82
12/24/82
12/25/82
12/26/82
12/27/82
12/28/82
12/29/82
12/30/82
12/31/82

D. KOS

GENE CRAIN
MANUEL PEREZ X
GEO. WILLIAMSON
PERVIS COTTON

A. J. DAVIDSON
M. WISEMAN
A. SOLIS - ~~REAL~~

PAT WARRER

PLAINTIFF'S EXHIBIT

MON-2907

N. BUSINESS - CLASS A+1 MATERIALS. - SOME ARE BINDING OR BULL

Plugged WITH OPENED VALVES. NEEDS TO BE UNIFORM.

DENNIS - OUTSIDE SOURCE SAW GAIN VALVES OPEN ENDED - COULD
LEAK. A SOURCE OF LEAKS.

PMSB - ALL AREAS AUDITED FOR OUTSIDE BATTERY LIMIT TONKS

+ GET BACK TO SAFETY FOR THEIR DISCRETION ON POSSIBLE LEAK SOURCES.

IN CYANIDE - NO BUILD FLANGE VALVE - GET RID OFF OR ~~FOR~~ LEAVE OPEN.

51 WOB - FLANGE w/ VALVE AFTER VALVE. PRODUCTION WANTS TO LEAK.

19 - EVERYTHING PLUGGED YELLOW/BLACK STRIPE LINES

MONITOR WILL GO OFF IN 51 AT 5PPM. COULD BE WATER
COMING OUT.

STANDARD FIRST FLANGE Rule. - IS THERE A STANDARD + IS
IT UNIFORM. NEW P-BULLETIN SHOULD CLARIFY THIS.

INCIDENT ON PUMP SEAL LEAK 51. WATER SPRAYED ON

LEAK ABOUT 3 WEEKS. LOW READINGS - NO BARRIERS

P15 - DID HYGIENE TAKE READINGS 12/11 - 12/21 2:2 PM

3 FT.
from LEAK
12/18/82

LAM013754

12-17 - ENVIRONMENTAL HYGIENIST

12-17 - IDA - HYGIENIST CALLED OUT. NEW PART OF ISOLATION

UNIT. DID HYGIENIST MAKE A REPORT - WHAT WAS OUTCOME.

$$\begin{aligned} 300 \times 3 &= 900 \\ 300 \times 15 &= 4500 \end{aligned}$$

(2)

DEPT 23 - 3rd DEPT - 2 PIPES WITH RUPTURE DISKS AT FACE
LEVEL.

DEC 10 INSULATOR ENTERING 44 COAL BOX w/o PERMIT. ALL GOT
LETTERS, WERE TOLD BY FOREMEN TO GO IN.

DENNIS REVIEW OF (1) FLARE INCIDENT

(2) QUARTERLY INSPECTION

(3) PHYSICAL FITNESS

(4) SAFETY SHOWER ALARM

AT LEAST 1 SAFETY MEETING IN 1983 QUARTER CONCERNING HOSES / CROWS FOOT
EYE BATH - DOUBLE EYE BATH WITH FREEZE PROTECTION.

★ INVESTIGATE NEW COMFORT SYSTEMS FOR PERSONNEL PROTECTION.
WHAT IS MARK DOING ON THIS.

WENT OVER 12/14 INCIDENT WHERE JANITOR POURED ACID INTO COSMETIC
WASTE CAN

1. LOOK AT SAMPLE DISPOSAL
2. BACK TO MAT. HANDLING

12/17 - NOISE - COAL BOX - WAS PUT ON LIST TO TAKE OFF + SHOULD NOT HAVE
BEEN, NO MAINTENANCE ON FLARE HEADER WHILE IN USE.
TAKE HEADER OUT OF SERVICE DURING SHUTDOWN

NO ORGANICS OR HCN IN AREA

SS Tubing WAS FULL HCN

ALL PARTIES OK'd be 4 REAVY

2-3 PM. NHY

SC

12561

LAM013756