

ABERDEEN CHEMICAL PLANT—DOSIMETRY RECORD

Name

V. ELLIOT

Shift

DN

Date

1-8-91

Social Security No.

587-09-8740

Job Code

GEN HELPER

Instrument No.	1742	Start		Stop	
		Time	1800 AM () PM (X)	0200 AM (X) PM ()	
Airflow					

	HAZARD	SAMPLE CONCENTRATION (Time Weighted Average)
☒	VCM	401 - PPM
☐	Lead	-Micrograms/M ³
☐	Total Dust	-Milligrams/M ³
☐		
☐		

Sample Time

PEL:

-Micrograms/M³

Analyst

Analysis Date

6-9-91

ABD00346682

No 000260

Hazard: VCM () Lead () Dust () ()

1. I came to work at 0700 AM () PM (X)2. I left work at 0700 AM (X) PM ()

3. I did the regular work ()

4. I used:

Firewatch Work?
Yes / No (Circle One)

Helper

Dust Mask	Air-Line Resp.	Scott Air-Pak	3 M Air Hat

5. The

exposed:

6. Other co

Please complete and return to Guard

Hazard: VCM () Lead () Dust () ()

1. I came to work at 0700 AM () PM (X)

Firewatch Work?
Yes / <u>No</u> (Circle One)

A

2. I left work at 0700 AM (X) PM ()3. I did the regular work of a (enter Job Class) Gen. Helper

4. I used a respirator during the following jobs (check one)

	None	Dust Mask	Air-Line Resp.	Scott Air-Pak	3 M Air Hat
_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____

5. The following unusual events may have caused me to be overexposed:

6. Other comments and information (Use reverse side of card)

Signature

Victor L. E. Head Jr.
 Please complete and return to Guard