

MARATHON OIL
ROBINSON, ILLINOIS
S.O. 7339
Page 2

- 6) For long term consideration a new steam chest cover may be considered to bring to up to date standards.
- 7) When work is complete hysteresis curves must be done on actuator and valve rack.
- 8) Long Term - Review movement of pneumatic actuator to eliminate some linkage.
- 9) Elliott to provide part numbers on thrust collar assembly of original rotor.

William G. Pacelli
July 15, 1991

(2917K)