

8/18/74

All existing walk-through were OK -

The ex-reactor hatches were found to have slight
leaks: reactor numbers C-5, B-5 and D-6.

The lead operator was present as all the hatches were
checked. Although the leaks were small (highest reading
was 300 ppm) the leak was present.

One utility man was inside an open reactor at
the time of the walk-through. Even though the reactor
had been open for 2-3 hours, when the probe was
placed inside, a reading between 300-500 ppm was obtained.
The utility man was not wearing a gas mask.

Tom D'Amico

Ray Price accompanied me on the walk-through.

OLI 5025