

*Machine
June 14, 1940*

ETHYL GASOLINE CORPORATION

CHRYSLER BUILDING
405 LEXINGTON AVENUE

SAFETY DIVISION

NEW YORK June 14, 1940

ROBERT A. KEHOE, M.D.
CHAIRMAN

OSCAR B. LEWIS
MANAGER

RUSSELL SCHELL
ASSISTANT MANAGER

Dr. R. A. Kehoe

Dear Dr. Kehoe:

Our safety engineers have recently supervised the cleaning or repairing of tanks having floating roofs in which a question arises upon which I should like to have your opinion.

These tanks are customarily cleaned with the roof in a down position, that is from 4 to 6' off the bottom. Workers congregate upon the roof and open manheads for ventilation or remove the pater side plates and work of similar nature. I feel sure that when such tank is gassy, a fire and explosion hazard exists around such openings. But the particular question I should like to ask you is whether or not, if such a tank contains significant amounts of organic lead, workmen operating as they customarily do without masks of any kind would be exposed to a lead hazard?

Very truly yours,

O. B. Lewis.

W:GCL

KE 0022569