

A U T O M O T I V E D A T A B O O K B U L L E T I N #1-951

October 6, 1995

		FRONT FMSI NO.	SYSTEM F/R	REAR FMSI NO.
<u>BUICK (See Comments & Corrections)</u>				
1995, LeSabre			/N	1487-S636 (Note #15)
1996, Park Avenue			/N	1487-S636
1996, Skylark		7554-D673** (Notes #9 & #26)	D/BH	2164-553
<u>CHEVROLET</u>				
1996, Beretta		7554-D673**	D/BH	2164-553
1996, Corsica		7554-D673**	D/BH	2164-553
1996, Cavalier		7554-D673**	D/BH	2164-553
<u>CHEVROLET TRUCK/GMC TRUCK</u>				
W4Series	1995	7425-D675** (Note #28)	D/N	1417-S612
	OR	1482-S699	N/N	1482-S699
	1994-92	7425-D546**	D/N	1417-S612
	OR	1482-S699	N/N	1482-S699
	1991-87	1417-S612	N/N	1417-S612
<u>CHRYSLER</u>				
1996, Town & Country		7470A-D642	D/N	1485-S703 (Notes #13 & #31)
1996, Town & Country AWD		7470A-D642	D/N	1485-S703
<u>DODGE</u>				
1996, Caravan		7470A-D642	D/N	1485-S703
1996, Grand Caravan		7470A-D642	D/N	1485-S703
1996, Grand Caravan AWD		7470A-D642	D/N	1485-S703
<u>EATON BRAKES</u>				
15dd x 6 Red. Env.		4716 (Note #18)	A/	
15dd x 8-5/8 Red. Env.		4717 (Note #19)	A/	
<u>FORD</u>				
1996, Crown Victoria Police			/D	7555-D674** (Notes #10 & #27)
<u>FORD TRUCK (See Corrections)</u>				
Ranger	1995		/BH	2180T-S704 (Notes #16 & #32)
	OR		/BH	2089AT-S705 (Note #33)
E350	1995	7535-D655**	D/BH	2140AT-314
	OR		/BH	2178T-583*

SEE DISCLAIMER AT END OF BULLETIN

FMSI® and FMS® are registered trademarks of the Friction Materials Standards Institute, Inc.

Copyright® by Friction Materials Standards Institute, Inc.

October 6, 1995

	FRONT FMSI NO.	SYSTEM F/R	REAR FMSI NO.
<u>FREIGHTLINER</u>			
Front Axle (Cam) 15 x 5 Q-Plus 1995	4703	A/	
<u>GEO</u>			
1995, Metro	7331-D451**	D/	
<u>HONDA</u>			
1995, Odyssey		/D	7418-D536**
<u>HYUNDAI (See Comments & Corrections)</u>			
1995, Accent	7376-D497**	D/N	1379-S707* (Note #35)
1995, Scoupe		/N	1451-S694*
1995, Sonata OR		/N	1400-S708* (Note #36)
<u>ISUZU (See Corrections)</u>			
Truck NPR 1995	7425-D675**	D/N	1417-S612
OR	1482-S699	N/N	1482-S699
<u>KIA</u>			
1996-95, Sportage	7550-D670** (Notes #5 & #23)	D/N	1486-S706* (Notes #14 & #34)
<u>LAND ROVER (See Corrections & Comments)</u>			
1992, Defender	7551-D671** (Notes #6 & #24)	D/	
1995-94, Defender	7552-D671** (Note #7)	D/D	7399-D518**
1995, Range Rover	7556-D676** (Notes #11 & #29)	D/	
<u>MAZDA (Pick-Up Truck)</u>			
1995, B2300	7532-D652**	D/BH	2180T-S704
OR		/BH	2089AT-S705
1995, B3000	7532-D652**	D/BH	2180T-S704
OR		/BH	2089AT-S705
1995, B4000	7532-D652**	D/BH	2180T-S704
OR		/BH	2089AT-S705
<u>NISSAN</u>			
1995, 200SX	7546-D668** (Notes #1 & #21)	D/N	1438-S638*
OR		/D	7547-D669** (Notes #2 & #22)
1995, Sentra	7546-D668**	D/D	7547-D669**
<u>OLDSMOBILE (See Comments)</u>			
1996, Achieva	7554-D673**	D/BH	2164-553
1996, Eighty Eight		/N	1487-S636
1996, Ninety Eight		/N	1487-S636
<u>PLYMOUTH</u>			
1996, Voyager	7470A-D642	D/N	1485-S703
1996, Grand Voyager	7470A-D642	D/N	1485-S703
1996, Grand Voyager AWD	7470A-D642	D/N	1485-S703
<u>PONTIAC</u>			
1996, Grand Am	7554-D673**	D/BH	2164-553
1996, Sunfire	7554-D673**	D/BH	2164-553

	FRONT FMSI NO.	SYSTEM F/R	REAR FMSI NO.
<u>ROCKWELL AXLE</u>			
16-1/2 x 6 Q Plus	4715 (Note #17)	A/	
16 1/2dd - 8 Q Plus	4718 (Note #20)	A/	
<u>SUZUKI</u>			
1995, Esteem	7557-D677** (Notes #12 & #30)	D/N	1461-S630*
1995, Swift	7331-D451**	D/N	1414-608*
1995, Samurai		/N	1408-600*
1995, Sidekick 2DR		/N	1440-S641*
<u>TOYOTA (See Comments)</u>			
1995, Avalon		/D	7553-D672** (Notes #8 & #25)
1995, Tacoma 2WD	7548-D433** (Note #3)	D/N	1358-505*
1995, Tacoma 4WD	7549-D436** (Note #4)	D/N	1397-589*

C O M M E N T SExisting lining used with new shoe:

Lining	Assembly	Application
1379	1379-S707	1995 Hyundai Accent Rear
1400	1400-S708	1995 Hyundai Sonata Rear
2089AT	2089AT-S705	1995 Ford Ranger Rear
		1995 Mazda Pick-Ups Rear
7425	7425-D675	1995 Chev.Truck/GMC Truck W4 Series Front
		1995 Isuzu NPR Front

Existing shoe with new lining:

Shoe	Assembly	Application
D433	7548-D433	1995 Toyota Tacoma Pick-Up 2WD Front
D436	7549-D436	1995 Toyota Tacoma Pick-Up 4WD Front
D671	7552-D671	1995-94 Land Rover Defender Front
S636	1487-S636	1995 Buick LeSabre Rear
		1996 Buick Park Avenue Rear
		1996 Oldsmobile Eighty Eight Rear
		1996 Oldsmobile Ninety Eight Rear

C O R R E C T I O N S

1995 Buick LeSabre rear was FMSI 1394-S636. The correct listing is FMSI 1487-S636.

1995 Catalog shows incorrect rears on 1995 Ford Ranger. The correct listings are 9" - FMSI 2180T-S704, 10" - FMSI 2089AT-S705.

1995 Hyundai Scoupe rear was listed as 1451-S663 should be 1451-S694.

The catalog shows 1995 Isuzu NPR front as FMS 7425-D546. The correct assignment is FMS 7425-D675.

The catalog shows 1995-92 Isuzu NPR rear as FMS 1414-S612. The correct assignment is FMS 1417-S612.

1995 Catalog lists 1995 Land Rover Defender with FMSI 7401-D520 front. This is incorrect. The correct listing is FMSI 7552-D671.

DISC BRAKE LINING ASSIGNMENTS

Note #1	<u>FMSI 7546</u> 39.1 x 15.8 x 105.9 (1.54 x .622 x 4.17)	7546-D668 4 IM
Note #2	<u>FMSI 7547</u> 29.0 x 14.8 x 91.7 (1.14 x .583 x 3.61)	7547-D669 4 IM
Note #3	<u>FMSI 7548</u> 48.0 x 17.4 x 107.7 (1.89 x .685 x 4.24)	7548-D433 4 IM
Note #4	<u>FMSI 7549</u> 52.5 x 17.0 x 117.5 52.5 x 17.0 x 117.5 (2.07 x .669 x 4.63) (2.07 x .669 x 4.63)	7549-D436 2 IM 2
Note #5	<u>FMSI 7550</u> 39.9 x 18.0 x 128.8 45.2 x 15.8 x 151.6 (1.57 x .709 x 5.07) (1.78 x .622 x 5.97)	7550-D670 2 IM 2
Note #6	<u>FMSI 7551</u> 52.8 x 17.8 x 124.2 (2.08 x .701 x 4.89)	7551-D671 4 IM
Note #7	<u>FMSI 7552</u> 52.8 x 16.9 x 124.2 (2.08 x .665 x 4.89)	7552-D671 4 IM
Note #8	<u>FMSI 7553</u> 33.5 x 17.5 x 87.6 (1.32 x .689 x 3.45)	7553-D672 4 IM
Note #9	<u>FMSI 7554</u> 45.7 x 14.6 x 123.4 45.7 x 13.6 x 123.4 (1.80 x .575 x 4.86) (1.80 x .535 x 4.86)	7554-D673 2 IM 2
Note #10	<u>FMSI 7555</u> 38.7 x 16.0 x 113.6 (1.52 x .630 x 4.47)	7555-D674 4 IM
Note #11	<u>FMSI 7556</u> 48.0 x 17.9 x 142.2 (1.89 x .705 x 5.60)	7556-D676 4 IM
Note #12	<u>FMSI 7557</u> 38.6 x 14.9 x 99.5 (1.52 x .587 x 3.92)	7557-D677 4 IM

DRUM BRAKE LINING ASSIGNMENTS

Note #13	<u>FMSI 1485</u> 250.0dd - 55.0 x 6.1 x 261.9 (9.84 - 2.17 x .240 x 10.31)	1485-S703 4 - 40
----------	--	---------------------

DRUM BRAKE LINING ASSIGNMENTS (con't)

Note #14	<u>FMSI 1486</u>								1486-S706
	250.0dd - 55.0	x	5.6	x	263.0				4 Bonded
	(9.84 - 2.16	x	.220	x	10.35)				
Note #15	<u>FMSI 1487</u>								1487-S636
	225.0dd - 45.0	x	6.8	x	226.0				4 - 40
	(8.86 - 1.77	x	.270	x	8.90)				
Note #16	<u>FMSI 2180T</u>								2180T-S704
	228.6dd - 44.5	x	4.7	x	155.7				2 - 36
	228.6 - 44.5	x	7.2	x	223.0				2
	(9.00 - 1.75	x	.185	x	6.13)				
	(9.00 - 1.75	x	.283	x	8.78)				

BRAKE BLOCK LINING ASSIGNMENTS

Note #17	<u>FMSI 4715</u>								
	16.50dd - 6.00	x	.875Tapered	x	8.13	4	1/4R	96	
				x	8.38	4			
Note #18	<u>FMSI 4716</u>								
	15.00dd - 6.00	x	7/8Tapered	x	7.70	8	1/4R	80	
Note #19	<u>FMSI 4717</u>								
	15.00dd - 8.63	x	.875Tapered	x	7.72	8	1/4R	112	
Note #20	<u>FMSI 4718</u> - Drawing will be released with later Bulletin.								
	16.50dd - 8.00	x	.875Tapered	x	8.42	4	1/4R	112	
	16.50dd - 8.00	x	.875Tapered	x	8.23	4			

DISC BRAKE SHOE ASSIGNMENTS

Note #21	<u>FMS D668</u>				7546-D668	Nissan
	108.7 x 5.0					
	(4.28 x .197)					
Note #22	<u>FMS D669</u>				7547-D669	Nissan
	99.4 x 5.0					
	(3.91 x .197)					
Note #23	<u>FMS D670</u>				7550-D670	KIA
	165.2 x 5.1					
	171.7 x 4.9					
	(6.50 x .201)					
	(6.76 x .193)					
Note #24	<u>FMS D671</u>				7551-D671	Land Rover
	126.5 x 5.0				7552-D671	Land Rover
	(4.98 x .197)					
Note #25	<u>FMS D672</u>				7553-D672	Toyota
	106.0 x 5.5					
	(4.17 x .217)					
Note #26	<u>FMS D673</u>				7554-D673	Buick
	147.8 x 5.1					Chevrolet
	190.0 x 5.0					Oldsmobile
	(5.82 x .201)					Pontiac
	(7.48 x .197)					

DISC BRAKE SHOE ASSIGNMENTS (con't)

Note #27	<u>FMS D674</u> 140.3 x 5.0 (5.52 x .197)	7555-D674	Ford
Note #28	<u>FMS D675</u> 183.2 x 7.9 238.2 x 8.1 (7.21 x .311) (9.38 x .319)	7425-D675	Chev. Truck GMC Truck Isuzu
Note #29	<u>FMS D676</u> 144.8 x 5.5 (5.70 x .217)	7556-D676	Land Rover
Note #30	<u>FMS D677</u> 111.5 x 5.2 (4.39 x .205)	7557-D677	Suzuki

DRUM BRAKE SHOE ASSIGNMENTS

Note #31	<u>FMS S703</u> 254.0 x 57.2 (10.00 x 2.25)	1485-S703	Chrysler/Dodge Plymouth
Note #32	<u>FMS S704</u> 228.6 x 44.5 (9.00 x 1.75)	2180T-S704	Ford Truck Mazda Truck
Note #33	<u>FMS S705</u> 254.0 x 63.5 (10.0 x 2.50)	2089AT-S705	Ford Truck Mazda Truck
Note #34	<u>FMS S706</u> 250.0 x 55.0 (9.84 x 2.16)	1486-S706	KIA
Note #35	<u>FMS S707</u> 180.0 x 30.0 (7.09 x 1.18)	1379-S707	Hyundai
Note #36	<u>FMS S708</u> 228.6 x 43.0 (9.00 x 1.69)	1400-S708	Hyundai

The data shown in this bulletin has been supplied by sources considered to be reliable. While we believe that such information is correct, the Institute cannot and does not accept any responsibility or liability for errors or omissions, or harm resulting therefrom.

The data shown in this bulletin indicates dimensions only and in no way refers to quality of any materials that may be embodied in the product or particular application involved, and moreover SINCE FIELD CONDITIONS AND OTHER FACTS MAY NECESSARILY VARY FROM ONE APPLICATION TO ANOTHER, FRICTION MATERIALS SUPPLIERS AND INSTALLERS SHOULD RELY ULTIMATELY AND SOLELY UPON THEIR OWN EXPERTISE AND JUDGMENT AS TO QUALITY AND DIMENSIONAL SIZE. Under no circumstances should replacement items be used when they do not appear to fit, nor be "forced" to fit, nor be modified in the field instead of obtaining a proper sized item from a supplier. If such items are modified in the field to fit, the Institute specifically disclaims all liability and responsibility for any harm resulting therefrom. If any error or omission is noted in this bulletin, it should be reported immediately to the Friction Materials Standards Institute, Inc., 588 Monroe Turnpike, Monroe, Connecticut 06468.