

ABD00342730

# CONOCO CHEMICALS - ABERDEEN PVC PLANT

## DOSIMETRY CARD (A)

SAMPLE NO 0927 A

Hazard: VCM (X) Lead ( ) Noise ( ) ( ) Date June 14-1980

Name Douglas M. Spann S. S. # 418-66-3073 Shift A

Department Vinyl Reactor Job Class chief operator

|                      |                           |                    |
|----------------------|---------------------------|--------------------|
|                      | Start                     | Stop               |
| Instrument No. 294   | Time 6:43 - AM ( ) PM (X) | 7:01 AM (X) PM ( ) |
| Noise Cell No. _____ | Airflow _____             | _____              |

Analyst: J. E. Hane Analysis Date: 6-26-80

| Hazard            |                              | TWA Exposure       |
|-------------------|------------------------------|--------------------|
| VCM               | PEL: 1 PPM                   | < 0.1 PPM          |
| Noise             | Over ( ) Under ( ) 115 dBA   | % of PEL           |
| Lead (Micrograms) | TOT: PEL: Per M <sup>3</sup> | Per M <sup>3</sup> |
|                   |                              |                    |

CONOCO CHEMICALS - ABERDEEN PVC PLANT  
DOSIMETRY DATA CARD (B)

SAMPLE NO 0927 A

Hazard: VCM (X) Lead ( ) Noise ( ) Date June 14-1980

Time Clock (Lead Sampling Only) : IN: 7 AM ( ) PM (X) OUT: 7 AM (X) PM ( )

List areas you spent most time in and estimate amount of time (nearest hour is sufficient) spent.

| Area     | Time | Area | Time |
|----------|------|------|------|
| Vinyl Rm | 4.5  |      |      |
| " "      | 4    |      |      |

List most likely causes of possible overexposure to the hazard.

1. \_\_\_\_\_
2. \_\_\_\_\_
3. \_\_\_\_\_

Check respiratory protection you used:

(X) None ( ) Dust Mask ( ) Air-line Respirator ( ) Scott Air-pak

Signature

Douglas M. Spano

Please complete and return to guard