

TABLE VII
CURTAIN COATER SLOT VENTILATION RATES
IN
DEPARTMENT 14
VICTOR MANUFACTURING AND GASKET COMPANY
CHICAGO, ILLINOIS

<u>Location of Test</u>	<u>Average F.P.M.</u>
Slot exhaust ventilation rate across slot on Curtain Coater # 1.	490
Slot exhaust ventilation rate across slot on Curtain Coater # 2.	400

VMG-31-0000278