

ENGINEERING
INDUSTRIAL HYGIENE SURVEY DATA SHEET (See instructions on reverse side)
THE TRAVELERS INSURANCE COMPANIES
HARTFORD, CONNECTICUT 06183 (Location 2-5-116)

PAGE 1 OF 4

CUSTOMER GENUINE PARTS CO., INC. - RAYLOC LOCATION 100 Rayloc Dr. Hancock, Maryland 21750 SURVEY DATE February 28, 1989

POLICY NUMBER/CLAIM NUMBER UB 168 T 3075 BUSINESS UNIT ☒ SAM/CAD ☐ CAM ☐ FIELD (AMG.) ☐ CLAIM ☐ CSSC ☐ OTHER (EXPLAIN)

INSTRUMENTATION

INSTRUMENT HI FLOW SAMPLER MANUFACTURER GILIAN MODEL HFS-113

SERIAL NUMBER	TIC NUMBER	REASON FOR SAMPLING - INCLUDE PROCESS OR OPERATION DESCRIPTION & CONTROLS
1017	3/81	Division management's request to assess employee's potential exposure to asbestos fibers in the
1994	25/82	Brake Shoe Department during typical brake rebuild operations such as chopping, midas belt sorting,
102	68/83	clutch disc drilling, burning, and disc brake riveting. Remanufacturing of automotive parts.
10459	181/85	
5879	101/84	

COLLECTION (SAMPLING) MEDIA MILIPORE FILTERS (OPEN FACED) ANALYSIS REQUIRED ASBESTOS FIBERS (Including TEMS Analysis)

SAMPLE DATA

TIC INST NO.	SAMPLE NUMBER HP	SAMPLING LOCATION (INCLUDE EMPLOYEE'S NAME)	COLLECTION TIME		COLLECTION DURATION (MINS)	FLOW RATE (LPM)	SAMPLER POSITION	NUMBER OF PERSONS IN AREA	EXPOSURE TIME (MINS)	SHIFT DURATION (MINS)	COMMENTS
			Start	End							
3/81	431F	Eugene Hart	0742	1151	249	2.0	PS	2	450	510	Local exhaust ventilation
		Chopper Operator									
3/81	433F	Eugene Hart	1244	1410	86	2.0	PS	2	450	510	Local exhaust ventilation
		Chopper Operator									
3/81	219F	Eugene Hart	1410	1555	105	2.0	PS	2	450	510	Local exhaust ventilation
		Chopper Operator									
25/82	434F	Rick Vance	0754	1149	235	2.0	PS	8	480	540	General ventilation
		Midal Belt Sorter									

OFFICE Baltimore ENGINEER J. E. David, III SIGNATURE Joseph E. David, III DATE SIGNED 5-19-89

NOVO20296