



Allied Automotive

Bendix Friction Materials Division
P.O. Box 238
Troy, NY 12181
Telephone (518) 273-6550

November 12, 1986

Vermont Container Corp.
P.O. Box 648
Bennington, VT 05201

Attention Mr. Ted Grant

Gentlemen

This will confirm our telephone conversation of November 11, 1986 requesting an additional change in the printing required on our Ford Service cartons.

We advised that the initial paragraph, starting with the word "CAUTION" should be deleted and replaced as follows:

DANGER
CONTAINS ASBESTOS FIBERS
AVOID CREATING DUST
CANCER AND LUNG DISEASE HAZARD

When servicing this brake lining or any component related to it or located near it, prevent asbestos dust from becoming airborne by vacuuming the assembly with an industrial type vacuum cleaner equipped with a high efficiency filter system and by washing the assembly with an appropriate brake parts washer, if necessary. Never remove dust or dirt from this assembly by blowing with compressed air.

L1516

Please confirm, by letter, when this change will be made and advise of costs involved.

Sincerely,

Guy H. Teats
Purchasing Supervisor

GHT/cl

cc: G. Thayer
C. Little
E. Rogers