

TO: DISTRIBUTION
FROM: S.B. VICK
DATE: SEPTEMBER 14, 1981
SUBJECT: VCM LEAK SURVEY - PROGRESS REPORT

ALL MAJOR EQUIPMENT AND PROCESSING AREAS
IN THE OLD UNIT, NEW UNIT, AND TANK FARM
HAVE BEEN CHECKED FOR VCM LEAKS. THE AREAS
LEFT TO BE CHECKED FOR LEAKS ARE PIPING
RUNS IN EACH UNIT.

TO DATE, A TOTAL OF FIFTY-ONE LEAKS OVER
50 PPM HAVE BEEN FOUND. ALL BUT SEVEN OF
THE FIFTY-ONE LEAKS HAVE BEEN REPAIRED.
SEE THE ATTACHED LIST (TABLE I) FOR A DESCRIPTION
OF THE LEAKS THAT HAVE NOT BEEN REPAIRED.

OPERATIONS, MAINTENANCE, AND PROCESS ENGINEERING
WILL CONTINUE WORKING TOGETHER TO FIND AND
REPAIR VCM LEAKS UNTIL THE CONCLUSION OF

THE VCM SURVEY.

IF THERE ARE ANY QUESTIONS OR COMMENTS
CONCERNING THE VCM LEAK SURVEY, PLEASE
CONTACT ME.

Bruce Vick.
Process Engineer

C: CLM, LRM, DEM, SJV, RAF, AHS, VEM, VLT, JPV,
ALB, TSD, SCH, MLN, MPB