

ING ATTEND

TOPIC: O.M.S. Collection with Temp 11 Catalyst DATE: 7/14/75
LOCATION: V. Shift Log. office field NUMBER OF HOURS: .2

OUTLINE OF PRESENTATION (Major points, demonstrations, what was practiced, slide/tape, film, etc.). Attach separate sheet if necessary.

Instructed operators to always use 3 gal. of O.M.S. when put Sup-11 Catalyst in the R Charge pots. Explained that Sup 11 Catalyst is a slow bicker but is more violent when starts. The O.M.S. is to help prevent explosion.

EMPLOYEE SUGGESTIONS AND PLANNED CORRECTIVE ACTION:

Instructor/Supervisor

TRAINEES

[illegible]