

To: Distribution

From: M. G. Schneider
Date: January 10, 1992

Subject: 1991 ANNUAL VCM SURVEY

Interoffice
Communication

VISTA

The Annual VCM Survey has been completed. This survey is used by maintenance to locate and repair the listed VCM leaks and to determine fugitive VCM emissions.

Attached is a list of the VCM leaks found in the 1991 survey. The 1991 survey located a total of 6 leaks. It was conducted during the weeks of December 16 and December 30 1991.

All the leaks have been tagged and the list of the leaks have been given to the maintenance department.

M. G. Schneider

M. G. Schneider
Co-op Process Engineer

cc: RWS, DCS, JDO, DAM, JBA, BLT, DFJ, JEN, TRM, KGA,
DEK

VCM Leaks 1991 Annual Survey

	PPM	LOCATION
1.	90	Pressure gauge between compressors 2 and 3 on the liquid line to the sphere under compressor shed at the vinyl tankfarm.
2.	130	Pressure gauge on the discharge of compressor 5 to the railcars under the compressor shed at the vinyl tankfarm.
3.	60	Pressure gauge on bleeder valve on VCM transfer pump PP-219.
4.	80	0.25 inch pressure gauge of rupture disc on south fresh VCM filter pack in the old module.
5.	110	0.25 inch pressure gauge on south end of fresh VCM filter pack.
6.	140	Cutoff Valve of highest sightglass on the south RVCM reciever.