

High	2.14	0.34	2.07	2.00	2.14	2.34	0	V	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
Avg	0.24	0.04	0.06	0.10	0.10	0.10	0	V	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100



THE DOW CHEMICAL COMPANY

TEXAS DIVISION
FREEPORT TEXAS

May 12, 1966

B. E. Hutton
A-702

cc: Medical Department
Safety Department
K. M. Tolleson
John Carter
R. L. Schwebel, D.V.M.

J. Richers, Plant A Safety
* L. G. Shelton
* H. L. Engelhardt
* E. A. Rozas

CLOTHING CONTAMINATED WITH MATERIALS IN V1 V2 AREA - -
MAINTENANCE PERSONNEL

Per your request Industrial Hygiene has reviewed the list of chemicals normally encountered by maintenance personnel in the V1 V2 area. The medical records were checked and the Texas Division toxicologist was consulted. From the standpoint of health there appears to be no problem resulting from clothing contaminated with the materials you listed as being used in this area.

It is assumed that safe job procedures presently exist to cover such things as protective clothing when contact with toxic chemicals is expected, i. e. breaking into a line. Also, as new chemicals are encountered, the toxicity of these materials should be studied and measures taken to prevent exposures.

If Industrial Hygiene can be of further assistance please feel free to call.

Yours truly,

Dow C. Atkins, Jr.

Dow C. Atkins, Jr.
Industrial Hygiene
B-204 Building
BE-8-2121

* Production supervision

DCA:mfr

R&S 020548