

FILE NAME: Baldwin (BALD)

DATE: 1939 May 17

DOC#: BALD056

DOCUMENT DESCRIPTION: Inspection Results - Report of Dust Count Taken in Foundry with Cover Memo from May 31

May 31, 1989

Thom Nelson, Department of Housing
Housing Group

Good morning

I am enclosing a report of conditions in your plant
as submitted to me by our Mr. Merritt. This is for your
information and guidance.

We note that he makes some recommendations which we
think should be complied with at your earliest convenience.

If you should want any further information or help
from us, keep in touch with this office. We shall be glad to
respond to your plant at an early date, and make a complete survey
of conditions in your factory.

Very truly yours,

Superintendent

L.H.W. (1)

COPY

888.017

It is recommended that the men working at the sand mixer and those working in the cement area be furnished with the use of proper approved respirators. It is also recommended that the men operating the sand blaster be furnished an outside air type of mask or helmet.

Respectfully submitted,

Lo HERRICK

Safety Engineer

COPY