

FILE NAME: Uniroyal (UNIR)

DATE: 1955 Nov 28

DOC#: UNIR006

DOCUMENT DESCRIPTION: Letter to Dr. Link, Hogansville Plant, from
US Rubber Co. RE Concerns about Asbestos Control Equipment



United States Rubber Company

Textile Production Management
Winnsboro, S. C.
November 28, 1955



Mr. A. C. Link
Stark Mills
Hogansville

I have noted Mr. Watkins' letter of November 22 on the subject of maintenance of Asbeston dust control equipment and I am very much concerned about what he reports.

My concern is further increased when I recall that on Mr. Sullivan's and my recent visit we tried to discuss the system you used for maintenance of this equipment and the persons responsible for this job. It was with some difficulty and after some telephoning that you were able to determine whose responsibility it is and the specified procedure. This, in spite of the fact that this question has been discussed many times and many suggestions have been given your organization from this office as to how it might be set up. Also, this condition exists in spite of the fact that about a year ago the only answer to the Asbeston dust problem your organization had was 'to go out of business'.

It seems to me you should come up with a written procedure and written assignment of responsibilities so that whenever dust control equipment is not operating we would at least know whose job it is to have had it in operation.

Please advise what you do about this.

RCU

R. C. Harrington
eh
cc: Mr. ... W. Watkins



0001538