

A U T O M O T I V E D A T A B O O K B U L L E T I N #4-931

February 2, 1994

	FRONT FMSI NO.	SYSTEM F/R	REAR FMSI NO.
<u>ACURA</u>			
1994, Legend	7382-D503**	D/D	7418-D536**
1994, Vigor	7382-D503**	D/D	7418-D536**
<u>AUDI</u>			
1994, 100 Wagon	7434-D555**	D/D	7309-D228**
1994, 100 Quattro Wagon	7434-D555**	D/D	7309-D228**
1994, S4	7434-D555**	D/D	7309-D228**
1993, S4	7306-D419**	D/D	7309-D228**
OR	7434-D555**	D/	
<u>BMW</u>			
1994, 525i	7437-D558**	D/D	7286-D396**
1994, 525i Touring Wagon	7284-D394**	D/D	7286-D396**
1994, 530i Touring Wagon	7284-D394**	D/D	7286-D396**
1994, 740i	7284-D394**	D/D	7286-D396**
1994, 740iL	7284-D394**	D/D	7286-D396**
<u>CADILLAC</u>			
1994, Brougham	7124A-D52	D/BH	2134BTT-S652
OR		/BH	2073AT-S653
1994, DeVille	7384-D623**	D/D	7387-D508**
1994, DeVille Concours	7384-D623**	D/D	7387-D508**
1994, Eldorado	7384-D623**	D/D	7387-D508**
1994, Seville	7384-D623**	D/D	7387-D508**
<u>CHEVROLET</u>			
1994, Caprice		/D	7505-D628**
1994(late), Lumina	7265-D376**	D/N	1394-S636
<u>CHEVROLET TRUCK/GMC TRUCK</u>			
Astro/Safari 1994	7214A-D52	D/BH	2117BTT-S651
Astro 4WD/Safari 4WD 1994	7259-D369**	D/BH	2117BTT-S651
S-10/Sonoma 1994	7480A-D202	D/BH	2117BTT-S651
T-10 4WD/Sonoma 4WD 1994	7480A-D202	D/BH	2117BTT-S651
S-Blazer/Jimmy 1994	7480A-D202	D/BH	2117BTT-S651
S-Blazer 4WD/Jimmy 4WD 1994	7480A-D202	D/BH	2117BTT-S651
K-Blazer/Yukon 1994	7259-D369**	D/N	1404A-S675
C-1500/Sierra 1500 1994	7259-D369**	D/N	1404A-S675
OR		/BH	2073AT-S653
Suburban C1500/Suburban C1500 1994	7259-D369**	D/N	1404A-S675
OR		/BH	2073AT-S653
C2500/Sierra 1500 1994	7259-D369**	D/BH	2073AT-S653
OR	7260-D370**	D/BH	2042BT-S655
Suburban C2500/Suburban C2500 1994	7259-D369**	D/BH	2073AT-S653
OR	7260-D370**	D/BH	2042BT-S655
C3500/Sierra 3500 1994	7260-D370**	D/BH	2157AT-S656
C3500DRW/Sierra 3500DRW 1994	7339-D459**	D/BH	2157AT-S656

SEE DISCLAIMER AT END OF BULLETIN

FMSI® and FMS® are registered trademarks of the Friction Materials Standards Institute, Inc.

Copyright© by Friction Materials Standards Institute, Inc.

		FRONT		SYSTEM	REAR
		FMSI NO.	F/R	FMSI NO.	
<u>CHEVROLET TRUCK/GMC TRUCK (con't)</u>					
K1500/Sierra 1500 4WD	1994	7259-D369**	D/N	1404A-S675	
	OR		/BH	2073AT-S653	
K2500/Sierra 2500 4WD	1994	7259-D369**	D/BH	2073AT-S653	
	OR	7260-D370**	D/BH	2042BT-S655	
K3500/Sierra 3500 4WD	1994	7260-D370**	D/BH	2157AT-S656	
K3500 DRW/Sierra 3500 4WD DRW	1994	7339-D459**	D/BH	2157AT-S656	
G1500/G1500	1994	7214A-D52	D/BH	2073AT-S653	
G2500/G2500	1994	7214A-D52	D/BH	2073AT-S653	
G3500/G3500	1994	7280A-D392	D/BH	2042BT-S655	
	OR	7081A-D149	D/BH	2157AT-S656	
<u>CHRYSLER (See Corrections)</u>					
1994, LeBaron 4Dr		7403A-D521	D/N	1456-S657*	
	OR	7404A-D522	D/D	7438A-D559	
1994, LeBaron Convertible		7403A-D521	D/N	1456-S657*	
	OR	7404A-D522	D/D	7438A-D559	
1994, LHS		7470A-D591	D/D	7438A-D559	
1994, New Yorker		7470A-D591	D/D	7438A-D559	
1994, Town & Country 4WD		7404A-D522	D/BH	2025T-446*	
<u>DODGE</u>					
1995, Neon (13" Wheels)		7511A-D633	D/		
		(Notes #2 & #18)			
1994, Spirit		7403A-D521	D/N	1456-S657*	
	OR	7404A-D522	D/D	7438A-D559	
1994, Grand Caravan 4WD		7406-D524**	D/BH	2025T-446*	
	OR	7404A-D522	D/		
<u>DODGE TRUCK</u>					
1994, Extended Caravan C/V		7406-D524**	D/BH	2176T-538	
	OR	7404A-D522	D/		
<u>EAGLE</u>					
1994, Talon		7365-D484**	D/D	7415-D533**	
1994, Talon 4WD		7412-D530**	D/D	7415-D533**	
<u>FORD</u>					
1994, Aspire		7219-D466**	D/N	1472-S688*	
				(Notes #13 & #30)	
<u>FORD TRUCK</u>					
Bronco	1994	7503-D626**	D/BH	2141AT-582	
	OR	7503-D632**	D/		
		(Note #17)			
E150	1994	7503-D626**	D/BH	2141AT-582	
	OR	7503-D632**	D/		
F150	1994	7503-D626**	D/BH	2141AT-582	
	OR	7503-D632**	D/		
<u>HINO</u>					
FA Series 1992-89		1468-S683	N/N	1468-S683	
		(Notes #9 & #25)			
FB Series 1992-91		1469-S684	N/N	1470-S685	
		(Notes #10 & #26)		(Notes #11 & #27)	
FB Series 1990-89		1468-S683	N/N	1468-S683	
FD Series 1992-86		1469-S684	N/N	1470-S685	
FE Series 1992-90		1422-S617	N/		

	FRONT FMSI NO.	SYSTEM F/R	REAR FMSI NO.
<u>HINO (con't)</u>			
FE Series 1989	1469-S684	N/	
FE Series 1987-86	1471-S687	N/	
	(Notes #12 & #29)		
FF Series 1992-91	1422-S617	N/	
FF Series 1989	1469-S684	N/	
GC Series 1992-89	1469-S684	N/N	1470-S685
<u>ISUZU</u>			
1994, Amigo	7347-D363**	D/N	1360-S619*
OR		/D	7460-D580**
<u>MAZDA</u>			
1994, 323	7219-D466**	D/N	8104-S659*
1994, 626	7515-D637**	D/	
	(Notes #6 & #22)		
1994, 929	7431-D552**	D/D	7432-D553**
1994, Miata	7513-D635**	D/D	7514-D636**
	(Notes #4 & #20)		(Notes #5 & #21)
1994, MX6	7515-D637**	D/	
<u>MITSUBISHI</u>			
1994, 3000GT VR4		/D	7510-D631**
			(Notes #1 & #16)
1994, Eclipse	7365-D484**	D/D	7415-D533**
1994, Eclipse 4WD	7412-D530**	D/D	7415-D533**
<u>MITSUBISHI FUSO (See Comments)</u>			
1993-90, FG Series	1467-S682	N/N	1467-S682
	(Notes #8 & #24)		
1988-87, FE Series	1467-S682	N/N	1467-S682
1993-88, FH Series	1410-602	N/N	1434-S632
1993-86, FK Series	1422-S617	N/N	1419-S686
			(Note #28)
<u>NISSAN</u>			
1994, Quest	7456-D576**	D/N	1452-S665
1994, Sentra 1.6L	7389-D510**	D/N	1438-S638*
1994, Sentra 2.0L	7388-D509**	D/N	1438-S638*
OR	7428-D549**	D/D	7390-D511**
<u>PLYMOUTH</u>			
1995, Neon (13" Wheels)	7511A-D633	D/	
1994, Acclaim	7403A-D521	D/N	1456-S657*
	OR 7404A-D522	D/D	7438A-D559
1994, Laser	7365-D484**	D/D	7415-D533**
1994, Laser 4WD	7412-D530**	D/D	7415-D533**
1994, Sundance	7403A-D521	D/N	1365-519
1994, Grand Voyager 4WD	7406-D524**	D/BH	2025T-446*
OR	7404A-D522	D/	
<u>ROCKWELL</u>			
16 1/2 dd 10	4552A	A/	
	(Note #14)		
10	4552B	A/	
	(Note #15)		
<u>VOLKSWAGEN</u>			
1993, Eurovan	7516-D638**	D/	
	(Notes #7 & #23)		

	FRONT FMSI NO.	SYSTEM F/R	REAR FMSI NO.
<u>VOLVO</u>			
1994, 850	7494-D618**	D/D	736-D31**
1994, 940	7512-D634**	D/D	7279-D391**
	(Notes #3 & #19)		
	OR	/D	7422-D541**
1994, 960	7512-D634**	D/D	7279-D391**
	OR	/D	7422-D541**

C O M M E N T SExisting lining used with new shoe:

<u>Lining</u>	<u>Assembly</u>	<u>Application</u>
1419	1419-S686	1993-86 Mitsubishi Fuso FK Series Rear
7503	7503-D632	1994 Ford Truck Bronco Front
		1994 Ford Truck E-; F150 Front

C O R R E C T I O N S

Bulletin #3-931 listed the rear drum brake for the 1994 Chrysler LeBaron Convertible as 1444-S657. The correct listing is 1456-S657.

DISC BRAKE LINING ASSIGNMENTS

Note #1	<u>FMSI 7510</u> 44.2 x 15.9 x 80.0 (1.74 x .626 x 3.15)	7510-D631 4 IM
Note #2	<u>FMSI 7511A</u> 37.5 x 12.0 x 113.2 (1.48 x .472 x 4.46)	7511A-D633 4 - 20
Note #3	<u>FMSI 7512</u> 48.0 x 17.1 x 113.3 (1.89 x .673 x 4.46)	7512-D634 4 IM
Note #4	<u>FMSI 7513</u> 52.6 x 12.9 x 100.3 (2.07 x .508 x 3.95)	7513-D635 4 IM
Note #5	<u>FMSI 7514</u> 29.5 x 12.4 x 88.6 (1.16 x .488 x 3.49)	7514-D636 4 IM
Note #6	<u>FMSI 7515</u> 41.7 x 15.4 x 117.9 41.7 x 14.5 x 117.9 (1.64 x .606 x 4.64) (1.64 x .571 x 4.64)	7515-D637 2 IM 2 IM
Note #7	<u>FMSI 7516</u> 47.2 x 18.8 x 121.4 (1.86 x .740 x 4.78)	7516-D638 4 IM

DRUM BRAKE LINING ASSIGNMENTS

Note #8	<u>FMSI 1467</u> 320.0dd - 74.7 x 9.0 x 346.0 (12.60 - 2.94 x .354 x 13.62)	1467-S682 4 - 48
---------	---	---------------------

DRUM BRAKE LINING ASSIGNMENTS (con't)

Note #9	<u>FMSI 1468</u>	1468-S683
	320.0dd - 75.0 x 8.3 x 321.5	4 - 40
	(12.60 - 2.95 x .327 x 12.66)	
Note #10	<u>FMSI 1469</u>	1469-S684
	320.0dd - 109.7 x 12.5 x 325.0	4 - 56
	(12.60 - 4.32 x .492 x 12.80)	
Note #11	<u>FMSI 1470</u>	1470-S685
	320.0dd - 124.8 x 12.5 x 325.0	4 - 56
	(12.60 - 4.91 x .492 x 12.80)	
Note #12	<u>FMSI 1471</u>	1471-S687
	400.0dd - 101.7 x 15.0 x 213.5	8 - 80
	(15.75 - 4.00 x .591 x 8.41)	
Note #13	<u>FMSI 1472</u>	1472-S688
	200.0dd - 29.7 x 3.9 x 190.5	4 Bonded
	(7.87 - 1.17 x .154 x 7.50)	

BRAKE BLOCK LINING ASSIGNMENTS

Note #14	<u>FMSI 4552A</u>	
	16.5dd - 10.00 x .750 Tapered x 8.38	4 1/4R 128
	10.00 x .750 Tapered x 8.13	4
Note #15	<u>FMSI 4552B</u>	
	16.5dd - 10.00 x .750 Tapered x 8.38	4 3/8 80
	- 10.00 x .750 Tapered x 8.13	4

DISC BRAKE SHOE ASSIGNMENTS

Note #16	<u>FMS D631</u>	7510-D631	Mitsubishi
	81.3 x 5.1		
	(3.20 x .201)		
Note #17	<u>FMS D632</u>	7503-D632	Ford Truck
	194.0 x 6.5		
	(7.64 x .256)		
Note #18	<u>FMS D633</u>	7511A-D633	Dodge Plymouth
	165.2 x 4.2		
	(6.50 x .165)		
Note #19	<u>FMS D634</u>	7512-D634	Volvo
	129.0 x 5.6		
	(5.08 x .220)		
Note #20	<u>FMS D635</u>	7513-D635	Mazda
	110.2 x 5.0		
	(4.34 x .198)		
Note #21	<u>FMS D636</u>	7514-D636	Mazda
	102.1 x 4.6		
	(4.02 x .181)		

DISC BRAKE SHOE ASSIGNMENTS (con't)

Note #22	<u>FMS D637</u>	7515-D637	Mazda
	131.6 x 6.1		
	131.6 x 5.1		
	(5.18 x .240)		
	(5.18 x .201)		
Note #23	<u>FMS D638</u>	7516-D638	Volkswagen
	129.9 x 5.6		
	(5.11 x .220)		

DRUM BRAKE SHOE ASSIGNMENTS

Note #24	<u>FMS S682</u>	1467-S682	Mitsubishi Fuso
	320.0 x 75.0		
	(12.60 x 2.95)		
Note #25	<u>FMS S683</u>	1468-S683	Hino
	320.0 x 75.0		
	(12.60 x 2.95)		
Note #26	<u>FMS S684</u>	1469-S684	Hino
	320.0 x 110.0		
	(12.60 x 4.33)		
Note #27	<u>FMS S685</u>	1470-S685	Hino
	320.0 x 125.0		
	(12.60 x 4.92)		
Note #28	<u>FMS S686</u>	1419-S686	Mitsubishi Fuso
	400.0 x 155.0		
	(15.75 x 6.10)		
Note #29	<u>FMS S687</u>	1417-S687	Hino
	400.0 x 100.0		
	(15.75 x 3.94)		
Note #30	<u>FMS S688</u>	1472-S688	Ford
	200.0 x 30.0		
	(7.87 x 1.18)		

The data shown in this bulletin has been supplied by sources considered to be reliable. While we believe that such information is correct, the Institute cannot and does not accept any responsibility or liability for errors or omissions, or harm resulting therefrom.

The data shown in this bulletin indicates dimensions only and in no way refers to quality of any materials that may be embodied in the product or particular application involved, and moreover SINCE FIELD CONDITIONS AND OTHER FACTS MAY NECESSARILY VARY FROM ONE APPLICATION TO ANOTHER, FRICTION MATERIALS SUPPLIERS AND INSTALLERS SHOULD RELY ULTIMATELY AND SOLELY UPON THEIR OWN EXPERTISE AND JUDGMENT AS TO QUALITY AND DIMENSIONAL SIZE. Under no circumstances should replacement items be used when they do not appear to fit, nor be "forced" to fit, nor be modified in the field instead of obtaining a proper sized item from a supplier. If such items are modified in the field to fit, the Institute specifically disclaims all liability and responsibility for any harm resulting therefrom.

If any error or omission is noted in this bulletin, it should be reported immediately to the Friction Materials Standards Institute, Inc., 588 Monroe Turnpike, Monroe, Connecticut 06468.