

Rockwell International
(Automotive Group)

EMPLOYEE'S NAME Local 1924 DEPARTMENT _____ CLASSIFICATION _____ SHIP _____

Around the assembly area there is a large accumulation of asbestos dust in the air and on the floor that is caused from employees sanding and drilling the brake shoe liners. This in turn is being blown around the shop by people using air hoses in this area.

ARMBEV 0003676