

To: Distribution

From: Brett Bass
Date: October 29, 1986

Subject: VCM LEAK DETECTION SURVEY

Interoffice
Communication

VISTA

Attached are the results of the completed 1986 Comprehensive VCM Leak Detection Survey. A total of eleven (11) leaks were detected and repaired. Every connection, flange, valve, etc. on the attached isometric drawings was checked with a portable hydrocarbon detector (HNU). The points with readings above 50ppm with the probe as close to the equipment as possible were considered leaks and were noted. A tabulated list of all the VCM leaks reading over 50ppm is attached.

A bar chart showing a decrease in the number of detected leaks over the past seven years is included on the following page.

If there are any questions or comments, please advise.

E. B. Bass

E. B. Bass
PROCESS ENGINEER

J. B. Popp

J. B. Popp
PROCESS ENGINEER

/beb

cc: JF, JWW; DWH, VEM, CWT, RAF, MLN, TFL, JGC,