

FILE NAME: Allied Signal Bendix (ASB)

DATE: 1976 Dec 10

DOC#: ASB141

DOCUMENT DESCRIPTION: Bendix Ballot RE FMSI Recommending
Procedures for Reducing Asbestos Dust During Brake Servicing

BALLOT

Friction Materials Standards Institute, Inc.
E-210 Route 4
Paramus, New Jersey 07652

Subject: Publication in FMSI Catalogs of Recommended
Procedures for Brake Service Shops

Gentlemen:

- | | <u>YES</u> | <u>NO</u> |
|---|------------|-----------|
| 1. I favor the Asbestos Study Committee recommending to the Board of Directors the printing of a page in FMSI Catalogs recommending procedures for reducing asbestos dust during brake servicing. | <u>X</u> | — |
| 2. I favor use of the write-up "Recommended Procedures for Reducing Asbestos Dust During Brake Servicing" as written. | <u>X</u> | — |
| 3. Those with <u>comment</u> , and those in favor of rewriting the recommended procedures, please enter comments below. | | |

1. PRINTING A PAGE IN THE FMSI CATALOGS STILL DOES NOT GET PROCEDURES
INTO THE HANDS OF THE GARAGE MECHANIC.
THE IDEAL SOLUTION IS FOR REBUILDERS OR OTHER PEOPLE PUTTING
LINING SETS INTO INDIVIDUAL BOXES TO INCLUDE A FOLDED
8 1/2 X 11 SHEET ON PROCEDURES IN EACH BOX.
THE DRAWBACK OF COURSE IS SEVERAL PENNIES COST.

BY David E. Stone

Company BENDIX - FRICTION MATERIALS DIV.
TROY N.Y.

Date DEC 10, 1976



FMSI 03182