



INTERNAL CORRESPONDENCE

*Cholomayor*  
RECEIVED

JUN 19 1975

R. N. WHEELER, JR.

CHEMICALS AND PLASTICS

SOUTH CHARLESTON PLANT

P. O. BOX 8004, SOUTH CHARLESTON, W. VA. 25303

To (Name) Mr. R. P. Fulkner  
Division  
Location LOCATION 514

Date June 18, 1975

FILE COPY

Originating Dept.

DC: NO

VE

Answering letter date

Copy to Mr. H. D. Barnes  
Mr. J. L. Carvajal  
Mr. M. E. Eisenhour, 515  
Mr. C. E. Fry  
Mr. R. N. Wheeler, Jr. ←

Subject VCM Model 1200  
Monitor Maintenance

The 085 Department shares the concern of the 083 Department regarding the quality of data appearing on VCM Model 1200 Monitor typewriter sheets.

The request made by Charlie Fry to have service-call results documented on the log sheets themselves is an excellent suggestion. Please extend this to apply to the 085 Department also.

At the present time, we have set both 08500 Terminet typewriters on "double space" to facilitate inclusion of operator comments regarding sources of any VCM peaks in the spaces between lines of print. This procedure puts the comment adjacent to the problem area on the sheet. This double-spacing procedure will facilitate better display of both operators' and technicians' comments.

Sincerely,

*Jay E. Giffin*

J. E. Giffin

JEG/ra

UCC  
023471