



Interoffice Communication

To G. T. Hinton
From R. W. Churns
Date January 4, 1973
Subject New Instrument Air Dryer

Attached is the flow sheet showing the installation of the new instrument air dryer which was obtained from Trainer. The recommended location for this dryer is between T-609, the instrument air receiver, and BL-606, the auxiliary air compressor.

Please proceed with the installation of this dryer as soon as possible.

R. W. Churns
Process Engineer

APPROVED:

is

Enc

CC: RHG-RDG-GTH(5)-JRH(4)-JDM-JCL-DCS

BY PHC DATE 1-2-73
CHKD. BY _____ DATE _____

SUBJECT INSTALLATION OF AIR DRYER

SHEET NO. _____ OF _____
JOB NO. _____

