


NEED SOURCE OF FEED WHEN
MAIN MILL IS DOWN



NEED BETTER ELEVATOR
FOR PHASE II

WE ARE NOW SIZED FOR 1000 TPD.
 $\frac{1000}{365} = 2.75 \text{ TPD}$. WE DO THIS?