

MODI Chemical

EDISON

MATERIAL SAFETY DATA SHEET

(Approved by U.S. Department of Labor "Essentially Similar" to Form OSHA 20)

Conforms to air pollution rules and regulations

SECTION 1	
MANUFACTURER'S ADDRESS P.O. Box 250, Edison, N.J. 08917	
CHEMICAL NAME OR FAMILY Oleoresinous Coating	EMERGENCY TELEPHONE 212/883-5353
FORMULA Not Applicable	TRADE NAME Chimney Dum Dum Cement Gray 97-F-36

HAZARDOUS INGREDIENTS		
SECTION	2 % WT.	TLV (Units)
ASBESTOS FIBRE	<5	NOT ESTABLISHED BY ACGIH
EXEMPT MIN. SPIRITS	20	100 PPM
TOLUENE	<5	100 PPM

PHYSICAL DATA					
BOILING POINT °F	VAPOR PRESSURE mm Hg at 68 °F	VAPOR DENSITY (AIR = 1.0)	SPECIFIC GRAVITY (H ₂ O = 1.0)	% VOLATILE BY VOLUME	EVAP. RATE (BUTYL ACET = 1)
206	2.30	4.7	1.23	37	0.10
SOLUBILITY IN WATER NO					
APPEARANCE AND ODOR NORMAL FOR A PAINT OR COATING TYPE PRODUCT					

SECTION 4 FIRE AND EXPLOSION HAZARD			
FLASH POINT TCC/PM °F	FLAMMABLE LIMITS LEL UEL		EXTINGUISHING MEDIA CARBON DIOXIDE, DRY CHEMICAL, FOAM, AND/OR WATER FOG.
101	1.0	6.0	
SPECIAL FIRE FIGHTING PROCEDURES Fire fighters must wear self contained breathing apparatus or air masks. Containers exposed to fire should be kept cool with water spray.			
UNUSUAL FIRE AND EXPLOSION HAZARDS NONE			

The information on this sheet is contained herein solely for informational purposes and is not intended to constitute a contract or warranty of any kind. The user of this product should read and understand the entire label and follow the directions for use.

HEALTH HAZARD DATA

THRESHOLD LIMIT VALUE	SECTION 2	Not Required for Mixtures
EFFECTS OF OVEREXPOSURE		
RESPIRATORY IRRITATION, DIZZINESS, NAUSEA, LOSS OF CONSCIOUSNESS		

EMERGENCY AND FIRST AID PROCEDURES		
INHALATION: REMOVE PERSON FROM EXPOSURE AREA		
IF BREATHING HAS STOPPED, USE MOUTH TO MOUTH RESUSCITATION		
AND GET MEDICAL ATTENTION		
EYE CONTACT: FLUSH WITH WATER FOR 15 MINUTES.		
SKIN CONTACT: WASH WITH SOAP AND WATER		

SECTION 3 REACTIVITY DATA		
STABLE	UNSTABLE	CONDITIONS TO AVOID
Y		
INCOMPATIBILITY NONE		
HAZARDOUS DECOMPOSITION PRODUCTS		
CARBON DIOXIDE AND CARBON MONOXIDE		
HAZARDOUS POLYMERIZATION CONDITIONS TO AVOID		
NONE	MAY OCCUR	
Y		

SECTION 7 SPILL OR LEAK PROCEDURES		
VENTILATE AREA. AVOID BREATHING OF VAPORS		
USE SELF-CONTAINED BREATHING APPARATUS OR AIR MASK		
FOR LARGE SPILLS IN A CONFINED AREA		
AVOID CONTACT WITH EYES		
WIPE UP OR ABSORB ON SUITABLE MATERIAL AND SHOVEL UP		

WASTE DISPOSAL METHOD		
Dispose in chemical disposal area or in a manner that complies with local, state and federal regulations		
Do not incinerate closed containers.		

SECTION 3			SPECIAL PROTECTION INFORMATION		
RESPIRATORY PROTECTION					
Use appropriate Bureau of Mines approved respiratory device in confined areas and for spray application					
VENTILATION		LOCAL		OTHER	
Required for spraying or in a confined area.					
Ventilation equipment should be explosion proof.				NONE	
PROTECTIVE GLOVES		USUAL HAND PROTECTION FOR PAINT APPLICATION			
EYE PROTECTION		USUAL EYE PROTECTION FOR APPLYING PAINT			
OTHER PROTECTIVE EQUIPMENT					
USUAL CLOTHING FOR PAINTING OPERATIONS					

SECTION IX SPECIAL PRECAUTIONS		
PRECAUTIONS TO BE TAKEN IN HANDLING AND STORAGE		
Containers should be grounded when pouring. Avoid free fall of liquid in excess of a few inches. Keep away from heat, sparks and open flames. Keep container closed when not in use. Do not store above 120 °F. Based on the product flash point and vapor pressure suitable storage should be provided in accordance with OSHA Regulation 1910.106		