

A U T O M O T I V E D A T A B O O K B U L L E T I N #4-921

February 19, 1993

	FRONT FMSI NO.	SYSTEM F/R	REAR FMSI NO.
<u>ACURA</u>			
1993, Vigor	7382-D503**	D/D	7418-D537**
<u>AUDI (See Corrections)</u>			
1992, 100		/D	7309-D228**
1993, 90 Quattro	7352-D419**	D/	
<u>BMW</u>			
1993-92, 318i	7437-D558**	D/D	7449-D396**
1993-92, 325i	7437-D558**	D/D	7449-D396**
1993, 325iS	7437-D558**	D/D	7449-D396**
<u>CHEVROLET</u>			
1993, Corvette	7300-D412**	D/D	7301-D413**
<u>CHEVROLET TRUCK (See Comments & Corrections)</u>			
1993-91, S-, T-10	7480A-D202 (Note #1)	D/	
<u>CHRYSLER (See Comments)</u>			
1993-92, Imperial	7481A-D478 (Note #2)	D/D	7438A-D559
<u>DODGE</u>			
1993, Colt 2DR	7482-D602** (Notes #3 & #7)	D/N	1442-S644*
1993, Colt 4DR	7483-D602** (Note #4)	D/N	1415-610*
1993, Colt 4DR w/ABS	7483-D602**	D/D	7474-D596**
<u>EAGLE</u>			
1993, Summit 2DR	7482-D602**	D/N	1442-S644*
1993, Summit 4DR	7483-D602**	D/N	1415-610*
1993, Summit 4DR w/ABS	7483-D602**	D/D	7474-D596**
<u>FORD (See Corrections)</u>			
1993, Crown Victoria Police	7082E-D346	D/	
1993, Taurus		/N	1395-599
<u>GEO</u>			
1993, Metro	7310-D420** OR 7331-D451**	D/N D/	1414-608*
1993, Storm	7348-D468**	D/N	1430-S628*
1993, Tracker	7305-D418**	D/N	1440-S641*
<u>GMC TRUCK (See Comments & Corrections)</u>			
1993-91, S-, T-15	7480A-D202	D/	
1993, B700	7818-D225** (Note #6)	D/D	7818-D225**

SEE DISCLAIMER AT END OF BULLETIN

FMSI® and FMS® are registered trademarks of the Friction Materials Standards Institute, Inc.

Copyright© by Friction Materials Standards Institute, Inc.

	FRONT FMSI NO.	SYSTEM F/R	REAR FMSI NO.
<u>HYUNDAI</u>			
1993, Elantra	7329-D449**	D/N	1448-S661*
1993, Excel	7376-D497**	D/N	1451-S663*
1993, Scoupe	7446-D566**	D/N	1451-S663*
1993, Sonata	7329-D449**	D/N	1395-599*
OR		/D	7419-D538**
<u>ISUZU</u>			
1993, Stylus	7348-D468**	D/N	1430-S628*
OR		/D	7393-D515**
1993, Trooper	7459-D579**	D/D	7460-D580**
1993, Pick-up	7348-D468**	D/N	1430-S628*
OR		/D	7393-D515**
<u>LEXUS</u>			
1993, ES300	7357-D476**	D/D	7223-D325**
1993, SC300	7357-D476**	D/D	7452-D572**
1993, SC400	7451-D571**	D/D	7452-D572**
<u>MERCEDES (See Corrections)</u>			
1992-91, 300 SD		/D	7484-D603**
			(Notes #5 & #8)
1992-91, 300 SE		/D	7484-D603**
1992-91, 400 SE		/D	7484-D603**
1992-91, 500 SEL		/D	7484-D603**
1992-91, 600 SEL		/D	7484-D603**
<u>MERCURY (See Corrections)</u>			
1993, Grand Marquis Police	7082E-D346	D/	
1993, Sable		/N	1395-599
<u>MITSUBISHI</u>			
1993, Mirage 2DR	7482-D602**	D/N	1442-S644*
1993, Mirage 4DR	7483-D602**	D/N	1415-610*
1993, Mirage 4DR w/ABS	7483-D602**	D/D	7474-D596**
1993, Precis	7376-D497**	D/N	1451-S663*
<u>NISSAN</u>			
1993-91, Axxess	7342-D462**	D/N	1428-S625*
1993, Maxima	7407-D526**	D/N	1381-607*
OR		/D	7421-D595**
1993, NX 1.6L	7389-D510**	D/N	1438-S638*
1993, NX 2.0L	7428-D549**	D/N	1438-S638*
1993, Sentra 1.6L	7389-D510**	D/N	1438-S638*
1993, Sentra 2.0L	7388-D509**	D/N	1438-S638*
OR	7428-D549**	D/D	7390-D511**
1993, 240SX	7307-D422**	D/D	7146-D272**
1993, 240SX w/ABS	7342-D485**	D/D	7146-D272**
1993, 300ZX	7340-D460**	D/D	7341-D461**
1993, Pathfinder	7228-D333**	D/N	1399-574*
OR		/D	7290-D401**
<u>OLDSMOBILE (See Comments & Corrections)</u>			
1993-91, Bravada	7480A-D202	D/	
<u>PLYMOUTH</u>			
1993, Colt 2DR	7482-D602**	D/N	1442-S644*
1993, Colt 4DR	7483-D602**	D/N	1415-610*
1993, Colt 4DR w/ABS	7483-D602**	D/D	7474-D596**

	FRONT FMSI NO.	SYSTEM F/R	REAR FMSI NO.
<u>SATURN</u>			
1993, Station Wagon	7386-D507**	D/N	1437-S637*
OR		/D	7387-D508**
<u>SUBARU</u>			
1993, Justy (12" wheels)	7362-D480**	D/N	1363-591*
1993, Justy (13" wheels)	7377-D498**	D/N	1363-591*
1993, Loyale	7213-D311**	D/N	1392-563*
1993, Loyale 4WD	7213-D311**	D/N	1392-562*
1993-92, Legacy	7350-D470**	D/D	7351-D471**
OR	7442-D563**	D/	
<u>SUZUKI (See Corrections)</u>			
1993, Sidekick 2DR	7305-D418**	D/N	1440-S641*
1993, Swift 4DR		/N	1461-S630*
<u>TOYOTA</u>			
1993, Camry	7441-D562**	D/N	1447-587*
OR	7357-D476**	D/D	7223-D325**
1993, Celica	7450-D570**	D/N	8104-588*
OR	7247-D356**	D/D	7223-D325**
1993, Corolla	7441-D562**	D/N	8105-597*
1993-92, Corolla Wagon 4WD	7153-D242**	D/N	8104-372*
1993, MR2	7153-D242**	D/D	7409-D528**
1993, MR2 Turbo	7462-D582**	D/D	7409-D528**
1993, Paseo	7153-D242**	D/N	1439-S642*
1993, Tercel	7153-D242**	D/N	1439-S642*
1993, Land Cruiser	7298-D502**	D/N	1383-549*
1993-92, Pick-up	7127-D207**	D/N	1358-505*
1993-92, Pick-up Longbed	7320-D589**	D/N	1358-505*
1993-92, Pick-up Xtra Cab	7320-D589**	D/N	1358-505*
1993, Previa Van	7380-D500**	D/N	1358-505*
OR	7408-D527**	D/D	7381-D501**
1993, 4-Runner		/N	1397-589*
1993, T100 4WD		/N	1397-589*
<u>VOLKSWAGEN</u>			
1993, Corrado	7143-D227**	D/D	7234-D340**
1993, Cabriolet	7183-D569**	D/N	1354-559
1993, Golf	7209-D280**	D/N	1450-S662
OR	7143-D227**	D/	
1993, Golf GTI	7177-D227**	D/D	7234-D340**
1993, Jetta	7209-D569**	D/N	1450-S662
OR	7143-D227**	D/D	7234-D340**
OR	7143-D290**	D/	

C O M M E N T S

Existing shoe with new lining:

Shoe	Assembly	Application
D202	7480A-D202	1993-91 Chev Truck S-, T-10 Front
		1993-91 GMC Truck S-, T-15 Front
		1993-91 Oldsmobile Bravada Front
D478	7481A-D478	1993-92 Chrysler Imperial Front
D225	7818-D225	1993 GMC Truck B700 Front & Rear

C O R R E C T I O N S

Bulletin #3-921 incorrectly listed 1992 Audi 100 Rear as FMSI 7144-D228. The correct listing is 7309-D228. Also, 1993 Audi 90 Quattro as FMSI 7306-D419. The correct listing is 7352-D419.

1993-91 Chevrolet Truck S-10 & T-10, GMC Truck S-15 & T-15 and Oldsmobile Bravada were originally shown with FMSI 7070A-D202. The correct listing is FMSI 7480A-D202.

Bulletin #3-921 listed 1993 Ford Crown Victoria Police and 1993 Mercury Grand Marquis Police Front as FMSI 7082B-D346. The correct listing is 7082E-D346.

Bulletin #3-921 listed FMSI 1395-566 for 1993 Ford Taurus and Mercury Sable Sedan rear. This is incorrect. The correct listing is 1395-599.

Bulletin #1-921 incorrectly listed FMSI 7374-D495 for rear application for 1992-91 Mercedes 300SD, 300SE, 400SE, 500SEL and 600SEL. The correct listing is 7484-D603.

Bulletin #3-921 listed 1993 Suzuki Swift 4DR Rear as FMSI 1461-S674. Shoe assignment S674 has been canceled. The correct listing is FMSI 1461-S630.

DISC BRAKE LINING ASSIGNMENTS

Note #1	<u>FMSI 7480A</u>				7480A-D202	
	46.0	x	10.4	x	125.0	2 - 16
	46.0	x	9.3	x	125.0	2 - 16
	(1.80	x	.409	x	4.92)	
	(1.80	x	.366	x	4.92)	
Note #2	<u>FMSI 7481A</u>				7481A-D478	
	45.8	x	12.7	x	128.5	2 - 10
	45.8	x	9.2	x	151.8	2 - 10
	(1.80	x	.500	x	5.06)	
	(1.80	x	.362	x	5.98)	
Note #3	<u>FMSI 7482</u>				7482-D602	
	44.5	x	15.0	x	96.0	4 IM
	(1.75	x	.591	x	3.78)	
Note #4	<u>FMSI 7483</u>				7483-D602	
	46.0	x	15.0	x	104.1	4 IM
	(1.81	x	.591	x	4.10)	
Note #5	<u>FMSI 7484</u>				7484-D603	
	49.5	x	15.7	x	61.7	4 IM
	(1.95	x	.618	x	2.43)	
Note #6	<u>FMSI 7818</u>				7818-D225	
	2.44	x	1.068	x	6.82	2 IM
	2.43	x	.877	x	10.47	2

DISC BRAKE SHOE ASSIGNMENTS

Note #7	<u>FMS D602</u>		7482-D602	Dodge Eagle Mitsubishi Plymouth
	114.3	x 5.1	7483-D602	
	(4.50	x .201)		

DISC BRAKE SHOE ASSIGNMENTS (con't)

Note #8	<u>FMS D603</u>	7484-D603	Mercedes
	61.7 x 4.1		
	(2.43 x .161)		

CLUTCH FACING APPLICATIONS BY MODELCHEVROLET/GMC TRUCK

1993-85, Chev/GMC Truck	11,004A
	(Note #18)

FORD

1989, Thunderbird SC 3.8L	11,014
	(Note #19)

FORD TRUCK

1992-87, Ford Truck	11,015
	(Note #20)
1992-87, Ford Truck	11,016
	(Note #21)

GEO

1992-89, GEO Metro 1.0L	660
	(Note #9)

HONDA

1988-85, Honda	8053
	(Note #13)

ISUZU

1989-88, Isuzu Pick-up	9041A
	(Note #15)
1989-88, Isuzu Trooper	9041A

MACK TRUCK

1988-80, Mack Truck	1399
	(Note #10)
1988-80, Mack Truck	1448
	(Note #11)

MAZDA

1989-81, Mazda	7000
	(Note #12)
1989-87, Mazda Pick-up	9041A

NISSAN

1988-79, Nissan	9041
	(Note #14)

SUZUKI

1989-86, Suzuki	7000
-----------------	------

TOYOTA

1989-88, Toyota 4 Runner	9042
	(Note #16)
1988-87, Toyota Land Cruiser	10,018
	(Note #17)

CLUTCH FACING ASSIGNMENTS

Note #9	<u>FMSI 660</u> 6.72 x 4.35 x .128	16 Gr A Str	-	16
Note #10	<u>FMSI 1399</u> 13.88 x 7.70 x .160	36 DGEP	-	36
Note #11	<u>FMSI 1448</u> 14.94 x 8.48 x .165	36 DGEP	-	36
Note #12	<u>FMSI 7000</u> 7.46 x 5.22 x .140	16 Gr A Str	-	16
Note #13	<u>FMSI 8053</u> 8.35 x 5.93 x .140	16 Gr A Str	-	16
Note #14	<u>FMSI 9041</u> 9.45 x 6.29 x .140	18 Gr A Str	-	18
Note #15	<u>FMSI 9041A</u> 9.45 x 6.29 x .140	32 DGAP	-	32
Note #16	<u>FMSI 9042</u> 9.30 x 5.95 x .140	16 Gr A Str	-	16
Note #17	<u>FMSI 10.018</u> 10.05 x 6.70 x .135	36 DGAP	-	36
Note #18	<u>FMSI 11.004A</u> 11.83 x 6.79 x .138	40 DGAP	-	40
Note #19	<u>FMSI 11.014</u> 11.00 x 7.81 x .135	16 Gr A Str	-	16
Note #20	<u>FMSI 11.015</u> 11.00 x 6.50 x .135	36 DGAP	-	36
Note #21	<u>FMSI 11.016</u> 11.00 x 6.50 x .142	36 DGAP	-	36

The data shown in this bulletin has been supplied by sources considered to be reliable. While we believe that such information is correct, the Institute cannot and does not accept any responsibility or liability for errors or omissions, or harm resulting therefrom.

The data shown in this bulletin indicates dimensions only and in no way refers to quality of any materials that may be embodied in the product or particular application involved, and moreover SINCE FIELD CONDITIONS AND OTHER FACTS MAY NECESSARILY VARY FROM ONE APPLICATION TO ANOTHER, FRICTION MATERIALS SUPPLIERS AND INSTALLERS SHOULD RELY ULTIMATELY AND SOLELY UPON THEIR OWN EXPERTISE AND JUDGMENT AS TO QUALITY AND DIMENSIONAL SIZE. Under no circumstances should replacement items be used when they do not appear to fit, nor be "forced" to fit, nor be modified in the field instead of obtaining a proper sized item from a supplier. If such items are modified in the field to fit, the Institute specifically disclaims all liability and responsibility for any harm resulting therefrom.

If any error or omission is noted in this bulletin, it should be reported immediately to the Friction Materials Standards Institute, Inc., 588 Monroe Turnpike, Monroe, Connecticut 06468.