

FILE #

PERSONNEL MONITORING RECORD

JOB DESCRIPTION

NAME

DATE 02-13-92

BADGE # VCM # 1614

BADGE #

TIME 750 MIN

START 0525

FINISH 1715

WORK DESCRIPTION

1. Cracking Area
2. Overhead Condenser Link
3. pulling support Bundles
4. Cracking furnace
- 5.
- 6.
- 7.

UNUSUAL EXPOSURE VCM 3.52 PPM

BREATHING AIR YES NO

CART. MASK YES NO

REASON HI LEVEL VCM READING

REASON HI LEVEL EDC READING

PROPOSED CORRECTIVE ACTION

Employee notified 03-06-92

- | | | |
|--------------------------|----|----|
| 1. Daily log | 5. | 9 |
| 2. fill monitor card | 6. | 10 |
| 3. turn around of sample | 7. | 11 |
| 4. | 8. | 12 |

NGC 09100

FOREMAN

EMPLOYEE

HEALTH MGR.

SAFETY ENGR

FILE #

PERSONNEL MONITORING RECORD

JOB DESCRIPTION

NAME

DATE 02-13-92

BADGE # VCM. #1614

BADGE #

TIME 750 AM

START 0525

FINISH 1715

WORK DESCRIPTION

1. Cracking Area
2. Overhead Condenser Tank
3. pulling nitrogen bundles
4. Cracking furnace
5. _____
6. _____
7. _____

UNUSUAL EXPOSURE VCM 3.52 PPM.

BREATHING AIR YES

NO

GART. MASK YES

NO

REASON HI LEVEL VCM READING

REASON HI LEVEL EDC READING

PROPOSED CORRECTIVE ACTION

Employee notified 03-06-92

FOREMAN

EMPLOYEE

HEALTH MGR.

SAFETY ENGR

NGC 09101

0955
420

50
001

Reading

05-12-83

7.0

WDA

10

pg-10

9890 -

7851'

0.25

0.39

123.86

Vacation

78-91-11

NAME