



P-C Commercial Lines
Loss Prevention and Engineering

250 W. Pratt Street
Suite 920
Baltimore, MD 21201
February 18, 1992

Mr. Ron Shives, General Manager
Genuine Parts Company
Rayloc Division
100 Rayloc Drive
Hancock, MD 21750

Dear Mr. Shives:

This confirms my survey of your facility to evaluate employee exposure to airborne asbestos fibers. This evaluation was done as part of an ongoing evaluation of controls implemented to reduce the employee exposure.

The results of the survey are contained in the attached report. Thank you for your cooperation, if you have any questions feel free to contact me.

Sincerely,

David W. Glassman
Engineering Specialist -
Industrial Hygiene &
Environmental Services Unit
410 962-6453

This report is based upon the information supplied by company personnel and/or the conditions and practices we observed at the time of the visit. The report may not list all unsafe conditions and practices; others may exist. This report is not an endorsement of and it may not be used to endorse or promote any practices, procedures or products. Surveys and recommendations made by The Travelers are advisory and designed to assist customers in the maintenance of their own safety activities. Recommendations are not designed or intended for any other purpose. The Travelers is not responsible for making changes in the operations/procedures of the location or for implementing any recommendations. Boilers, pressure vessels and machinery are inspected only for conformance with jurisdictional laws, regulations and/or Travelers underwriting requirements. C-19102(R491)

NOVO20434